

ASS. REC. BY:

REF

CS3/CTI18021104/Ncd307

Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

Minimen

From (Person):

Elaine cheong

of

CTI

Date/Time:

22/11/18 @ 9.25am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB1180Y

Insured:

Yp 4945S

at Workshop m/s

Kent Seng Car

Tel:

9004 8759

of

Blk 1016 Yishun Ind. park A #01-238

Policy No:

DMCVS N 3094151700

Claim No:

8NML8 D05457C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9.56am @ 22/11/18

Person Contacted:

Kent Seng

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	GBB1180Y - NA/CTI18020956 /h4	DOA: 19/11/18
	Yp 4945S - NA/CTI18020956 /h4	DOA: 19/11/18
	After repair: 8/12/2018	

Barcode

NA2

REF: CT1

ASSIGNMENT

From: Date: 22/11/2018

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBB 1180Y

at Workshop m/s Kent Seng Car

of Blk 1016, Yishun Ind. Park A #01-238

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Kent Seng @ 9004 8759

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBB 1180Y Yr Regn: Aug / 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA DYNA C.C. 2982

Colour: SILVER A/C: ☒ Insured / Std / NI / NA

Sp. Reading: 712, 144 T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

C/No: 3TFN124305000237

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 195 / R15 C

R: 155 / R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or YOKO (R), DUN (R)

Front

Rear

R/Bal: 6 mm R/Bal: 5 mm

L/Bal: 6 mm L/Bal: 5 mm

D.O.A. D.O.I. 22/11/18

Survey held at KENT SENG

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / ☒ Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$6,000 - \$7,000 CT1

RECEIVED 06 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + R5. \$1

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format: PRE.

Lump Sum / I.B.I: (\$

150

150

30/11/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		22 Nov 2018 09:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S MENTAL LINK HARDWARE PTE LTD, Co. Reg. No.: -		
Main Claimant:	KEYON CONSTRUCTION PTE LTD, Co. Reg. No.: 200209463Z		
Vehicle Reg. No.:	GBB1180Y	Date of Loss:	19/11/2018 11:00 - :59
Claim Type:	TP / SNM18D05457C02	Policy/Cover Note No.:	DMCVSN3094151700 (Comprehensive)
Vehicle Reg. No. (Insured):	YP4945S	Policy No. (Claimant):	2100310120-06
		Excess:	S\$0.00
Repairer:	Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/12/2018]		
Driver/Custodian (Insured):	TAN CHUNG ENG (49 / Male), NRIC: S6905691A, Tel: +6596328989		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

⇒ Branch Office:

Please reply to our Branch Office for this matter

11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/K2/1812781/st
Your Reference : YP 4945S

Date : 20 November 2018

BY EMAIL: claimsdept@sg.cntaiping.com ONLY

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 19/11/2018 INVOLVING VEHICLE NOS. GBB 1180Y AND YP 4945S ALONG KJE.**

We are instructed by MARKANDAN SENTHIL (driver of motor vehicle no. GBB 1180Y) and/or KENT SENG CAR SERVICES (the motor workshop for GBB 1180Y) to notify you of a road traffic accident on 19/11/2018 at about 1130 hours along KJE involving our client's vehicle registration number [GBB 1180Y] and [YP 4945S] driven by you at the material time.

As a result of the accident, our client's vehicle has been damaged.

Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO
(Branch Office)

Encl

c.c. 1) METAL LINK HARDWARE PTE LTD

(Vehicle : YP 4945S)

- 2) **NAME OF WORKSHOP:**
KENT SENG CAR SERVICES
Blk 1016 Yishun Industrial Park A
#01-238 Singapore 768758
Tel: 9004-8759

(Vehicle: GBB 1180Y)

(Contact person: Ah Seng)

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBB1180Y		
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup		
Vehicle Attachment 1 :	With Hood		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	DYNA 100 MANUAL		
Chassis No. :	JTFNT24Y305000237		
Propellant :	Diesel		
Engine No. :	1KD1826207		
Engine Capacity :	2982 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3000 kg		
Unladen Weight :	1860 kg		
Year Of Manufacture :	2008		
Original Registration Date :	07 Aug 2008		
Lifespan Expiry Date :	06 Aug 2028		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$15,582.00		
COE Expiry Date :	06 Aug 2023		
Road Tax Expiry Date :	06 Aug 2019		
Inspection Due Date :	06 Aug 2019		
Intended Transfer Date :	06 Dec 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9463Z
Vehicle Details	
Vehicle No.:	GBB1180Y
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 100 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1826207
Chassis No.:	JTFNT24Y305000237
Maximum Power Output:	-
Open Market Value:	\$21,247.00
Original Registration Date:	07 Aug 2008
First Registration Date:	07 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$1,063.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$14,543.00
Total Rebate Amount:	\$14,543.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 06 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2018 10:49
Date Of Accident	19/11/2018 11:30
Exact Location Of Accident	TENGAH FLYOVER AFTER KJE HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB1180Y
Insured/Policyholder	
Name Of Registered Owner	KEYON CONSTRUCTION PTE LTD
Co Reg No	200209463Z
Email Address	JASKOH@KEYON.COM.SG
Mobile Phone No	
Alternative Phone No	Office-63626618

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 100 MANUAL-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100310120-06
Cover Note Number	

Driver

Name of Driver	MARKANDAN SENTHIL
Passport No/FIN	g7817977k
Date Of Birth	01/06/1981
Occupation	OUTDOOR
Date Of Driving Pass	26/04/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-99999999

Fax Number

Contact Number

EMail Address

JASKOH@KEYON.COM.SG

Address

61 WOODLAND INDUSTRIAL PARK E9 #02-03/04/05/06 EP PREMIUM

Postcode

757047

Was driver an employee of the Insured's Company

YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-
-
-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP4945S

Vehicle Make/Model/Colour

FUSO

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

M. H. H.


Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

KJE
(Highway) After
Tengah Flyover



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

In front car stop and I follow stop and vehicle yp 4945S unable to stop and hit my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

M. Hatt

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		22 Nov 2018 09:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S MENTAL LINK HARDWARE PTE LTD , Co. Reg. No.: -								
Main Claimant:	KEYON CONSTRUCTION PTE LTD , Co. Reg. No.: 200209463Z								
Vehicle Reg. No.:	GBB1180Y	Date of Loss:	19/11/2018 11:00 - :59 [123 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05457C02	Policy/Cover Note No.:	DMCVSN3094151700 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP4945S	Policy No. (Claimant):	2100310120-06						
		Excess:	S\$0.00						
Repairer:	Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238, 768758 Yishun - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 03/12/2018]								
Driver/Custodian (Insured):	TAN CHUNG ENG (49 / Male), NRIC: S6905691A, Tel: +6596328989								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB1180Y (SNM18D05457C02)
[YP4945S]
TP
KEYON CONSTRUCTION PTE LTD
Nov 19 2018 11:00AM
[M/S MENTAL LINK HARDWARE PTE LTD]
Kent Seng Car Services (yishun)

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	20/11/18 12:17	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 12:16	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
17	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
18	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
19	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
20	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
21	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
22	20/11/18 12:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	20/11/18 12:07	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/11/18 09:24	PRS		Load PDF	
2	22/11/18 09:24	OI GIA		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	20/11/18 12:17	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 12:16	Identification Card		Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
15	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
18	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
19	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
20	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
21	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
22	20/11/18 12:16	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	20/11/18 12:07	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>					
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>					

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18021104/NCD3E2

Date: 13/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3094151700
Claimant Vehicle No:	GBB1180Y	Insured Vehicle No:	YP4945S
Date of Loss:	19/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05457C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB1180Y		
Make & Model:	TOYOTA DYNA 100 MANUAL, 3.0 D (M)	Engine No:	1KD1826207
Reg. Date:	07/08/2008 (Man. Year: 2008)	Chassis No:	JTFNT24Y305000237
Colour:	Silver	Odometer:	712144 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/11/2018	
Date Inspected:	22/11/2018 Inspected At:	Kent Seng Car Services (yishun) (HQ) Blk 1016 Yishun Industrial Park A #01-238 Singapore 768758
Estimated Period of Repair:	7.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Dec 2018)

Parts: N/A TOYOTA DYNA 100 MANUAL 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBB1180Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >