

ASS. REC. BY:

REF:

CS/AIG/802/129/Tigd36

Special Instructions:

Surveyor

Member

ASSIGNMENT (Office)

From (Person):

Winnie Fan

of

AIG

Date/Time:

22/11/18 @ 11:53am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 4122M

Insured:

8KX854X

at Workshop m/z

The Sincere Motor

Tel:

of

20 shaw road # 01-03 ching shing Ind. Building

Policy No:

2100439214

Claim No:

10360287756

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/3/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:57am @ 22/11/18

Person Contacted:

Roy

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

FBM 4122M-X

SHC1544F-CCA/III 18015927/Gua 3q2

D.O.A: 19/7/2018

31/1/19 @ 3:22pm

Confirmed with Angeline LS \$1950, 5 days.

(P.R. \$1502, 447)

Signature: *Tanpin*

REF:

AICG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no/s: _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5

days

Res: _____

Yes or No

Lum Sum: _____

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

May

Veh No: *FBM4122M* Yr Regn: *2017* *alt*
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Jamster Jupiter

cc: *114*

Colour: _____

Black

AC: Insured / Std / NI / NA

Sp Reading: _____

20767

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MH34.E1120M J144277.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

20/10R17

R: _____

80/40R17

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1000 Gordide.

Front: _____

Rear: _____

R/Bal: _____

5

mm

R/Bal: _____

5

mm

L/Bal: _____

mm

L/Bal: _____

mm

D.O.A: _____

D.O.I: _____

23/11/2017

Survey held at _____

Since date.

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

459 2100, 5 days

RECEIVED 31 JAN 2019

Cons/Time: File Pass u?

30/1/2019

Cons/Time: File Return u?

u?

☐

: Preli. Report

☐

: Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee

Transport

3.00 - P1.00

1.00

1.00

1.00

TOTAL

Add Fee:

☐

Site Insp: *15*

☐

Interview: *15*

☐

Tech. Insp: *15*

☐

Week-end: *15*

Report Format: *MEATP*

Lump Sum / I.B.F. *1950*

250

10

260

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Fan, Winnie-LW
To:
Cc: Fong, Andy-SY, Chin, Lee-Ying
Sent: 22/11/2018 11:53:39 AM
Attachments:  tmp122F.TIF

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416
winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

19 November 2018

Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120



Dear Sir,

Re: Accident Involving FBM4122m AND SKX854X
Along Poh Huat Road
On 19 March 2018 @1845 Hrs

We are giving you notice of the above-mentioned accident involving our vehicle No. FBM4062C and Vehicle No. SHC1544E insured by your company.

As the accident was caused solely by the negligence of your insured rider, we hold your company fully responsible for all the damages sustained by us as a result of the said accident.

We would appreciate it if you could call us to arrange for the survey of the vehicle.

Our Vehicle is now lying at

THE SINCERE MOTOR REPAIRING PTE LTD
20 SHAW ROAD #01-03
CHING SHINE INDUSTRIAL BUILDING
SINGAPORE 367956

If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our vehicle and we shall proceed to engage Independent surveyor without further reference to you.

We henceforth reserve our rights to claim for loss of use during any delayed period of this survey arrangement.

This is an Initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is survey by a Motor surveyor appointed by the Insurance company.

Your kind co-operation in this respect will be very much appreciated.

Yours truly,


Angeline

Shiau Chan (LKKAuto)

From: Angie SH Cycle <angie@shcycle.sg>
Sent: Thursday, 31 January 2019 3:22 PM
To: Shiau Chan (LKKAuto)
Subject: RE: FBM4122M , DOA 19 Mar 2018

Dear Ms Chan,

We confirmed .

Thank you.

Angeline

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 30 January 2019 4:32 PM
To: Angie SH Cycle <angie@shcycle.sg>; SUR <sur@lkkauto.com>
Subject: RE: FBM4122M , DOA 19 Mar 2018

Dear Angie,

WITHOUT PREJUDICE

Offer Lump Sum \$1,950.00 and 5 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angie SH Cycle <angie@shcycle.sg>
Sent: Monday, 28 January 2019 1:44 PM
To: SUR <sur@lkkauto.com>
Subject: FBM4122M , DOA 19 Mar 2018

Dear Sir,

Please provide the final figure for the above mentioned vehicle that you survey on 23 Nov 2018.

Regards

Angeline

Shiau Chan (LKKAUTO)

From: Angie SH Cycle <angie@shcycle.sg>
Sent: Monday, 28 January 2019 1:44 PM
To: SUR
Subject: FBM4122M , DOA 19 Mar 2018

Dear Sir,

Please provide the final figure for the above mentioned vehicle that you survey on 23 Nov 2018.

Regards

Angeline

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0420C
Vehicle Details	
Vehicle No.:	FBM4122M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2018
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER 115 Z1
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	E3R5E0152503
Chassis No.:	MH3UE1120HJ144272
Maximum Power Output:	-
Open Market Value:	\$1,479.00
Original Registration Date:	25 Oct 2017
First Registration Date:	25 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$222.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,001.00
COE Rebate Amount:	\$5,346.00
Total Rebate Amount:	\$5,346.00

The information contained herein is correct as at 26 Nov 2018

OK

[.> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBM4122M		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	JUPITER 115 Z1		
Chassis No. :	MH3UE1120HJ144272		
Propellant :	Petrol		
Engine No. :	E3R5E0152503		
Engine Capacity :	114 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	223 kg		
Unladen Weight :	98 kg		
Year Of Manufacture :	2017		
Original Registration Date :	25 Oct 2017		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,001.00		
COE Expiry Date :	24 Oct 2027		
Road Tax Expiry Date :	24 Apr 2019		
Inspection Due Date :	24 Oct 2020		
Intended Transfer Date :	26 Nov 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/03/2018 11:24
Date Of Accident	19/03/2018 18:45
Exact Location Of Accident	POH HUAT ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM4122M
Insured/Policyholder	
Name Of Registered Owner	S. H. CYCLE PTE LTD
Co Reg No	200000420C
Email Address	SHCYCLE@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62998782
Vehicle Particulars	
Manufacturer	YAMAHA
Model	JUPITER 115 Z1-114CC
Exact Purpose for which vehicle was being used at time of accident	HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	SD18V00326
Cover Note Number	
Driver	
Name of Driver	DUAN XIN NING
Passport No/FIN	G2236646M
Date Of Birth	11/12/1988
Occupation	OUTDOOR
Date Of Driving Pass	29/08/2013
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84015219
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	220 HOUGANG ST 21 #02-52
Postcode	530220
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PAYA LEBAR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 114 HOUGANG AVENUE 1 #01-1270 , POSTCODE: 530114 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2899999 - FAX NO: 62815961
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN AND POLICE REPORT T/20180321/2116 DATED 21 MAR 2018

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS854X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEW SOEN PING
NRIC/Passport Number	S1803174D
Contact Number	97555248
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	DUAN XIN NING
Approximate Age	29
Injuries Sustain	
Injured person in which vehicle?	FBM4122M
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	220 HOUGANG ST 21 #02-52
Postcode	530220

Done IRAC
29/3/2018
1142am

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA), may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**), and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers), who have insured vehicles involved in this accident shall be collectively referred to as the **Insurers**, the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as of the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the **Purposes**).

(c) all insurers, who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(d) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms, which may be based outside of Singapore) for one or more of the above Purposes.



星發島
新加坡保險公司

殷新宇

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A-FBU 4122 M

B-SKS 854 X



← Poh Huat Rd

Poh Huat Crescent



Describe Circumstances of the Accident

I was riding along Poh Huet Road on 19-3-2018
at about 6:45pm

Suddenly a car cut into my lane to make
a right turn into Poh Huet Crescent.

I do not have enough time to react and
collided onto the car.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Drivers Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20180321/2116

1 of 3

Report No. T/20180321/2116

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/03/2018 16:43	Vide Report No.:	Station Diary No.: 28
--	------------------	--------------------------

Informant's Particulars

Name of Informant: DUAN XIN NING			Address: 220 Hougang st 21 #02-52 SINGAPORE 530220		
ID Type / ID No.: FIN NO / G2236646M			Contact No.: Home/Office: Mobile: 84015219		
Nationality: CHINESE			Email:		
Sex: Male	Age: 29	Date of Birth: 11/12/1988	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Motorcycle delivery man			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/03/2018 18:45	Type of Location:
Location: Along Road 1 POH HUAT ROAD Along Poh Huat road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM4122M	Motorcycle				Slightly Damaged	0
SKS854X	Car					0



**SINGAPORE
POLICE FORCE**



T/20180321/2116

2 of 3

Report No. T/20180321/2116

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

CONTINUATION OF REPORT

Brief Details.

On 19/03/2018 at about 1845hrs, I was on my way for a delivery and I was travelling along Poh Huat road in my motorcycle (FBM 4122M), everything was in order. I wish to state that the traffic there was not congested. As I was travelling along the road, there was a vehicle (SKS 854X) in front of me. Subsequently, I decided to go across the vehicle and before I knew it, the vehicle suddenly turned right which collided onto my motorcycle.

I went down and exchange particulars with the other driver, I suffered muscle strain on both legs and also on my right arm. In addition my vehicle suffered scratches on the motorcycle, the handle bar was damaged and it was not straight and the headlight was damaged from the impact of the accident. I wish to state that I was given three days Medical certificate for my injuries.

Driver's particulars for SKS 854X
Chew Soen Ping
S1803174D
Contact no: 9755 5248

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20180321/2116

3 of 3

Report No. T/20180321/2116

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /
Sgt 1 ONG YU HAN

Signature Of Informant:

[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
21/03/2018 16:43

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

Authentication Stamp
NP168

THE SINCERE MOTOR REPAIRING PTE LTD

20 Shaw Road #01-03 Ching Shine Industrial Building Singapore 367956

Tel: 6383 2767 Fax: 6296 4548

Company Registration Certificate: 200720671G

Date : 16 November 2018

OUR REF: ACCQ18110021

S. H. CYCLE PTE LTD

20 SHAW ROAD #01-03

CHING SHINE INDUSTRIAL BUILDING

SINGAPORE 367956

RE : ESTIMATED COST TO REPAIR YAMAHA JUPITER

VEHICLE NO : FBM4122M

DATE OF ACCIDENT : 19 March 2018 @1845 Hrs

LOCATION: POH HUAT ROAD

S/NO	UNIT	DESCRIPTION	U/PRICE	AMOUNT
1	1	MIRROR SET	\$ 50.00	\$ act 50.00
2	1	NIPPLE SET	\$ 18.00	\$ m.? 18.00
3	1	HANDLE BAR	\$ 115.00	\$ # 115.00
4	1	HANDLE BAR 'Y' BRACKET	\$ 135.00	\$ 71.2 135.00
5	1	HANDLE BAR TOP COVER	\$ 88.00	\$ act 88.00
6	1	HANDLE BAR FRONT COVER	\$ 68.00	\$ act 68.00
7	1	HEAD LAMP ASSY	\$ 110.00	\$ act 110.00
8	1	BRAKE LEVER	\$ 29.00	\$ act 29.00
9	1	FRONT SHIELD	\$ 270.00	\$ act 270.00
10	1	FOOT REST BAR AND RUBBER	\$ 95.00	\$ bb 95.00
11	2	FRONT FORK ASSY	\$ 200 320.00	\$ 4.80 640.00 bt
12	1	STEERING STEM WITH BEARING	\$ 195.00	\$? 195.00 act
13	1	EXHAUST HEAT SHIELD CHROME	\$ 68.00	\$ act 68.00
14	1	EXHAUST HEAT SHIELD METT	\$ 39.00	\$ act 39.00
15	1	REAR SIDE COVER (RH)	\$ 57.00	\$ act 57.00
16	1	DECAL SET	\$ 30.00	\$ act 30.00
17	1	REAR SHIELD	\$ 212.00	\$ act 212.00
				\$ 2,180.00 1979.
LESS 10 % DISCOUNT				\$ 218.00 1781.10
				\$ 1,962.00
18		TO RE-SPRAY CHARGE		\$ 350 600.00
19		TO STRAIGHTEN CHASSIS		photo? \$ 280 X 450.00 mm.
20		TO DISMANTLE & ASSEMBLE PARTS FOR REPAIR		\$ 250. 380.00
21		TOWING VEHICLE TO WORKSHOP		\$ ✓ 60.00 660
TOTAL AMOUNT :				\$ 3,452.00


26/11/18

3487.10

TOTAL AMOUNT :

Tanjil 97495749 / 6236356
-wp,
23/11/18 @ 1220 2441.11

Repair after repair
5 days
SVC @ luhauto.com

4581950

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018 Edit Reg		22 Nov 2018 00:00 Edit Adj Rpt	S\$1,950.00 Edit Estimates	S\$1,950.00 View Rpt		Pending for Survey Report Cancel Case




































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHEW SOEN PING , ID: S1803174D								
Main Claimant:	-								
Vehicle Reg. No.:	FBM4122M	Date of Loss:	19/03/2018 00:00 - :59 [4 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1036028777SG	Policy/Cover Note No.:	2100439714 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX854X	Policy No. (Claimant):							
		Excess:							
Repairer:	The Sincere Motor Repairing Pte Ltd (Shaw Rd) 20 Shaw Road #01-03, Ching Shine Industrial Building, 367956 Macpherson - Tel: 63832767								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (05/12/2018): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
















































Claim Documents

*FBM4122M (1036028777SG)
[SKX854X]

TP

Mar 19 2018 12:00AM
[CHEW SOEN PING]
The Sincere Motor Repairing Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	30/01/19 16:25	Odometer Reading									 Load JPG	<input checked="" type="checkbox"/>		
2	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
3	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
4	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
5	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
6	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
7	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
8	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
9	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
10	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
11	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
12	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
13	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
14	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
15	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
16	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
17	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
18	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
19	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
20	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
21	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
22	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
23	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
24	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
25	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
26	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
27	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
28	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
29	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
30	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
31	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
32	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
33	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
34	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
35	30/01/19 16:25	General View									 Load JPG	<input checked="" type="checkbox"/>		
36	30/01/19 16:25	General View									Load JPG	<input checked="" type="checkbox"/>		
37	30/01/19 16:25	General View									Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	30/01/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	30/01/19 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	30/01/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	30/01/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	30/01/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	30/01/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	30/01/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/19 16:24	Singapore Accident Statement	 Load PDF	
2	30/01/19 16:24	Police Report	 Load PDF	
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 11:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18021129/T1QD3E2

Date: 31/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100439714
 Claimant Vehicle No: FBM4122M Insured Vehicle No: SKX854X
 Date of Loss: 19/03/2018 Nature of Claim: TP Claim No: 1036028777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM4122M**
 Make & Model: YAMAHA JUPITER 115 Z1, 114cc Engine No: E3R5E0152503
 Reg. Date: 25/10/2017 (Man. Year: 2017) Chassis No: MH3UE1120HJ144272
 Colour: Black Odometer: 20267 km
 Engine Capacity: 114 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 80/90 R17
 Front Left Side: Goodride 5 mm Rear Left Side: Goodride 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,997.10	1,781.10	216.00	10.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	660.00	830.00	55.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,487.10	2,441.10	1,046.00	30.00
Approved Total (Overridden) (S\$)		1,950.00		
Nett Amount (S\$)	3,487.10	1,950.00	1,537.10	44.08

INSPECTION

Date of Assignment: 22/11/2018
 Date Inspected: 23/11/2018 Inspected At: The Sincere Motor Repairing Pte Ltd
 (Shaw Rd)
 20 Shaw Road #01-03, Ching Shine
 Industrial Building
 Singapore 367956

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR	Cut	50.00 FL	*50.00 FL
2	1		*SET NIPPLE	Missing	18.00 FL	*18.00 FL
3	1		*HANDLE BAR	Bent	115.00 FL	*115.00 FL
4	1		*HANDLE BAR Y BRACKET	Bent	135.00 FL	*135.00 FL
5	1		*HANDLE BAR TOP COVER	Cut	88.00 FL	*88.00 FL
6	1		*HANDLE BAR FRONT COVER	Cut	68.00 FL	*68.00 FL
7	1		*HEAD LAMP ASSY	Cracked	110.00 FL	*110.00 FL
8	1		*BRAKE LEVER	Cut	29.00 FL	*29.00 FL
9	1		*FRONT SHIELD	Cut	270.00 FL	*270.00 FL
10	1		*FOOT REST BAR AND RUBBER	Bent	95.00 FL	*95.00 FL
11	2		*FRONT FORK ASSY	Bent	640.00 FL	*400.00 FL
12	1		*STEERING STEM WITH BEARING	Necessary	195.00 FL	*195.00 FL
13	1		*EXHAUST HEAT SHIELD CHROME	Dented	68.00 FL	*68.00 FL
14	1		*EXHAUST HEAT SHIELD METT	Dented	39.00 FL	*39.00 FL
15	1		*REAR SIDE COVER (RH)	Cut	57.00 FL	*57.00 FL
16	1		*SET DECAL	Necessary	30.00 FL	*30.00 FL
17	1		*REAR SHIELD	Cut	212.00 FL	*212.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,219.00	1,979.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	221.90	197.90
Total Parts (\$\$)	1,997.10	1,781.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RE-SPRAY CHARGE	New	600.00	350.00
2	TO STRAIGHTEN CHASSIS	New	450.00	0.00
3	TO DISMANTLE & ASSEMBLE PARTS FOR REPAIR	New	380.00	250.00
4	TOWING VEHICLE TO WORKSHOP	New	60.00	60.00
Gross Labour Cost (S\$)			1,490.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >