

ASS. REC. BY:

REF: C3/FCU8021141/Usbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Cws Karen Tan of FCI Date/Time: 23-11-2018 21:43pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLX 5554S Insured: SHC 8916Uat Workshop m/s Tastech Auto Tel: 6746 5405of Blk 1 Kaki Bukit Ave 6 #01-46Policy No: _____ Claim No: DIS008327MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21-11-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: Nany Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 5554S - NM / AXA 18021146 / h4
	SHC 8916U - C3 / AXA 12022416 / Hw/Bsg 2

DCA: 21-11-2018

DCA: 27-11-2018

(08/11/13) , wef

ASS. REC. BY: MARCUS

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 5254Sat Workshop m/s SL

of _____

Insured: SLC 8916M

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 11.5K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/4/2019
3 door 4mth plus ashy flr. LTA 747426/11/18 L/S \$4000 confirmed with Ather.27/11/18 Confirmed L/S \$ 4,000/- @ 5 days with Marcus
(\$ 18,541.00 Red - 83%)MV - \$ 11,500.00LTA - \$ 7,494.00Net - \$ 4,006.00

RECEIVED 27 NOV 2018

Date/Time, File Pass to?

27/11/181) Typist

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$ 4,000/- L/S)Veh No: SLX 5254SYr Regn: 9/4/09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CarMake: ZIA Tautoc.c. 1368Colour: BlackA/C: Insured / Std / NI / NASp. Reading: 148388T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA19900000293451Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/11/18D.O.I. 22/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

12x15=180

170+180

50

50

97

547

MOTOR SURVEY ASSIGNMENT

Date	23-11-2018	Our Ref No. D18008327MFSH
Accident Date	21-11-2018	Claim Type. Third Party
Insured Vehicle	SHC8916U	Third Party Vehicle. SLX5554S
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

LOOKING FOR AN
INDEPENDENT SPECIALIST?

► Find the specialty Workshops for

Fiat

Price Range ▾

Depreciation ▾

2009 ▾

Vehicle Type ▾



Home » Used Cars » Platinum Group Pte Ltd » Fiat Bravo 1.4A T-Jet

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Fiat Bravo 1.4A T-Jet

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$16,588	
Depreciation	\$5,740 /yr View models with similar depreciation	?
Reg Date	30-Nov-2009 (1yr 6days COE left)	
Manufactured	2009	?
Mileage	101,000 km (11.2k /yr)	
Transmission	Auto	
Engine Cap	1,368 cc	
Road Tax	\$608 /yr	?
Power	88.0 kW (118 bhp) View specs of the Fiat Bravo (2007-2016)	
Curb Weight	1,335 kg	?
Features	1.4L Turbocharged Engine Powering 118Bhp, 6 Speed SMT Auto Transmission, Folding Side Mirrors, Multi SRS Airbags, Fuel Efficient.	
Accessories	Leather Seats, Sports Rims, 4 SRS Airbags, Factory Fitted Audio, Multi Function Steering, ABS, EBD, TCS, Fog Lamps, Solar Film.	
Description	Cheaper Than Rental And Ideally For Short Term Usage. Responsive Turbo Charged Engine That Delivers The Much Needed Pickup And Speed! Spacious Legroom And Boot Space For The Whole Family! Flexible Bank/In House Loan Available! Trade In Welcome! Hurry Down Before It's Gone!	
COE	\$18,267	?
OMV	\$21,508	?
ARF	\$21,508	?
Dereg Value	\$13,686 as of today (change)	?
No. of Owners	4	?
Type of Veh	Hatchback	
Category	PARF Car	
Availability	Available	



Seller Information

Company	Platinum Gro » dealer's pricelis » 22 vehs sold :
Address	8 Kaki Bukit Aven
Location	Premier @ Kaki B
Office No	69177880
Contact Person(s)	Derrick Vincent Tan Chye Yong Vincent Alan

Useful Services

Afraid of lemons? Requi
this car evaluated prof

Vehicle Evaluation

Find out the market va
Get a free Car Valuatic

Free Valuation

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?

[Click here to see all Auspicious Numbers!](#)

[Compare](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4747H
Vehicle Details	
Vehicle No.:	SLX5554S
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	FIAT
Vehicle Model:	GRANDE PUNTO 1.4 3DR M DYNAMIC
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	350A10003886042
Chassis No.:	ZFA19900000293451
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$14,454.00
Original Registration Date:	09 Apr 2009
First Registration Date:	09 Apr 2009
Transfer Count:	3
Actual ARF Paid:	\$14,454.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Apr 2019
PARF Rebate Amount:	\$7,227.00
Intended COE Rebate Details	
COE Expiry Date:	08 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$267.00
Total Rebate Amount:	\$7,494.00

The information contained herein is correct as at 23 Nov 2018

OK

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 21/11/18 at 2230hrs, I was driving my vehicle A along
 PIE towards Town. vehicle C stop, I follow suit, suddenly
 vehicle B hit on my rear and cause my car to push
 forward and hit on vehicle C. There were 3 cars
 involved in an accident

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Authorized
Name
4/5 @ 4000/
5 day.

VEHICLE NO: SLX 5554S

QTY	PARTICULAR
1 PCS	REAR BUMPER 1100.00
1 PCS	REAR BUMPER REINFORCEMENT
2 PCS	REAR BUMPER SIDE RETAINERS @ \$90.00
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REFLECTOR O/S
1 PCS	REAR FENDER O/S
1 PCS	REAR END PANEL
1 PCS	BONNET 1250.00
2 PCS	BONNET HINGES @ \$105.00
1 PCS	FRONT BUMPER 1080.00
1 PCS	FRONT BUMPER CENTRE GRILLE 185
1 PCS	FRONT BUMPER REINFORCEMENT 620
2 PCS	FRONT BUMPER SIDE RETAINERS @ \$90.00
1 SET	FRONT BUMPER CLIPS
1 PCS	FRONT BUMPER FOG LAMP
2 PCS	HEADLAMPS @ \$925.00 805.00
1 PCS	FRONT SUPPORT PANEL 662.00
1 PCS	AIR CON CONDENSER
1 PCS	RADIATOR
1 PCS	FRONT FENDER
1 PCS	FRONT LICENCE PLATE W/HOLDER

De/DJ	\$1,680.00
11	\$795.00 X
0/5 surf	\$180.00 1PC
ner	\$50.00
11	\$115.00 X
11	\$2,220.00 X
11	\$950.00 X
Bar/Buc	\$1,680.00
11	\$210.00 X
0/5 PC	\$1,650.00
10/10.5	\$315.00
10/10.5	\$715.00
Surf	\$180.00
11	\$50.00
11	\$388.00 X
11/550.0/550	\$1,850.00 1PC
11	\$885.00
11	\$1,110.00
11	\$1,688.00
11	\$755.00 X
Surf	\$45.00 405.00
	\$17,511.00

102

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REFIX REVERSE SENSOR
TO REFILL AIR CON GAS
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO SPRAY RUSF PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
\$80.00 50
\$150.00 100
11 \$100.00 X
\$120.00 50
\$1,500.00 800
\$3,000.00 1100
TOTAL \$22,541.00

6072
54648
7634.8
6107.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021141/Usbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8916U	Veh. Inspected	SLX 5554S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008327MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT PUNTO (M)	c.c	1368	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZFA19900000293451	Colour	BLACK	
Odometer	148358	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2018	Inspection Date	22/11/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 5554S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED / DISTORTED	1,680.00	1,100.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	795.00	-
2	REAR BUMPER SIDE RETAINERS @\$90.00	O/S BENT	180.00	90.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	115.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	2,220.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	950.00	-
1	BONNET	BENT / BUCKLED	1,680.00	1,250.00
2	BONNET HINGES @\$105.00	NOT NECESSARY	210.00	-
1	FRONT BUMPER	DENTED / DEFORMED	1,650.00	1,080.00
1	FRONT BUMPER CENTRE GRILLE	TORN / MISSING	315.00	185.00
1	FRONT BUMPER REINFORCEMENT	DENTED / BENT	715.00	620.00
2	FRONT BUMPER SIDE RETAINERS @\$90.00	BENT	180.00	180.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	388.00	-
2	HEADLAMPS @\$925.00	N/S BROKEN / O/S NOT NECESSARY	1,850.00	805.00
1	FRONT SUPPORT PANEL	CRACKED	885.00	662.00
1	AIR CON CONDENSER	NOT NECESSARY	1,110.00	-
1	RADIATOR	NOT NECESSARY	1,688.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	755.00	-
	LESS 10% DISCOUNT		-	-607.20
			17,466.00	5,464.80
SPECIAL NETT ITEMS				
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	45.00	40.00
			45.00	40.00

Report Ref No. CS/FCI18021141/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REFIX REVERSE SENSOR.		80.00	50.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.	NOT NECESSARY	100.00	-
	TO SPRAY RUSF PROOFING.		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S,REAR END PANEL AND FRONT FENDER.		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,100.00
			5,030.00	2,130.00
	GRAND TOTAL		22,541.00	7,634.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/FC118021141/Usbn2

MARKET VALUE: \$11,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,494.00=NETT VALUE: \$4,006.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.