



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLJ 1053 X**  
Make & Model : **TOYOTA WISH**  
Chassis No : **JTDGG20W30J006279**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1			
2	Rear windscreen sealant	1			
3	Reverse sensor	2			
4	Rear number plate	1			
6	Rear No.plate lamp LH	1			
7	Rear No.plate lamp RH	1			
8	Rear bumper	1			
9	Rear bumper clip	10			
10	Rear bumper side retainer LH	1			
11	Rear bumper side retainer RH	1			
12	Rear bumper bracket LH	1			
13	Rear bumper bracket RH	1			
14	Rear bumper sponge	2			
14	Rear Bumper reinforcement	1			
15	Rear bumper reflector LH	1			
16	Rear bumper reflector RH	1			
17	Rear bumper reflector garnish LH	1			
18	Rear bumper reflector garnish RH	1			
19	Tail door	1			
20	Tail door lock	1			
21	Tail door emblem	1			
22	"GREEN" Sticker	1			
23	Tail door chrome	1			

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*

**Spare Parts**

Vehicle No. : **SLJ 1053 X**  
Make & Model : **TOYOTA WISH**  
Chassis No : **JTDGG20W30J006279**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim	1			
25	Tail door trim clip	10			
26	Taildoor reflector LH	1			
27	Taildoor reflector RH	1			
28	Tail end panel	1			
29	Tail end panel garnish	1			
30	Tail end panel garnish clip	10			
31	Boot weatherstrip	1			
32	Tail lamp LH	1			
33	Tail lamp RH	1			
34	Spare tyre well panel	1			
35	Spare tyre board	1			
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLJ 1053 X** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA WISH** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LH REAR FENDER)	\$1,200.00	
3	To check Wiring	\$50.00	
4	To remove & refit reverse sensor	\$120.00	
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	
6	To remove & refit rear windscreen.	\$120.00	
7	To tuff coat.	\$250.00	
8	To transfer boot mechanism to new boot	\$120.00	
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/11/2018 11:33
Date Of Accident	17/11/2018 22:20
Exact Location Of Accident	TOA PAYOH OPPOSITE BLK 159
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ1053X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98347330
Alternative Phone No	OFFICE-98347330

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V00033/VPZ/R03
Cover Note Number	

### Driver

Name of Driver	IVAN LEE YOONG CHUE
NRIC No	S7732588C
Date Of Birth	05/11/1977
Occupation	INDOOR
Date Of Driving Pass	20/10/1998
Driving Experience	20 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98347330
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	25 AIRLINE ROAD 05A AIRLINE HOUSE
Postcode	819829
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF624A
Vehicle Make/Model/Colour	TOYOTA RUSH / GREEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOSHUA S/O KOVIL PILLAI
NRIC/Passport Number	S1292810F
Contact Number	90235691
Address	BLK 173 LORONG 1 TOA PAYOH #02-1264
Postcode	310173
Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	1



# SKETCH PLAN



## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


## 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Name & Time	 Driver's Signature (if driver is not the policyholder) / Date & Time	WITNESSED BY / 16/NOV/2016 Witnessed by Reporting Centre Personnel
---	---	---

## Sketch Plan



**Describe Circumstance of the Accident \***



On 17<sup>th</sup> Nov 2018 (SAT), around 2220 hrs, I exited the PTE at Toa Payoh Lorong 2. The traffic light at junction between Lorong 1 and Lorong 6 turned red. So I stopped in the red light, behind a few cars. I was around or near lamppost number 79454. And I can see Block 159 on ~~my~~ <sup>the</sup> my left. My car was stationary at the center lane waiting for the traffic light to turn green.


At stationary, the car SJF 624 A impacted me from the rear. The collision from the rear damaged the boot and rear bumper badly.

The front of the car SJF 624 A was seen with heavy damages. Both ~~drivers~~ <sup>drivers</sup> acknowledged the damages and ~~we~~ <sup>both</sup> both were not injured. We both had no passengers on board. We then proceeded to exchange details and left the ~~spot~~ <sup>scene</sup> scene.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Stamp  
  


Driver's Signature / Driver is not the policyholder / Date  
 17/11/18 Nov 2018

Witnessed by Reporting Centre Personnel