

15/5/2010

INS. CASE OWNER:

Winnie

CC

/AXA1802

1448, R/K/63⁵²

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KASOL

DOI:

05/12/18

Date / Time:

V/M/148

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKO 7107E

Name of Insured:

AMY WIR NEE Amy Wm Mary HUEN

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

16/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JOEL WONG 40

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SGM 0121V/ 83483

Policy No.:

01926461

Make / Model:

BMW

Place of Accident:

BAYVIEW VP

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

WIRNLS

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
10/11/18	SKO 7107E-X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
22/11/18	# start claim	After call ltr to OI:	20/11/18 - vic
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$5 days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 16/11/18 Confirm with: Suharmi Email ☐ Call ☐

Final Liability: % 100 Agreed / Assessed) BOLA S/N No. : If NO or B 28. Ass. Lia: (COI GOT STOP CLAIM/GIA)

Repair Cost: \$5 10967.79 9 days X 100

Loss of Rental (LOR): \$5 (S x days)

Loss of Use (LOU): \$5 (S x days)

Loss of Income (LOI): \$5 (S x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: \$5

Medical: \$5

Disbursement: \$5 (e.g. Tow/ Independent)

Legal Cost: \$5

Total: \$5 11930.79 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: \$5 11930.79 Name 1: Wearnes Automotive Pte Ltd. (GIA)

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

Signature: *[Signature]*

REF: ASM(UAA)

h

1563A

ASSIGNMENT

From: _____ Date: 05-12-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLU 1207L

at Workshop m/s: Wearnes

of 249 Alexandra Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Dork

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 99K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 1207L Yr Regn: 2017 NBV

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: RENAULT GRAND SCENIC / S c.c 1461

Colour: WHITE A/C Insured / Std / NI / NA

Sp. Reading: 20833 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1RFA00158580930

Gen Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 195/55R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 16/11/18 D.O.I. 05/12/18

Survey held at WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/FRT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

PIP \$ 10250.00 / Reel # 3845.35 / 2472

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18021148/hb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 22-11-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 3107E	Veh. Inspected	SLU 1207L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/11/2018	Inspection Date		
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

in 051218

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC
 Mr Goh Koon Wee GST Reg.No:M28920628X
 Blk 3128 Clementi Avenue 4 Inv.No. : B&P 0 Page 1
 #35-183 Inv.date. : 20/11/2018
 WIP No. : 39237
 Singapore 122312 Veh.In/Out: 20/11/2018
 *Tel.No. : Mobile: 86688082
 Reg.No. : SLU1207L
 Closed by : Derek Oh Siong Wee Reg.date : 23/11/2017
 Svc Consultant : Mileage : 0
 Remarks : Mr Goh Koon Wee Chassis No: VF1RFA00158580930

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BONNET, FRT BUMPER, FRT BRACKET, FRT LH HEADLAMP, FRT LH FENDER, FRT WHEEL ARCH, ETC	0	2250.00	0		2,250.00 S	1575 ✓
800	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, ETC	0	1600.00	0		1,600.00 S	1200 ✓
0031	TO REPLACE FRONT LH RIM	0	50.00	0		50.00 S	✓
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00 S	✓
280	TO FOCUS HEADLAMP	0	110.00	0		110.00 S	✓
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00 S	✓
RESETTING OF ALL ELECTRICAL MODULES							
	BUMPER LOWER GS4	1.0 EA	356.20			356.20 S	320.53 ✓
	BUMPER FRT GS4	1.0 EA	1165.50			1,165.50 S	1048.95 ✓
	BUMPER FRT CENTER IN	1.0 EA	122.10			122.10 S	109.89 ✓
	BUMPER BRACKET FRT R	1.0 EA	104.50			104.50 S	94.5 ✓

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4
#35-183

Singapore 122312

GST Reg.No: H28920628X

Inv.No. : B&P 0 Page 2

Inv.date: 20/11/2018

WIP No. : 39237

Veh.In/Out: 20/11/2018

*Tel.No. : Mobile: 86688082

Reg.No. : SLU1207L

Reg.date: 23/11/2017

Mileage : 0

Chassis No: VF1RFA00158580930

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Goh Koon Wee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BUMPER BRACKET FRT L	1.0 EA	104.50				104.50 S	94.05
CONVERGENT AIR KIT S	1.0 EA	114.90				114.90 S	
FOG LAMP MOULDING OU	1.0 EA	191.30				191.30 S	172.17
FOG LAMP COVER CHORM	1.0 EA	191.30				191.30 S	172.17
BUMPER FRT SUPPORT B	1.0 EA	91.80				91.80 S	82.62
BUMPER FRT TOP INNER	1.0 EA	560.90				560.90 S	
SUPPORT BRACKET, HEA	1.0 EA	38.90				38.90 S	59.94
SUPPORT BRACKET, HEA	1.0 EA	38.90				38.90 S	59.94
BUMPER FRT REINFORCE	1.0 EA	510.00				510.00 S	
FENDER FRT LH GS4	1.0 EA	512.70				512.70 S	461.43
BRACKET, FENDER FRT	1.0 EA	85.30				85.30 S	88.29
FENDER BRACKET FRT L	1.0 EA	78.20				78.20 S	80.91
WHEEL ARCH - FRT LH	1.0 EA	204.60				204.60 S	184.14
WHEEL ARCH CLIP J5AL	10.0 EA	5.30				53.00 S	47.70
HEADLAMP LH R9A3 GS4	1.0 EA	677.30				677.30 S	609.57
ALLOY RIM 20" R9A3 S	1.0 EA	558.00				558.00 S	887.76
TYRE PRESSURE SENSOR	1.0 EA	119.10				119.10 S	107.19

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4

#35-183

Singapore 122312

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Goh Koon Wee

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 20/11/2018

WIP No. : 39237

Veh.In/Out: 20/11/2018

*Tel.No. : Mobile: 86688082

Reg.No. : SLU1207L

Reg.date. : 23/11/2017

Mileage : 0

Chassis No: VF1RFA00158580930

Op.No Description Mech Qty Price Disc% Pkg Amount G

ADHESIVE SEALER FL2	1.0 EA	549.10	549.10 S	404.19
FOG LAMP LH/RH S3/ H	1.0 EA	185.50	185.50 S	X
PARK SENSOR BOTH CTR	4.0 EA	429.90	1,719.60 S	386.91

Resul
Hp 90010068
8 days
05/12/18 @ 1430
Repair by paint

Labour Total	4,620.00
Parts Total	8,333.20
Package Total	0.00

Gross Total.	12,953.20	14582.85
Net.....	12,953.20	
GST @ 7.0%	906.72	
Total.....	13,859.90	
Paid.....	0.00	
Please Pay..	13,859.90	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

- = supp.*
- ① Harness - Bumper Frt \$136.98 ✓ Shunter
 - ② Air Intake Hose, Bum \$95.22 ✓ CRA
 - ③ Fender Screw \$50.40 ✓ nee
 - ④ Gonna Panel Inner A \$738.54 ✓ CRA
 - ⑤ Eguerre G F \$53.82 ✓ CRA
 - ⑥ " D F \$67.86 ✓ CRA

SERVICE ESTIMATE

0 - A00005 SL: AXA INSURANCE PTE LTD
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date. : 18/01/2019
 WIP No. : 39237
 Veh.In/Out: 05/12/2018 14/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SLU1207L
 Reg.date : 23/11/2017
 Mileage : 20,868
 Chassis No: VF1RFA00158580930

Closed by : Derek Oh Siong Wee
 Svc Consultant : ACC
 Remarks : Mr Goh Koon Wee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BONNET,FRT BUMPER,FRT BRACKET,FRT LH HEADLAMP,FRT LH FENDER,FRT WHEEL ARCH,ETC	0	1575.00	0		1,575.00	S
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,FRT LH FENDER,ETC	0	1200.00	0		1,200.00	S
0031	TO REPLACE FRONT LH RIM	0	50.00	0		50.00	S
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S
280	TO FOCUS HEADLAMP	0	110.00	0		110.00	S
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S
RESETTING OF ALL ELECTRICAL MODULES							
	BUMPER FRT GS4	1.0 EA	1165.50	10		1,048.95	S
	BUMPER BRACKET FRT L	1.0 EA	104.50	10		94.05	S
	FOG LAMP COVER CHORM	1.0 EA	191.30	10		172.17	S
	BUMPER FRT SUPPORT B	1.0 EA	91.80	10		82.62	S

SERVICE ESTIMATE

0 - A00005
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
 Inv.date. : 18/01/2019
 WIP No. : 39237
 Veh.In/Out: 05/12/2018 14/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SLU1207L
 Reg.date. : 23/11/2017
 Mileage : 20,868
 Chassis No: VF1RFA00158580930

Closed by : Derek Oh Siong Wee
 Svc Consultant : ACC
 Remarks : Mr Goh Koon Wee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SUPPORT BRACKET, HEA ①	1.0 EA	66.60	10		59.94	S
	FENDER FRT LH GS4 ①	1.0 EA	512.70	10		461.43	S
	BRACKET, FENDER FRT ①	1.0 EA	98.10	10		88.29	S
	FENDER BRACKET FRT L ①	1.0 EA	89.90	10		80.91	S
	WHEEL ARCH CLIP J5AL ①	10.0 EA	5.30	10		47.70	S
	HEADLAMP LH R9A3 GS4 ①	1.0 EA	677.30	10		609.57	S
	ALLOY RIM 20" R9A3 S ①	1.0 EA	986.40	10		887.76	S
	TYRE PRESSURE SENSOR ①	1.0 EA	119.10	10		107.19	S
	ADHESIVE SEALER FL2 ①	1.0 EA	549.10	10		494.19	S
	BUMPER LOWER GS4 ①	1.0 EA	356.20	10		320.58	S
	SUPPORT BRACKET, HEA ①	1.0 EA	66.60	10		59.94	S
	WHEEL ARCH - FRT LH ①	1.0 EA	204.60	10		184.14	S
	PARK SENSOR BOTH CTR ①	1.0 EA	429.90	10		386.91	S
	HARNES- BUMPER FRT ①	1.0 EA	152.20	10		136.98	S
	AIR INTAKE HOSE, BUM ①	1.0 EA	105.80	10		95.22	S
	BUMPER FRT CENTER IN ①	1.0 EA	122.10	10		109.89	S
	FENDER SCREW ①	10.0 EA	5.60	10		50.40	S

SERVICE ESTIMATE

O - A00005
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3
 Inv.date. : 18/01/2019
 WIP No. : 39237
 Veh.In/Out: 05/12/2018 14/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SLU1207L
 Reg.date. : 23/11/2017
 Mileage : 20,868
 Chassis No: VF1RFA00158580930

Closed by : Derek Oh Siong Wee
 Svc Consultant : ACC
 Remarks : Mr Goh Koon Wee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET FRT R <i>Q</i>	1.0 EA	104.50	10		94.05	S ✓
	FOG LAMP MOULDING OU <i>Q</i>	1.0 EA	191.30	10		172.17	S ✓
	GRILLA PANEL INNER A <i>supp car /</i>	1.0 EA	820.60	10		738.54	S
	EQUERRE G F <i>supp car /</i>	1.0 EA	59.80	10		53.82	S
	EQUERRE D F <i>supp car /</i>	1.0 EA	75.40	10		67.86	S

Gross Total. 10,250.27

Labour Total 3,545.00
 Parts Total 6,705.27
 Package Total 0.00

Net..... 10,250.27
 GST @ 7.0% 717.52
 Total..... 10,967.79
 Paid..... 0.00
 Please Pay.. 10,967.79

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



Service Request Details

Claim

S8M013TV

Reference

None 

Loss Date

November 16, 2018

Request Date

November 22, 2018

Due Date

November 29, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

22/11/2018 @ 1001AM
Jerek veh. not in.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLU1207L

Make

TPVD RENAULT

Model
GRAND SCENIC

Service Address

...

Primary Contact/Insured

LIM MENG CHIEW AMY LOW NEE AMY
1 SERENADE WALK, 575750, Singapore

lowjoe@singnet.com.sg

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 8 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S645500202 / GST Reg. No.: M409017785

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MHLW18148682 Vehicle Registration No: SKD 3107E
 Name (as shown in NRIC): JOE LOW TENG KUWAY NRIC/FIN/Passport No: S 0034440J
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: 1 SERENADE WALK Singapore (757501)
 Contact (Tel): _____ Mobile No.: 9818 9832
 Email Address: LOWJOE@SINGNET.COM.SG
 Date of Accident: 16-11-2018 Time of Accident: 14:30
 Place of Accident: BASEMENT 2 CARPARK WEST GATE
 Insurance Company: AXA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO AMEND FROM THIRD PARTY CLAIM TO OWN DAMAGE
CLAIM THEN DO RECOVERY

Policyholder / Driver's Signature
 Date: 17/11/18

Reporting Centre Personnel's Signature
 Name: Anna
 NRIC/FIN No.: _____
 Date: _____

Hsiao Tong (LKKAUTO)

From: Suhaimi Saidi <suhaimisaidi8069@gmail.com>
Sent: Wednesday, 12 June 2019 10:07 AM
To: Vic (LKKAUTO)
Subject: Re: SLU1207L / SKD3107E DOA

Dear Vic,

Please revert.

Regards

Suhaimi Saidi
Hp:93865752
For Wearnes Automotive Pte Ltd

On Wed, 29 May 2019 at 11:30, Suhaimi Saidi <suhaimisaidi8069@gmail.com> wrote:
Hi Vic,

We refer to our email below.

Any update?

Regards,
Suhaimi

----- Forwarded message -----

From: Suhaimi Saidi <suhaimisaidi8069@gmail.com>
Date: Wed, 15 May 2019 at 08:05
Subject: Re: SLU1207L / SKD3107E DOA
To: Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Dear Vic,

We refer to our emails below.

Please let us have your offer of settlement soonest as matter has been protracted.

Regards,
Suhaimi

On Mon, 29 Apr 2019 at 09:26, Suhaimi Saidi <suhaimisaidi8069@gmail.com> wrote:
Dear Vic,

Any update?

Regards,
Suhaimi

On Tue, 16 Apr 2019 at 11:45, Suhaimi Saidi <suhaimisaidi8069@gmail.com> wrote:

Yr ref: CC4/ASM18021148/hb3

Dear Vic,

Refer to the above, please revert with your settlement.

Regards

Suhaimi Saidi
Hp:93865752
For Wearnes Automotive Pte Ltd

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 15 June 2019 11:00 AM
To: Suhaimi Saidi
Cc: Admin A; Rasul (LKKAUTO)
Subject: RE: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3
Attachments: 2601_001.pdf

Without Prejudice

Hi Suhaimi,

We refer to the above matter.

As per our surveyor, kindly let us have the following damage photos for our necessary action: -

- Tyre Pressure Sensor *me*
- Harness – Bumper Frt *short* ✓

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vic (LKKAUTO)
Sent: Thursday, 13 June 2019 4:38 PM
To: Suhaimi Saidi <suhaimisaidi8069@gmail.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3

Without Prejudice

Dear Suhaimi,

We refer to your below email and the contents were noted.

Please be informed that this matter is now handled by my colleague Ms Hsiao Tong and she will get back to you for an update/offer.



<TP - Mandate IA> - S8M013TV [ACCIDENT INVOLVING SKD 3107E(OI) & SLU 1207L(TP) ON 16/11/2018]

Type

🔗 Question

Message

Liability: 100%. There is a yellow stop line on OI side. Inform OI about third party claim. We seek your mandate at 12,037.79. TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction.

Hsiao Tong - 17 July 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/07/2019

Survey Details:

Date of loss	16-Nov-18
Date of appointment	22-Nov-18
Date of survey	5-Dec-18
Location of survey	VEARNES AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLU 1207L
Make and Model	RENAULT GRAND SCENIC IV 1.5 DCI AT FLU6
Date of registration	23/11/2017
Excess	
Market Value	\$99,000
Part Rebate	\$48,892
Nett Loss	\$50,108

Repair details:

Initial Estimate	\$ 12,953.20
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,562.45
Check items (estimate)	NIL
Labour	\$ 3,545.00
Supplementary	\$ 1,142.82
Total	\$ 10,250.27
Lump Sum(if applicable)	\$ -

Number of days for repair	8
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	10,967.79
Loss of use		NIL
Loss of rental (w/GST)	\$	1,070.00 (10days x \$100.00)
Loss of income		NIL
LTA search fees		\$
Others		\$
Proposed Total	\$	12,037.79



<TP - Mandate IA> - S8M013TV [ACCIDENT INVOLVING SKD 3107E(OI) & SLU 1207L(TP) ON 16/11/2018]

Type

 Question

Message

Hi Hsiao Tong, COR-proceed. LOR - propose @ \$100 per day @ 8 days. Tks

Reply



RE: <TP - Mandate IA> - S8M013TV [ACCIDENT INVOLVING SKD 3107E(OI) & SLU 1207L(TP) ON 16/11/2018]

Type

🔗 Question

Message

Hi, For LOR, third party rejected our offer at 8days and proposed 10days. The total amount counter proposed by third party is \$12,037.79(all-in). Kindly let us have your further mandate/ instruction please. Thank you. Hsiao Tong - 26 Aug 2019

Reply

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, 26 August 2019 9:49 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 83483, vehicle number SLU1207L

☐ Offered TP at \$11,823.79	CHT	28/7/2019 10:03:41 AM
☐ 300719 TP asked for LOR at 10days	CHT	26/8/2019 7:54:24 AM
☐ Message Hi, For LOR, third party rejected our offer at 8days and proposed 10days. The total amount counter proposed by third party is \$12,037.79(all-in). Kindly let us have your further mandate/ instruction please. Thank you. Hsiao Tong - 26 Aug 2019	CHT	26/8/2019 7:58:46 AM
☐ 8/26/19 8:23 AM HO Winnie---Hi Hsiao Tong, accident date - 16.11.18 @ 14:15 reporting date - 21.11.18 @ 17:03 received assignment - 21.11.18 @ 17.20pm appointment - @ 22.11.18 - veh not in workshop surveyed - @ .5.12.2018 there's no lapse in PRI, ok to revised to 9 days max (full & final). Tks	LSP	26/8/2019 9:36:36 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 26 August 2019 8:39 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 83483, vehicle number SLU1207L

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: winnie.ho@axa.com.sg <winnie.ho@axa.com.sg>
Sent: Monday, 26 August, 2019 8:33 AM
To: admin-d@lkkauto.com
Subject: New message for service request 83483, vehicle number SLU1207L

AXA Insurance has sent you a message for claim number S8M013TV.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.