

ASS. REC. BY:

REF: CS/CT118021158/RICd3021 Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Memmen Catherine Chia of CTI Date/Time: 22/11/18 @ 2:18pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLX 1028X Insured: GBC 7129Cat Workshop m/s Kok Wang Car Tel: 9183 9633of No. 1 Soon Lee Street #06-40Policy No: DMCVSN3079591700 Claim No: SNM18D05447C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/11/2018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp'23/11/18

H.O.D. Endorsement: _____

Date/Time: 2:43pm @ 22/11/18 Person Contacted: Mr. Kok Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLX 1028X - X</u>
	<u>GBC 7129C - X.</u>
	<u>Dismantle: 27/11/2018</u>
	<u>After repair: 29/11/2018</u>

Signature: *[Signature]*

REF: CT1

C
1338a

ASSIGNMENT

From: Date: 23/11/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 1028X

at Workshop m/s Kok Wang Car
of No. 1 Soon Lee St # 06-40

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *lup*

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLX 1028X Yr Regn: 2018 / *msk*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel Hybrid 1.5XA c.c. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 047736 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: R031266793

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: 1.

BS / ☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/11/18 D.O.I. 23/11/18

Survey held at Kok Wang

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$8,000 - \$9,000

[Signature]
30/11/2018

RECEIVED 6 DEC 2018

Date/Time, File Pass to?

☐ : Prefi. Report

Days Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ Site Insp (\$

Transportation:

☐ Interview (\$

) \$ + RS. SI

☐ Tech. Invs (\$

) Photos

☐ Weekend (\$

) Others

Report Format: PRO

Lump Sum / I.B.I. (\$

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2018		22 Nov 2018 14:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	IQUARTZ PTE LTD, Co. Reg. No.: 199901511H		
Main Claimant:	LEE KUN HO, ID: S2602069G		
Vehicle Reg. No.:	SLX1028X	Date of Loss:	19/11/2018 20:00 - :59
Claim Type:	TP / SNM18D05447C02	Policy/Cover Note No.:	DMCVSN3079591700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC7129C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/12/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1338W
Vehicle Details	
Vehicle No.:	SLX1028X
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB5966814
Chassis No.:	RU31266793
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$23,979.00
Original Registration Date:	15 Mar 2018
First Registration Date:	15 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$15,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2028
PARF Rebate Amount:	\$11,678.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,390.00
COE Rebate Amount:	\$41,989.00
Total Rebate Amount:	\$53,667.00

The information contained herein is correct as at 06 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 16:17
Date Of Accident	19/11/2018 20:40
Exact Location Of Accident	SELETAR EXIT AREA AT TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX1028X
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	123 LEASING PTE LTD
Co Reg No	201801338W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91445805

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994697
Cover Note Number	

Driver

Name of Driver	LEE KUN HO
NRIC No	S2602069G
Date Of Birth	03/03/1952
Occupation	OUTDOOR
Date Of Driving Pass	06/12/2005
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91445805
Fax Number	
Contact Number	
Email Address	GUMHO0303@YAHOO.COM.SG

Address	APT BLK 503A CANBERRA LINK #07-07
Postcode	751503
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC7129C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

RECEIVED: 26/11/2018 23:09

KOK LEE NG

Recd 14-11-18, 09:23

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)

Date & Time: 20/11/2018


11:50 AM



[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHEN I DRIVING on KPE TOWARDS YISHUN,
 MY SPEED OF CAR WAS ABOUT 60 km/Hr.
 I suddenly hear somebody's car banged
 from behind and my car was stuck about
 20m. Due to the heavy traffics on the
 expressway I switch on Emergency
 lights and come down from Driver Seat
 and check what happened.
 The Lorry Driver was Indian Worker and
 he admitted he banged my car by his
 fault. So I took his I/C, DRIVING
 licence and his car No plate photos and
 relay to my car company, MR. Berry.

My car still can drive so that I drove
 away from the accident spot to release
 the congestion.

this statement is truth.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder Signature
 Date

[Signature]

Driver's Signature
 (If driver is not the policyholder)

Date & Time: 20/11/2018
 11:50 AM



[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Nov 2018		22 Nov 2018 14:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: IQUARTZ PTE LTD , Co. Reg. No.: 199901511H									
Main Claimant: LEE KUN HO , ID: S2602069G									
Vehicle Reg. No.: SLX1028X		Date of Loss: 19/11/2018 20:00 - :59 [8 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05447C02		Policy/Cover Note No.: DMCVSN3079591700 (Comprehensive)							
Vehicle Reg. No. (Insured): GBC7129C		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/12/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












































Claim Documents

*SLX1028X (SNM18D05447C02)
[GBC7129C]
TP
LEE KUN HO
Nov 19 2018 8:00PM
[IQUARTZ PTE LTD]
Kok Wang Car Grooming - Pioneer















Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)								Thumbnail	Print
1	20/11/18 15:15	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)								Thumbnail	Print
1	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 15:13	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	20/11/18 15:14	SCENE [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	20/11/18 15:14	SCENE [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
2	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
3	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
4	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
5	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
6	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
7	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
8	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
9	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
10	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
11	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
12	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
13	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
14	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
15	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
16	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
17	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
18	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
19	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
20	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
21	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>
22	05/12/18 14:59	General View								Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
23	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/12/18 14:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	05/12/18 14:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
73	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
123	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	05/12/18 15:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
138	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
143	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
145	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
146	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
147	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
148	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
149	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
150	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
151	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
152	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
153	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
154	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
155	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
156	05/12/18 15:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/11/18 14:18	PRS	 Load PDF	
2	22/11/18 14:18	TP GIA	 Load PDF	
3	22/11/18 14:18	OI GIA	 Load PDF	
No.	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	20/11/18 15:13	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 15:13	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 15:13	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 15:13	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 15:13	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 15:13	Sketch Plan #6 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View <input type="button" value="View in Browser"/>	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
1	20/11/18 15:15	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/11/18 15:14	SCENE	 Load JPG	<input checked="" type="checkbox"/>
8	20/11/18 15:14	SCENE	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	20/11/18 15:13	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 15:13	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 15:13	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 15:13	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 15:13	Sketch Plan #5	 Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 15:13	Sketch Plan #6	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT18021158/R1CD3E2

Date: 13/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3079591700

Claimant Vehicle
No : SLX1028XInsured Vehicle
No : GBC7129C

Date of Loss: 19/11/2018

Nature of Claim: TP

Claim
No: SNM18D05447C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX1028X

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5966814

Reg. Date: 15/03/2018 (Man. Year: 2017)

Chassis No: RU31266793

Colour: Grey

Odometer: 47736 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/11/2018

Date Inspected: 23/11/2018 Inspected At:

Kok Wang Car Grooming - Pioneer (HQ)
No. 1 Soon Lee Street, #06-40 Pioneer
Centre
Singapore 627603

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$9,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1028X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >