

ASS. REC. BY:

REF.

CS/ASM18021169 / Krd3et

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Kitty Teo

68804602

of

ASM (AXA)

Date/Time:

22

23/11/2018

Estimated Cost:

Bill to:

(1)

/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SJZ 8668R

Insured:

at Workshop in/s

Wega Engineering

Tel:

64521493 / 82450276

of

176 Sin Ming Drive #04-16

8491 7168

Policy No:

Claim No:

98 M013KZ

Sum Insured:

Excess:

\$ 400.00

Make of Veh:

(Client's Record)

D.O.A.

18/11/2018

CA / REV

/ REP. / REV 24 HRS

23/11/18

H.O.D. Endorsement:

Date/Time:

5:11pm 23/11/18

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

pls offer cost + 10% mark up on parts.

SJZ 8668R-X

26/11/18

@ >19pm Ah - Kwang said unable to provides cost price,

26/11/18

Revert via SMART claim

27/11/18

Revert to Kitty by email (cost price)

27/11/18

Rece authorise Repair from Kitty by email

REF: ASM(GAXA)

ASSIGNMENT

From: Date: 23/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJZ 8668R
at Workshop n/s: Wegel Engineering
of: 176 Sn Ming Drive #01-16

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$400.00

(Client's Record)

Make of Veli: pls offer cost + 10% mark up on parts.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$451c

IDAC Accident Report: Consistent? Yes or No

GIA / FR Seen: Consistent? Yes or No

Est. Repairs: 05 days Res: Yes or No

Lump Sum: 1.13.1 % 3 Val: Yes or No

CA / (REV) / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJZ 8668R Yr Regn: 07 10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Primo Mover /
Truck / Trailer or

Make: BMW A135i C.C. 2879

Colour: White A/C Insured / Std / NI / NA

Sp Reading: 84984 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: WBA UN 720 70 VM 22419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / S/A/Rim or

Tyre Size: F: 225/40ZR18
R: 245/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: R/Bal. 8 mm L/Bal. 8 mm D.O.I. 18/11/18

Rear: R/Bal. 5 mm L/Bal. 5 mm D.O.I. 23/11/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S R/L & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/11 15h pass to Carhite

27/11/18 @ 331pm Informed mr Chia c/A ex \$400, to res check items and supplementary parts

\$4134.70 email

4/1/19 @ 211pm 6349.00 (Red 1950-50, 2419) (No LS) Confirmed with Ah Kwang

Signature

4/1/2019

RECEIVED 20 FEB 2019

Date/Time: File Pass to:

☐ : Preli. Report

Days Of Repair: 5

11

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to:

Survey Fee: 200

Transportation:

1. S + R/L 10

1. Phone

1. Other:

1. :

TOTAL:

200

2019 - typist

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Report Format: SMART claim

Lump Sum / L.B.1: (\$ 6349 1/2)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 27 November 2018 3:45 PM
To: 'wega claim'; SUR
Subject: RE: ACCIDENT INVOLVING SJZ8668R & SJY7240C ON 18/11/2018

Dear Sir/Madam,

As instructed by our client , please proceed to repair the **insured vehicle SJZ 8668R (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: wega claim <wegaclaim@gmail.com>
Sent: Monday, 26 November 2018 5:54 PM
To: SUR <sur@lkkauto.com>
Subject: ACCIDENT INVOLVING SJZ8668R & SJY7240C ON 18/11/2018

Dear Sir/Mdm,

Please kindly refer to attached and getting the authoriz approved

--

Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 27 November 2018 3:33 PM
To: 'TEO Kitty'
Cc: SUR
Subject: RE: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)

Dear Kitty,

We have informed repairer authorise repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TEO Kitty <kitty.teo@axa.com.sg>
Sent: Tuesday, 27 November 2018 3:17 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)

Hi Veron,

Please authorise.

Best Regards

Kitty Teo

Specialist, Motor Claims Department
AXA Insurance Pte Ltd

8 Shenton Way, #24-01 AXA Tower, Singapore 068811

Email: kitty.teo@axa.com.sg

Customer Care No. 1800 8804741 Press 3

www.axa.com.sg

#1 GLOBAL INSURANCE
BRAND FOR **10**
CONSECUTIVE **YEARS**

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 27 November, 2018 11:39 AM
To: TEO Kitty <kitty.teo@axa.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)

Dear Kitty,

Enclosed IA of vehicle SJZ 8668R
Date of survey: 23/11/2018
Number of days : 5 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Veron Chen (LKKAUTO)

From: TEO Kitty <kitty.teo@axa.com.sg>
Sent: Tuesday, 27 November 2018 3:17 PM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: RE: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)
Attachments: IA (COST PRICE).pdf; MARK ESTIAMTE (COST PRICE).pdf

Hi Veron,

Please authorise.

Best Regards

Kitty Teo
Specialist, Motor Claims Department
AXA Insurance Pte Ltd

8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Email: kitty.teo@axa.com.sg
Customer Care No. 1800 8804741 Press 3
www.axa.com.sg

**#1 GLOBAL INSURANCE
BRAND FOR 10
CONSECUTIVE YEARS**

Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 27 November, 2018 11:39 AM
To: TEO Kitty <kitty.teo@axa.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)

Dear Kitty,

Enclosed IA of vehicle SJZ 8668R
Date of survey: 23/11/2018
Number of days : 5 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 27 November 2018 11:39 AM
To: Kitty Teo Poh Guek
Cc: SUR
Subject: IA FOR SJZ 8668R-(AXA REF: S8M013KZ)
Attachments: IA (COST PRICE).pdf; MARK ESTIAMTE (COST PRICE).pdf

Dear Kitty,

Enclosed IA of vehicle SJZ 8668R

Date of survey: 23/11/2018

Number of days : 5 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

81 UBI AVENUE 1, #01-25 UFA/UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (665) 62863581 FAX : (665) 62864318

Immediate Advice

To : AXA Insurance Pte Ltd

Date:27/11/2018

Survey details

Date of loss	18/11/2018
Date of appointment	22/11/2018
Date of survey	23/11/2018
Location of survey	WEGA ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJZ 8668R
Make and Model	BMW 135i (A)
Date of registration	20/7/2010
Excess	\$400
Market Value	\$45,000.00
Part Rebate	\$32,701.00
Nett Loss	\$12,299.00

Repair details

Initial Estimate	\$8,299.50
------------------	------------

Proposed/Revised repair cost:

Parts	\$2,318.00
"Check Items (Estimated)	\$3,397.00
Labour	\$1,020.00
Total	\$6,735.00
Lump Sum (Estimated)	

Number of days of repair	5 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the n/s front portion and undercarriage

Damages Consistent
Repair Cost Economical

New Message

Type *

☒ Message

Subject *

IA SUBMITTED FOR SJZ 8668R

Message *

Dear Kitty,

Please be informed that IA submitted. Repairer unable to provides cost price,we have Not Authorize repair. Kindly let us have your approval please.Thanks Veron Chen

Cancel

Send



Auto
Consultants
Pte Ltd

81 UBI AVENUE 1, #01-23 UVA INDUSTRIAL PARK, SINGAPORE 408033 TEL : (665) 6286386 FAX : (665) 6286438

Immediate Advice

To : AXA Insurance Pte Ltd

Date:26/11/2018

Survey details

Date of loss	18/11/2018
Date of appointment	22/11/2018
Date of survey	23/11/2018
Location of survey	WEGA ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJZ 8668R
Make and Model	BMW 135i (A)
Date of registration	20/7/2010
Excess	\$400
Market Value	\$45,000.00
Parf Rebate	\$32,701.00
Nett Loss	\$12,299.00

Repair details

Initial Estimate	\$11,107.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$3,641.00
"Check items (Estimated)	\$5,746.00
Labour	\$1,020.00
Total	\$10,407.00
Lump Sum (Estimated)	

Number of days of repair	5 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the n/s front portion and undercarriage

Damages Consistent
Repair Cost Economical

Repairer unable to provides cost price.



Service Request Details

Claim

S8M013KZ

Reference

None 

Loss Date

November 18, 2018

Request Date

November 22, 2018

Due Date

November 29, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJZ8668R

Make

BMW

Service Address

176 Sin Ming Drive, , , 575721

Primary Contact/Insured

ARTHUR LO FOO MAN (ARTHUR LUO FUWEN)
5 THOMSON LANE, #33-01, 297724, Singapore

a2000lo@yahoo.com.sg

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS \$400

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

11/22/18 4:06 PM

FROM

TEO Kitty

SUBJECT

WP SURVEY

BODY

Hi Please offer cost + 10% mark up on parts.



RATAN BHOSALE Pragati

From: wega claim <wegaclaim@gmail.com>
Sent: Wednesday, November 21, 2018 1:21 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ACCIDENT INVOLVING SJZ8668R & SJY7240C ON 18/11/2018
Attachments: SJZ8668R.PDF

Categories: Pragati

Dear Sir/Mdm,

Please kindly help to arrange surveyor , Kindly refer to the attachment.

--

Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7187C
Vehicle Details	
Vehicle No:	SJZ8668R
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2018
Vehicle Make:	B.M.W.
Vehicle Model:	135i M A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	16237392N55B30A
Chassis No.:	WBAUN72070VM22419
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$48,090.00
Original Registration Date:	20 Jul 2010
First Registration Date:	20 Jul 2010
Transfer Count:	0
Actual ARF Paid:	\$48,090.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2020
PARF Rebate Amount:	\$26,449.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$6,252.00
Total Rebate Amount:	\$32,701.00

The information contained herein is correct as at 26 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/11/2018 18:41
Date Of Accident	18/11/2018 16:30
Exact Location Of Accident	50B JALAN BUKIT MERAH OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ8668R
Insured/Policyholder	
Name Of Registered Owner	ARTHUR LO FOO MAN
NRIC No	S7317187C
Email Address	A2000LO@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96925196
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	BMW
Model	1351MA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA218851
Cover Note Number	20/07/2018 TO 19/07/2019

Driver

Name of Driver	SOMSAMAI KAEWSUWAN
NRIC No	S7562816A
Date Of Birth	01/10/1975
Occupation	INDOOR
Date Of Driving Pass	20/11/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96925196
Fax Number	
Contact Number	
Email Address	A2000LO@YAHOO.COM.SG

Address 5 THOMSON LANE #33-01
 Postcode 297724
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY7240C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 18.11.2018 Time: 1630 Location: 50B Jalan Bukit Merah Carpark.
 My Vehicle A: SJZ 8668R Vehicle B: SJY 7240C Vehicle C: /
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS I WAS turning out of Carpark of 50B Jalan Bukit Merah
 I hit vehicle SJY 7240C with the left side of my car

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: wega Engineering

Email address: Cheekwongwega@gmail.com

& myself

Email address: a200010@yahoo.com.sg

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SJZ 8668R

Policyholder's Signature

Date & Time:

19/11/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Su. S. S. S.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Ma Li
19/11/2018



Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01/02

Date : 21/11/2018

Vehicle No : SJZ866BR
Chassis No : WBAUN72070VM22419
Make/Model : BMW 1351MA
Year :

Not Marked



Not Marked
1-B1
Resurvey B4pam
Ex B400

Fax: 62564315

S/N	Qty	Description	Unit Price	Amount
1	1pc	FRONT BUMPER	\$ 1,649.00	\$ 1,649.00
2	1pc	FRONT HEADLAMP LH	\$ 2,900.00	\$ 2,900.00
3	1pc	FRONT HEADLAMP BRACKET LH	\$ 78.00	\$ 78.00
4	1pc	FRONT SENSOR REVERSE	\$ 288.00	\$ 288.00
5	1pc	FRONT FENDER LH	\$ 782.00	\$ 782.00
6	1pc	FRONT FENDER INNER SHIELD	\$ 220.00	\$ 220.00
7	1pc	FRONT FENDER WHEEL HOUSE LH	\$ 162.00	\$ 162.00
8	1pc	FRONT BUMPER REINFORCEMENT LH	\$ 55.00	\$ 55.00
9	1pc	FRONT RIM LH	\$ 880.00	\$ 880.00
10	1pc	FRONT RIM LOGO COVER LH	\$ 55.00	\$ 55.00
11	1pc	FRONT TYRE LH	\$ 230.00	\$ 230.00
12	1pc	FRONT KNUCKER ARM LH	\$ 276.00	\$ 276.00
13	1pc	FRONT WHEEL HUP LH	\$ 564.00	\$ 564.00
14	1pc	FRONT LOWER AMP LH	\$ 276.00	\$ 276.00
15	1pc	FRONT ABSORBER LH	\$ 442.00	\$ 442.00
16	1pc	FRONT TIE ROD LH	\$ 336.00	\$ 336.00
17	1pc	FRONT TORSION BAR LINK LH	\$ 114.00	\$ 114.00

10%

Labour Charges

- 1 To check wiring and system function
- 2 To wheel alignment
- 3 To cutting welding, knuckling and remove and refix undercarriage
- 4 To respray accident portion

\$ 120.00
\$ 80.00
\$ 800.00
\$ 800.00

20%
80%
500%
500%

Grand Total

\$ 11,107.00

Wega Engineering Pte Ltd

Authorised Signature
Leong Shee Kwong
Mobile No: 84917768

Workshop not agree on Com plus 10%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / %

Claim Ref:

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY, #27-01/02

Date : 21/11/2018

Vehicle No : SJ28668R
Chassis No : WBAUN72070VM22419
Make/Model : BMW 1351MA
Year :

NOT APPROVED
Returning 84 point
Ex 8400
8 6349.00 before excess

S/N	Qty	Description	cost Price	Amount	
1	1pc	FRONT BUMPER <i>mtg cfa</i>	\$ 1,116.00	\$ 1,116.00	✓
2	1pc	FRONT HEADLAMP LH <i>?</i>	\$ 2,013.00	\$ 2,013.00	✓
3	1pc	FRONT HEADLAMP BRACKET LH <i>?</i>	\$ 63.00	\$ 63.00	✓
4	1pc	FRONT SENSOR REVERSE <i>?</i>	\$ 160.00	\$ 160.00	X
5	1pc	FRONT FENDER LH <i>BT</i>	\$ 529.00	\$ 529.00	✓
6	1pc	FRONT FENDER INNER SHIELD <i>cfa</i>	\$ 150.00	\$ 150.00	✓
7	1pc	FRONT FENDER WHEEL HOUSE LH <i>?</i>	\$ 110.00	\$ 110.00	X
8	1pc	FRONT BUMPER RENTANNER LH <i>DIS</i>	\$ 28.00	\$ 28.00	✓
9	1pc	FRONT RIM LH <i>DD</i>	\$ 480.00	\$ 480.00	✓
10	1pc	FRONT RIM LOGO COVER LH <i>DD</i>	\$ 15.00	\$ 15.00	✓
11	1pc	FRONT TYRE LH	\$ 195.00	\$ 195.00	X
12	1pc	FRONT KNUCKER ARM LH	\$ 81.00	\$ 81.00	✓
13	1pc	FRONT WHEEL HUP LH	\$ 127.00	\$ 127.00	✓
14	1pc	FRONT LOWER AMP LH	\$ 81.00	\$ 81.00	✓
15	1pc	FRONT ABSORBER LH	\$ 299.00	\$ 299.00	X
16	1pc	FRONT TIE ROD LH	\$ 150.00	\$ 150.00	✓
17	1pc	FRONT TORSION BAR LINK LH	\$ 37.00	\$ 38.00	✓

Pls 10%

Labour Charges

- 1 To check wiring and system function
- 2 To wheel alignment
- 3 To cutting welding, knucking and remove and refix undercarriage
- 4 To respray accident portion

\$ 120.00 *20*
\$ 80.00 *160*
\$ 800.00 *500*
\$ 800.00 *500*

Grand Total

\$ 8,299.50

Wega Engineering Pte Ltd

Authorised Signature
Leong Chee Kwong
Mobile No: 84917768

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / 7.

Claim Ref:

AXA INSURANCE SINGAPORE PTE LTD
B SHENTON WAY, #27-01/02

Date : 21/11/2018

Vehicle No : S/28668R
Chassis No : WBAUN72070VM22419
Make/Model : BMW 1351MA
Year :

Not for sale



Not for sale
1-B1
Returning Bumper
Lx Bumper

Ref: 62564315

S/N	Qty	Description	Unit Price	Amount
1	1pc	FRONT BUMPER	\$ 1,649.00	\$ 1,649.00
2	1pc	FRONT HEADLAMP LH	\$ 2,900.00	\$ 2,900.00
3	1pc	FRONT HEADLAMP BRACKET LH	\$ 78.00	\$ 78.00
4	1pc	FRONT SENSOR REVERSE	\$ 288.00	\$ 288.00
5	1pc	FRONT FENDER LH	\$ 782.00	\$ 782.00
6	1pc	FRONT FENDER INNER SHIELD	\$ 220.00	\$ 220.00
7	1pc	FRONT FENDER WHEEL HOUSE LH	\$ 162.00	\$ 162.00
8	1pc	FRONT BUMPER REINFORCEMENT LH	\$ 55.00	\$ 55.00
9	1pc	FRONT RIM LH	\$ 880.00	\$ 880.00
10	1pc	FRONT RIM LOGO COVER LH	\$ 55.00	\$ 55.00
11	1pc	FRONT TYRE LH	\$ 230.00	\$ 230.00
12	1pc	FRONT KNUCKER ARM LH	\$ 276.00	\$ 276.00
13	1pc	FRONT WHEEL HUB LH	\$ 564.00	\$ 564.00
14	1pc	FRONT LOWER ARM LH	\$ 276.00	\$ 276.00
15	1pc	FRONT ABSORBER LH	\$ 442.00	\$ 442.00
16	1pc	FRONT TIE ROD LH	\$ 336.00	\$ 336.00
17	1pc	FRONT TORSION BAR LINK LH	\$ 114.00	\$ 114.00

Labour Charges

- 1 To check wiring and system function
- 2 To wheel alignment
- 3 To cutting welding, knocking and remove and refix undercarriage
- 4 To respray accident portion

\$ 120.00
\$ 80.00
\$ 800.00
\$ 800.00

Grand Total

\$ 11,107.00

Wega Engineering Pte Ltd
Authorised Signature
Leong Kwee Kwong
Mobile No: 84917768

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshop not agree on cost plus 10%

Order: R051811
 mso: SJZ8668R
 r: 09
 2 26.11.18 17:00

BMW 2007-13 E82 18"

Front : Left

Actual	Before	Specified Range
-1°24'	-1°24'	-0°42' 0°18'
6°48'	6°48'	
0°10'	0°10'	0°02' 0°14'
14°13'	14°13'	
12°49'	12°49'	
		-2°08' -1°08'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-3°06'	-3°05'	-0°42' 0°18'
7°06'	7°06'	
-0°07'	-0°06'	0°02' 0°14'
16°42'	16°42'	
13°36'	13°36'	
		-2°08' -1°08'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
1°42'	1°42'	-0°30' 0°30'
-0°19'	-0°19'	-0°30' 0°30'
-2°29'	-2°29'	
0°03'	0°04'	0°04' 0°28'

Rear : Left

Actual	Before	Specified Range
-1°27'	-1°28'	-1°55' -1°05'
-0°13'	-0°12'	0°03' 0°15'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°27'	-1°26'	-1°55' -1°05'
0°35'	0°36'	0°03' 0°15'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°01'	0°01'	-0°30' 0°30'
0°23'	0°22'	0°06' 0°30'
-0°24'	-0°24'	-0°04' 0°04'

k Order: R051812
 Inno: SJZ8668R
 r: 09
 28.11.18 13:08

BMW 2007-13 E82 18"

Front : Left

Actual	Before	Specified Range
-1°20'	-1°22'	-0°42' 0°18'
6°45'	6°45'	
0°07'	0°17'	0°02' 0°14'
14°24'	14°26'	
13°04'	13°04'	
		-2°08' -1°08'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°37'	-0°35'	-0°42' 0°18'
7°07'	7°07'	
0°06'	-0°04'	0°02' 0°14'
14°08'	14°06'	
13°31'	13°31'	
		-2°08' -1°08'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°43'	-0°47'	-0°30' 0°30'
-0°23'	-0°23'	-0°30' 0°30'
0°16'	0°20'	
0°12'	0°13'	0°04' 0°28'

Rear : Left

Actual	Before	Specified Range
1°26'	-1°27'	-1°55' -1°05'
0°10'	0°11'	0°03' 0°15'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°27'	-1°55' -1°05'
0°11'	0°11'	0°03' 0°15'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°02'	0°00'	-0°30' 0°30'
0°22'	0°22'	0°06' 0°30'
0°00'	0°00'	-0°04' 0°04'

Veron Chen (LKKAUTO)

From: wega claim <wegaclaim@gmail.com>
Sent: Wednesday, 20 February 2019 11:54 AM
To: Veron Chen (LKKAUTO)
Subject: OD Claim for SJZ 8668 R
Attachments: OD Claim SJZ 8668 R.pdf

Dear Ms. Veron,

Enclosed are the document for your perusal and kindly reply us as soon as possible.

--
Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493



INTEGRATED GLOBAL NETWORK ENTERPRISE

Block 9 Kaki Bukit Road 1 #01-07/08 Eunos Technolink Singapore 415938 Email: mail@ign.com.sg www.ign.com.sg
Tel: 65-6348 3083 Fax: 65-6440 4375 • Business Reg. No.: 53045422W • GST Registration No.: M9-0010002-A

TAX INVOICE

No. : 1118-060849

300-0182

Wega Engineering Pte Ltd
176 Sin Ming Drive
#04-13/16 Sin Ming Autocare
Singapore 575721

Ah Chia 8245 0276

Tel : 6452 1493

Fax : 6452 9153

Your Ref. : SJZ8668R VM22419
Model :
Terms : CASH
Date : 28-11-2018
Salesman :
Page : 1 of 1
Ship Via :

Item	Part No.	Description	Qty	U/	Price SGD	Disc.	Amount SGD
1	31 126 770 849P	LOWER ARM E90 LH [GER]	1	PC	81.00		81.00
2	32 106 765 235BM	TIE ROD E90 LH	1	PC	150.00		150.00
3	31 356 765 933G	THRUST ROD E90 LH [GER]	1	PC	38.00		38.00
4	31 216 765 157	WHL BRG FRT E90	1	PC	127.00		127.00
5	51 118 045 961	FENDER UNDER COVER E82/88 LH	1	PC	150.00		150.00
6	51 118 057 508	BUMPER FRT E82/88 M [HLC, NO PDC]	1	PC	1,116.00		1,116.00
7	51 117 148 761	HEADLAMP BKT LH	1	PC	63.00		63.00
8	41 357 133 227	FENDER FRT E81/82/87/88 LH	1	PC	529.00		529.00
9	36 116 768 854	RIM	1	PC	480.00		480.00
10	36 131 180 419	HUB CAP	1	PC	15.00		15.00
11	51 117 134 097	BUMPER BKT FRT LH	1	PC	28.00		28.00

Remarks:

SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED SEVENTY ONE AND CENTS
THIRTY NINE ONLY

Sub Total : 2,777.00
GST 7.00 % : 194.39
Total SGD : 2,971.39

Notes

- 1 Goods sold are not returnable unless otherwise arrange
- 2 All cheques should be crossed and made payable to
INTEGRATED GLOBAL NETWORK ENTERPRISE
- 3 For T/T, pls remit to DBS Bank Ltd - A/C No 027-902196-5 [SGD] or
UOB Bank Ltd - A/C No 356-300-274-1 [SGD]
- 4 Goods remain our property unless full payment is received

Received in good order and condition

for Integrated Global Network Enterprise

Customer's Chop & Signature

HQ

Our BMW and MINI Parts - Driven by Quality & Value

28-Nov-18 2:29:42 P

TAX INVOICE

No. : 1218-061343

Your Ref. : SJZ8668R VM22419
Model : E88 135i N55
Terms : CASH
Date : 24-12-2018
Salesman :
Page : 1 of 1
Ship Via :

300-0182
Wega Engineering Pte Ltd
176 Sin Ming Drive
#04-13/16 Sin Ming Autocare
Singapore 575721

Chia 8245 0276

Tel : 6452 1493

Fax : 6452 9153

Item	Part No.	Description	Qty	U/ Price SGD	Disc.	Amount SGD
1	63 117 181 295	AHL XENON H/ LAMP E82/88 LH	1	PC 2,013.00		2,013.00

marks:

**SINGAPORE DOLLAR TWO THOUSAND ONE HUNDRED FIFTY THREE AND CENTS
ONLY**

Sub Total : 2,013.00
GST 7.00 % : 140.91
Total SGD : 2,153.91

Items sold are not returnable unless otherwise arrange.
Cheques should be crossed and made payable to
INTEGRATED GLOBAL NETWORK ENTERPRISE
If T/T, pls remit to DBS Bank Ltd - A/C No 027-902198-5 [SGD] or
Bank Ltd - A/C No 356-300-274-1 [SGD]
We remain our property unless full payment is received

Received in good order and condition

Integrated Global Network Enterprise

Customer's Chop & Signature

Our BMW and MINI Parts - Driven by Quality & Value

29-Dec-18 10:58:51 AM



WEGA ENGINEERING

automotive workshop and beyond

24hrs Towing, Insurance Claims, Car Repairs & Spray Painting

TEL : 65-6452 1453 FAX : 65-6452 9153

GST REG NO : 1999 00741 Z

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #24-01

AXA Tower, Singapore 068811

Attn: Claims Department

INVOICE : OD201901

INV DATE : 07/01/2019
VEHICLE NO : SJZ 8668 R
MAKE / MODEL : BMW
TERMS : 2 WEEKS
YOUR REF NO :

S/N Particular

Quantity

Amount SGD

Accident between SJZ 8668 R & SJY 7240 C dated 18/11/2018

1 OD CLAIM FOR SJZ 8668 R

Lump Sum Repair Cost \$ 6,349.00

Less: Excess \$ (400.00)

5,949.00

GST 7% \$ 416.43

6,365.43

DOLLARS: SIX THOUSAND THREE HUNDRED SIXTY FIVE AND CENTS FORTY THREE ONLY.

GRAND TOTAL

6,365.43

TERMS : 30 DAYS



Wega Enginnering Pte Ltd

Cheques should be made payable to WEGA ENGINEERING PTE LTD



WEGA ENGINEERING

automotive workshop and beyond
24hrs Towing, Insurance Claims, Car Repairs & Spray Painting

Blk 176 Sin Ming Drive, #04-16, 13 Sin Ming Autocare Singapore 575721

Tel: 6452 1493 Fax: 6452 9153 Website: <http://www.wega.com.sg> E-mail: wegaclaim@gmail.com

OST Reg. No: 19-9900741Z

Date : 21/12/19

Our Ref : 00201901

Your Ref :

WITHOUT PREJUDICE

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #24-01 AXA Tower Singapore 068811

Dear Sir,

Accident involving SJ2 P618R & SJ4 7840 dated 18/11/2018

We enclosed the following documents for your perusal:-

- * Original Survey report bill / 1 original copies of photographs -
 - * Original Tax Invoice no. 1 * Original Rental Invoice no. -
 - * GIA report / police report of - * Police result 1
 - * Certificate of insurance 1 * LTA search and receipt of 1
 - * Original Medical Bill/Receipt - * Driver's Letter of Authority -
 - * Satisfaction Cum Discharge Voucher - * Others -
- * Survey under insurance instruction / independent Surveyor

We would like to claim all the following losses on behalf of our client:-

1)	Cost of Repair (Inclusive GST)	\$ 6365.43
2)	Surveyor fees (with/without GST)	\$ -
3)	Rental Fees/Loss of Use for ___ days at \$___ per day	\$ -
4)	LTA / GIA / Police Fees	\$ -
5)	Medical Fees	\$ -
	Total Claim	\$ 6365.43

If you agree to the above, please forward your full settlement directly to WEGA ENGINEERING PTE LTD
Your prompt action is most appreciated.

Yours truly,

Ee Sin Guan



TO:

VEHICLE NO: SJZ 8668 R

DATE OF ACCIDENT/REPAIR: 18/11/2018 /

Accident Involving SJZ 8668 and SJY 7240C along

508 Jalan Bukit Merah open Gasport

This is to confirm that my/ our vehicle SJZ 8668 R is under repair at

WEGA ENGINEERING PTE LTD.

Repairs had been carried out to my satisfaction.

DATED/TIME IN: 19.11.2018 /

DATED/TIME OUT: 29.12.2018

SIGNATURE

(OWNER/AUTHORISED PERSONNEL COLLECTING VEHICLE)

NAME:

I/C NO:

Date:

To: Wega Engineering Pte Ltd
Blk 176 Sin Ming Drive
#04-16 Sin Ming Autocare
Singapore 575721.

LETTER OF AUTHORITY & INDEMNITY

ACCIDENT INVOLVING VEHICLE NO. SJZ 8668R

I / We ARTHUR LO FOO MIAN UEN / NRIC No. S7317187C
Owner of Vehicle No. SJZ 8668R, hereby authorise **M/S WEGA ENGINEERING PTE LTD**
To commence repairs to my vehicle and to forward the claim for damages sustained in the above
Accident to the third party driver and / or his employer and / or the vehicle owner and / or the insurer
Concerned. I / We agree that in consideration of your giving up your repairer's lien I / We agree to
Assign the whole proceeds of my / our third party claim to you and if applicable, our solicitors (to be
Appointed by you on my/ our behalf) shall accept this as my/ our irrevocable authority to pay the
Amount compensated direct to you after deduction of their costs on a solicitor & clients basis. I / We
Undertake to co-operation fully with you and our solicitors to see the claim to a successful conclusion.

If third party driver and/ or his employer and / or the vehicle owner and /or the insurer reject liability,
I / We will fully be responsible for the repair costs and other incidentals.

I / We also authorize you to sign all discharge vouchers / Indemnity forms and all necessary paper in
Connection with the above claim in my/ our absence.

I / We authorise you to appoint such a firm of solicitors on my/ our behalf as you shall deem fit for the
Purpose of the third party/ own insurer's claim.

I / We undertake to inform you and/or the solicitors appointed by you on my /our behalf in the event
of the third party's insurance company communicate with me/ us directly by telephone or in writing
and I / We further undertake not to accept any monies of offer of settlement from the third party's
insurer without first communicating with you.

My/our vehicle is repaired by the repairer on my/our own will without any inducement, threat
and /or promise.

In the event that the repairer is completed to enforce this undertaking, I / We agree that I / We shall
Pay for the legal costs incurred by repairer on a solicitor and client's full indemnity basis.

Owner Signature
(Company Stamp if applicable)

TO :

Dear Sirs,

CLAIMANT :

ACCIDENT INVOLVING SJ2 8668R AND SJY7240C
ON 18.11.2018 AT 50B Jalan Bukit merah open carpark

I/We, ARTHUR LO FOO MAN, am /are the
registered owner of vehicle No. SJ2 8668R.

Please note that I have assigned all compensation monies due to me/ us in the above said
Accident to **WEGA ENGINEERING PTE LTD**.

I/We, hereby authorize you to release all compensation monies pertaining to the above said
Accident to **WEGA ENGINEERING PTE LTD** and forward you settlement cheque
To **WEGA ENGINEERING PTE LTD** whom I/we had authorized to collect the said
Compensation monies.

Thank you.

Signature of Claimant 

(Company Stamp, If applicable)

Name :

NRIC No :

Date: