

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.11.2018

Time: 12:09:46

Page: 1

FWD-CP(P)

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305242028
REGN NO : SH 9037T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 22.12.2016
DATE/TIME IN : 21.11.2018 22:25
ACCIDENT DATE : 21.11.2018

1215

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRONT BUMPER	1	1,052.20	20.00	841.76	X repair
0002 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	?
0003 04-01-0103-0640-G	FRT BUMPER BRKT RH	1	24.60	20.00	19.68	/
0004 04-01-0103-4991-G	FRT BUMPER GRILLE RH	1	51.70	20.00	41.36	X
0005 04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40	X
0006 04-01-0103-0573-A	FRT FENDER RH	1	566.30	20.00	453.04	/
0007 04-01-0103-2934-G	FRT FENDER SHIELD RH	1	175.90	20.00	140.72	X

SUB-TOTAL : 2,624.88

JOB NATURE

0000 20-05	Frt Fender Adv.Sticker RH	100.00	/
0001 L	PANEL BEATING	440.00	200
0002 23-502	SPRAYPAINT ON AFFECTED AREA	440.00	400
0003 17-01	CHECK ALL LIGHTING	40.00	X

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.11.2018

Time: 12:09:46

Page: 2

FWD-cp/p)

R TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305242028
REGN NO : SH 9037T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 22.12.2016
DATE/TIME IN : 21.11.2018 22:25
ACCIDENT DATE : 21.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-00 TUFF COAT ON AFFECTED PARTS.

~~40.00~~ 20

SUB-TOTAL : 1,060.00

TOTAL : 3,684.88

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Ka Lun 16/11/18
22/11/18
2 Days
PIP
Before Paint photo

1505h

LKK Auto Consultants hereby certify
the Repairer of the following:
• To resurvey before/after survey
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without prejudice" basis
• No illegal modification is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance company
Acknowledged by Repairer
Signature:
Date: