22/03/2002	DEE	V		
SULVOYOF:	REF: OS MSG1802	1194/N	d30 pecial Instr	ruction:
MONMON	ASSIGNME	NT (Office)		
From (Person):	Monica Chung of	M8(G	Date/Ti	ime: 23/11/18@ 9.26am
		DILL IO.		
OD TP/WS	TP RES / OD RES / EVA / INV / MV 7 CS	3		
To Inspect Vel	nicle No: SDS 9955	M	Insured:	FBF 8718E
at Workshop in	cheng Hore Mo	othe	Tel:	6755 6142
of	BIK 1019 # 01-374 /382	Yishun 1	nd. Park A	
Policy No: M	ISD/VMS/18-376417-CA	Claim No: _	MSCVII	8-001466
Sum Insured:		Excess:		
Make of Veh: (Client's Record)			D.O.A.	05/11/2018
10	20			
	REP. / REV 24 HRS (W)		H.O.D	. Endorsement:
Date/Time: 0	520m @ 23/h 8 Person Contacted:	wei Ling	Vehicle_	IN (OUT)
Date/Time	Action/Instruction () Estimate			
	8DS9955M-X			
	FBF8718F -x.			
26/11/18-	VNI			
4/12/18-	unhille not in		1	-
21/12/18-	VAI YU.			
23/1/19	0	nermen		

ASS. REC. BY:	
Kennerh AS	SSIGNMENT
From: Date:	The state of the s
Estimated Cost:	Veh No: SOS P P 55 M Yr Regn: 12, 17
OD MP WS I TP RES / OD RES / EVA / INV / MV	- Corry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s Cheng 140e	Make: Perodup MBezze co 1329
of Chery Hae	- South Insured / Std / NI / NA
Insured:	Sp.Reading 7599 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: PM 2B301500307864
Sum Insured: Excess:	Gen. Cond: 800d' Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F:
Remark: The yeh had common and to	R:195/50R15
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYOTYOKO OF Read Stone
IDAC Accident Rport: Consistent? : Yes or No	<u>Front</u> Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. Z mm R/Bal. 3 mm
Est. Repairs: 04 days Res.: Yes or No	L/Bal. 2 mm L/Bal. 3 inm
Lum Sum: 1-B./ % 3 Val.: Yes or No	D.O.A. 5/11/18 D.O.I. 21/1/19
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	_ Ma
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
WI File pars to Con	months
Day at at	
82110.38 Cahmel Efect	10
(\$210.00 Red - 9%)	18/3/2019
RECEIV	ED 1-9 MAR 2019:
Date/Time File Pass to?	
	ys Of Repair: 4
Outo/Time, File Return to?	survey No. of Trip: Survey Fee: IGO
20	Transportation:
Add Fee:	: Site Insp (\$)_s - Rs_si
Report Format :	: Interview (\$) Fixotos
	Tech Invs (\$) Others 10
Lump Sum / I.B.I: (\$ 2,110-28 P/P)	Weekend (\$
	101AL 160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	The A	Continued to the said	Table 1		
Main	07 Nov 2018		23 Nov 2018 09:26 Assign	ing tipe	[Adj	Submitted	Ins Auth'ed		Assignment
1	dain	Ref	erence		laim Detail	ls	Docume	ents	Show Al
CLAIM SU	BFOLDER DE	TAILS				-			
Insured:	SUHAIRI	BIN SABRI, ID:	S9614944A, T	el: +659224:	3454	[Create	ed by insurer]		
Main Claimant:	LIM BOON			-11 1003224.	3404				
Vehicle Reg. No.:	SDS9955	5M			Date of Los	SS: 05/11/2	018 18:00 - :59	- 07.00 0 7 51 Wellier 8 157	
Claim Type:		/V/18-001466			Policy/Cove	MSD/VM	5/18-376417-CA	(TP Fire &	Reg Date (Man Yr) Theft)
Vehicle Reg. No. (Insured):	FBF8718E				Note No.: Policy No. (Claimant):	Coverage	e: 28/12/2017 - 2	27/12/2018	
Repairer:	Cheng Hoe	Motor Pte Ltd ()	Vichus DIL 101		Excess:				
Handling Insurer:	MSIG Insu	Motor Pte Ltd (Y	e) Pte. Ltd. (HC	9 #01-374/3	82, Yishun I	ndustrial Par	k A, 768761 Yish	un - Tel: 67	755 6142
Adjuster:	LKK Auto C	onsultante Dto I	hd (110) = 1 -	., 101. +03	0027 7888	[Handled	by Monica Chun	g Pei Zher	1 - 6594 2552]
Driver/Custo fian Insured):	DANISH IRS	onsultants Pte L	DDIN AL'HELMY	256-3561 (18 / Male),	NRIC: TOO	lvice due 2	24/11/2018]		
Adj Asg. Remarks:	liab-100%; 5	SJE AGREE LKK - k	Kenneth Kong, pl	s contact Jun	e Phua @67	556142			
SSOCIATE	D MAIL RECE								
	mail for this ca							View All	Compose Case Ma
ALL ASSOC	IATED TASKS	s=				View All	1		
Due Date	Priority	Type Task Gr	oup Subjec	t Handle		View All	Search Tasks Completed On	Create Ne	w Task Complet

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Monica Chung Pei Zhen Date: 23 Jan 2019

Preliminary Advice

Insured Vehicle No : FBF8718E

TP Vehicle No

: SDS9955M

Accident Date

: 05/11/2018

Make

: PERODUA BEZZA

Assignment Date

: 23/11/2018

Date of Inspection : 21/01/2019

Est. Duration of Repair : 4.00

Inspection At

: CHENG HOE MOTOR PTE LTD (YISHUN)

BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A

SINGAPORE 768761

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

	Repairer's Estimate (Gross)	:S\$	2,320.38
nena	Revised Amount	:S\$	2,110.38
	Check Items (Estimated)	:S\$	0.00
	Total	:S\$	2,110.38

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7466E

Vehicle Details

Vehicle No.:

SDS9955M

Vehicle to be Exported:

No

Intended Deregistration Date:

07 Nov 2018

Vehicle Make:

PERODUA

Vehicle Model:

BEZZA PREMIUM X 1.35MT

Primary Colour:

Black

Manufacturing Year:

2017

Engine No.:

1NR0A83767

Chassis No.:

PM2B301S003078641 70.0 kW (93 bhp)

Maximum Power Output:

\$11,246.00

Open Market Value: Original Registration Date:

15 Dec 2017

First Registration Date:

15 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 Dec 2027

PARF Rebate Amount:

\$3,750.00

Intended COE Rebate Details

COE Expiry Date:

14 Dec 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$46,791.00

COE Rebate Amount:

\$42,589.00

Total Rebate Amount:

https://wel Ita gazy ca/Ita/sollasticas/ans

\$46,339.00

The information contained herein is correct as at 07 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	07/11/2018 11:09
Date Of Accident	05/11/2018 18:20
Exact Location Of Accident	ALONG CHOA CHU KANG AVE 1 AFTER TECK WHYE LANE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SDS9955M
Insured/Policyholder	
Name Of Registered Owner	LIM BOON SENG
NRIC No	S1257466E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93835050
Alternative Phone No	OTHERS-93835050
Vehicle Particulars	
Manufacturer	PERODUA
Model	BEZZA PREMIUM X 1.3 5MT
Exact Purpose for which vehicle was being used at time of accident	GOING TO MEET LEARNER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096646379
Cover Note Number	15/12/17 - 14/12/18
Driver	
Name of Driver	MOHAMED RAZIF BIN MOHAMED AYOOB
NRIC No	S1318333C
Date Of Birth	09/11/1958
Occupation	OUTDOOR
Date Of Driving Pass	24/07/1979
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE

(LOCAL) +65-93835050

NOEMAIL

Address

BLK 20 BEDOK SOUTH ROAD #02-29

Postcode

460020

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I was driving a Perodua SDS9955M along Choa Chu Kang Ave 1 and coming to a stop behind a bus at the junction of Teck Whye Lane. It was raining slightly. Suddenly I saw through my rear windscreen, a motorbike FBF8718E hit the rear left bumper of my car. The said rider fell off his bike to the left side of the lane in front of an MPV (Car B). The MPV just in time stop to avoid the motorcyclist but collided onto his bike. The rider was slightly injured. He refused to convey to hospital although the ambulance was activated to the scene. The MPV (Car B) has provided his car in-built footage of the accident to me.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBF8718F

Vehicle Make/Model/Colour

Details Of Properties

MOTORCYCLE

Vehicle Category Name of Driver

DANISH

NRIC/Passport Number

Contact Number

97125976


Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The second secon
I was driving a Perodua SDS 9955m along Choa Chy Kang Ave 1.
and coming to a stop behind a bus at the junction of
Teck Whye Lane. It was raining slightly. Suddenly I saw
through my rear windscreen, a milite FBF 8718E hit the rear
left bumper of my car. The said rider fell off his bike to the
left side of the lane in front of an MPV (car B.) The MPV
but collided esta lair like
just in time stop to avoid the motorcyclist. The rider was
Just in time stop to avoid the motorcyclist. The order was
slightly injured. He refused to convey to hospital although the
anibulance was activated to the scene. The MPV (car B) has provided
k
his car in built comera footage of the accident to me.
Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
under your own comprehensive policy. Please check with your policy for more information.
DECLARATION

DECLARATION		
/We declare the foregoing	narticulars are true	in over and

Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature Date & Time: (If driver is not the policyholder) Name: (YS) Date & Time: NRIC/FIN No.: (V) Claim Third Party () Reporting Only GIARMC SketchPlanForm_V3 () Claim Own Policy () Claim OD/TP at other workshop (

SKETCH PLAN

VEHICLE NO .: SDS 9955 M

DATE & TIME: 03

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No .:



Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singret.com.sg GST:201001158E RCB NO:201001158E



MSIG INSURANCE (S) PTE LTD (SGX) M/S:

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660 FAX: 62257402 7

ATTN: Motor Claim Department

Resurry Bepaint 4days

WS Ref:

TP MSIG

Claim Type:

Third Party

Accident Date:

05/11/2018

TP Veh Reg No: FBF8718E Estimate No:

ES1991066/WS

Date:

21 Jan 2019

Policy No:

Veh Reg No:

SDS9955M

Make/Model:

PERODUA PERODUA

BEZZA PREMIUM 1.3 PM2B301S003078641

Chassis No:

Engine No: Reg. Date:

15/12/2017

Estimate Repair Cost to Vehicle No :SDS9955M

	Description	U/Price	Quantity	List Price	Amoun
	Net Price			<u>S\$</u>	<u>S</u> 5
1	REAR BUMPER	594.00	1 PC	Bulli's 594.00	
2	REAR BOOT EMBLEM -BEZZA	48.50	1 PC	na 48.50	
3	REAR BOOT EMBLEM - X	39.50	1 PC	ne 39.50	
4	REAR BOOT EMBLEM - Wti	45.20	1 PC	na 45.20	
5	TAILLAMP LH	351.00	1 PC	CU 351.00	_
			Less 10%	1,078.20 107.82	970.38
	Labour				
6	TO PANEL BEATING	650.00	1 LA	650.00	5401
7	TO PUTTY AND RESPRAY PAINTING	700.00	1 LA	700.00	6001
				1,350.00	1,350.00

Total S\$ 2,320.38 Add GST @ 7% 162.43 Total Amount Payable S\$ 2,482.81

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed

 Supplementary (lem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	Submitted	Ins Auth'ed	Sta	atus	
Main	07 Nov 2018		23 Nov 2018 09:26 Edit Adj Rpt	S\$2,110.38 Edit Estimates	1 market	,110.38 ew Rpt		Re	Pending for Survey Report Cancel Case	
	Main	R	eference	Claim De	tails		Documents			Show All
CLAIM SU	BFOLDER DE	TAILS				[Created I	by insurer]			
Insured:	SUHAIRI	BIN SABRI, ID	S9614944A, Tel:	+6592243464						
Main Claimant:	LIM BOOK	SENG, ID: S1	257466E							
Vehicle Re	le Reg. SDS9955M Date of Loss: 05/11/2018 18:00 - :59 [10 Months and 21 Days From LTA Reg D					Reg Date (Man Yr)]			
Claim Type	TP / MS	C/V/18-001466		Policy/0 Note No			18-376417-CA (TP 28/12/2017 - 27/1			
Vehicle Rev No. (Insured):	g. FBF8718E			Policy N (Claima						
				Excess						
Repairer:	Cheng Ho	e Motor Pte Ltd	(Yishun) Blk 1019	#01-374/382, Yishi	ın Indu	istrial Park A	, 768761 Yishun -	Tel: 6	755 6142	
Handling Insurer:			ore) Pte. Ltd. (HQ)							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by K	ENNETH KO	ONG] [Final F	lpt du	ie 23/12/	2018]
Driver/Cus dian (Insured):	DANISH IF	SAN BIN BURHAN	IUDDIN AL'HELMY (18 / Male) , NRIC	T0015	369E Email:				
Adj Asg. Remarks:	liab-100%	; SJE AGREE LKK	- Kenneth Kong. pls	contact June Phua	@6755	6142				
ASSOCIA	TED MAIL RE	CEIVED					Vie	w All	Compos	e Case Ma
There are	no mail for this	case.								
ALL ASS	OCIATED TAS	iks⊟			V	/iew All	Search Tasks C	reate N	ew Task	Complet
Due Dat		Type Task	Group Subject	t Handler	Assign	ed By	Completed On	C	reated On	Don

Claim Documents

*SDS9955M (MSC/V/18-001466) [FBF8718E] TP LIM BOON SENG Nov 5 2018 6:00PM [SUHAIRI BIN SABRI] Cheng Hoe Motor Pte Ltd

Up	load Documents	Upload Photos Compose New Letter	View View i	n Brows	ser 🗸
Ass	essment Reports		1 per page	V	~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thun	nbnail	Print
1	22/11/18 09:53	Accident Statement From:SC - Reg. No: FBF8718E, Claimant: SUHAIRI BIN SABRI	1 Load	нтм	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thun	Thumbnail Pri	
1	23/01/19 11:47	Adjuster Immediate Advice	■ Load	НТМ	
Doc	umentation		1 per page	V	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thun	nbnail	Print
1	22/11/18 09:53	TP SDS9955M E-REPORT	£ Load	PDF	
2	22/11/18 15:47	liab-100%; SJE AGREE LKK - Kenneth Kong	£ Load	PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18021194/KSD3E2

Date:

19/03/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte.

Policy No:

MSD/VMS/18-376417-

Claimant Vehicle No:

SDS9955M

Insured Vehicle No:

FBF8718E

Date of Loss:

05/11/2018

Nature of Claim:

TP

Claim No:

MSC/V/18-001466

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDS9955M

Make & Model:

PERODUA BEZZA, 1.3 Premium (A)

Engine No:

1NR0A83767

75988 km

Reg. Date:

15/12/2017 (Man. Year: 2017)

Chassis No: Odometer:

PM2B301S003078641

Colour: Engine Capacity: Metallic Black

1329 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

195/50 R15

Rear Tyre Size:

195/50 R15

Front Tyre Size: Front Left Side:

Roadstone 2 mm

Rear Left Side:

Roadstone 3 mm

Front Right Side:

Roadstone 2 mm

Rear Right Side:

Roadstone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	970.38	970.38	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	1,140.00	210.00	15.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,320.38	2,110.38	210.00	9.05
+ GST 7.00/7.00% (S\$)	162.43	147.73	14.70	9.05
Nett Amount (S\$)	2,482.81	2,258.11	224.70	9.05

INSPECTION

Date of Assignment:

23/11/2018

Date Inspected:

21/01/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial

Park A

Singapore 768761

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)	
Parts:	143	PERODUA BEZZA 1.3 Premium (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SDS9955M)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Distorted	594.00 FL	*594.00 FL
2	1		*REAR BOOT EMBLEM - BEZZA	Necessary	48.50 FL	*48.50 FL
3	1		*REAR BOOT EMBLEM - X	Necessary	39.50 FL	*39.50 FL
4	1		*REAR BOOT EMBLEM - WTI	Necessary	45.20 FL	*45.20 FL
5	1		*TAILLAMP LH	Cut	351.00 FL	*351.00 FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	1,078.20	1,078.20
			- List Item Discount of	107.82	107.82	
				Total Parts (S\$)	970.38	970.38
			Report was unsubmit	ted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEATING	New	650.00	540.00
2	TO PUTTY AND RESPRAY PAINTING	New	700.00	600.00
		Gross Labour Cost (S\$)	1,350.00	1,140.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >