

ASS. REC. BY:

REF:

CS/SMO18021198/R/SD3N2

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

FROM (Person):

Chan Shuhui Agnes

of

SMO

Date/Time:

22/11/18 @ 4:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 7763G

Insured:

SIM1962E

at Workshop m/s

Rong sheng Auto

Tel:

8239 0099

of

42 Joh Guan Rd East #01-79

Policy No:

D18MTPV01010933

Claim No:

CMTD1805042

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/11/18

CA / REV / REP. / REV 24 HRS

Lup

H.O.D. Endorsement:

Date/Time:

5:14pm @ 23/11/18

Person Contacted:

Eric

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

GBA 7763G - X

SIM1962E - CD3/AIG6902502/DXX

26/11/18

@ 17:11 p.m. revert pending estimate from repairer to Agnes Chan via mrimer.


ASSIGNMENT

100 KPMG 2023/2024

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / IWS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GPA 7763G
 at Workshop m/s Rong Sheng
 of 42, TONG HUN RD GRS # 01-79
 Insured: Smo
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GPA 7763G Yr Regn: 2008 / Jan
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: 7546TA DYNA 150 M c.c. 2982
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 345403 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 5TFAT354503001422
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nir / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15
 R: 195 R12
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 5/5 mm
 L/Bal. 6 mm L/Bal. 5/5 mm
 D.O.A. 15/11/18 D.O.I. 23/11/18
 Survey held at Rong Sheng
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/12/18	Confirmed HS \$1,000/- @ 3 days with Resu 1 (\$1,280-50 Red - 56%)

RECEIVED 10 DEC 2018

17/12/2018

Date/Time, File Pass to?

12/12/18

1) Typist
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 1,000/- HSDays Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

250

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2018		22 Nov 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALLIANCE PAPER & BOARD PRODUCTS PTE LTD, Co. Reg. No.: 0		
Main Claimant:	SEA GULL TRADING PTE LTD, Co. Reg. No.: 197300385D		
Vehicle Reg. No.:	GBA7763G	Date of Loss:	15/11/2018 14:00 - :59
Claim Type:	TP / CMTD1805042	Policy/Cover Note No.:	D18MTPV01010933 (Comprehensive)
Vehicle Reg. No. (Insured):	SJM1962E	Policy No. (Claimant):	
		Excess:	
Repairer:	Rong Sheng Auto Engineering Trading (Toh Guan Rd East) No 42 Toh Guan Road East, #01-79 Enterprise Hub, 608583 Jurong East - Tel: 92399009		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/12/2018]		
Driver/Custodian (Insured):	CHANG PENG HAW (), NRIC: S1202524F, Tel: +6596327008		
Adj Asg. Remarks:	REPAIER PIC: Eric Kee 8239 0099		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 22 November 2018 3:59 PM
To: rsauto_eng@yahoo.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1805042/AGC - LKK(LIA)/ SJM1962E & GBA7763G ACC ON 15.11.18

Without Prejudice

Our Claim Reference: CMTD1805042/AGC
Your Reference: GBA7763G

Hi Eric,

We acknowledged receipt of your claim documents

Please be informed that Ms. Agnes Chan is the handler of this case.

As spoken, we will appoint **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for GBA7763G on a without Prejudice and any admission of liability basis.

Please submit with your report via merimen upon completion of survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Eric Kee <rsauto_eng@yahoo.com.sg>
Sent: Thursday, 22 November, 2018 1:37 PM
To: claimsreport <claimsreport@sompo.com.sg>
Subject: Third party claim (GBA7763G claim SJM1962E)

Hi Officer in charge

Kindly arrange to survey for the mentioned vehicle below :

- 1) Our customer vehicle No : GBA7763G
- 2) Your Insured vehicle No : SJM1962E
- 3) Accident date : 15/11/2018
- 4) workshop at : Rong Sheng Auto Engineering Trading
No 42 Toh Guan Road East #01-79
Enterprise Hub
Singapore 608583

5) vehicle in workshop

6) Contact person : Eric Kee 8239 0099

We would like to do direct TP claim (direct settlement) for this case

Please see attach file for GIA report

We will provide our estimate for the surveyor

Kindly let us know the officer in charge of this case and the liability

Thank you

Regards
Eric kee



Virus-free. www.avg.com

View Sent Message

This mail is associated with :

***GBA7763G (CMTD1805042)
[SJM1962E]**

TP

SEA GULL TRADING PTE LTD
Nov 15 2018 2:00PM
[ALLIANCE PAPER & BOARD PRODUCTS PTE LTD]
Rong Sheng Auto Engineering Trading

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 26/11/2018 17:11 PM.
To agnes.chan@sompo.com.sg
CC sur@lkkauto.com
Subject GBA7763G (CMTD1805042) [SJM1962E] TP

Dear Agnes,

Please be informed that we have inspected the vehicle GBA 7763G on 23/11/2018.

We are pending for estimate from repalrer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/11/2018 10:18
 Date Of Accident 15/11/2018 14:00
 Exact Location Of Accident ALONG NEW UPPER CHANGI RD AFTER BEDOK MRT STATION
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA7763G
 Insured/Policyholder
 Name Of Registered Owner SEA GULL TRADING PTE LTD
 Co Reg No 197300385D
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-62741033
 Vehicle Particulars
 Manufacturer TOYOTA
 Model DYNA 150-3.0 D (M)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
 Insurance Company
 Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number D18MTPCVE000162
 Cover Note Number
 Driver
 Name of Driver CHIA PENG @ CHIA KAM PING
 NRIC No S2507399A
 Date Of Birth 06/10/1946
 Occupation OUTDOOR
 Date Of Driving Pass 08/04/1964
 Driving Experience 54 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93256659
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address	BLK 840 YISHUN ST 81 #09-368
Postcode	760840
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: AH BOON GENDER: MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SJM1962E
Vehicle Make/Model/Colour	HYUNDAI AVANTE (SILVER)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHANG PENG HAW
NRIC/Passport Number	S1202524F
Contact Number	96327008
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or to a third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared /disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:

 16-11-2018
 Driver's Signature
 (If Driver is not the policyholder)
 Date & Time:


 Reporting Centre Person's Signature
 Name:
 NRIC/IN No.:

SKETCH PLAN

A - GBA 7763 G
B - SJM 1962 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/11/2018 about 2.00 PM, I was driving my company lorry (GBA 7763 G) along New Upper Changi Road intend turn right into Bedok North Ave 1. While waiting for traffic light to turn green suddenly I felt an impact from behind which was hit by a Hyundai car (SJM 1962 E) and due to the impact my lorry was been pushed forward no other vehicle was involve I went down to check and exchange particulars No injury involve.

CP

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

READING

Policyholder's signature
Date & Time

16-11-2018
Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 8239 0099

REG NO : 53181821K

695.92
35.00
540.00
1270.92
2020
1016.73
45.1,000

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON TOYOTA DYNA

TO : SOMPO INSURANCE SINGAPORE PTE LTD

VEHICLE NO : GBA7763G

DATE : 23/11/2018

REFER NO : RSA/2018/11/0010

PARTS DESCRIPTION

LIST ITEMS

- 1 LH REAR TAILLAMP *Photo*
- 2 LH REAR TAILLAMP PANEL *PA*
- 3 RH REAR TAILLAMP *X inconsistent car*
- 4 RH REAR TAILLAMP PANEL *X an*
- 5 REAR NUMBER PLATE PANEL *PA*
- 6 REAR NUMBER PLATE LAMP *X an*
- 7 REAR SPARE TYRE BRACKET *PA*

QTY	UNTIL PRICE	AMOUNT
1	\$352.60	\$352.60
1	\$156.70	\$156.70
1	\$352.60	\$352.60
1	\$156.70	\$156.70
1	\$181.65	\$181.65
2	\$38.40	\$76.80
1	\$236.95	\$236.95

3 days
?

927.90
25%
695.92

TOTAL :

\$1,475.60

\$1,514.00

LESS 25 % :

\$368.90

\$378.50

TOTAL PARTS :

\$1,106.70

\$1,135.50

S/NETT ITEMS

- 8 REAR NUMBER PLATE *PA*

35

1

\$45.00

~~\$45.00~~ 35

TOTAL :

\$45.00

\$45.00

TOTAL SPARE PARTS :

\$1,151.70

\$1,180.50

VEHICLE NO : GBA7763G

LABOUR DESCRIPTION

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 TO RUST PROOF ON REAR ACCIDENT AREAS
- 4 WIRING CHECK

540

AMOUNT

\$600.00

\$300.00

\$120.00

\$80.00

300
150
60
30

TOTAL LABOUR :

\$1,100.00

TOTAL PARTS AND LABOUR :

\$2,280.50



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18021198/R1SD3N2
Date: 21/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01010933
Claimant Vehicle No :	GBA7763G	Insured Vehicle No :	SJM1962E
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805042

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA7763G	Engine No:	1KD1693927
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y503001422
Reg. Date:	02/01/2008 (Man. Year: 2007)	Odometer:	345403 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,180.50	730.92	449.58	38.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	540.00	560.00	50.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,280.50	1,270.92	1,009.58	44.27
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	2,280.50	1,000.00	1,280.50	56.15

INSPECTION

Date of Assignment:	22/11/2018	
Date Inspected:	23/11/2018 Inspected At:	Rong Sheng Auto Engineering Trading (Toh Guan Rd East) No 42 Toh Guan Road East, #01-79 Enterprise Hub Singapore 608583

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Dec 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA7763G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR TAILLAMP	Broken	352.60 FL	*352.60 FL
2	1		*LH REAR TAILLAMP PANEL	Bent	156.70 FL	*156.70 FL
3	1		*RH REAR TAILLAMP (CRACKED)	Not Consistent With The Impact	352.60 FL	*- FL
4	1		*RH REAR TAILLAMP PANEL	Not Necessary	156.70 FL	*- FL
5	1		*REAR NUMBER PLATE PANEL	Bent	181.65 FL	*181.65 FL
6	2		*REAR NUMBER PLATE LAMP	Serviceable	76.80 FL	*- FL
7	1		*REAR SPARE TYRE BRACKET	Bent	236.95 FL	*236.95 FL
8	1		*REAR NUMBER PLATE	Bent	45.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,559.00	962.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	378.50	231.98
Total Parts (\$\$)	1,180.50	730.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	600.00	300.00
2	LABOUR FOR SPRAYPAINTING	New	300.00	150.00
3	TO RUST PROOF ON REAR ACCIDENT AREAS	New	120.00	60.00
4	WIRING CHECK	New	80.00	30.00
Gross Labour Cost (S\$)			1,100.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >