

ASS. REC. BY:

REF

CS3/AIG18021213/Ucd307

Special Instruction:

Surveyor
Merrin

Marcus

ASSIGNMENT (Office)

From (Person): Winnie Fan

of

AIG

Date/Time: 23/11/18 @ 9:19am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 5595M

Insured:

SKA 100J

at Workshop m/s

Autowerke Automotive

Tel:

9474 3434

of

8 Kallie Bkf Ave 4 # 05-01 / 02

Policy No:

1800068039

Claim No:

337444567536

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

11:20am @ 23/11/18

Person Contacted:

Merina

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 5595M - CCA / AXA 17004356 / R126392
	SKA 100J - X
	Dismantle: 26/11/2018
	After repair: 6/12/2018

DOA: 28/10/17

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

Acc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 559SM

at Workshop m/s Autoworld 0501

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 81

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 559SM Yr Regn: 10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota wish c.c. 1798

Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: 29158 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J706620W62J02580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/11/18 D.O.I. 23/11/18

Survey held at e 12a.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2nd O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Alex no suffic.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

180
20
200

Report Format : DAR

Lump Sum / I.B.I. (\$) _____)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKA100J AND SLG5595M ON 20/11/2018

From: Fan, Winnie-LW
To:
Cc: Fong, Andy-SY, Chin, Lee-Ying
Sent: Friday, 23 November, 2018 9:19:40 AM
Attachments:  tmp8F5B.tif

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416
winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SKA 100J

Our Ref: AL.INS.2018.SLG5595M

22 November 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY FAX; 6835 7416

78, Shenton Way
AIG Building, #08-16
Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SLG 5595M & SKA 100J ALONG MOULMEIN ROAD /
JALAN TAN TOCK SENG ON 20 NOVEMBER 2018 AT ABOUT 1320 HOURS**

We act for the owner of vehicle no. SLG 5595M

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -


AUTOWERKE AUTOMOTIVE PTE LTD

8 Kaki Bukit Avenue 4
#05-01/02 Premier Building
Singapore 415875
Person In-Charge: Merina Chia
Mobile Number: 9474 3434

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jeremy Peh at 6438 3303 or email us at jeremypeh@alt.sg for future correspondences.

Yours faithfully



ALLISTER LIM

ALLISTER LIM & THRUMURGAN

111 North Bridge Road, #11-04 Peninsula Plaza, Singapore 179098 UEN & GST Reg. No.: 53130941W
Tel: 6438 3303 Fax: 6438 1211 (Not for service of court documents) Email: mail@alt.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6660C
Vehicle Details	
Vehicle No.:	SLG5595M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	2ZR1844212
Chassis No.:	JTDGG20W60J005580
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	05 Oct 2016
First Registration Date:	05 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$19,955.00 9977
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2026
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$44,823.00
Total Rebate Amount:	\$59,789.00

The information contained herein is correct as at 23 Nov 2018

OK

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88% p.a. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$568
GV Credit Pte Ltd StailAd



Browse by Category ▼

◀ Back (1 2) Next ▶









Sort by Date Posted ▼

20 results/page ▼

27 vehicles

toyota wish

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota wish	Any	Any	2016	Any	Any	Any	Available	
	Toyota Wish 1.8A	\$83,800	\$9,190 /yr	05-Dec-2016	1,798 cc	40,353 km	MPV	Available	
Immaculate Condition Like New. 5 Years Unlimited Mileage Warranty With Borneo Motors. Service And Maintenance By Agent.Flexible Loan Package Can Be Arrange, Trade In Welcome.call Now For An Non Obliga...									
Posted: 23-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish 1.8A	\$86,800	\$9,640 /yr	11-Nov-2016	1,798 cc	31,623 km	MPV	Available	Premium
Agent Warranty Till Nov 2021! Evergreen And Reliable Toyota Wish Mid-Size MPV, Equipped With A 1.8L Dual VVT-i Engine Providing You Sufficient Power For Your Daily Drive, Yet Returning Good Fuel Effic...									
Select By Performance Premium Selection									
Posted: 23-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish 1.8A	\$75,800	\$9,070 /yr	24-Feb-2016	1,798 cc	49,194 km	MPV	Available	Premium
Reliable And Well Maintained! All Time Favorite, Spacious And Fuel Efficient! Selling Cheap! High Loan And Various Financing Options Available Here! We Are A Case Trust Company! Call For A Viewing App...									
Mayfair Motoring									
Posted: 22-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish 1.8A X	\$82,800	\$10,260 /yr	22-Jan-2016	1,797 cc	30,000 km	MPV	Available	
Low Down Payment, 1 Careful Owner With Low Mileage Done, Servicing And Maintenance Done By Reputable Workshop, Clean And Neat Interior With Nice Exterior, STA And Extended Warranty Can Be Arranged For...									
Starise Automobile									
Posted: 21-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Dynamics Mechanic Pte Ltd - Repair & Servicing								
DM-Dynamics Mechanic Garage, the only Boutique Garage in Singapore. They are a fully equipped garage serving JDM (Japanese) and Continental vehicles.									
More info about this shop									
	Toyota Wish 1.8A	\$77,800	\$9,170 /yr	15-Apr-2016	1,798 cc	46,603 km	MPV	Available	
\$0 Drive Away, Agent Unit With Low Mil Done At 46000Km.									
Posted: 19-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish 1.8A	\$83,800	\$9,130 /yr	23-Dec-2016	1,798 cc	39,500 km	MPV	Available	
\$0 Drive Away, Borneo Unit. Recently Serviced By Borneo With Receipt Proven. Warranty By Borneo Till December 2019. Owned By Single Owner, Low Mileage, Low Depreciation! Immaculate Condition! Buy With...									
Posted: 19-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish 1.8A X	\$79,900	\$9,690 /yr	10-Mar-2016	1,797 cc	46,900 km	MPV	Available	
Elegant White MPV, With Navigation System And Reverse Camera, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan...									
Motor & Leasing									
Posted: 18-Nov-2018 Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 11:41
Date Of Accident	20/11/2018 13:20
Exact Location Of Accident	MOULMEIN ROAD / JALAN TAN TOCK SENG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5595M
Insured/Policyholder	
Name Of Registered Owner	CHEW AH MOI
NRIC No	S2606660C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98417991
Alternative Phone No	OTHERS-98417991

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29023224 QMY (COMP)
Cover Note Number	

Driver

Name of Driver	LEE CHENG CHONG
NRIC No	S9314488J
Date Of Birth	25/04/1993
Occupation	INDOOR
Date Of Driving Pass	06/08/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87509210
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	45C DUNSFOLD DRIVE
Postcode	359418
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA100J
Vehicle Make/Model/Colour	PORSCHE CAYENNE TURBO 4.8 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 21 NOV 2018

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I, vehicle A was travelling straight on the stated lane. As traffic was in my lane, I proceed straight. Suddenly, vehicle B cut into my lane and we collided.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21 NOV 2018

LDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416597 Fax: 67492305
Reporting Centre Personnel's Signature: 
Name:
NRIC/FIN No.:

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR		
1005	992341	Frt Bumper Clips	NEC	6	
1006	991325	Frt Bumper Bracket	DIS		
1007	991462	Frt Bumper Side Retainer	DIS	2	
1008	991433	Frt Bumper Reinforcement	DD		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	CRA		
1021	991793	Frt Grille	CRA		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	BUC		
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SLG5595M

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	DD		
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member	BT	R	
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC		
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt RH Door	STR	R	
		1st Fender inner shield			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI






































CLAIM SUBFOLDER TRACKING














































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2018 Edit Reg		23 Nov 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TENG SU PING , ID: S7226470C								
Main Claimant:	20/11/2018								
Vehicle Reg. No.:	SLG5595M	Date of Loss:	20/11/2018 00:00 - :59 [25 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3374445675SG	Policy/Cover Note No.:	1800068039 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKA100J	Policy No. (Claimant):							
		Excess:							
Repairer:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building, 415875 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/12/2018]								
Claimant's Solicitor:	ALLISTER LIM & THRUMURGAN - Tel: 64222187								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/11/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG5595M (3374445675SG)
[SKA100J]
TP
20/11/2018
Nov 20 2018 12:00AM
[TENG SU PING]
Autowerke Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		View		
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
2	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
3	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
4	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
5	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
6	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
7	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
8	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
9	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
10	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
11	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
12	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
13	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
14	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
15	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
16	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
17	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
18	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
19	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
20	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
21	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
22	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
23	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
24	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
25	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
26	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
27	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
28	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
29	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
30	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
31	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
32	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
33	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
34	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
35	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
36	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			
37	06/12/18 17:51	General View										 Load JPG		<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
60	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
61	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
62	06/12/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
63	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	06/12/18 17:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	06/12/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/11/18 15:37	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18021213/UCD3E2

Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800068039

Claimant Vehicle No : SLG5595M

Insured Vehicle No : SKA100J

Date of Loss: 20/11/2018

Nature of Claim: TP

Claim No: 3374445675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG5595M**

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1844212

Reg. Date: 05/10/2016 (Man. Year: 2016)

Chassis No: JTDGG20W60J005580

Colour: Maroon

Odometer: 29156 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/11/2018

Date Inspected: 23/11/2018 Inspected At:

 Autowerke Automotive Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #05-01/02, Premier
 Building
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET O/S	Dented	0.00 F	*- F
4	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
8	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
9	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
10	1		*FRT GRILLE	Cracked	0.00 F	*- F
11	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
12	1		*FRT SUPPORT PANEL TOP GARNISH COVER	* Check	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
14	1		*BONNET	Buckled	0.00 F	*- F
15	1		*BONNET LOGO	Necessary	0.00 F	*- F
16	1		*WIPER WASHER TANK	Dented	0.00 F	*- F
17	1		*WIPER WASHER TANK MOTOR	* Check	0.00 F	*- F
18	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
19	1		*FRT RH FENDER	Buckled	0.00 F	*- F
20	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
21	1		*FRT RH DOOR	Repair	0.00 F	*- F
22	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >