

ASS. REC. BY:

REF: CS/FCL18021234/K15bn2

Special Instruction:

Surveyor:

Kalvin

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of FCL

Date/Time: 23/11/2018 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8705S

Insured:

SHD 6916C

at Workshop m/s

Premier Automotive

Tel:

of

23 Chungi South Ave 2 #01-02

Policy No:

Claim No:

D18008318 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

23-11-2018 3:19pm

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 8705S - CS / ALH15018794 / H119352

DA: 02/11/2018

SHD 6916C - CS / FCL18009524 / Agd3112

DA: 20/05/2018

26/11/18

@ 17:40 p.m. revised RA to Karen via email.

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

29/11/18 Check L/S \$850/ 2 days

29/11/18 Confirmed HS \$850/- @ 2 days with Kalvin. 4/5

(\$1,031.00 Red - 55%)

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

☐ : Prel. Report

1) Typist

☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / I.B.I: (\$ 850/- 4/5)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

100
50
50
17
217

Veh No: SHB 87055 Yr Regn: 25 Nov, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 671408 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CNA 6M414M E5452068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 22/11/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 23/11/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008318MFSH

Date: 26 November 2018

Our Ref: CS/FCI18021234/K1sb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8705S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/11/2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,881.00</u>
Revised Estimate Amount	: S\$ <u>1,081.00</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 Days

Yours faithfully,
Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-11-2018	Our Ref No. D18008318MFSH
Accident Date	22-11-2018	Claim Type. Third Party
Insured Vehicle	SHD6916C	Third Party Vehicle. SHB8705S
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2013 / 09:51:28	Receipt No.:	AACCK001-AX239-131125-000003
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHB8705S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131125095128242470		

Vehicle No.:	SHB8705S
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	25 Nov 2013
Original Registration Date:	25 Nov 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5452068
Engine No.:	D4FDDH308758
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,721.00
Minimum PARF Benefit:	\$7,332.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	25 Nov 2013 09:51:28
COE No.:	2013112501000897E
COE Expiry Date:	24 Nov 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$63,297.00
Lifespan Expiry Date:	24 Nov 2021
Owner ID Type:	Company

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 5:40 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D18008318MFSH/1
Attachments: SHB 8705S - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SHB 8705S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 23 November 2018 3:29 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008318MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 23 November, 2018 2:56 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008318MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8705 S

1 pc	o/s mirror assy @ \$590.00	<i>Broken</i>	\$ 590.00
			\$ 590.00
	<i>d/s Front Door x repair</i>	Less 10%	\$ 59.00
			\$ 531.00
S/NETT			
1 set	o/s door stickers	<i>new</i>	\$ 100.00
	Sundry		\$ 50.00 <i>20</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, etc.		\$ 500.00 <i>200</i>
	To putty and spray painting on o/s mirror assy, front o/s door,		\$ 400.00 <i>230</i>
	To apply rustproofing on the repaired and replaced panels.		\$ 120.00 <i>11</i>
			\$ 1,881.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahr / Uka
23/11/18 1615 hrs
2 Rs
4s
Atta Rep pth.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary damage must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021234/K1sbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6916C	Veh. Inspected	SHB 8705S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008318MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5452068	Colour	SILVER	
Odometer	641408	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2018	Inspection Date	23/11/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8705S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S MIRROR ASSY	BROKEN	590.00	590.00
1	O/S FRONT DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-59.00	-59.00
			531.00	531.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
	<u>LABOUR</u>			
	TO DISMANTLE/REFIT THE INNER GARNIEHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT O/S DOOR, ETC.		500.00	200.00
	TO PUTTY AND SPRAY PAINTING ON O/S MIRROR ASSY, FRONT O/S DOOR.		400.00	230.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,200.00	430.00
	GRAND TOTAL		1,881.00	1,081.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			850.00

Report Ref No. CS/FCI18021234/K1sbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.