22/03/2001 ASS, REC, BY:	RE	CS3 FCTIR	021238/3	Cd300 pecial lestruc	tion:
Surveyor:	the re		ENT (Office)		
From (Person):		of			23/11/180 12.57pm
Estimated Cost	*		Bill to:		
OD TP WS	TTP RES / OD RES / I	VA/INV/MV7	CS		
To Inspect Vel	nicle No:	FBN 196	5L	Insured: SH	C 1689X
at Workshop m	vsG	p Motonir	2	Tel: 01	686744
of		82 Mache		ıd	
Policy No:		1000	Claim No:	D1800824	SMESH
Sum Insured:_			Excess:		
Make of Veh: (Client's Record)			1/2	D.O.A	17/11/8
CA / REV /	REP. / REV 24 HRS	Cups		нор	Endorsement:
Date/Time:	3-08pm@23/11/18	Person Contacted:	Marca		
Date/Time	Action/Instruction (	×) Estimat	P		•
	FBN19651	×			
	3HC 1689X-	C3/AIGIA	008052	/Fn/f2k2	DOA: 23/4/2010
	Dismantle: 29/1		UU-3/		
		Jour		1	
-				-	

PRS REF: FCI	
	SIGNMENT
Estimated Cost:  OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Veli No FBN 1965 L Yr Regn: 1 ( Aug 2018- Type: M.Car / M.Cype / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No: FBN 1965L at Workshop m/s GP Motoring of 282 Macpherson Road Insured:	Make: Youngtta Karax c.c 292  Colour Blue A/C: Insured / Std / NI / NA  Sp. Reading T/Radio: Insured / Std / NI / NA  Eng/No:
Policy No. Claims No. Sum Insured: Excess: (Client's Record)	Gen. Cond: Good / Fair / Poor / Burnt Steering: Norder / Jammed / Leaked / Burnt or Brake: Norder / Jammed / Leaked / Burnt or
Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.	Modi: Nil / STRIM / STD A/Rim or  Tyre Size: F: (20 # 70 £ 15  R: (40 / 70 £ 14  BS/OUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/  TOYO/YOKO or
Bal. or Market Value:  IDAC Accident Rport: Consistent?: Yes or No  GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: days Res.: Yes or No  Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS (4)	Front   Rear   R/Bal.   G   mm   R/Bal.   G
Date: Person Contacted:  Date / Time   Action / Instruction   MV - \$15,300   PV - \$5,352   NV - \$9,948	The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time, File Pass to?    Preli. Report   Final Report   Preli. Report   Pre	Days Of Repair:  Resurvey No. of Trip:   Survey Fee: 190
2) - Add F Report Format : PRR	

Weekend (\$

150

FOTAL

Lump Sum / I.B.I: (\$



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

## MOTOR SURVEY ASSIGNMENT

Date

20-11-2018

Our Ref No. D18008245MFSH

**Accident Date** 

17-11-2018

Claim Type. Third Party

Insured Vehicle

SHC1689X

Third Party Vehicle. FBN1965L

Survey Location

282 MACPHERSON ROAD

Contact Person.

MARCUS

Contact No.

67464240/ 91686744

Fax No. 67464596

Survey Type

WITHOUT PREJUDICE: NO EST. \*

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

Cc: Workshop

GP MOTORING PTE LTD

Attention, NIL

Cc: TP Solicitor

JUSEQUITY LAW CORPORATION

TP Solicitor Fax No. NA

Officer Incharge

SERENE

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/	ClaimWS/Surveyor/JobSheet,	/246138) 🚣 PI	RI Documents 😃 Close 🗶		
		¥	PRI Header Details		
Claim No	D18008245MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & JUSEQUI MOTORING P
Workshop Name	GP MOTORING PTE LTD (Contact Person : MARCUS )	Survey Location & Contact Details	282 MACPHERSON ROAD  Mobile: 91686744 , Phone EmailId: ALFRED_NG@JUS	e: 67464240 , SEQ.COM.SG	<b>Fax:</b> 6746459
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO	EST. *	
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1689X	TP Vehicle No	FBN1965L
PRI Recieved Date	22-11-2018 10:23:10 PM	Surveyor Appointed Date	23-11-2018 12:56:16 PM	Surveyor Accept Date	26-11-2018 0
		12	Survey Report Upload		
Surveyor Inspection Date *:		Surveyor Report Date	26-11-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year *
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	cuments Upload				
		Upload Multiple	Documents		
File Nam	е			Action	
Surveyor Jo	ob Remarks				
Remarks				Save	

,

					FINAL SUMMARY	
Surveyor Final Adjusted Amount	I	Surveyor Fees	1	Remarks		
					Submit Assessment	

Action

Date

**Job Remarks** 

Copyright © 2015 MS First Capital Insurance Limited (http://www.msfirstcapital.com.sg/). All rights reserved.

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: <b>Vehicle Details</b>	7553F	
Vehicle No.:	FBN1965L	
Vehicle to be Exported:	No	
Intended Deregistration Date:	26 Nov 2018	
Vehicle Make:	YAMAHA	
Vehicle Model:	CZD300A/XMAX300	
Primary Colour:	Brown	
Manufacturing Year:	2018	
Engine No.:	H336E0031634	
Chassis No.:	MH3SH0849JK003849	
Maximum Power Output:	÷	
Open Market Value:	\$4,284.00	
Original Registration Date:	11 Aug 2018	
First Registration Date:	11 Aug 2018	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$643.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	10 Aug 2028	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
QP Paid:	\$5,514.00	
COE Rebate Amount:	\$5,352.00	
Total Rebate Amount:	\$5,352.00	

The information contained herein is correct as at 26 Nov 2018

ОК



**Share This Listing** 



# Yamaha Xmax 300

- 3 weeks ago by
- S\$13,800
- 55 Likes
- 9 Used
- In Class 2A (/categories/class-2a-1594)

(i)

read more

Make

Yamaha



# Registered date: July 2017

- Been riding it for 1 year and 3 months, and everything is working as expected. Condition is good.
- Never drop my bike or accident.
- All stock condition except change of battery in Aug 2018.
- Always park under shelter carpark.
- low mileage of 12k+ km. Equivalent to 9.6k km per year as I only use it to travel to work.
- Average 37km per litre as shown in photo(due to discipline bike run-in)
- well maintain and always service on time
- COE worth 6k.

Reason for selling is because I'm changing to car.

## Make

Yamaha

## Type

Scooter



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

<b>2008年2月1日 1000年100日 1000日</b>	ACCIDENT STATEMENT
Date Of Report	19/11/2018 14:30
Date Of Accident	17/11/2018 16:50
Exact Location Of Accident	ALONG PANDAN LOOP ROAD NEAR TO PANTECH BUILDING
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	FBN1965L
Insured/Policyholder	
Name Of Registered Owner	AZMAN BIN ABDUL RAHMAN
NRIC No	S8417553F
Email Address	SURAYA_YACOB@MOE.EDU.SG
Mobile Phone No	(LOCAL) +65-84884535
Alternative Phone No	OFFICE-84884535
Vehicle Particulars	
Manufacturer	YAMAHA
Model	CZD300A / XMAX300-292CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D18MTMC01004807
Cover Note Number	
Driver	
Name of Driver	AZMAN BIN ABDUL RAHMAN

Name of Driver AZMAN BIN ABDUL RAHMAN

 NRIC No
 S8417553F

 Date Of Birth
 21/06/1984

 Occupation
 INDOOR

 Date Of Driving Pass
 17/03/2003

Driving Experience 15 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-84884535

Fax Number

Contact Number OFFICE-84884535

EMail Address SURAYA\_YACOB@MOE.EDU.SG

Address

BLOCK 487A CHOA CHU KANG AVENUE 5

#04-83

Postcode

681487

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - U-TURN

Weather Conditions

CLEAR

Road Surface

ambulance?

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

OEWDID.

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

CHOA CHU KANG NPC - PLEASE REFER TO THE ATTACHED POLICE

REPORT

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan and Police Report for the accident details

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SHC1689X

Vehicle Make/Model/Colour

SONATA BLUE TAXI

**Details Of Properties** 

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

**DETAILS OF INJURED PERSON 1** 

Page 2 of 12

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

AZMAN BIN ABDUL RAHMAN

LEFT ELBOW CONFUSION, CONFUSION OF LEFT HIP & LEFT FOOT

FBN1965L

YES

BLOCK 487A CHOA CHU KANG AVENUE 5

#04-83

681487

## Sketch Plan Pg. 1

## SKETCH PLAN

## **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed;
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time:

Name:

NRIC/FIN No .:

Reporting Centre Personnel's Signature

## Sketch Plan Pg. 2

SKETCH PLAN					
		) (A)	)		Pandan
		///		2	Loap
Look	can Tour	D40			->)
SCRIBE CIRCUMSTANC	EES OF THE ACCIDENT				
REFER TO POLI	CE REPORT				
					Han bearing and the second
Motoroja	is still on	801:00	0000/20		
	rticulars are true in every re	espect.			
licyholder's S gnature te & Time;	Driver's Signature (If driver is not the Date & Time:		Name		sonnel's Signature

## Sketch Plan #2 Pg. 1





Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999

1 of 3 Report No. T/20181118/2060

REPORT	OF A	TRAFFIC	ACCIDENT

	ne Report N 018 17:06	Made:	Vide Report No.:	Station Diary No.:		
Informa	nt's Partic	ulars				
Name of	f Informant:	L RAHMAN	Address: APT BLK 487A CHOA CHU P SINGAPORE 681487	KANG AVENUE 5 #04-83		
ID Type / ID No.: NRIC NO / S8417553F			Contact No.: Home/Office:	Mobile: 84884535		
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Male	Age: 34	Date of Birth: 21/06/1984	Type of Informant:			
Race: Malay			Language:	Institution / School Name:		
Occupation: TECHNICIAN			Driving Licence Information: Class: 2A,2,3  Date of Expiry:			

Type of Accident:	Injury Conveyed By Ambula	Drink Drive: No	Date/Time of Accident: 17/11/2018 16:50	Type of Location
Location: Along Road 1 PANDAN LO	OP			
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Two Way  Type of Collis				

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN1965L	Motorcycle	YAMAHA	CZD300A / XMAX300	Brown	Seriously Damaged	0
SHC1689X	Car	HYUNDAI	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO		Damaged	0

Details of Vo	ehicle Insurance		MARIA SECURIO SE ANTO SE	
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
		THE PROPERTY OF THE PROPERTY O	LICONYC	LAPITY Date

## Sketch Plan #2 Pg. 2





Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999 2 of 3 Report No. T/20181118/2060

## CONTINUATION OF REPORT

Details of V	ehicle Insurance	Land State Control of the	general de la company	San Maria (San Carlo)
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN1965L	TENET SOMPO INSURANCE PTE. LTD.	D18MTMC0100480	11/08/2018	10/08/2019

	n Involved	Hall State of the A	<b>基础的</b>		in this	型是
Any Pedestrian II	nvolved: No					The state of the s
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			
Rider			196	uman k		
Name	AZMAN BIN ABDUL RAHMAN		10110220190911900	ID No.		S8417553F
Related Vehicle	FBN1965L (Motorcycle)			Contact No.		84884535
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		SPITAL	Class of Driving Licence & Expiry Date		Class: 2A,2,3 Date of Expiry: NIL
Date Treatment	17/11/2018		Date Discharge   18/11/2018		/2018	
No. of Days granted Medical Leave 05		05	Degree of			

#### Brief Details.

On 17/11/2018 at about 1645hrs I was riding my vehicle bearing the plate number of FBN1965L. I exited the carpark of 207B Pandan Loop. I then check for any incoming traffic. As it was safe, I made a right turn. I then observed One Taxi bearing the plate number of SHC1689X on the left kerb stationary. I then inch to the right. Out of a sudden, the taxi made an abrupt U-turn. I didn't managed to stop in time and hit onto the right side of the taxi. The taxi driver then alighted, i then called my colleague to assist me. The ambulance and traffic police came to the scene. I was conveyed by ambulance and was sent to NTFH. I then suffered left elbow contusion, contusion of left hip, Contusion of foot, left. I did not have any video recording. I am lodging this report for the police to investigate.

## Sketch Plan #2 Pg. 3





Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999 3 of 3 Report No. T/20181118/2060

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report:  J / Staff Sgt AHMAD ADHA BIN SAHARI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/11/2018 17:06
Officer In Charge Of Case: TP AND SI TECHNICAL STATES A 176213 Signature: Authentication Stamp NP168	Classification Of Case:

# REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8417553F





Name

## AZMAN BIN ABDUL RAHMAN

1

Race MALAY

Date of birth 21-06-1984

M

584**1755**3F

Country of birth SINGAPORE

4616811



NRIC No. S8417553F




Date of Issue 16-08-2010

APT BLK 487A CHOA CHU KANG AVENUE 5 #04-83 SINGAPORE 681487

NRIC No: \$8417553F

Date: 22/06/2015

Driving License Pg. 1



84884535

Email: Suraya-yarob@moe.edu.sg

# YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Class 2A Class 3 Motorcycles =< 200 cc

Motorcycles between 201 cc and 400 cc

Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg

17 Mar 2003 26 Jul 2018

05 Jul 2008

NP 428A

Licence No:S8417553F

## Certificate of Insurance Pg. 1



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/05 Singapore Land Tower, Singapore 048623 Tel 8461 6555 I Fax: 8221 3302 I Website: www.sompo.com.sg Co. Reg. No. 198905490E I GST Reg. No. M200903196

GP Motor Ken. /

#### Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES,1959 (MALAYSIA)

Cert No./Policy No.

: D18MTMC01004807

Insured

: AZMAN BIN ABDUL RAHMAN

Motor Vehicle (Regn No.)

: FBN1965L

Cover

: Third Party, Fire & Theft Policy Commencement Date : 11 AUGUST 2018 00:00

Policy Expiry Date

: 10 AUGUST 2019 23:59

Maximum Liability (Section I): Market value at time of loss

Excess\*

: \$500 - Section I

Named Driver 1

: AZMAN BIN ABDUL RAHMAN

HIRE PURCHASE OWNER : YEW HENG CREDIT ENTERPRISE PTE LTD

Persons or Classes of Persons entitled to drive\*

AZMAN BIN ABDUL RAHMAN

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Chapter 276) and Its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

#### Limitations As To Use

Use only for social, domestic and pleasure purposes and

- (a) by the Insured in person in connection with his business or profession or (b) in connection with the Insured's business or profession

The Policy does not cover

- (i) Use for hire or reward
- (ii) Use for racing pacemaking, reliability trial or speed-testing
- (iii) Use for the carriage of goods (other than samples) in connection with any trade or business (iv) Use for any purpose in connection with the Motor Trade

Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6461 6555.

We hareby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Transport Act, 1987 (Malaysia), and (2) the policy terms, conditions and exceptions of the Motorcycle Policy (Ref.MCY-MTMC 01)

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue: 08 AUGUST 2018 17:11

## IMPORTANT NOTICE

Keep the Certificate in your Motor Vehicle;
Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
On the sale of the Motor Vehicle or if for any reason the insurance is terminated during its currency, the insured must surrender the Certificate of insurance and the Policy to the insurance cannay. If the Certificate of insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation). Act (Chapter 189),
This Policy will cause to be valid once the Motor Vehicle in the Motor Vehicles.

Intermediary Code & Name: 11E07901 & ENSURE PTE, LTD, (MOTORCYCLE) CI Code: MY3 4JDLZ5444J0MMZAJ

<sup>\*</sup> Subject to GST wherever applicable



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

	CONTROL OF THE SECOND	NSPECTION REPORT		
MS FIRST CAPITAL IN	ISURANCE LTD	Ref: CS3/FCI18021238		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 13-12-2018		
		Code: FCI2		
1.		ars :- (THIRD PARTY CLAIN		
Insured Veh.	SHC 1689X	Veh. Inspected	FBN 1965L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18008245MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	23/11/2018	
2.	Vehicle F	Particulars & Condition		
Make & Model	YAMAHA XMAX300	c.c	292	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3SH0849JK003849	Colour	BLUE	
Odometer	(4)	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3.	Co	enditions of Tyres		
	Size	Make	Balance	
R/H Front Tyre	120/70 R15	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R14	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4.	Desc	ription of Damages		
THE VEHICLE SU	STAINED DAMAGES AT THE	E N/S AND O/S BODY.		
5.	Ge	neral Information		
Accident Date	17/11/2018	Inspect Date / Time	26/11/2018 ( 09:52 AM )	
Survey held at	GP MOTORING PTE LTD			
	282 MACPHERSON ROAD SINGAPORE 348607			
5a.		Remarks	WELL SEVERAL PROPERTY.	
B) THE REPAIR E	STIMATE WAS NOT PRESEN WAS TOLD TO PREPARE THI LEASE FIND DAMAGED VEHI			

Report Ref No. CS3/FCI18021238/Jcd3e2

Inspected By

ONG HWEE JIE

and

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.