



Report No. T/20181120/2070

Police Station Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025

Tel No: 1800-4529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/11/2018 13:47			Vide Report No.: E/20181120/0087	Station Diary No.: 16		
Informant	t's Partic	ulars		AND THE PROPERTY OF THE PROPER		
Name of Informant: TEO CHYE LIAN			Address: APT BLK 237 CHOA CHU KANG CENTRAL #05-71 SINGAPORE 680237			
ID Type / ID No.: NRIC NO / S1397723B Nationality: SINGAPORE CITIZEN			Contact No.: Home/Office: Email:	Mobile: 91190923		
Sex: Male	Age: 59	Date of Birth: 30/01/1959	Type of Informant:			
Race: Chinese		500 E	Language:	Institution / School Name:		
Occupation:			Driving Licence Information: Class: 3,4,5	Date of Expiry		

General Inform	mation of the Accident	PSS (AND COMMENTAL AND COMMENTAL COM		
Type of Accident:	Injury Attended by Police	Drink Date/T		Type of Location: Straight Road
	EXPRESSWAY 	afra LP 736		*
Lamp Post Nu Weather: Clear	umber: 736	Road Surface:		Road Speed Limit:
Traffic Flow: Traffic Control: Dual Carriage Way Not Controlled			Traffic Volume:	
Type of Collisi Chain Collision				Anyone conveyed by ambulance: Yes

Vehicle No.		Make	Model	Color	Condition	No of Passenge
SGD9501H					Slightly Damaged	1
SJL6874Z	Car	SUZUKI	SWIFT 1.6 AT	Grey	Slightly Damaged	0
SLH5273L	Car			100	Slightly Damaged	1
WQD2956	Car				Slightly Damaged	0





T/20181120/2070

2 of 4

Report No. T/20181120/2070

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025

Tel No: 1800-4529999

CONTINUATION OF REPORT

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SJL6874Z	TOKIO MARINE INSURANCE	MT100891	28/03/2018	27/03/2010

Any Pedestrian In	n Involved				
No. of Pedestrian		Use of Pe	of Pedestrian Crossing: NA		
Driver	S IIIJul Cu. INIL	000 0 0			
	Liow Swee Hoe		ID No.		S7337331Z
Name	LIOW Swee Hoe		10 140.		0,00,00,1
Related Vehicle	SGD9501H (Car)		Contac	t No.	92749469
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment NIL Date			e Discharge NIL		
No. of Days gran	Degree of Injury NIL				
Driver	ted Medical Leave NIL	The second secon	and the second s	CHARLES THE CLASS OF SCHOOL	100 St. 100 St
Name	TEO CHYE LIAN		ID No.		S1397723B
Related Vehicle	SJL6874Z (Car)		Contact No.		91190923
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Dis	Date Discharge NIL		A SIGNATURE AND PROCESSION AND ADMINISTRATION OF STREET AND PROCESSION AND ADMINISTRATION OF THE CORP.
	ted Medical Leave NIL	Degree of Injury NIL			
Driver	TEC INEGICAL COAVO				asseption from the provided of the Company of the C
Name	Masngut		ID No.		S1412653H
Related Vehicle	SLH5273L (Car)		Contact No.		9842237
Hospital/Clinic	NIL .		Class of Driving Licence &		Class: NIL Date of Expiry: NIL
A STATE OF THE STATE OF				/ Date	
Date Treatment	NIL	THE RESIDENCE OF THE PROPERTY	Discharge NIL		
	nted Medical Leave NIL	Degree	of Injury	NIL	





T/20181120/2070

3 of 4

Report No. T/20181120/2070

Police Station Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025

Tel No: 1800-4529999

CONTINUATION OF REPORT

Driver		titti dikala kati untuk kati a kati dika titulih kanpa wakusa na pinga na mala pangana na pangana na pangana n				о 100 го 10 мгл на том на том на
Name	Lim Chee Siong		4	ID No		730905-02-5283
Related Vehicle	WQD2956 (Car)			Conta	ict No.	NIL
Hospital/Clinic	NIL			Class Drivin Licen Expir	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	NIL	Degree o	CONTRACTOR OF THE PROPERTY OF THE PARTY OF T	COMPANIES DOLUME CARDON CARDON COMPANIES	meters for the contract of the	

Brief Details.

On the above mentioned, date and time, I was driving my car(SJL6874Z) along PIE towards Changi. The traffic was heavy at that point of time. I was driving on the rightest lane of a four lane road. As I was nearing the 16 km mark, my car was stationary as the car (SLH5273L) in front of me is also stationary.

While stationary, I suddenly felt a strong impact coming from the rear. The impact was strong enough that it causes my car to move forward and hit onto the rear portion of the car in front of me. I alight to make a check and discovered that a car(SGD9501H) had hit onto the rear portion of my car. I also discover that a Malaysian car(WQD2956) had hit onto the rear portion of the car (SGD9501H).

Awhile later Traffic police and ambulance came. One of the passenger from SGD9501H was conveyed to hospital. I exchange particulars with the other drivers and took photos of the accident. I was then told to lodge a police report. I wish to informed that I have in-car camera.





Police Station Of Origin: Thomson NPP 25 Sin Ming Road #01-180 SINGAPORE 570025 Tel No: 1800-4529999

4 of 4 Report No. T/20181120/2070

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

E /	Signature Of Informant:
Sgt 3 MUHAMMAD RIDZUAN BIN ABDUL RAHMAN	The state of the s
Signature Of Interpreter:	Date/Time:
Not applicable	20/11/2018 13:47
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Sr Staff Sgt NOR FAIZAL BIN YAHYA	•
Contact No.: 65476202	
Authentication Stamp NP168	X