

10/01/2018

ASS. REC. BY

REF: CS/MSG18015778/RVD3-1

Print Instructions

Submitted by  
Mei Men

Rasul  
Christina Wong

ASSIGNMENT (Office)

of MSG

Date/Time: 23/11/18

22/8/18 @ 4:27pm

Estimated Cost

Bill to:

OD / IT / WS / IT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 818 G589K

Insured: YP 6507K

at Workshop m/s: AM# Auto care

Tel: 8778 3636

of 36 Joh Guan Rd East #01-36

Policy No: 329087288 MCC

Claim No: 56 8476

Stm Insured

Excess:

Make of Vch  
(Client's Record)

D.O.A: 21/08/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement

Date/Time: 9:41am @ 21/8/18

Person Contacted

Mei Men

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	818 G589K - X
	YP 6507K - X
	Dismantle: 30/8/2018
	After repair: 3/9/2018

30/11/18 Submit LS \$ 3250 (Red 3050, 4890), 5 days

RECEIVED 10 NOV 2018

  
30/11/2018



## Nivitha (LKK Auto)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Friday, 23 November 2018 5:09 PM  
**To:** Christina Wong; assignments  
**Subject:** RE: Our Ref:M568476 Your Ref:SJS6589K

Dear Christina,

Thank you for the email.

**Dear Assignment Team,**

**FYNA**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Christina Wong <Christina\_Wong@sg.msig-asia.com>  
**Sent:** Friday, 23 November 2018 5:04 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Our Ref:M568476 Your Ref:SJS6589K

Hi Veron

Please do paper survey I have sendback the report in merimen.

thanks





Best Regards

**Christina Wong**

Senior Executive, Claims Services (Motor)

Direct line +65 6643 1311 | Direct fax +65 6225 7402 | [christina\\_wong@sg.msig-asia.com](mailto:christina_wong@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

# S K AUTO CONSULTANTS

## Invoice

Bill To: GOH YEE CHU  
C/o AMA Autocare Pte Ltd  
Enterprise Hub #01-36  
36 Toh Guan Road East  
Singapore 608580

Invoice No:	2018524
Date:	28/9/2018
Our Ref	TP/018/0524SK

Description	Amount (S\$)
PARTICULARS	
Vehicle Registration No. : SJS 6589K	380.00
Date of Accident : 21/08/2018	
Date of Inspection : 28/08/2018	
SERVICES:	
Assessment with report (inclusive of transport charges and photographs etc)	
Total	380.00
Balance Due	380.00

We would appreciate your cheque crossed and made payable to:  
S K AUTO CONSULTANTS



Authorized Signature

## AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/018/0524SK  
Your Reference: TBA

Date: 28/9/2018

TO: GOH YEE CHU  
C/o AMA Autocare Pte Ltd  
Enterprise Hub #01-36  
36 Toh Guan Road East  
Singapore 608580

Assessment of Vehicle No : SJS 6589K  
Date of Accident : 21/08/2018  
Date of Inspection : 28/08/2018

We have carried out a physical assessment of SJS 6589K at AMA Autocare Pte Ltd according to your instructions on 28/08/2018 and are pleased to submit our report as follows;

### 1. VEHICLE PARTICULARS

Registration No.	:	SJS 6589K
Make & Model	:	HONDA STREAM
Year of Registration	:	2009
Engine Capacity (cc)	:	1799
Chassis No.	:	RN610556547
Engine No.	:	NA
Colour	:	BLACK
Mileage (km)	:	306949

### 2. VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

### 3. TYRE PARTICULARS & CONDITION

#### Front

RH Make/Size	:	YOKOHAMA 215/50R17 - 70%
LH Make/Size	:	YOKOHAMA 215/50R17 - 70%

#### Rear

RH Make/Size	:	YOKOHAMA 215/50R17 - 70%
LH Make/Size	:	YOKOHAMA 215/50R17 - 70%


Note: % denotes the remaining percentage of the tyre

Our Reference      TP/018/0524SK  
Vehicle No.        SJS 6589K

#### 4.DESCRPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Rear portion

Please see attached schedule for details.



Estimated Amount                : S\$8,839.04  
Adjusted Amount                : S\$6,300/-  
Estimated Repair Days        : 6 days

Pursuant to your instruction, we have NOT AUTHORIZED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 Days from the date hereof, this report shall be treated as correct

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by S K AUTO CONSULTANTS for any reliance on this report by any third party.

2.3

Our Reference	TP/018/0524SK
Vehicle No.	SJS 6589K

QTY	DESCRIPTION	CONDITIO		NT(\$\$)
	<b><u>PARTS (LIST ITEMS)</u></b>			
1	Rear Bumper	Deformed	665.4 +	
1	Rear Bumper tow cover	Missing	42.5 +	
2	Rear Bumper Lower Bracket L/R@\$7.00	Bent	14. +	
2	Rear Bumper Side Retainer L/R @ \$19.40	Necessary	38.8 +	288.00
1	Rear end panel	Dented	189.5 +	105.00
1	Rear end panel top garnish	Deformed	903.2 +	14.00
1	Rear Tailgate	Distorted	31.6 +	38.80
1	Rear Tailgate "Stream" Emblem	Necessary	72. +	780.00
1	Rear Tailgate Honda badge	Necessary	109.4 +	238.00
1	Rear Tailgate Inner Trim Board	Reuse	172. +	425.00
1	Rear Tailgate Mechanism Lock	Damaged	704.8 +	31.60
1	Rear Boot weatherstrip	Deformed	2,943.2	72.00
1	Rear exhaust silencer assembly	Damaged	x	0.00
2	Rear exhaust silencer assembly mountings	Necessary	80. x	109.40
1	Rear RH Taillamp	Grazed	2,354.56 x	172.00
			..0..	782.00
			200. +	870.00
			30. +	973.80
			60. +	194.76
			290. +	779.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1 set	Rear Bumper Reverse Sensor	Damaged	..0..	250.00
1 set	Rear Tailgate Inner Trim Board Clips	Necessary		30.00
1	Rear Tailgate Windscreen Sealant	Necessary	500. +	80.00
			600. +	
			30. +	
		TOTAL PART	60. +	139.04

...

$$\begin{array}{r} 2,354 \cdot 56 + \\ 290 \cdot + \\ 1,450 \cdot + \\ 4,094 \cdot 56 \end{array}$$

	x
80	x
3,275	x

# S K AUTO CONSULTANTS

Page No. 4

Our Reference TP/018/0524SK

Vehicle No. SJS 6589K

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	<del>1200.00</del> 500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1200.00	<del>900.00</del> 600
3	To remove, refix wiring system at accident damaged areas check for proper function	200.00	<del>120.00</del> 30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00	<del>120.00</del> 60
5	To remove and refix rear windscreen	140.00	<del>120.00</del>
6	To remove and replace reverse sensors and check for proper function	120.00	<del>80.00</del> 60
7	To perform anti-rust treatment on affected areas	180.00	<del>150.00</del> 80
Labour Total :		3390.00	2690.00
TOTAL (PARTS & LABOUR):		8839.04	7829.04

**Note: (For Lump Sum Repair)**

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lump Sum contract amount is S\$6,300/-

  
S.Kumanan  
Motor Surveyor



P - 2354.56  
S/N - 290.00  
L - 1450.00  
T - 4094.56  
20%  
3275.64  
41 - 3250  
5 days



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4859A
<b>Vehicle Details</b>	
Vehicle No.:	SJS6589K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A1763329
Chassis No.:	RN61056547
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,804.00
Original Registration Date:	27 Aug 2009
First Registration Date:	27 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$20,804.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2019
PARF Rebate Amount:	\$10,402.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Aug 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$10,046.00
COE Rebate Amount:	\$895.00
<b>Total Rebate Amount:</b>	<b>\$11,297.00</b>

The information contained herein is correct as at 04 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/08/2018 16:25
Date Of Accident	21/08/2018 15:30
Exact Location Of Accident	ALONG PIONEER ROAD NORTH TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS6589K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOH YEE CHU
NRIC No	S7985645B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98799250
Alternative Phone No	OFFICE-98799250

### Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00148408/04
Cover Note Number	

### Driver

Name of Driver	TAN KING GUAN
Work Permit No	S7985645B
Date Of Birth	17/05/1979
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2005
Driving Experience	12 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91864751
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 605 JURONG WEST STREET 62 08-215
Postcode	640605
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE SKETCH PLAN


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6507K
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SHAHIDULAH MD
NRIC/Passport Number	061905731
Contact Number	91950217
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

when I was driving along pioneer Rd North toward Ate and my car stop at the corner beside the road about to give way to other vehicle. Suddenly, there is a hit from behind, a 10 foot long lorry just hit my car back.

**Important:**

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

<input type="checkbox"/>	- Reporting Only
<input type="checkbox"/>	- Claim OD
<input type="checkbox"/>	- Claim TP
<input checked="" type="checkbox"/>	- Claim OD/TP at other workshop

**DECLARATION**

I/WE declare the foregoing particulars are true in every respect.

STE AUTO (S) PTE LTD

Policyholder's signature  
Date & Time

Driver's Signature  
(if driver not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name: Kenneth  
Nric/Fin No.

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Kenneth  
NRIC/TIN No:

**kenneth Patrick Cornelius**

---

**From:** GOH YEE CHU <gohyeechu@hotmail.com>  
**Sent:** Friday, August 24, 2018 4:27 PM  
**To:** kenneth Patrick Cornelius  
**Subject:** autorisation

Dear Kenneth

I hereby authorise my husband, Tan King Guan(S7985645B) to process the necessary claim on my behalf for the reported car accident.

Should there be any clarification, please do not hesitate to contact me. Thanks!

Best Regargds  
Ms Goh Yee Chu  
S7874859A  
98799250

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

License Number: **S7985645B**

Name: **TAN KING GUAN**

Birth Date: **17 May 1979**  
Issue Date: **13 Nov 2010**

00190-41389



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S7985645B**



Name: **TAN KING GUAN**

Race: **CHINESE**

Date of birth: **17-05-1979**

Country/Place of birth: **MALAYSIA**

Sex: **M**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)**

Class	Description	Effective Date
Class 2B	Motorcycles <= 200 cc	07 Dec 2006
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	07 Dec 2006

NP 42BA



License No: **S7985645B**



9406362

NRIC No. **S7985645B**



Nationality: **MALAYSIAN**

Date of Issue: **31-05-2016**

Address:  
**APT BLK 605 JURONG WEST STREET 62  
#08-215  
SINGAPORE 640605**

Sketch Plan Pg. 5

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7874859A



Picture

GOH YEE CHU

吳以秋

Race

CHINESE

Date of birth

05-11-1978

Country/Place of birth

MALAYSIA

Sex

F

S7874859A



3170063



NRIC No. S7874859A



Date of issue

10-05-2013

Address

APT BLK 605 JURONG WEST STREET 62  
#05-215  
SINGAPORE 640605



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/08/2018 08:59
Date Of Accident	21/08/2018 15:00
Exact Location Of Accident	PIONEER NORTH ROAD ROUNDABOUT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6507K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD
Co Reg No	-
Email Address	GWENKIMSOONLEE@GMAIL.COM
Mobile Phone No	
Alternative Phone No	Office-67412222

### Vehicle Particulars

Manufacturer	HINO
Model	XZU710R-HKFMS3-4.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S 29087288 MKC
Cover Note Number	06/07/2018 TO 05/07/2019

### Driver

Name of Driver	SHAHIDULLAH MD
NRIC No	G0040239M
Date Of Birth	01/05/1972
Occupation	OUTDOOR
Date Of Driving Pass	20/06/2008
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91950217



Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	-
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-
<b>General Information of the Accident</b>	
Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY
<b>Other Information</b>	
Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1
<b>Details of Police Action</b>	
Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	
<b>Circumstances of Accident</b>	
REFER TO THE ATTACHED.	
<b>Attachment(s)</b>	
Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO
<b>DETAILS OF OTHER VEHICLE PROPERTY 1</b>	
Vehicle Registration Number	SJS6589K
Vehicle Make/Model/Colour	HONDA/ STREAM/ BLACK
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	NIL
NRIC/Passport Number	
Contact Number	91864751
Address	NIL
	NIL
Postcode	NIL

Insurance Company Name

Nature Of Damage

NIL

No. Of Passenger (Including Driver)

1

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23/08/2018  
@0915HRS



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



A: YP6507K

B: SJS6589K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE MENTIONED DATE & TIME, I WAS STATIONARY AT THE JUNCTION OF PIONEER NORTH ROAD & WAITING TO GO INSIDE OF THE ROUNDABOUT. SAW VEHICLE SJS6589K MOVE INTO THE ROUNDABOUT, I RELEASED BRAKES AND FOLLOWED. OUT OF A SUDDEN, VEHICLE SJS6589K E-BRAKE FOR NO REASON. I TRIED TO STOP TO AVOID COLLISION BUT IT WAS STILL TOO LATE. AS A RESULT, MY VEHICLE HIT THE BACK OF THE SAID VEHICLE. NO INJURY WAS INVOLVED. THERE WAS NO VISIBLE DAMAGES TO MY VEHICLE AS THE IMPACT WAS WEAK.

DECLARATION

I, HEREBY DECLARE that:-

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.



INS: MSIG

VEH NO.: YP6507K

CLAIM TYPE: REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23/08/2018  
@0915HRS



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way, # 21 01, SGX Centre 2, Singapore 068907  
 Tel: +65 6827 7888, Fax: +65 6827 7800  
 Co Reg No 200412212G, GST Reg No 20 0412212G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.E.360  
 Goods Carrying Vehicle - BKK :

**COMMERCIAL VEHICLE**  
 Comprehensive

**Certificate No.** S 29087288 MKC

**Excess:** SGD700

**1. Index Mark and Registration Number of Vehicle**

YP6507K

**2. Name of Policyholder**

Kim Soon Lee (LIM) Heavy Transport Pte Ltd

**3. Effective Date of the Commencement of Insurance for the purposes of the Act**

06/07/2018

**4. Date of Expiry of Insurance**

05/07/2019

**5. Persons or Classes of Persons entitled to drive\***

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6. Limitations as to use\***

Use in connection with the Policyholder's business.  
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.  
 Use for social domestic and pleasure purposes.  
 The Policy does not cover  
 (1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.  
 (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
 Approved Insurers

  
 for Chief Executive Officer

FCV2201807031124

driver's work permit & license



driver's work permit & license

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

**Class 3** Motor cars with unladen weight  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of driver; and other motor vehicles with unladen weight  $\leq$  2500kg **28 Jun 2008**

NP 4284



Licence No: G0040239M

**VISIT PASS**  
Immigration Regulations

07-10-2017

**Name**  
SHAHMOULAH MO

**ID No**  
G0040239M

**Date of Birth** 01-05-1972 **Sex** M

**Nationality**  
BANGLADESH

**MULTIPLE JOURNEY VISA ISSUED**

YOU ARE TO SURVEYOR THIS CARD WHEN IT CANCELLER OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download QRWorkPass App to check status






Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo





































## ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018		28 Aug 2018 16:27 <a href="#">Edit Adj Rpt</a>	<b>S\$3,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>GOH YEE CHU</b> , ID: S7985645B								
Vehicle Reg. No.:	<b>SJS6589K</b>	Date of Loss:	21/08/2018 15:00 - :59 [107 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 568476</b>	Policy/Cover Note No.:	S29087288MKC (Comprehensive) Coverage: 06/07/2018 - 05/07/2019						
Vehicle Reg. No. (Insured):	<b>YP6507K</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ama Autocare Pte Ltd (HQ)</b> 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 27/11/2018]								
Driver/Custodian (Insured):	SHAHIDULLAH MD (). NRIC: G0040239M, Tel: +6591950217								
Adj. Asg. Remarks:	Liability is down. TP disagree with SJE list, proceed to appoint LKK. Contact Person: Mr Melvin   8778 3636								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (23/11/2018): Report Send Back Alerts - SJS6589K (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJS6589K (568476)  
 [YP6507K]  
 TP  
 GOH YEE CHU  
 Aug 21 2018 3:00PM  
 [KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD]  
 Ama Autocare Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/18 11:26	<b>Accident Statement</b> <small>From: SC - Reg. No: YP6507K, Claimant: KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD</small>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/08/18 15:31	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	30/08/18 15:31	General View		<input checked="" type="checkbox"/>
35	30/08/18 15:31	General View		<input checked="" type="checkbox"/>
36	30/08/18 15:31	General View		<input checked="" type="checkbox"/>
37	30/08/18 15:31	General View		<input checked="" type="checkbox"/>
38	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	04/09/18 12:32	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
67	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
68	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
69	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
70	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
71	07/09/18 18:10	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/18 11:26	SJ56589K GIA Rpt From: SC - Reg. No: YP6507K, Claimant: KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD		<input checked="" type="checkbox"/>
2	23/11/18 16:57	TP survey report		<input checked="" type="checkbox"/>
3	23/11/18 17:00	TP survey photos		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 17:30	PRS Invoice		<input checked="" type="checkbox"/>
2	03/12/18 17:30	Colour Photo		<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015778/R1VD3E2-1

Date: 03/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S29087288MKC

Claimant Vehicle  
No : SJS6589K

Insured Vehicle No : YP6507K

Date of Loss: 21/08/2018

Nature of Claim: TP

Claim No: 568476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS6589K

Make &amp; Model: HONDA STREAM, 1.8 X (A)

Engine No: R18A1763329

Reg. Date: 27/08/2009 (Man. Year: 2008)

Chassis No: RN61056547

Colour: Black

Odometer: 306949 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	5,449.04	2,644.56	2,804.48	51.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,450.00	1,940.00	57.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,839.04</b>	<b>4,094.56</b>	<b>4,744.48</b>	<b>53.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,839.04</b>	<b>3,250.00</b>	<b>5,589.04</b>	<b>63.23</b>

INSPECTION

Date of Assignment: 28/08/2018

Date Inspected: 29/08/2018 Inspected At:

Ama Autocare Pte Ltd (HQ)  
36 Toh Guan Road East, #01-36  
Singapore 608580

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2018)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJS6589K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,288.00 FL	*665.40 FL
2	1		*REAR BUMPER TOW COVER	Missing	105.00 FL	*42.50 FL
3	2		*REAR BUMPER LOWER BRACKET L/R	Bent	14.00 FL	*14.00 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	38.80 FL	*38.80 FL
5	1		*REAR END PANEL	Repair	780.00 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	238.00 FL	*189.50 FL
7	1		*REAR TAILGATE	Distorted	1,425.00 FL	*903.20 FL
8	1		*REAR TAILGATE STREAM EMBLEM	Necessary	31.60 FL	*31.60 FL
9	1		*REAR TAILGATE HONDA BADGE	Necessary	72.00 FL	*72.00 FL
10	1		*REAR TAILGATE INNER TRIM BOARD	Reuse	325.00 FL	*- FL
11	1		*REAR TAILGATE MECHANISM LOCK	Damaged	109.40 FL	*109.40 FL
12	1		*REAR BOOT WEATHERSTRIP	Deformed	172.00 FL	*172.00 FL
13	1		*REAR EXHAUST SILENCER ASSEMBLY	Not Necessary	782.00 FL	*- FL
14	2		*REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	Not Necessary	48.00 FL	*- FL
15	1		*REAR RH TAILLAMP	Grazed	870.00 FL	*704.80 FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
17	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,708.80</b>	<b>3,233.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,259.76</b>	<b>588.64</b>
<b>Total Parts (S\$)</b>	<b>5,449.04</b>	<b>2,644.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	500.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,200.00	600.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS CHECK FOR PROPER FUNCTION	New	200.00	30.00
4	TO REMOVE / REFIX INNER TRIMS, FITTINGS, GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	150.00	60.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	120.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	60.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	80.00
Gross Labour Cost (S\$)			3,390.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >