

ASS. REC. BY:

REF:

CS3/AIG18021300/Ucd302

Special Instruction:

Surveyor:  
Meinera

Marcus

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

26/11/18 @ 1:02pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SKM 9475E

Insured:

SLM 6362E

at Workshop m/s

Autowerke Automotive

Tel:

9474 3434

of

8 kaki Bkt Ave 4 # 05-01

Policy No:

Claim No:

879811517SSG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

1:41am @ 26/11/18

Person Contacted:

Meinera

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (4) Estimate
	SKM 9475E -X
	SLM 6362E -X
	Dismantle: 28/11/2018
	After repair: 12/12/2018.

(08/11/13) wef

ASS. REC. BY: MORCUG

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 9475E

at Workshop m/s MORCUG

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 150k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: 3 yrs 7 mo

Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>Ma sett. p. LTA 94388 rep 3ok.</u>

Veh No: SKM 9475E Yr Regn: 7112

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Porsche Cayenne c.c. 4806

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 199570 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WP1222922CLA48107

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 23/11/18

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 26/11/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) S + RS, SI

☐ : Interview (\$ \_\_\_\_\_) Photos

☐ : Tech. Invs (\$ \_\_\_\_\_) Others


☐ : Weekend (\$ \_\_\_\_\_) TOTAL

Report Format : DAR

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Survey Fee:	<u>180</u>
Transportation:	
	<u>20</u>
TOTAL	<u>200</u>

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 26/11/2018 1:02:58 PM  
Attachments:  tmp6AD5.tif

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SLM 6362E

Our Ref: AL.INS.2018.SKM 9475E

23 November 2018

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**  
78, Shenton Way  
AIG Building, #08-16  
Singapore 079120

**BY FAX; 6835 7416**

Dear Sirs,

**ACCIDENT INVOLVING SKM 9475E & SLM 6362E ALONG AYER RAJAH EXPRESSWAY AFTER ALXANDRE EXIT ON 23 NOVEMBER 2018 AT ABOUT 1125 HOURS**

We act for the owner of vehicle no. SKM 9475E

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

**AUTOWERKE AUTOMOTIVE PTE LTD**  
8 Kaki Bukit Avenue 4  
#05-01/02 Premier Building  
Singapore 415875  
Person In-Charge: Merina Chia  
Mobile Number: 9474 3434

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jeremy Peh at 6438 3303 or email us at [jeremypch@alt.sg](mailto:jeremypch@alt.sg) for future correspondences.

Yours faithfully



ALLISTER LIM

**ALLISTER LIM & THURMURGAN**

111 North Bridge Road, #11-04 Peninsula Plaza, Singapore 179098 UEN & GST Reg. No.: 53130941W  
Tel: 6438 3303 Fax: 6438 1211 (Not for service of court documents) Email: [mail@alt.sg](mailto:mail@alt.sg)

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5776A
<b>Vehicle Details</b>	
Vehicle No.:	SKM9475E
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2018
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE S 4.8 A
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	M4802C08779
Chassis No.:	WP1ZZZ92ZCLA48107
Maximum Power Output:	294.0 kW (394 bhp)
Open Market Value:	\$99,282.00
Original Registration Date:	03 Jul 2012
First Registration Date:	03 Jul 2012
Transfer Count:	2
Actual ARF Paid:	\$99,282.00 49641
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2022
PARF Rebate Amount:	\$64,533.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Jul 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$85,889.00
COE Rebate Amount:	\$29,855.00
<b>Total Rebate Amount:</b>	<b>\$94,388.00</b>

The information contained herein is correct as at 27 Nov 2018

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

9/13 BMW 316i, Responsive 1.6L Twin Power TurboEngine



Sporty BMW 3 Series. Well  
Maintained By 1 Owner, Low  
Mileage Done.  
[Shine Connect](#) [StarAd](#)







**HIN LUNG AUTO**  
Ho Bee Group  
**One Stop Car H**  
Finance, Insurance, Wor  
New and Used Cars

[Browse by Category](#)
[Sort by Date Posted](#)

12 vehicles

Porsche Cayenne

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Ty
<b>Search Selection</b>	<b>Porsche Cayenne</b>		Any	Any	<b>2012</b>	Any	Any	Ar
	<b>Porsche Cayenne Hybrid S 3.0A Tip</b>		<b>\$153,000</b>	<b>\$29,120 /yr</b>	<b>28-Dec-2012</b>	<b>2,995 cc</b>	<b>50,863 km</b>	<b>SU</b>
	<b>Fuel Type:</b> Petrol-Electric First Class Commuting Experience, Unparalleled Status And Comfort. Often Compared, Always Unrivalled. Second To None. It Also Offers User Impeccable Comfort, Safety And Utility. Handles Beautiful... Posted: 24-Nov-2018 Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche							
	<b>Porsche Cayenne S 4.8A Tip</b>		<b>\$168,000</b>	<b>\$32,060 /yr</b>	<b>06-Jul-2012</b>	<b>4,806 cc</b>	<b>48,000 km</b>	<b>SU</b>
	Low Mileage, Well Maintained And Taken Care By Owner. Please Call To Arrange For Viewing! Posted: 23-Nov-2018 Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche							
	<b>Porsche Cayenne 3.6A Tip</b>		<b>\$151,888</b>	<b>\$27,470 /yr</b>	<b>19-Dec-2012</b>	<b>3,598 cc</b>	<b>155,333 km</b>	<b>SU</b>
	Stuttgart Warranty Till Mid Dec 18 And Extendable. Full Maintenance Record. Downgrading To A Smaller Car For The Wife. Will Consider A Tra Feasible. Agents Assistance Not Necessary. Going On A ... Posted: 22-Nov-2018 Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche							
	<b>Porsche Cayenne 3.6A Tip</b>		<b>\$145,800</b>	<b>\$30,590 /yr</b>	<b>04-May-2012</b>	<b>3,598 cc</b>	<b>71,000 km</b>	<b>SU</b>
	14 Ways Power Memory Package Seats, 3 Spoke Steering Wheel, Cruise Control, Aluminium Package. 10% Down Payment Under Leasing Avail There Are No Old Porsche Only New Owner. Porsche Pre-Owned Centre Posted: 16-Nov-2018 Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche							
	<b>Chasing electric dreams with Porsche</b> A night at Sepang proves that as Porsche pursues an increasingly electrified future, it is always performance that leads the way. <a href="#">Read this article</a>							
	<b>Porsche Cayenne 3.6A Tip</b>		<b>\$144,800</b>	<b>\$26,310 /yr</b>	<b>16-Nov-2012</b>	<b>3,598 cc</b>	<b>95,000 km</b>	<b>SU</b>
	1 Owner With Full Servicing Record At Stuttgart Workshop. One Of The Most Popular SUV Under Luxury Brand Segment. Iconic Porsche Cayer Spacious Cabin Size & Unforgettable Porsche Driving Experi... Porsche Pre-Owned Centre ad: 13-Nov-2018 Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche							

[Compare](#)



**Porsche Cayenne 3.6A Tip**      **\$130,000**      \$23,150 /yr      11-Oct-2012      3,598 cc      101,200 km      SU

Cheapest In Market.Stuttgart Unit.1 Owner.Fully Agent Maintained.Very Well Maintain By Owner And Interior Still Looks Like New.100% Accident Free.Mint Condition.Trade In Welcome.Pls Call Or Whatsapp F...

Posted: 09-Nov-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



**Porsche Cayenne Diesel 3.0A Tip**      **\$165,000**      \$32,510 /yr      21-Sep-2012      2,967 cc      73,000 km      SU

**Fuel Type:** Diesel (Euro 5 Engine and Above)

1.98% Loan Interest Now Available. Stuttgart Unit! Full Wald Bodykit With 22" Rims, The Pinnacle Of All Premium SUV, First Class Commuting Experience, Unparalleled Status And Comfort. Often Compared, A...

DM Pre-Owned Pte Ltd

Posted: 05-Nov-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



**Porsche Cayenne Hybrid S 3.0A Tip**      **\$144,800**      \$30,990 /yr      04-Jul-2012      2,995 cc      72,027 km      SU

**Fuel Type:** Petrol-Electric

Cheapest & Best Condition With Full Service History At Porsche Agent! Preventive Maintenance Done, All Wear And Tear Parts Replaced Include Brand New Hybrid Batteries! Genuine Low Mileage! L100% Acc...

Posted: 05-Nov-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



**Porsche Cayenne 3.6A Tip**      **\$157,800**      \$30,860 /yr      24-Sep-2012      3,598 cc      88,926 km      SU

Fully Serviced At Stuttgart Auto, 1 Owner, Low Mileage, Elegant Sand Interior, Accident Free, Showroom Condition, Number Plate To Be Retain Viewing By Appointment Only!

Car Search

Posted: 03-Nov-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



**Porsche Cayenne GTS 4.8A Tip**      **\$201,000**      \$34,260 /yr      14-Dec-2012      4,806 cc      51,000 km      SU

Porsche Sports Exhaust System (Black), PCM With Navigation, PA SM. GTS Sound Symposer Enhanced Interior Sound. Cruise Control. Daytime Lights & Much More. Fully Serviced With New Brake Rot...

Posted: 28-Oct-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



### Save up to 25% on petrol

Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.

Find out more!



**Porsche Cayenne Turbo 4.8A Tip**      **\$188,800**      \$32,530 /yr      18-Jun-2012      4,806 cc      48,000 km      SU

Pristine Condition. Rare Model. Black Leather Interior. In House Financing Available. No Admin Charges, Contact Our Friendly Sales Staff For E Now!

Posted: 26-Oct-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche



**Porsche Cayenne Hybrid S 3.0A Tip**      **\$155,800**      \$33,610 /yr      10-Aug-2012      2,995 cc      109,000 km      SU

**Fuel Type:** Petrol-Electric

Full Service Records At Stuttgart Auto. Hybrid Drive System SUV Model With Spacious Cabin, Power Tailgate, Electric Seats And Excellent Fuel Efficiency For Daily Used. Buying With Peace Of Mind From Po...

Porsche Pre-Owned Centre

Posted: 22-Sep-2018      Tags: 2012 Porsche Cayenne, 2012 porsche cayenne, Porsche Cayenne, porsche cayenne, Porsche, Cayenne, cayenne, Used Porsche

Save this search criteria, to get email alerts whenever a match is found.

Make      Model      Price      Depreciation      Reg Date      Eng Cap      Mileage      Veh Ty

For old advertisements view Archived ads

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/11/2018 11:37
Date Of Accident	23/11/2018 11:25
Exact Location Of Accident	AYER RAJAH EXPRESSWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM9475E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG HOCK TEE(NOT DRIVING)
NRIC No	S1485776A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96364651
Alternative Phone No	OTHERS-96364651

### Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYENNE S 4.8 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V08412/VPS/R04
Cover Note Number	

### Driver

Name of Driver	LIM YAM GUAN
NRIC No	S0382889A
Date Of Birth	18/08/1947
Occupation	OUTDOOR
Date Of Driving Pass	13/06/1977
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96536876
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 56 TELOK BLANGAH HEIGHTS #11-163
Postcode	100056
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PERSONAL DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	RIVER VALLEY NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 4 DELTA AVENUE , POSTCODE: 161004 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2789999 - FAX NO: 62786427
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT NO.T/20181123/2066

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM6362E
Vehicle Make/Model/Colour	HYUNDAI ELANTRA AD 1.6 GLS AT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME: ;

GENDER: ;

Passenger 2

NAME: ;

GENDER: ;

#### DETAILS OF INJURED PERSON 1

Name

PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLM6362E

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Reporting Centre Personnel's Singapore  
Singapore 415933  
Name:  
Tel: 67416697 Fax: 6749230  
NRIC/PR NO.:  
Email: yackb@singnet.com.sg

SKETCH PLAN

AYE EXPRESSWAY AFTER ALEXANDRA EXIT



VEH A: 9KM9475E  
VEH B: 9LM6362E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT NO: T/20181123/2066

PASSENGER: MR ONG HOCK TEE  
MR LIM BENH HWEE

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(if Driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4  
Singapore 415933  
Name: *[Name]*  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181123/2066

Police Station Of Origin:  
River Valley NPP  
4 Delta Avenue #01-02 SINGAPORE 161004  
Tel No: 1800-2789999

1 of 3

Report No. T/20181123/2066

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/11/2018 13:14		Vide Report No.: D/20181123/0050		Station Diary No.: 23	
<b>Informant's Particulars</b>					
Name of Informant: LIM YAM GUAN			Address: APT BLK 56 TELOK BLANGAH HEIGHTS #11-163 SINGAPORE 100056		
ID Type / ID No.: NRIC NO / S0382889A			Contact No.: Home/Office: Mobile; 96536876		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 71	Date of Birth: 18/08/1947	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PERSONAL DRIVER			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/11/2018 11:25	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE Expressway after Alexandre Exit.				
Weather:		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKM9475E	Car				Seriously Damaged	2
SLM6362E	Car				Seriously Damaged	2

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181123/2066

Police Station Of Origin:  
River Valley NPP  
4 Delta Avenue #01-02 SINGAPORE 161004  
Tel No: 1800-2789999

2 of 3

Report No. T/20181123/2066

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	LIM YAM GUAN	ID No.	S0382889A
Related Vehicle	SKM9475E (Car)	Contact No.	96536876
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	MOHAMED AKKARAM S/O GHULAM MOHAMED	ID No.	S7145545I
Related Vehicle	SLM6362E (Car)	Contact No.	97895546
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 23/11/2018 at about 1125hrs, I was driving a car, SKM9475E along Ayer Rajah road towards MCE direction. When I was around Alexandra exit, a car in front of me suddenly stopped, as such I e-brake. Shortly after, I felt an impact coming from behind. I alighted from my vehicle and saw a car, SLM6362E collided onto the rear of my vehicle causing the exhaust pipe to drop and the rear body of my vehicle badly dented. Whereas the other party's vehicle front bumper was dislodged and badly dented as well.

My passenger, the other driver and I sustained no injury. However, the passengers from the other vehicle were conveyed by ambulance. Police attended to us vide D/20181123/0050. No government property or foreign vehicle involved.



**SINGAPORE  
POLICE FORCE**



T/20181123/2066

Police Station Of Origin:  
River Valley NPP  
4 Delta Avenue #01-02 SINGAPORE 161004  
Tel No: 1800-2789999

3 of 3


Report No. T/20181123/2066

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 3 HENGKY SETIAWAN HOO	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/11/2018 13:14
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIAN BIN MOHAMED JUNID Contact No.: 65476247	Classification Of Case:
Authentication Stamp NP168	SN-069



## MOTORCAR (Rear)

Vehicle No: SKM 9475E

## Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CRA		
1141	992958	Rear Bumper	DD		
1142	993085	Rear Bumper Top Guard	BT		
1143	993017	Rear Bumper Lower	DD		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	CRT		
1146	992341	Rear Bumper Clips	KEC		
1147	992976	Rear Bumper Bracket	Sub		
1148	993068	Rear Bumper Side Retainer	CRT		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam	DIS		
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CRT		
1157	993023	Rear Bumper Lower Spoiler	CRA		
1158	994023	Reverse Sensor	DM		
1159	993327	Rear End Panel	DD		
1160	993339	Rear End Panel Top Garnish	CRA		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BUC		
1182	991328	Tailgate Emblem	KEC		
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA		
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass Switch	SCR		
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	BT		
1198	994651	Tailgate Rubber	OD		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy	BT		
1211	990532	Centre Exhaust Mounting	DIS		
1212	993364	Rear Exhaust Pipe	DD		
1213	993357	Rear Exhaust Chrome Pipe	DD		
1214	993361	Rear Exhaust Mounting	DIS		
1215	993358	Rear Exhaust Heat Shield	BT		
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	Ben		
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	torn		
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Handwritten signature: *[Signature]*  
 Date: 12/12/2018  
 Tailgate lower chassis assembly



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Nov 2018 <a href="#">Edit Reg</a>		26 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>		<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	--	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

POPULAR RENT A CAR PTE LTD, Co. Reg. No.: 199608195Z

Main Claimant:

-

Vehicle Reg. No.:

SKM9475E

Date of Loss:

23/11/2018 00:00 - :59  
[76 Months and 20 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 8798115175SG

Policy/Cover Note No.:

(Comprehensive)

Vehicle Reg. No. (Insured):

SLM6362E

Policy No. (Claimant):

Excess:

Repairer:

Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building, 415875 Kaki Bukit - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/12/2018]

Claimant's Solicitor:

ALLISTER LIM & THRUMURGAN - Tel: 64222187

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG\_SG (27/11/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents


**\*SKM9475E (8798115175SG)  
[SLM6362E]  
TP**

**Nov 23 2018 12:00AM  
[POPULAR RENT A CAR PTE LTD]  
Autowerke Automotive Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
2	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
3	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
4	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
5	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
6	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
7	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
8	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
9	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
10	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
11	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
12	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
13	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
14	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
15	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
16	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
17	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
18	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
19	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
20	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
21	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
22	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
23	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
24	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
25	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
26	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
27	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
28	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
29	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
30	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
31	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
32	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
33	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
34	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
35	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
36	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	
37	10/01/19 09:13	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
61	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
62	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
63	10/01/19 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
64	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	10/01/19 09:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	10/01/19 09:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/11/18 11:15	OI GIA REPORT	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18021300/UCD3E2

Date: 10/01/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKM9475E

**Insured Vehicle No :** SLM6362E

Date of Loss: 23/11/2018

Nature of Claim: TP

Claim No: 8798115175SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM9475E**

Make &amp; Model: PORSCHE CAYENNE, 4.8 S Tiptronic (A)

Engine No: M4802C08779

Reg. Date: 03/07/2012 (Man. Year: 2012)

Chassis No: WP1ZZZ92ZCLA48107

Colour: Black

Odometer: 199570 km

Engine Capacity: 4806 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/55 R18

Rear Tyre Size:

255/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 26/11/2018

Date Inspected: 26/11/2018 Inspected At:

 Autowerke Automotive Pte Ltd (HQ)  
 8 Kaki Bukit Ave 4, #05-01/02, Premier  
 Building  
 Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER TOP GUARD	Bent	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
6	1		*REAR BUMPER RETAINER	Cracked	0.00 F	*- F
7	1		*REAR BUMPER BEAM	Distorted	0.00 F	*- F
8	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
9	1		*REAR BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
10	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
11	1		*REAR END PANEL	Repair	0.00 F	*- F
12	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
13	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
14	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
15	1		*TAILGATE	Buckled	0.00 F	*- F
16	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
17	2		*TAILGATE LAMP	Cracked	0.00 F	*- F
18	1		*TAILGATE SWITCH	Scratched	0.00 F	*- F
19	1		*TAILGATE LOCK	Bent	0.00 F	*- F
20	1		*TAILGATE RUBBER	Dented	0.00 F	*- F
21	1		*TAILGATE DAMPER	* Check	0.00 F	*- F
22	1		*CENTRE EXHAUST PIPE ASSY	Bent	0.00 F	*- F
23	1		*CENTRE EXHAUST MOUNTING	Distorted	0.00 F	*- F
24	1		*REAR EXHAUST PIPE	Dented	0.00 F	*- F
25	1		*REAR EXHAUST CHROME PIPE	Dented	0.00 F	*- F
26	1		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
27	1		*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*- F
28	1		*REAR LH FENDER INNER TRIM	Torn	0.00 F	*- F
29	1		*REAR RH FENDER INNER TRIM	Torn	0.00 F	*- F
30	1		*TAILGATE LOWER CHROME MOULDING	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >