

Surveyor:

m. Arrens

DOI:

ASSIGNMENT

21.11.18

Date / Time:

26.11.18

Registered in Meritmen:

26.11.18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMD 4777R

Claim No.:

Name of Insured:

GTH WOLFE YAM

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 19.11.18

Place of Accident:

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: ☒ YES / NO)

Insured Liability: %

Final ? Yes / No

Fbm 1958m



INSRS:

WSP:

Tel:

Liability:

RMKS:

60 fpa



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/12/18

Fbm 1958m X; SMD 4777R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 11.3.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: GS

Repair Cost:

US \$5,000

(4 days) Reduction:

41 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 04.04.19

Confirm with: IEE IEE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

9a

If NO or B 28, Ass. Lia:

Repair Cost:

\$5,000.00

OIO MAKE A RM TURN #120 MINOR ROAD

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5,000.00

(\$20 x 5 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TV

3) Survey fee:

+320

Total:

\$5,000.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 04.04.19

Confirm with: IEE IEE

Email ☒ Call ☐

Payee 1:

\$5,000.00

Name 1:

GTHA MORE TOWING PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

COPY SENT
12/11/18

(08/11/23) wel

ASS. REC. BY: MDV 145

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 1958Mat Workshop m/s enfc

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 3/2

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or NoCA / REV / REP. / 24 HRS L 7A 687Date: _____ Person Contacted: 10/8/2024

Vehicle: IN / OUT

Date / Time Action / Instruction

24054/12/18 confirmed up to 2000 with M270.ISS: +1801.20 411-1Veh No: FBM 1958M Yr Regn: 8.11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha F150 cc 114Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 12208 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 4D0670.667Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or affectedBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/90-12R: 110/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TimSun

Front _____ Rear _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A. 19/11/18 D.O.I. 26/11/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 10/5/2018

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

TOTAL

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4182J
Vehicle Details	
Vehicle No.:	FBM1958M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FINO 115 A
Primary Colour:	Brown
Manufacturing Year:	2008
Engine No.:	4D0670667
Chassis No.:	4D0670667
Maximum Power Output:	-
Open Market Value:	\$1,884.00
Original Registration Date:	11 Aug 2011
First Registration Date:	11 Aug 2011
Transfer Count:	3
Actual ARF Paid:	\$283.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,502.00
COE Rebate Amount:	\$687.00
Total Rebate Amount:	\$687.00

The information contained herein is correct as at 26 Nov 2018

OK

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Ong Eng Chuan

Accident Date : 19-Nov-18

Vehicle No : FBM 1958 M

Vehicle Model : Yamaha Fino

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ one 85.00
2	Fork inner tubes	\$ 2x 160.00
2	Fork outer tubes	\$ 2x 180.00
1	Fork under bracket	\$ 145.00
1	Front brake disc	\$ 115.00
1	Front rim shaft	\$ 38.00
1	Front rim	\$ 280.00
1	Headlamp	\$ 139.00
2	Front signals	\$ 140.00
1	Handle bar	\$ 138.00
1	Handle bar end	\$ 18.00
1	Brake lever (1 set)	\$ 68.00
1	Side mirror (1 set)	\$ 120.00
1	Front cowling	\$ 198.00
1	Front cowling inner panel	\$ 108.00
1	Centre inner cowling	\$ 79.00
1	Front lower cowling	\$ 80.00
1	Lower belly cowling	\$ 95.00
1	Front footstep panel	\$ 116.00
1	Passenger footrest (1 set)	\$ 98.00
1	Main stand	\$ 85.00
1	Side stand	\$ 70.00
1	Rear signal	\$ 65.00
1	Rear tailboard	\$ 138.00
		\$ 2,758.00
	Less 10%	\$ 275.80
		\$ 2,482.20

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Ong Eng Chuan

Accident Date : 19-Nov-18

Vehicle No : FBM 1958 M

Vehicle Model : Yamaha Fino

Estimated Repair Costs

c/f: \$ 2,482.20

Special Nett Items

1	Number plate (1 set)	\$	SCR	28.00	10
2	Fork oils	\$	11	30.00	2
2	Fork oil seals	\$	11	56.00	2
1	Steering cone (1 set)	\$	11	75.00	2
1	ERP IU	\$	11	175.00	2
		\$		364.00	

S/No.

Labour

1	To provide towing service.	\$		45.00	35
2	To check wiring and reset headlamp focusing.	\$	11	80.00	2
3	To provide labour.	\$		480.00	300
4	To repair body frame.	\$		350.00	780
		\$		955.00	

Grand Total

\$ 3,801.20

Dollars: Three Thousand Eight Hundred One And Twenty Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices - subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
E-Mail: erofia@singnet.com.sg
Co Registration No: 201202259N

Our Ref: EMT1411/18/lt/FBM1958M

WITHOUT PREJUDICE

Your reference: TO BE ADVISED

BY HAND TO LKK

04 December 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir

Re: **ACCIDENT INVOLVING SMD4777R AND FBM1958M ON 19 NOVEMBER 2018**

We are instructed by our client Ong Eng Chuan to claim damages against your insured SMD4777R in connection with a road traffic accident on 19 November 2018 at about 14.20hrs along Moulmein Road with our client's motorcycle registration number FBM1958M

As a result of the accident, our client's motor bike was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Final Repair Bill as per Surveyor's recommendation	S\$ 2,000.00
2.	Loss of Use (6 days X S\$20.00/day) Repair Day + PRI	S\$ 120.00
	Total to Claim	<u>S\$ 2,120.00</u>

Attached final repair bill for your early process of our claim

Kindly revert soonest

Thank you

Yours faithfully
Erofia Motor Trading Pte Ltd

Teo Hwa Heng



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 11 March 2019 12:27 PM
To: 'SOLUTIONCHECKLIST@GMAIL.COM'; 'GINNGOH@GMAIL.COM'
Subject: ACCIDENT INVOLVING SMD 4777R AND FBM 1958M ON 19/11/2018

Our Ref: CC4/AIG18021313/Uea3

11 MAR 2019

GOH GEOK YAN / EUGENE GOH CHEN HOWE

Dear Sir/Madam,

ACCIDENT INVOLVING SMD 4777R AND FBM 1958M ON 19/11/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, ong Eng Chuan ("the third party claimant")
of 158 Lorong 1 Teapayoh H09-1516 S 310158 (address),
owner of FBM 1958 m (vehicle no.) hereby authorize
Erofia Motor Trading pte ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. FBM 1958 m that was
damaged pursuant to the accident which occurred on 19-11-2018 (date) along
Moulmein Road (location)
involving vehicle no/s SMD 4777 R ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment furtherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/Insurers of the other vehicle/s is concerned.

Date this 20 day of 11 (month) 20 18 (year)

Provide always that this discharge of my
claim for damages relating to the damage to
my vehicle shall not prejudice or affect or
preclude me from making a further claim for
general and special damages for my personal
injuries sustained in the same accident.



[Signature]
Signed by "the third party claimant"

[Signature]
Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, EROFIA MOTOR TRADING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS2,000.00 (Repair Cost), SS100.00 (Loss of Use/Rental), SS - (Disbursement) for vehicle no. FBM 1958M that was damaged pursuant to the accident which occurred on 19/11/2018 (date) along MOULMEIN ROAD (location) involving vehicle no/s SMD 4777R.

This is pursuant to the inspection conducted on 26/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ONG ENG CHUAN ("the third party claimant") of vehicle no. FBM 1958M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBM 1958M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of 04 (month) 20 19 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

INVOICE

Number	Date	Page
FBE1958M	04-Dec-18	1

YOUR REF:
VEHICLE NO: FBM1958M
MAKE/MODEL: YAMAHA FINO
NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ACCIDENT INVOLVING SMD4777R AND FBM1958M ON 19 NOVEMBER 2018

FINAL REPAIR COST AS PER SURVEYOR'S RECOMMENDATION	S\$	2,000.00
LOSS OF USE (6 DAYS X \$20.00/DAY) REPAIR & PRI	S\$	120.00

SUB-TOTAL: S\$ 2,120.00

SINGAPORE DOLLARS: TWO THOUSAND ONE HUNDRED AND TWENTY ONLY

TOTAL : S\$ 2,120.00

EROFIA MOTOR TRADING PTE LTD



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2018 Edit Reg		26 Nov 2018 00:00 Edit Adj Rpt	\$2,000.00 Edit Estimates	\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	GOH GEOK YAN, ID: S1780524Z		
Main Claimant:	ONG ENG CHUAN, ID: S7184182J		
Vehicle Reg. No.:	FBM1958M	Date of Loss:	19/11/2018 00:00 - :59 [87 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3497951372SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SMD4777R	Policy No. (Claimant):	5102814803
		Excess:	
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/12/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (27/11/2018): Request To Upload TP GIA Report














































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBM1958M (3497951372SG)
[SMD4777R]
TP
ONG ENG CHUAN
Nov 19 2018 12:00AM
[GOH GEOK YAN]
Erofia Motor Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	
<hr/>				
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	26/11/18 18:33	Odometer Reading	1 Load JPG <input checked="" type="checkbox"/>	
2	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
3	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
4	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
5	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
6	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
7	26/11/18 18:33	General View	1 Load JPG <input checked="" type="checkbox"/>	
8	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
9	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
10	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
11	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
12	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
13	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
14	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
15	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
16	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
17	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
18	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
19	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
20	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
21	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
22	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
23	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
24	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
25	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
26	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
27	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
28	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
29	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
30	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
31	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
32	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
33	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	
34	26/11/18 18:34	General View	1 Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/11/18 18:35	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
76	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
77	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
78	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
79	26/11/18 18:36	General View	 Load JPG	<input checked="" type="checkbox"/>
80	26/11/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
81	26/11/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
82	26/11/18 18:36	General View	Load JPG	<input checked="" type="checkbox"/>
83	26/11/18 18:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	26/11/18 18:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/11/18 18:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/11/18 18:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/11/18 18:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	26/11/18 18:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	04/12/18 09:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	04/12/18 09:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	04/12/18 09:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	04/12/18 09:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/11/18 15:59	ACKNOWLEDGEMENT EMAIL TO AIG DD 26.11.2018	 Load PDF	
2	26/11/18 15:59	NOTIFICATION FROM LAWYER	 Load PDF	
3	26/11/18 15:59	EMAIL FROM AIG DD 26.11.2018	 Load PDF	
4	06/12/18 11:19	TP ESTIMATE - MARKED	 Load PDF	
5	06/12/18 11:19	TP GIA REPORT	 Load PDF	
6	26/04/19 11:33	WORKSHOP INVOICE	 Load PDF	
7	26/04/19 11:33	AUTHORISATION TO ACT FORM	 Load PDF	
8	26/04/19 11:33	Release Voucher	 Load PDF	
9	26/04/19 11:33	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/11/18 10:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD4777R (Insd veh)	Model:	YAMAHA FINO 114CC (A)
	FBM1958M (TP veh)		
Date of Accident:	19/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$			3,801.20
Final Repair Cost	: \$			2,000.00
Loss of Use	: \$			100.00
				5.00 days at \$20.00 per day
Rental (if any)	: \$			0.00
				days
LTA / GIA Search Fee	: \$			0.00
Others:	: \$			0.00
	: \$			
Final Settlement Sum	: \$			2,100.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Erofia Motor Trading Pte Ltd	: \$	2,100.00
2)		: \$	

JOANNE LEE KHANG MIN

26 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021313/UEA3Q2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBM1958M

Insured Vehicle No : SMD4777R

Date of Loss: 19/11/2018

Nature of Claim: TP

Claim No: 3497951372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM1958M

Make & Model: YAMAHA FINO, 114cc (A)

Engine No: 4D0670667

Reg. Date: 11/08/2011 (Man. Year: 2011)

Chassis No: 4D0670667

Colour: Blue

Odometer: 12208 km

Engine Capacity: 114 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-12

Rear Tyre Size:

110/70-12

Front Left Side: Timsun 6 mm

Rear Left Side:

Timsun 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,846.20	2,044.00	802.20	28.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	955.00	515.00	440.00	46.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,801.20	2,559.00	1,242.20	32.68
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	3,801.20	2,000.00	1,801.20	47.39
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		2,100.00		

INSPECTION

Date of Assignment: 26/11/2018

Date Inspected: 26/11/2018 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	85.00 FL	*85.00 FL
2	2		*FORK INNER TUBES	Bent / Twisted	160.00 FL	*160.00 FL
3	2		*FORK OUTER TUBES	Twisted	180.00 FL	*180.00 FL
4	1		*FORK UNDER BRACKET	Bent	145.00 FL	*145.00 FL
5	1		*FRONT BRAKE DISC	Bent	115.00 FL	*115.00 FL
6	1		*FRONT RIM SHAFT	Bent	38.00 FL	*38.00 FL
7	1		*FRONT RIM	Dented / Bent	280.00 FL	*280.00 FL
8	1		*HEADLAMP	Cracked	139.00 FL	*139.00 FL
9	2		*FRONT SIGNALS	Not Necessary	140.00 FL	*- FL
10	1		*HANDLE BAR	Bent	138.00 FL	*138.00 FL
11	1		*HANDLE BAR END	Scratched	18.00 FL	*18.00 FL
12	1		*SET BRAKE LEVER	Scratched	68.00 FL	*68.00 FL
13	1		*SET SIDE MIRROR	Dented	120.00 FL	*120.00 FL
14	1		*FRONT COWLING	Cut / Cracked	198.00 FL	*198.00 FL
15	1		*FRONT COWLING INNER PANEL	Cut	108.00 FL	*108.00 FL
16	1		*CENTRE INNER COWLING	Cracked	79.00 FL	*79.00 FL
17	1		*FRONT LOWER COWLING	Cut	80.00 FL	*80.00 FL
18	1		*LOWER BELLY COWLING	Cut	95.00 FL	*95.00 FL
19	1		*FRONT FOOTREST PANEL	Cut	116.00 FL	*116.00 FL
20	1		*SET PASSENGER FOOTREST	Cut	98.00 FL	*98.00 FL
21	1		*MAIN STAND	Repair	85.00 FL	*- FL
22	1		*SIDE STAND	Repair	70.00 FL	*- FL
23	1		*REAR SIGNAL	Not Necessary	65.00 FL	*- FL
24	1		*REAR TAILBOARD	Not Necessary	138.00 FL	*- FL
25	1		*SET NUMBER PLATE	Scratched	28.00 FS	*10.00 FS
26	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
27	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
28	1		*SET STEERING CONE	Not Necessary	75.00 FS	*- FS
29	1		*ERP IU	Not Necessary	175.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	3,122.00	2,270.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	275.80	226.00
Total Parts (\$\$)	2,846.20	2,044.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	45.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	300.00
4	TO REPAIR BODY FRAME	New	350.00	180.00
Gross Labour Cost (\$\$)			955.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >