

ASS. REC. BY:

REF:

CS/AWA18021317/Ktd3

Special Instruction:

Surveyor:

Kenneth

## ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

AWAC

Date/Time:

26/11/18 3:35pm

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 8971M

Insured:

SJW 5399C

at Workshop m/s

Falcon - Air Auto

Tel:

64520880

of

176 Sin Ming Drive # 01-06 / 07

Policy No:

AVHWSB0029201804

Claim No:

NSV1806634/HLF

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/2018

CA / REV / REP. / REV 24 HRS

(up)

28/11/18 morning

H.O.D. Endorsement:

Date/Time:

3:56pm 26/11/18

Person Contacted:

Falcon

Vehicle in

OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 8971M - X

SJW 5399C - X

11/1 8 2125.60 email (Red: 1718.88; 44%)

REF: AWAC

## ASSIGNMENT

From: Date: 28/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STQ 897IM  
at Workshop m/s: Falcon - Air Auto  
of 176 Sin Ming Drive #01-06/07

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lum Sum: 1.B.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 897IM / Regn: OF 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru A Forester Wagon C.C. 1995

Colour:

M.P. White A/C Insured / Std / NI / NA

Sp Reading:

37613 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF-1875K0514G-092009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

23/11/18

Rear

R/Bal.

7 mm

L/Bal.

7 mm

D.O.I.

28/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11 File ready

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

1) 16/1 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B. (\$ 2125.60)

TP

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

) \$ + RS, SI

) Photos

) Others

TOTAL

150

**Nivitha (LKK Auto)**

---

**From:** Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Monday, 26 November 2018 3:35 PM  
**To:** assignments  
**Cc:** SUR; Florence Loh; joshua@falconair.com.sg; francine.gail@falconair.com.sg  
**Subject:** TP Survey assignment for SLQ 8971M - DOA: 23/11/2018 Our ref: NSV1800634/HLF

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Kenneth Kong** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SLQ 8971 M
Insured Vehicle	:	SJW 5399 C
Policy Number	:	AVHWSB0029201804
Name of Workshop	:	Falcon-Air Auto Services Pte Ltd
Contact Number	:	6452 0880
Person to Contact	:	Florence Loh
Estimated Cost of repairs	:	\$ NA

Regards,  
Claims Division

Copy to Falcon-Air Auto Services Pte Ltd via Email

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group  
Global Market

---

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6643I
<b>Vehicle Details</b>	
Vehicle No.:	SLQ8971M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	FB20Y720934
Chassis No.:	JF1SJ5KC5HG092009
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,689.00
Original Registration Date:	26 Jul 2017
First Registration Date:	26 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$14,689.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2027
PARF Rebate Amount:	\$11,016.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$43,403.00
<b>Total Rebate Amount:</b>	<b>\$54,419.00</b>

The information contained herein is correct as at 26 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/11/2018 11:50
Date Of Accident	23/11/2018 18:55
Exact Location Of Accident	ALONG BKE TOWARDS SLE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ8971M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KOK CHENG (CHEN GUOQING)
NRIC No	S7226643I
Email Address	KEL72@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98336892
Alternative Phone No	OFFICE-98336892

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700039895
Cover Note Number	

### Driver

Name of Driver	TAN KOK CHENG (CHEN GUOQING)
NRIC No	S7226643I
Date Of Birth	06/08/1972
Occupation	INDOOR
Date Of Driving Pass	28/11/1995
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98336892
Fax Number	
Contact Number	OFFICE-98336892
EMail Address	KEL72@SINGNET.COM.SG

Address	BLK 507A WELLINGTON CIRCLE #04-162
Postcode	751507
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : LOH GEK HWANG , LISA (96933972)
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW5399C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FOO JONG CHANG
NRIC/Passport Number	S6913405Z
Contact Number	98181432
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SLU741S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE TIONG YEOW
NRIC/Passport Number	S7835690A
Contact Number	97323757
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along BKE towards SLE at the 1/2 km. front vehicle slow down and came to a stop and I followed. A few seconds later, I felt a bang from behind. I came out from my vehicle and realised it's a chain collision.

From my video clip, veh B had stop when veh C hit into into veh B and veh B hit into my stationary vehicle

Nobody was injured.

veh B: SJW 5399C, Foo Jong Chang, IC: S6913405Z  
N/P: 98181432

veh C: SLU 7413, Lee Tiong Siew, IC: S7835690A  
N/P: 97323757

veh A: SLA 8971M, N/P: 98336892, email: kel72@singnet.com.sg  
passenger in veh A: Loh Gek Hwang (female) (outdoor-occupation).

DOA: 23/11/2018, 18:53, along BKE towards SLE  
weather was clear (after rain) road surface wet.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*TAK SOLOMAN*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Signature, Stamp and Date



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 1995011400  
GST Reg. No.: 1995011400

FALCON-AIR

MR TAN KOK CHENG  
C/O 176 SIN MING DRIVE #01-06  
SIN MING AUTOCARE 575721Attention : Motor Claim Department  
Contact : 62540770 98336892*Not Authorized**Assembly B4 paint**2 days**82125.60*

Estimate : ES011729

Date : 28/11/2018  
Vehicle Num. : SLQ 8971M  
Make/Model : SUBARU FORESTER 2.0-L CVT AWD-2  
Chassis/Eng# : JF1SJ5KC5HG092009  
Accident Date : 23/11/2018  
Claim No. :  
Reference : TP - AIG AGT ALLIED (SM)  
Policy No. : 1700039895

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	TAILGATE LOGO		
2.	1 PC	TAILGATE EMBLEM (SUBARU)		
3.	1 PC	TAILGATE EMBLEM (FORESTER)		
4.	1 PC	TAILGATE EMBLEM (AWD)		
5.	1 PC	REAR BUMPER	690.30	
6.	10 PCS	REAR BUMPER CLIPS		
7.	2 PCS	REAR BUMPER SIDE RETAINER		
8.	1 PC	REAR BUMPER TOP GARNISH		
9.	1 PC	LH REAR BUMPER LOWER COVER		
10.	1 PC	REAR BUMPER REINFORCEMENT	380.30	
11.	1 PC	REAR BUMPER TOW COVER		

List Total S\$ :  
20.00% Discount S\$ :

108.30	X
92.40	X
95.70	X
92.40	X
800.30	X
5.00	X
36.30	X
480.90	X
45.40	X
520.80	X
34.30	X
2,393.10	
478.62	
1,914.48	

1.	1 SET	SPECIAL NETT ITEMS : REVERSE SENSOR
----	-------	--

Special Nett Total S\$ :

LABOUR :  
TO CHECK REAR WIRING

250.00	
250.00	
50.00	X

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
 Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110  
 Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D  
GST Reg. No.: 199501140D

FALCON - AIR

MR TAN KOK CHENG  
C/O 176 SIN MING DRIVE #01-06  
SIN MING AUTOCARE 575721

Attention : Motor Claim Department

Contact : 62540770 98336892

Estimate : ES011729

Date : 28/11/2018  
Vehicle Num. : SLQ 8971M  
Make/Model : SUBARU FORESTER 2.0I-L CVT AWD-2  
Chassis/Eng# : JF1SJ5KC5HG092009  
Accident Date : 23/11/2018  
Claim No. :  
Reference : TP - AIG AGT ALLIED (SM)  
Policy No. : 1700039895

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REFIT REVERSE SENSOR ONTO NEW BUMPER		50.00 ✓
		TO RUSTPROOF ACCIDENT DAMAGE AREA		120.00 X
		TO STRAIGHTEN TAILGATE, REAR END PANEL, REAR COMPARTMENT		
		PANEL AND REPLACEMENT OF PARTS		580.00 2501
		TO SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR END PANEL		
		AND REAR COMPARTMENT PANEL		880.00 2501
		Labour Total S\$ :		1,680.00

E. &amp; O.E.

Total S\$ : 3,844.48

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18021317/Ktd3n2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 16-01-2019



Code : AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 5399C	Veh. Inspected	SLQ 8971M
Policy No.	AVHWSB0029201804	Coverage (\$)	0.00
Claim No.	NSV1800634/HLF	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	26/11/2018

### 2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1SJ5KC5HG092009	Colour	METALLIC PEARL WHITE
Odometer	37613	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	7 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	7 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	7 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	23/11/2018	Inspection Date	28/11/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8971M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE LOGO	NOT NECESSARY	108.30	-
1	TAILGATE EMBLEM (SUBARU)	NOT NECESSARY	92.40	-
1	TAILGATE EMBLEM (FORESTOR)	NOT NECESSARY	95.70	-
1	TAILGATE EMBLEM (AWD)	NOT NECESSARY	92.40	-
1	REAR BUMPER	BENT	800.30	690.30
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER @\$36.30	DISTORTED	72.60	72.60
1	REAR BUMPER TOP GARNISH	DENTED / NECESSARY	480.90	480.90
1	LH REAR BUMPER LOWER COVER	DISTORTED	45.40	45.40
1	REAR BUMPER REINFORCEMENT	BENT	520.80	380.30
1	REAR BUMPER TOW COVER	SERVICEABLE	34.30	-
	LESS 20% DISCOUNT		-478.62	-343.90
			1,914.48	1,375.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR (SN)	DENTED	250.00	200.00
			250.00	200.00
<b><u>LABOUR</u></b>				
	TO CHECK REAR WIRING.	NOT NECESSARY	50.00	-
	TO REFIT REVERSE SENSOR ONTO NEW BUMPER.		50.00	50.00
	TO RUSTPROOF ACCIDENT DAMAGE AREA.	NOT NECESSARY	120.00	-
	TO STRAIGHTEN TAILGATE, REAR END PANEL, REAR COMPARTMENT PANEL AND REPLACEMENT OF PARTS.		580.00	250.00
	TO SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR END PANEL AND REAR COMPARTMENT PANEL.		880.00	250.00
			1,680.00	550.00
<b>GRAND TOTAL</b>			<b>3,844.48</b>	<b>2,125.60</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,125.60</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/AWA18021317/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.