

CC3/MSG18021399/Usd3n2

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLW12535at Workshop m/s Lp.

of \_\_\_\_\_

Insured: SLU130E

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS with

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time Action / Instruction 21/12/18Veh No: SLW12535 Yr Regn: 1.18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Kia ceato k3 C.C. 1591Colour: blue A/C: Insured / Std / NI / NASp. Reading: 7420 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAPJ 411 MJS 761770Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexen

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 21/12/18 D.O.I. 27/11/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop oro/s H. & o/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 21/12/1804/12/18 @ 11:35 a.m. revert pending estimate from repairer to Jowyn via merimer.17/12/18 confirmed H/S \$ 7700 with Alu.17/12/18 Confirmed H/S \$ 7,700/- @ 6 days with Marcus 17/12/2018  
( \$ 19,107.00 Red - 71% )

RECEIVED 17 DEC 2018

Date/Time, File Pass to?

17/12/181) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 7,700/- H/S)20010210

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 28 November 2018 3:31 PM  
**To:** elaine\_ngu@sg.msiga-asia.com; iryani\_amin@sg.msiga-asia.com  
**Cc:** KKLau; Accounts (LKKAuto); SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 27/11/2018, SLW 1253S (TP VEHICLE), SLU 130E (OI VEHICLE)  
**Attachments:** TP GIA REPORT.pdf

Dear Iryani/Elaine,

Please be informed that we had inspected the vehicle SLW 1253S at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 27/11/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Sent Message

This mail is associated with :

**\*SLW1253S (577289)  
[SLU130E]**

TP

SONGGARAM VIRABHAK @MOHD BASHIR S/O GANY  
Nov 27 2018 12:00PM  
[GWEE SIN SIEW]  
Fastech Auto Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 04/12/2018 11:35 AM.  
**To** Jowyn\_tay@sg.msg-asia.com  
**CC** sur@lkkauto.com  
**Subject** SLW1253S (577289) [SLU130E] TP

Dear Jowyn,

Please be informed that we have inspected the vehicle SLW 1253S on 27/11/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2012Z

**Vehicle Details**

Vehicle No.: SLW1253S

Vehicle to be Exported: No

Intended Deregistration Date: 27 Nov 2018

Vehicle Make: KIA

Vehicle Model: FORTE K3 1.6A

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: G4FGHH692073

Chassis No.: KNAFJ411MJ5761770

Maximum Power Output: 95.3 kW (127 bhp)

Open Market Value: \$11,476.00

Original Registration Date: 30 Jan 2018

First Registration Date: 30 Jan 2018

Transfer Count: 0

Actual ARF Paid: \$11,476.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jan 2028

PARF Rebate Amount: \$8,607.00

**Intended COE Rebate Details**

COE Expiry Date: 29 Jan 2028

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,791.00

COE Rebate Amount: \$42,916.00

**Total Rebate Amount: \$51,523.00**

The information contained herein is correct as at 27 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 27/11/2018 15:37  
 Date Of Accident 27/11/2018 11:45  
 Exact Location Of Accident CHARTWELL DRIVE  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW1253S

#### Insured/Policyholder

Name Of Registered Owner SONGGARAM VIRABHAK @MOHD BASHIR S/O GANY  
 NRIC No S0012012Z  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-96617615  
 Alternative Phone No OFFICE-96617615

#### Vehicle Particulars

Manufacturer KIA  
 Model FORTE K3 1.6A  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 5097631667 CLASSIC  
 Cover Note Number

#### Driver

Name of Driver SONGGARAM VIRABHAK @MOHD BASHIR S/O GANY  
 NRIC No S0012012Z  
 Date Of Birth 27/12/1941  
 Occupation INDOOR  
 Date Of Driving Pass 20/04/1964  
 Driving Experience 54 YEARS AND 7 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-96617615  
 Fax Number  
 Contact Number OFFICE-96617615  
 EMail Address NOEMAIL

Address	74 KENSINGTON PARK ROAD
Postcode	557308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU130E
Vehicle Make/Model/Colour	HONDA VEZEL 1.5X SENSING CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF4313R
Vehicle Make/Model/Colour	TOYOTA DYNA 150 MANUAL

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

SONGGARAM VIRABHAK @MOHD BASHIR S/O GANY

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLW1253S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


27 NOV 2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IOAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492303  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time, I was driving my vehicle A from Serangam Garden circle, when I reach along chartwell Drive. Suddenly vehicle B rush out from the carpark and hit on my RH side portion, vehicle B also hit on vehicle C that was stationery

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

27 NOV 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492301

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date of Accident : 27/11/18 Accident Time: 11.45am (24-HR-Format)  
Accident Place : at chartwell Drive  
Vehicle. No. (Car Plate No.) : SLW 12535 Make/Model: \_\_\_\_\_  
Insurance Company : MSIG Policy No: \_\_\_\_\_  
Owner or Company Name /IC No. : \_\_\_\_\_  
Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp 96617615 Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : \_\_\_\_\_  
DRIVER'S Date Of Birth : \_\_\_\_\_ DRIVER'S License Pass Date \_\_\_\_\_  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
DRIVER'S Address : \_\_\_\_\_  
DRIVER'S Contact No./ Alt No. : (1) \_\_\_\_\_ 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address : \_\_\_\_\_  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 1 Driver  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle. No: <u>SLW 130E (motor)</u>	Vehicle. No: <u>GB F4313R</u>
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-46/48/50  
SINGAPORE 417883

Not Authorized  
27/11/18  
L/S \$7700  
Take photo After repair  
6dy.

VEHICLE NO: SLW 1253S

QTY	PARTICULAR	Ref/Buc	\$1,415.00
1 PCS	BONNET 1224	17	\$180.00 X
2 PCS	BONNET HINGES @\$90.00	17	\$199.00 X
1 PCS	BONNET LOCK	Dis	\$801.00
1 PCS	FRONT BUMPER 639	Ref	\$495.00
1 PCS	FRONT BUMPER REINFORCEMENT 496	Toin	\$266.00
1 PCS	FRONT BUMPER SPONGE 185	o/scre	\$100.00 loc
2 PCS	FRONT BUMPER SIDE RETAINERS @\$50.00	ner	\$42.00
1 SET	FRONT BUMPER CLIPS	SCA	\$82.00
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	SCA/TWI	\$166.00
1 PCS	FRONT BUMPER CENTRE GRILLE	TWI	\$25.00
1 PCS	FRONT BUMPER CORNER SIDE GRILLE O/S	17	\$30.00 X
1 PCS	FRONT BUMPER BRACKET O/S	grezed	\$405.00
1 PCS	FRONT GRILLE 366	o/scre	\$488.00
1 PCS	FRONT GRILLE TOP GARNISH 301	ner	\$60.00
1 PCS	FRONT GRILLE TOP GARNISH LOGO	cm	\$2,400.00
1 PCS	HEADLAMP O/S 1039	17	\$2,400.00 X
1 PCS	HEADLAMP N/S	cm	\$899.00
1 PCS	FRONT SUPPORT PANEL 675	SLW	\$268.00
1 PCS	WIPER WASHER TANK 201	BUC	\$655.00
1 PCS	FRONT FENDER O/S 344	Toin	\$205.00
1 PCS	FRONT FENDER INNER SHIELD O/S 166.00	ner	\$30.00
1 SET	FRONT FENDER INNER SHIELD CLIPS O/S	cm	\$85.00
1 PCS	FRONT FENDER SIGNAL LAMP O/S	17	\$1,100.00 X
1 PCS	FRONT DOOR O/S	17	\$1,090.00 X
1 PCS	REAR DOOR O/S	17	\$971.00 X
1 PCS	REAR FENDER O/S	ner	\$45.00
1 PCS	REAR FENDER LOWER STICKER O/S	Repa/cm	\$805.00
1 PCS	REAR BUMPER 701	ner	\$39.00
1 SET	REAR BUMPER CLIPS	17	\$45.00 X
1 PCS	REAR BUMPER SIDE RETAINER O/S	17	\$680.00 X
1 PCS	TAILLAMP O/S	cm	\$1,600.00
1 PCS	FRONT SPORT RIM O/S 3505.~	17	\$399.00 X
1 PCS	FRONT SHOCK ABSORBER O/S	17	\$321.00 X
1 PCS	FRONT LOWER ARM O/S	17	\$305.00 X
1 PCS	FRONT KNUCKLE ARM O/S	17	\$150.00 X
1 PCS	FRONT KNUCKLE ARM BEARING O/S	17	\$911.00 X
1 PCS	FRONT DRIVE SHAFT O/S	cm	\$1,600.00
1 PCS	REAR SPORT RIM O/S 3505.~		\$21,757.00

107



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18021399/USD3N2

Date: 20/12/2018

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29051188QMX
Claimant Vehicle No :	SLW1253S	Insured Vehicle No :	SLU130E
Date of Loss:	27/11/2018	Nature of Claim:	TP
		Claim No:	577289

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLW1253S	Engine No:	G4FGHH692073
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFJ411MJ5761770
Reg. Date:	30/01/2018 (Man. Year: 2017)	Odometer:	7420 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,757.00	6,964.00	14,793.00	67.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	2,680.00	2,370.00	46.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>26,807.00</b>	<b>9,644.00</b>	<b>17,163.00</b>	<b>64.02</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,700.00</b>		
<b>(\$\$)</b>	26,807.00	7,700.00	19,107.00	71.28
<b>+ GST 7.00/7.00% (\$\$)</b>	1,876.49	539.00	1,337.49	71.28
<b>Nett Amount (\$\$)</b>	<b>28,683.49</b>	<b>8,239.00</b>	<b>20,444.49</b>	<b>71.28</b>

**INSPECTION**

Date of Assignment:	03/12/2018	
Date Inspected:	27/11/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2018)
<b>Parts:</b> 143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLW1253S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent/Buckled	1,415.00 F	*1,224.00 FL
2	2	*BONNET HINGES	Not Necessary	180.00 F	*- FL
3	1	*BONNET LOCK	Not Necessary	199.00 F	*- FL
4	1	*FRONT BUMPER	Distorted	801.00 F	*639.00 FL
5	1	*FRONT BUMPER REINFORCEMENT	Bent	495.00 F	*495.00 FL
6	1	*FRONT BUMPER SPONGE	Torn	266.00 F	*185.00 FL
7	1	*FRONT BUMPER SIDE RETAINERS	O/s Cracked	100.00 F	*50.00 FL
8	1	*SET FRONT BUMPER CLIPS	Necessary	42.00 F	*42.00 FL
9	1	*FRONT BUMPER FOG LAMP COVER O/S	Scratched	82.00 F	*82.00 FL
10	1	*FRONT BUMPER CENTRE GRILLE	Scratched/Twisted	166.00 F	*166.00 FL
11	1	*FRONT BUMPER CORNER SIDE GRILLE O/S	Twisted	25.00 F	*25.00 FL
12	1	*FRONT BUMPER BRACKET O/S	Not Necessary	30.00 F	*- FL
13	1	*FRONT GRILLE	Grazed	405.00 F	*366.00 FL
14	1	*FRONT GRILLE TOP GARNISH	Dented/Deformed	488.00 F	*301.00 FL
15	1	*FRONT GRILLE TOP GARNISH LOGO	Necessary	60.00 F	*60.00 FL
16	1	*HEADLAMP O/S	Cracked	2,400.00 F	*1,039.00 FL
17	1	*HEADLAMP N/S	Not Necessary	2,400.00 F	*- FL
18	1	*FRONT SUPPORT PANEL	Cracked	899.00 F	*675.00 FL
19	1	*WIPER WASHER TANK	Broken	268.00 F	*201.00 FL
20	1	*FRONT FENDER O/S	Buckled	655.00 F	*344.00 FL
21	1	*FRONT FENDER INNER SHIELD O/S	Torn	205.00 F	*166.00 FL
22	1	*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	30.00 F	*30.00 FL
23	1	*FRONT FENDER SIGNAL LAMP O/S	Cracked	85.00 F	*85.00 FL
24	1	*FRONT DOOR O/S	Repair	1,100.00 F	*- FL
25	1	*REAR DOOR O/S	Repair	1,090.00 F	*- FL
26	1	*REAR FENDER O/S	Repair	971.00 F	*- FL
27	1	*REAR FENDER LOWER STICKER O/S	Necessary	45.00 F	*45.00 FL
28	1	*REAR BUMPER	Deep Cut	805.00 F	*701.00 FL
29	1	*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
30	1	*REAR BUMPER SIDE RETAINER O/S	Not Necessary	45.00 F	*- FL
31	1	*TAILLAMP O/S	Not Necessary	680.00 F	*- FL
32	1	*FRONT SHOCK ABSORBER O/S	Not Necessary	399.00 F	*- FL
33	1	*FRONT LOWER ARM O/S	Not Necessary	321.00 F	*- FL
34	1	*FRONT KNUCKLE ARM O/S	Not Necessary	305.00 F	*- FL
35	1	*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	150.00 F	*- FL
36	1	*FRONT DRIVE SHAFT O/S	Not Necessary	911.00 F	*- FL
37	1	*FRONT SPORT RIM O/S	Cut	1,600.00 FS	*350.00 FS
38	1	*REAR SPORT RIM O/S	Cut	1,600.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,757.00</b>	<b>7,660.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>696.00</b>
<b>Total Parts (\$\$)</b>	<b>21,757.00</b>	<b>6,964.00</b>

Report was unsubmitted during this print-out.





## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	-
3	TO TRANSFER BOTH DOOR MECHANISM	New	150.00	-
4	TO SPRAY RUST PROOFING	New	120.00	80.00
5	TO REFILL AIR CON GAS	New	120.00	100.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
7	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	180.00	-
8	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,000.00	850.00
10	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,500.00
Gross Labour Cost (S\$)			5,050.00	2,680.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;