

ASS. REC. BY:

REF:

CS/SM018021407/71sd3ⁿ²

Special Instruction:

Surveyor:
menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Chan shu hui agnes

of

SMO

Date/Time:

27/11/18 @ 3:51pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 6433D

Insured:

SLT 5144M

at Workshop m/s

8MP7

Tel:

6866 2672

of

60 Woodlands Ind. Park E4

Policy No:

DI8M7pv01017247

Claim No:

CMTD1805192

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/11/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

4:34pm @ 27/11/18

Person Contacted:

Shanti

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 6433D-X

SLT 5144M-CS/SM018021402/d3

D.O.A: 25/11/18

30/11/18

revised IA to Chan shu hui Agnes via menmen.

Signature: Taylor

REF: Sampo S

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured _____ Excess: _____
(Client's Record)
Make of Veh: _____

X	
N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SHD6433D Yr Regn: 2017 Nov
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Prius c.c. 1798
Colour: Maroon A/C Insured / Std / NI / NA
Sp. Reading: — T/Radio: Insured / Std / NI / NA
Eng/No: _____
Ch No: STOK B3F4 203573401
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 175/65R15
R: 175/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 27/11/18
Survey held at SMKT
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Bulky mech TAX 11/18/2018
07/12/18 Confirmed P/P \$ 4,592.27 @ 3 days with Tautch SLT 5144m.
(\$ 4,760.23 Red - 51%)

RECEIVED 07 DEC 2018

Date/Time, File Pass to? 07/12/18 Typist
1) ☐ : Preli. Report
☒ : Final Report
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip: 1

Survey Fee
Transportation
S + RC (\$)
Photos
Others

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format :
Lump Sum / I.B.F. (\$ 4,592.27 P/P

350
10
360

TOTAL

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 30 Nov 2018

Preliminary Advice

Insured Vehicle No	: SLT5144M	Accident Date	: 25/11/2018
TP Vehicle No	: SHD6433D	Assignment Date	: 27/11/2018
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 3 days
Date of Inspection	: 27/11/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,352.50
Revised Amount	:S\$	4,592.23
Check Items (Estimated)	:S\$	872.18
Total	:S\$	5,464.41

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018		27 Nov 2018 15:51 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	PARANJOTHY MICHAEL ALFONS, ID: S1334825A		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHD6433D	Date of Loss:	25/11/2018 12:00 - :59
Claim Type:	TP / CMTD1805192	Policy/Cover Note No.:	D18MTPV01017247 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT5144M	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2018]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 27 November 2018 3:47 PM
To: Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Subject: CMTD1805192/AGC - SUV(LKK)/ SLT5144M & SHD6433D & OTHER ACC ON 25.11.18

Without Prejudice

Our Claim Reference: CMTD1805192/AGC
Your Reference: SHD6433D

Hi Alex,

We acknowledged receipt of your claim documents.

Please be informed that Ms. Agnes Chan is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SHD6433D on a without Prejudice and any admission of liability basis.

Please submit with your report via merimen upon completion of survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:weisiong@smrt.com.sg]

Sent: Tuesday, November 27, 2018 1:52 PM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

Subject: SHD6433D - Sompo Insurance (PRI)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHD6433D** within 48 hours according to GIA guide line, involving your insured **SLT5144M**

Vehicle in Woodlands Depot

Regards,

Alex Lim Wei Siong

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2682 | weisiong@smrt.com.sg

www.smrt.com.sg



Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 27 November 2018 4:32 PM
To: SUR; assignments
Subject: RE: FBM2133U v GBE2874G (GA) on 12 Feb 2018 || GAIC ref: CLMOMVC000002849

REMINDER

From: Ng, Sharon
Sent: Thursday, November 01, 2018 6:48 PM
To: 'SUR' <sur@lkkauto.com>
Subject: RE: FBM2133U v GBE2874G (GA) on 12 Feb 2018 || GAIC ref: CLMOMVC000002849

Dear Sir

Please update status of the PRI.

Regards
Sharon
Great American

From: Tan, Rachel
Sent: Thursday, February 22, 2018 9:53 AM
To: 'Daniel Poon & Co.' <law@dpco.com.sg>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: FBM2133U v GBE2874G (GA) on 12 Feb 2018

Without Prejudice

Dear Sir

Contents of your email on 22 Feb 2018 noted.
We will arrange for LKK to conduct pre-repair inspection on a without prejudice basis. Thank you.

Dear LKK
Please accept assignment to conduct PRI request. Attached documents for reference.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Daniel Poon & Co. [mailto:law@dpco.com.sg]
Sent: Thursday, February 22, 2018 9:39 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: RE: FBM2133U v GBE2874G (GA) on 12 Feb 2018

Dear Sir/s,

We refer to your E-mail dated 21 February 2018.

We will not be appointing any of your appointed surveyor as a single joint expert.

Kindly note that in the event that you are not agreeable to our list of appointed surveyor attached with our fax dated 21 February 2018, kindly contact the workshop to arrange a pre-repair inspection.

Yours faithfully,

Daniel C. K. Poon
Advocate & Solicitor

DANIEL POON & CO.

Advocates & Solicitors
Commissioners for Oaths
Notary Public

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227 2469
Fax: +65 6225 2579
E-mail: law@dpc.com.sg

Note: We do not accept service of Court documents via email

This email is confidential. If you are not the intended recipient, please inform us and then delete it from your system; you should not copy, disclose, or distribute its contents to anyone nor act in reliance on this email, as this is prohibited and may be unlawful.

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Wednesday, 21 February, 2018 5:36 PM
To: Daniel Poon & Co. <law@dpc.com.sg>
Subject: FBM2133U v GBE2874G (GA) on 12 Feb 2018

Without Prejudice

Dear Sir

We refer to your Pre-repair inspection letter dated 21 Feb 2018.

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



avast

This email has been checked for viruses by Avast antivirus software.
www.avast.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 December 2018 11:13 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))'
Cc: SUR; CS A Team; Taufikh (LKKAuto)
Subject: RE: SHD6433D

Hi Poh Suan,

Confirmed final fig of \$4,592.27 (part by part) @ 3 days of repairs.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Thursday, 6 December 2018 3:14 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHD6433D

Hi Taufikh,

Attached herewith the repair estimate of SHD 6433D having Case No:
TAX/11/18/2118.

There is no change to the approved amount of \$4,592.27 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Thursday, 6 December 2018 3:11 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2018 09:06
Date Of Accident	25/11/2018 12:00
Exact Location Of Accident	MARYMOUNT LANE JUNCTION UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6433D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	CHIA TIONG GUAN
NRIC No	S1550195B
Date Of Birth	28/06/1962
Occupation	OUTDOOR
Date Of Driving Pass	23/10/1980
Driving Experience	38 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 19
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ALJUNIED NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 13 JOO SENG ROAD , POSTCODE: 360013 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2809999 - FAX NO: 62815960
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20181125/2054 On 25/11/2018 at about 1200hrs, I was driving my taxi (SHD6433D) along Marymount Lane on the second lane from the left. I was ferrying an adult female and a young girl at that point in time. When I reached the x-junction, I was making a left turn into Upper Thomson Road towards Lornie Road when a vehicle (SLT5144M) suddenly came out from nowhere from the opposite direction. SLT5144M collided into a vehicle that was in front of me before colliding into the front left side of my vehicle. Upon collision, my passengers and I got out of my vehicle. We made a check and did not have any visible injuries on us. A few passer-bys also stopped to render assistance. Upon checking on SLT5144M, we discovered that the driver was unconscious. Ambulance arrived shortly after and the paramedics made a check on the driver of SLT5144M. I called the police as advised by the paramedics. The driver of SLT5144M was conveyed unconscious prior to police arrival. When the police arrived, they interviewed me on what happened. After which they provided me with the incident number E/20181125/0129. He also seized the SD card of my in-car camera. After taking pictures of the vehicles, the police officer informed me to contact my own company to tow back the vehicle. The vehicle SLT5144M was towed away by the police. I exchanged contact details with my passenger before they left the scene.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT5144M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJF6983Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	UNKNOWN DRIVER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLT5144M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/2018/125/2054



I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26/11/2018



**SINGAPORE
POLICE FORCE**



T/20181125/2054

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-69 SINGAPORE
360013
Tel No: 1800-2809999

1 of 3

Report No. T/20181125/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/11/2018 16:24		Vide Report No.:		Station Diary No.: 26
Informant's Particulars				
Name of Informant: CHIA TIONG GUAN		Address: APT BLK 19 JOO SENG ROAD #10-122 SINGAPORE 360019		
ID Type / ID No.: NRIC NO / S1550195B		Contact No.: Home/Office: Mobile: 97877082		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 56	Date of Birth: 28/06/1962	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/11/2018 12:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 MARYMOUNT LANE UPPER THOMSON ROAD Junction of Marymount Lane and Upper Thomson Road				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD6433D	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Maroon		2
SLT5144M	Car	SUBARU	FORESTER 2.0I-L CVT AWD SR	Brown		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181125/2054

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-69 SINGAPORE
360013
Tel No: 1800-2809999

2 of 3

Report No. T/20181125/2054

CONTINUATION OF REPORT

Driver			
Name	CHIA TIONG GUAN	ID No.	S1550195B
Related Vehicle	SHD6433D (Car)	Contact No.	97877082
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Peining Ng	ID No.	NIL
Related Vehicle	SHD6433D (Car)	Contact No.	96541868
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/11/2018 at about 1200hrs, I was driving my taxi (SHD6433D) along Marymount lane on the second lane from the right. I was ferrying an adult female and a young girl at that point in time. When I reached the X-Junction, I was making a left turn into Upper Thomson Road towards Lornie Road when a vehicle (SLT5144M) suddenly came out from nowhere from the opposite direction. SLT5144M collided into a vehicle that was in front of me before colliding into the front left side of my vehicle

Upon collision, my passengers and I got out of my vehicle. We made a check and did not have any visible injuries on us. A few passer-bys also stopped to render assistance. Upon checking on SLT5144M, we discovered that the driver was unconscious. Ambulance arrived shortly after and the paramedics made a check on the driver of SLT5144M. I called the police as advised by the paramedics. The driver of SLT5144M was conveyed unconscious prior to police arrival.

When the police arrived, they interviewed me on what happened. After which they provided me with the incident number E/20181125/0129. He also seized the SD card of my in-car camera. After taking pictures of the vehicles, the police officer informed me to contact my own company to tow back the vehicle. The vehicle SLT5144M was towed away by the police. I exchanged contact details with my passenger before they left the scene.



**SINGAPORE
POLICE FORCE**



T/20181125/2054

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-69 SINGAPORE
360013
Tel No: 1800-2809999

3 of 3

Report No. T/20181125/2054

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 TAN YILONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/11/2018 16:24
Officer In Charge Of Case: TP / GIT / Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN Contact No.: 65476185	Classification Of Case:
Authentication Stamp NP168	 SIGNATURE



Case Details

Case Reference Number : TAX/11/18/2118
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6433D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4710-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompoo Insurance Singapore Pte. Ltd
 Accident Date and Time : 25/11/2018 04:00 AM
 Vehicle Age(In Months) : 12

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0 <i>Rp</i>	Repair
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67 <i>nu</i>	Replace
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0 <i>nu x</i>	Not Give
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0 <i>nu x</i>	Not Give
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63 <i>de</i>	Replace
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0 <i>xm</i>	Not Give
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72 <i>nu</i>	Replace
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	1	21.08 <i>de</i>	Replace

Total Spare Part Cost 6,755.50

Surveyor Total 3,756.23

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,755.50

Final Sur Total 3,756.23

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0 <i>un</i>	Check
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	1	52.72 <i>de</i>	Replace
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0 <i>un</i>	Check
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	1	87.22 <i>un</i>	Replace
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0 <i>un</i>	Check
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0 <i>un</i>	Check
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01 <i>un</i>	Replace
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	1	819.18 <i>un</i>	Replace
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0 <i>un</i>	Not Give
Total Spare Part Cost									6,755.50		Surveyor Total	3,756.23	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									6,755.50		Final Sur Total	3,756.23	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	845.00	300	
Total:		845.00	300.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		1,116.00	400.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT FENDER LH	378.00	200	
2	TO RESPRAY RIM	180.00	0	
3	TO REPSRAY FRONT BUMPER	378.00	200	
4	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
Total:		1,116.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	56.00	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
6	TO WASH AND VACUUM	60.00	0	
7	TO REPLACE SUNDRY PARTS	100.00	20	
Total:		636.00	136.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,755.50	3,756.23
Total Labour Cost	845.00	300.00
Total Spray Painting	1,116.00	400.00
Other	636.00	136.00
Overall Total	9,352.50	4,592.23
Lump Sum Repair Option		
Lump Sum Total	0.00	4,592.23

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Approved Amount

4,592.23

No of Repair Days*

5

3

Remarks

Resurvey before paint

Surveyor Name

Taufikh

Signature



Save

Clear

Survey Date

27/11/2018


30/11/18

Taufikh 27475429

27/11/18

Resurvey before paint
03 days**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHD6433D
Case Reference Number	TAX/11/18/2118
Registration Date	01/11/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHIA TIONG GUAN
Type of Accident	Head On
Accident Date and Time	25/11/18 12:00 PM
Accident Reported Date and Time	26/11/18 9:14 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	25/11/18 12:49 PM
Replacement Vehicle issued?	No
Job Card Number	24098927
Special Instruction to ARC, if any	TOWED \$40 / SOMPO
Prepared Date and Time	27/11/18 11:20 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	


Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$645.00	\$300.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$6,755.50	\$3,756.27
Total Other Cost	\$636.00	\$136.00
TOTAL COST	\$9,352.50	\$4,592.27 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Zhi Yang Phua	Taufikh (LKK) / Sompo
ARC / Surveyor Sign Off Date	27/11/2018 11:44 AM	27/11/2018 5:20 PM
Signature		
Remarks		Resurvey before paint



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757706	
Fax Number: 63885562	
Estimator Telephone Number: 69462623	
Accident Reporting Number: 68602072	

Date Generated : 06/12/2018

User ID : 1 PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0104	Invoice Number	
Quotation Date	06.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
Total Other Costs	\$636.00	\$136.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given
		42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace
		52128479 06	COVER, FR BUMPER LH	1.00	\$26.10	25.00	\$21.08	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check

	52102470 20	EXTENSION SUB-ASSY, RH	1.00	\$116.30	✓	25.00	\$87.23	Replace	Replace	✓
	52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	✓	0.00	\$0.00	Replace	Check	✗
	52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	✓	0.00	\$0.00	Replace	Check	✗
	81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	✓	10.00	\$2,303.01	Replace	Replace	✓
	81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	✓	10.00	\$819.18	Replace	Replace	✓
	53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	✓	0.00	\$0.00	Replace	Not Given	✗
Total				\$8,313.50			\$3,756.27			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 3756.27 \\
 + 300.00 \\
 + 536.00 \\
 \hline
 4592.27
 \end{array}$$

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18021407/T1SD3N2

Date: 13/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017247
Claimant Vehicle No :	SHD6433D	Insured Vehicle No :	SLT5144M
Date of Loss:	25/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805192

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6433D	Engine No:	2ZRS100566
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU203573401
Reg. Date:	01/11/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,313.50	3,756.27	4,557.23	54.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,597.00	836.00	1,761.00	67.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,910.50	4,592.27	6,318.23	57.91

INSPECTION

Date of Assignment:	27/11/2018	
Date Inspected:	27/11/2018 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6433D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM SIDE PANEL (HYBRID)(DISC 25%)	Necessary	52.90 F	*39.68 F
2	1		*COVER,FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F
3	1		*SUPPORT,FR BUMPER LH (DISC 25%)	Necessary	82.30 F	*61.73 F
4	1		*COVER,FR BUMPER LH (DISC 25%)	Deformed	28.10 F	*21.08 F
5	1		*ABSORBER,FR BUMPER (DISC 25%)	Deformed	70.30 F	*52.73 F
6	1		*EXTENSION SUB-ASSY,RH (DISC 25%)	Necessary	116.30 F	*87.23 F
7	1		*UNIT,HEADLAMP,LH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
8	1		*LAMP ASSY,FOG,LH (DISC 10%)	Cracked	910.20 F	*819.18 F
9	1		*LINER,FR FENDER,LH	Not Necessary	194.30 F	*- F
10	1		*WHEEL,DISC	Not Necessary	1,555.10 F	*- F
11	1		*SUPPORT,FR BUMPER RH	Not Necessary	76.90 F	*- F
12	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
13	1		*EXTENSION SUB-ASSY,LH	Not Necessary	116.30 F	*- F
14	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
15	1		*ABSORBER FR BUMPER LOWER	Not Necessary	117.00 F	*- F
16	1		*SUPPORT,RADIATOR UPPER LH	Not Necessary	76.70 F	*- F
17	1		*FENDER SUB-ASSY,FR,LH	Repair	933.10 F	*- F
					Total Parts (S\$)	8,313.50 3,756.27

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORKS	New	845.00	300.00
2	SPRAY PAINT	New	1,116.00	400.00
3	TOWING CHARGE	New	56.00	56.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	-
7	TO DO WHEEL ALIGNMENT/TYRE BALANCING	New	120.00	-
8	TO WASH AND VACUUM	New	60.00	-
9	TO REPLACE SUNDRY PARTS	New	100.00	20.00
Gross Labour Cost (S\$)			2,597.00	836.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >