

INS. CASE OWNER:

Sinhua

CC 4, ALG 180 21410, Uea34

Surveyor:

MARCUS

DOI:

ASSIGNMENT

27/11/2018

Date / Time:

27/11/18

Registered in Merimen:

27/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 4360R

Name of Insured:

Joy Hong Lan Amy

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :SS

D.O.A: 19-11-18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO )

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLQ 6028 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Precise Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

MAR 01.03.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: OK

Repair Cost:

SS 3,600

( 7

days) Reduction:

41

%

Email

Call

FINAL SETTLEMENT

Date/Time: 05.04.19

Confirm with: YPH HONG

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

26

If NO or B 28, Ass. Lia:

Repair Cost:

WSP: SS 3,700

QMS OPEN CODE 111 77

Loss of Rental (LOR):

SS 600.00

( 6

days) x 100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 23.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9330

Total:

SS 3,405.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 05.04.19

Confirm with: YPH HONG

Email

Call

Payee 1:

SS 3,405.00

Name 1:

PRECISE AUTO SERVICE

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF

REF: CS/AIG1802410/4vd3

Special Instructions

Surveyor

Meinungen

From (Person):

ASSIGNMENT (Office)

4

AIG

Date/Time

Date/Time: 27/11/18 @ 9:35am

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SLQ 6028A

Insured:

91x 4360R

at Workshop m/s

precise Auto

Tel:

67457367

of

1 kaki Bkt AveG #02-34

Policy No.

Claim No.

Sum Insured:

### Excess

Make of Veh:

(Client's Record)

D.O.A. 19/11/18

CA / REV / REP. / REV 24 HRS

(up?)

H.O.D. Endorsement

Date/Time: 10:13am @ 27/11/18

Person Contacted:

Avingue

Vehicle ~~IN~~OUT

Date/Time

Action/Instruction (✓) Estimate
---------------------------------

Estimate

SL06024A-X

SLX-4360D-X

(08/11/13) • web

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐To Inspect Vehicle No: SLQ 6028Aat Workshop m/s precise

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 46752

Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLQ 6028A Yr Regn: 7.17Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or CAIMake: Mercedes Shuttle H/V No: 1496Colour: Blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 30263 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: GP7115248Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 185/60215

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mmL/Bal: 7 mmD.O.A. 19/11/18

Survey held at: \_\_\_\_\_

Rear

R/Bal: 7 mmL/Bal: 7 mmD.O.I. 27/11/18Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or24 N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

ready to start95.72400 (RBD = 1.81160 11%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

31-12-18

Accident Date : 19-11-18

OUR REF : SLQ 6028A/T/18

Ong Siew Har

Blk 203B Compassvale Road

#05-39

Singapore 542203

Marcus

Date in/out : 04/12/18 to 11/12/18

## ESTIMATE BILL ON VEH. NO. : SLQ 6028A

MODEL : HONDA SHUTTLE

CHASSIS NO : GP71115248

### LIST ITEM

Front Bumper Fascia

Front Bumper Reinforcement

Front Bumper Side Retainer LH

Front Bumper Clips

Front Bumper Center Air Grille

Front Bumper Center Air Grille Garnish LH

Front Bumper Fog Lamp Cover LH

Front Grille Base

Front Grille Clips

Head Lamp Assy LH

Front Grille Chrome (Centre)

Front Grille Lower Chrome

not added  
L/S \$2600  
4/27  
27/11/18

10pcs @ 3.50

6pcs @ 3.50

Less Dis 20%:

100 1,050.20

312 420.80

312 15.60

112 35.00

24/27 145.20

24/27 38.20

711 45.20

112 395.20

112 21.00

112 950.00

112 302.30

112 220.80

3,639.50

727.90

2,911.60

### LABOUR CHARGE

To check wiring system

To tuff coat affected areas

To respray affected areas

To renew damaged parts, straighten & repair front LH fender, front support panel & aligned all parts

20 80.00

112 120.00

500 700.00

300 600.00

4,411.60

308.81

4,720.41

GST 7% :

AMOUNT DUE :

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 9768A

### Vehicle Details

Vehicle No.: SLQ6028A  
Vehicle to be Exported: No  
Intended Deregistration Date: 27 Nov 2018  
Vehicle Make: HONDA  
Vehicle Model: SHUTTLE HYBRID 1.5 A  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: LEB6318595  
Chassis No.: GP71115248  
Maximum Power Output: 101.0 kW (135 bhp)  
Open Market Value: \$20,902.00  
Original Registration Date: 17 Jul 2017  
First Registration Date: 17 Jul 2017  
Transfer Count: 0  
Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 16 Jul 2027  
PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 16 Jul 2027  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$49,802.00  
COE Rebate Amount: \$43,002.00  
**Total Rebate Amount: \$46,752.00**

The information contained herein is correct as at 27 Nov 2018

OK

**ACCIDENT INVOLVING VEHICLE NO.SLQ 6028A AND SLX 4360R ON 19/11/2018**

Precise Auto Service <Support@preciseauto.sg>  
To: "Asher Sng (LKKAuto)" <ashersng@lkkauto.com>

15 January 2019 at 14:41

**Without Prejudice**

Your Ref. : SLX 4360R  
Vehicle No. : SLQ 6028A/T/18

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#08-16 CHARTIS Building  
Singapore 079120

Dear Ms. Asher

We are the repairer for vehicle no. **SLQ 6028A** and instructed by the owner, Ong Siew Har, on his behalf to submit the claims against your insured's vehicle no. **SLX 4360R** that was involved in the above mentioned accident.

The accident was clearly caused by your insured's negligence. In order to save the legal cost, we will process the claim to you directly as follows:

1. Cost of Repair (Survey By Mr. Marcus)	\$ 2,782.00	(Including GST)
2. Loss Of Use (2 days X \$100.00)	\$ 200.00	
3. Car Rental (6 days X \$120.00)	\$ 720.00	
4. LTA / GIA Search	\$ 23.00	
<b>Total :</b>	<b>\$ 3,725.00</b>	

Please let us have your payment in our favour of "**Precise Auto Service**".  
Your prompt reply of the above claims will be much appreciated.

Thank You

Best Regards  
Yan Hong

—

**T : 6745 7367 | F : 6841 3390****E : support@preciseauto.sg****W: www.preciseauto.sg****A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883****PRECISE AUTO SERVICE**

準確汽車服務

***Follow us on social media:***

Instagram <https://www.instagram.com/preciseautosvs/>



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG18021410/Uea3**

07 MAR 2019

**TAY HONG LAN AMY**  
BLK 631 PASIR RIS DRIVE 3  
#02-390  
SINGAPORE 510631

Dear Sir/Madam,

**ACCIDENT INVOLVING SLX 4360R AND SLQ 6028A ON 19/11/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [Ashersng@lkkauto.com](mailto:Ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

TO: **PRECISE AUTO SERVICE**  
**NO. 1 KAKI BUKIT AVENUE 6**  
**#02-34/36**  
**SINGAPORE 417883**

**LETTER OF AUTHORITY & INDEMNITY**

**ACCIDENT INVOLVING VEHICLE NO. SLQ 6028 A AND SLX 4360R**

I/We, Ong Siew Hai NRIC No. S1579768A  
owner of vehicle no. SLQ 6028 A, hereby authorise **M/S PRECISE AUTO SERVICE** to commence repairs to my motor vehicle and to forward the claim for damages sustained in the above accident to the third party driver and/or his employer and/or the vehicle owner and/or the insurer concerned. I/We agree that in consideration of you giving up your repairer's lien I agree to assign the whole proceeds of my/our third party claim to you and if applicable, our solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authority to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and our solicitors to see the claim to a successful conclusion. In the event the proceeds of claim for damages, interest, costs and expenses including legal costs are paid to me directly by the third party insurer, I undertake to indemnify and/or reimburse the said proceeds of claim to you.

If the third party driver and/or his employer and/or the vehicle owner and/or the insurer reject liability, I will be fully responsible for the repair costs.


I/We also authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence.

I/We authorise you to appoint such a firm of solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurers' claim.

I/We undertake to inform you and/or the solicitors appointed by you on my/our behalf in the event the third party's insurance company communicates with me/us directly by telephone or in writing and I/we further undertake not to enter into any compromise Settlement Agreement with the third party insurance without your consent as I understand that this may jeopardise a fair recovery of the third party claim.

My vehicle is repaired by the repairer on my own free will without any inducement, threat and/or promise.

In the event of any breach of my undertaking and the repairer is compelled to enforce this undertaking, I agree that I shall pay for the legal costs incurred by the repairer on a solicitor and client's full indemnity basis.

  
\_\_\_\_\_  
**Owner Signature**  
**(Company Stamp, if Applicable)**



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **PRECISE AUTO SERVICE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,782.00** (Repair Cost), **S\$600.00** (Loss of Use/Rental), **S\$23.00** (Disbursement) for vehicle no. **SLQ 6028A** that was damaged pursuant to the accident which occurred on **19/11/2018** (date) along **NO.44 TANNERY LANE (CARPARK LOT 28)** (location) involving vehicle no/s **SLX 4360R**.

This is pursuant to the inspection conducted on **27/11/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ONG SIEW HAR** ("the third party claimant") of vehicle no. **SLQ 6028A** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLQ 6028A** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 05 (day) of April (month) 2019 (year)



**CKS**

Signed by appointed surveyor



Signed by "the workshop" (with chop)

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

Accident Date : 19-11-18

OUR REF : SLQ 6028A/T/18

**Ong Siew Har**

Blk 203B Compassvale Road

#05-39

Singapore 542203

## TAX INVOICE

Invoice No. : TP1812-011

DATE : 31-12-18

**FINAL BILL ON VEH. NO. : SLQ 6028A**

**VEHICLE MODEL : HONDA SHUTTLE**

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

2,600.00

SUB-TOTAL : 2,600.00

ADD GST 7% : 182.00

TOTAL AMOUNT SGD : 2,782.00

This is a computer generated document and requires no signature.

# Precise Car Rental Pte Ltd

# INVOICE

1 Kaki Bukit Avenue 6 #02-34 Autobay@KakiBukit  
Singapore 417883  
Phone 67457367 Fax 68413390


DATE: December 10, 2018  
INVOICE # PCR/RI/2018/12/076  
RA # R-0478  
FOR: Accident Car  
Replacement  
Vehicle # SJL 6500 C  
Payment Method:

Bill To:  
PRECISE AUTO SERVICE  
CO : ONG SIEW HAR  
BLK 203B COMPASSVALE ROAD #05-39  
SINGAPORE 542203

DESCRIPTION	NUMBER OF DAYS	RATE	AMOUNT
RENTAL (04/12/2018 - 10/12/2018) YOUR REF : SLQ 6028 A	6	\$120	\$720
TOTAL			\$ 720.00

Make all cheques payable to **Precise Car Rental Pte Ltd**

Signature





# PRECISE CAR RENTAL

1 Kaki Bukit Avenue 6 #02-34 Autobay @ Kakibukit S(417883)

Tel: 6745 7367 Fax: 6841 3390

RA No.: R-0478

PRECISE CAR RENTAL

## VEHICLE HIRING AGREEMENT

TP CLAIM

Workshop: PRECISE

### HIRER'S PARTICULARS

Name (as in IC): ONG SEW HAR  
 NRIC/Passport No: 91879768A Date of Birth: 05/12/1963  
 Address: BLK 208 B COMPASSVALE ROAD Age: 54  
#05-39 SI 542203  
 Name & Address of Employer: \_\_\_\_\_  
 Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_  
 Driving Licence No: \_\_\_\_\_ Passed Date: \_\_\_\_\_  
 D/L Type: Local/Int'l/Other: \_\_\_\_\_  
 Tel(O): \_\_\_\_\_ (R): \_\_\_\_\_ HP 9792 4998

### DRIVER'S PARTICULARS

Name (as in IC): \_\_\_\_\_  
 NRIC/Passport No: \_\_\_\_\_ Date of Birth: \_\_\_\_\_  
 SS: \_\_\_\_\_ Age: \_\_\_\_\_  
 S( ): \_\_\_\_\_  
 Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_ Yrs \_\_\_\_\_  
 Driving Licence No: \_\_\_\_\_ Passed / Expiry Date: \_\_\_\_\_  
 D/L Type: Local/Int'l/Other: \_\_\_\_\_ Contact No: \_\_\_\_\_

Hirer's Own Vehicle No: SLG 6028A Replace Veh No: \_\_\_\_\_  
 Loan Vehicle No: SLG 6000 C VR No: \_\_\_\_\_  
 Make & Model: HONDA STREAM Auto/Manual Group: \_\_\_\_\_  
 CHARGES: \$ \_\_\_\_\_ cts  
 Daily 6 day @ \$ 120.00 Per day 720.00  
 Weekly/Monthly week @ \$ \_\_\_\_\_ Per week/Monthly \_\_\_\_\_  
 Others: \_\_\_\_\_  
 CDW/PAI @ \$ \_\_\_\_\_ Per day/Monthly \_\_\_\_\_  
 Delivery/Collection Svc: \_\_\_\_\_  
 GST: \_\_\_\_\_  
 OR No: \_\_\_\_\_ (A) SUB-TOTAL: \_\_\_\_\_  
 Petrol Level & Surcharge: 

OUT	E	1/4	1/2	3/4	F
IN	✓				

  
 First \_\_\_\_\_ km FREE per day GST: \_\_\_\_\_  
 Excess mileage is chargeable at \_\_\_\_\_ cents per km TOTAL CHARGES: 720.00

Security Deposit: \$ \_\_\_\_\_ Bank: \_\_\_\_\_  
 CASH/NETS/VISA/MC/AMEX/CHQ No: \_\_\_\_\_  
 Expiry Date: \_\_\_\_\_ Card ID No: \_\_\_\_\_  
 Name as in Card: \_\_\_\_\_


NON WAIVER EXCESS (Subject to GST): \$ 2000 + \$2000/-

### ACCESSORIES CHECK

- ☐ IU ☐ STD Tools ☐ Hub Cap ☐ Radio / CD Cartridge  
☐ Jack ☐ Tyre Changer ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: \_\_\_\_\_ Additional Driver's Signature: \_\_\_\_\_

SINGAPORE Use Only



I read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given **Precise Car Rental** in connection with this agreement is true.

### IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling) is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of **Precise Car Rental**. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserves the right not to replace a replacement vehicle if an accident occurred. Any damage to the car will be repair at our authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
  - The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
  - In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
  - The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer.
  - All customers' data will be kept strictly confidential and is used for the purpose of completing the sales transactions and other related matters.
  - I understand and agree to the personal data collection statement.

Date Out	Time Out	Mileage	Check By	Remarks
4/12/18	11:00AM			

Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Entered Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To **Precise Car Rental**. And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupon, etc).

Date In	Time In	Mileage	Check By	Remarks
10/12/18	3:55 PM			

Hirer's/Driver Signature

Hirer's/Driver Signature

## SEARCH RESULTS

Our Ref No: GR-18-180675

Date of Request: 21/11/2018

Your Ref No: WALK IN OH SER TIAN

PRECISE AUTO SERVICE  
NO 1 KAKI BUKIT AVE 6, #02-34/36  
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SLQ6028A  
Date of Accident: 19/11/2018  
Place of Accident: NO 44 TANNERY LANE (CARPARK LOT 28)  
Involving Vehicle No: SLX4360R (NO REPORT - SEARCH VALID UNTIL 30/11/18)

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

DOCUMENTS	ACCIDENT LOCATION	ACCIDENT DATE	PER DOC (S\$)
No match found.			

With reference to your application for the accident report, we were unable to process your application and we draw your attention to the following:

- ☒ The requested party is not found in our database. We will continue to check daily for a period of one week, after which if there are no records found, your application will be deemed as cancelled and no notification will be sent to you.
- ☐ Your vehicle's accident report is not found in our database. Please lodge your non-injury accident report with your insurer.
- ☐ Your client's vehicle accident report is not found in our database. Please inform your client accordingly.
- ☐ Others \_\_\_\_\_

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-180675

Date of Request: 21/11/2018

Your Ref No: WALK IN OH SER TIAN

PRECISE AUTO SERVICE  
NO 1 KAKI BUKIT AVE 6, #02-34/36  
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SLQ6028A  
Date of Accident: 19/11/2018  
Place of Accident: NO 44 TANNERY LANE (CARPARK LOT 28)  
Involving Vehicle No: SLX4360R (NO REPORT - SEARCH VALID UNTIL 30/11/18)

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

Enquire Vehicle & Owner Information ( Vehicle No. SLX4360R As At 19 Nov 2018 / 13:49:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PRECISE-SLQ6028A

### Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: 57122357D

Owner Name: TAY HONG LAN AMY

Registered Address Type: HDB / HUDC

Registered Block/House No.: 631

Registered Street Name: PASIR RIS DRIVE 3

Registered Unit No.: # 02-390

Registered Building Name: -

Registered Postal Code: S10631

### Current Vehicle Details

Vehicle No.: SLX4360R

Make Description/Model: KIA / CERATO K3 1.6A SUNROOF

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2018 <a href="#">Edit Reg</a>		27 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>TAY HONG LAN AMY</b> , ID: S7122357D		
Main Claimant:	<b>ONG SIEW HAR</b> , ID: S1579768A		
Vehicle Reg. No.:	<b>SLQ6028A</b>	Date of Loss:	19/11/2018 13:00 - :59 [16 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 3523704704SG</b>	Policy/Cover Note No.:	1800032122 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLX4360R</b>	Policy No. (Claimant):	D18MPC0000387
		Excess:	
Repairer:	<b>Precise Auto Service (HQ)</b> No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 06/12/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (28/11/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)










































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLQ6028A (3523704704SG)  
[SLX4360R]  
TP  
ONG SIEW HAR  
Nov 19 2018 1:45PM  
[TAY HONG LAN AMY]  
Precise Auto Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit			
Photos/Images															3 per page			<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail		Print	
1	27/11/18 17:03		Chassis Number												1			Load JPG		<input checked="" type="checkbox"/>	
2	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
3	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
4	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
5	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
6	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
7	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
8	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
9	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
10	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
11	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
12	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
13	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
14	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
15	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
16	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
17	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
18	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
19	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
20	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
21	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
22	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
23	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
24	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
25	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
26	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
27	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
28	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
29	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
30	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
31	27/11/18 17:04		General View												1			Load JPG		<input checked="" type="checkbox"/>	
32	27/11/18 17:04		Odometer Reading												1			Load JPG		<input checked="" type="checkbox"/>	
33	06/12/18 11:09		Reinspection Photo												1			Load JPG		<input checked="" type="checkbox"/>	
34	06/12/18 11:09		Reinspection Photo												1			Load JPG		<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/12/18 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/18 16:32	EMAIL FROM AIG DD 27.11.2018	 Load PDF	
2	28/11/18 16:32	NOTIFICATION FROM WORKSHOP + LTA SEARCH	 Load PDF	
3	05/12/18 20:30	TP GIA REPORT	 Load PDF	
4	01/04/19 11:34	LETTER TO OI	 Load PDF	
5	11/04/19 10:39	WORKSHOP INVOICE	 Load PDF	
6	11/04/19 10:39	AUTHORISATION TO ACT FORM	 Load PDF	
7	11/04/19 10:39	Release Voucher	 Load PDF	
8	11/04/19 10:39	RENTAL RECEIPT	 Load PDF	
9	11/04/19 10:39	LTA SEARCH	 Load PDF	
10	11/04/19 10:39	GIA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/11/18 11:52	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX4360R (Insd veh)	Model:	HONDA SHUTTLE HYBRID
	SLQ6028A (TP veh)		1.5 (A)
Date of Accident:	19/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,720.41
Final Repair Cost	:	\$	2,782.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	600.00 6 days
LTA / GIA Search Fee	:	\$	23.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,405.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Precise Auto Service	:	\$ 3,405.00
2)		:	\$
3)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
11 Apr  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021410/UEA3Q2

Date: 11/04/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800032122  
**Claimant Vehicle No :** SLQ6028A **Insured Vehicle No :** SLX4360R  
 Date of Loss: 19/11/2018 Nature of Claim: TP Claim No: 3523704704SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ6028A**  
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6318595  
 Reg. Date: 17/07/2017 (Man. Year: 2017) Chassis No: GP71115248  
 Colour: Blue Odometer: 30263 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,911.60	2,476.32	435.28	14.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	820.00	680.00	45.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,411.60</b>	<b>3,296.32</b>	<b>1,115.28</b>	<b>25.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
(S\$)	4,411.60	2,600.00	1,811.60	41.06
<b>+ GST 7.00/7.00% (S\$)</b>	308.81	182.00	126.81	41.06
<b>Nett Amount (S\$)</b>	<b>4,720.41</b>	<b>2,782.00</b>	<b>1,938.41</b>	<b>41.06</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		23.00		
<b>Nett Liability (S\$)</b>		<b>3,405.00</b>		

### INSPECTION

Date of Assignment: 27/11/2018  
 Date Inspected: 27/11/2018 Inspected At: Precise Auto Service (HQ)  
 No 1 Kaki Bukit Ave 6, #02-34/36  
 Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Dented	1,050.20 FL	*1,050.20 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	420.80 FL	*420.80 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Bent	15.60 FL	*15.60 FL
4	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
5	1		*FRONT BUMPER CENTER AIR GRILLE	Deformed / Twisted	145.20 FL	*145.20 FL
6	1		*FRONT BUMPER CENTER AIR GRILLE GARNISH LH	Deformed / Twisted	38.20 FL	*38.20 FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Twisted	45.20 FL	*45.20 FL
8	1		*FRONT GRILLE BASE	Cracked	395.20 FL	*395.20 FL
9	6		*FRONT GRILLE CLIPS	Not Necessary	21.00 FL	*- FL
10	1		*HEAD LAMP ASSY LH	Cracked	950.00 FL	*950.00 FL
11	1		*FRONT GRILLE CHROME (CENTRE)	Not Necessary	302.30 FL	*- FL
12	1		*FRONT GRILLE LOWER CHROME	Not Necessary	220.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,639.50</b>	<b>3,095.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>727.90</b>	<b>619.08</b>

<b>Total Parts (S\$)</b>	<b>2,911.60</b>	<b>2,476.32</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO TUFF COAT AFFECTED AREAS	New	120.00	0.00
3	TO RESPRAY AFFECTED AREAS	New	700.00	500.00
4	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT LH FENDER ,FRONT SUPPORT PANEL & ALIGNED ALL PARTS	New	600.00	300.00
Gross Labour Cost (S\$)			<b>1,500.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >