

22/03/2001

ASS. REC. BY:

REF: CS/AIG18021441/11td301

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Azlan Syazairdina

AIG

Date/Time: 27/11/18 @ 8:37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 2147 L

Insured:

SMC 4005R

at Workshop m/s

Win Automotive

Tel:

9750 6777

of

Blk G, Woodlands Rd 349 J Yew Tee Ind. Est

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:39am 27/11/18

Person Contacted:

WINSON

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKA 2147 L - CS/AXA13000741/71M42

DUA: 8/1/13

SMC 4005R - X.

25/3

Pending Taufik finalize.

winson-tingwei@hotmail.com

Signature: *Tan Jhu*

REF: AIG

ASSIGNMENT

From: Date: 29/11/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA2147L

at Workshop m/s Zhong Cheng

of BLK 4 Yew Tee Ind. 393-H

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$37K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted: Vehicle: IN / OUT: Winson

Veh No: SKA2147L Yr Regn: 2011 Jan

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry G.C. 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 140426 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MROS3BK 410 706/654

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/60R16 R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 29/11/18

Survey held at Zhong Cheng

Des. of Damages: Frt / Rear / O/S / N/S U/C / Rooftop or Fnt N/S, U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 97506777 Rebate \$28,545 \$8K repair limit.

Lump Sum \$4600/- (Red: 12157.98, 72%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 26/3 Typst ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:	250
Transportation	
\$ * RS * SI	
Photos	
Others	20
TOTAL	270

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: TP
Lump Sum / I.B.I: (\$ 4600/-)

Denise Tay (LKKAUTO)

From: Winson Tan <winson_tingwei@hotmail.com>
Sent: Tuesday, 26 March 2019 4:04 PM
To: Denise Tay (LKKAUTO)
Subject: Re: FINALIZE SKA 2147L / 23/11/2018

hi denise.. i have check and confirm with the finalised offer for ska 2147L.. thanks..

best regards: winson tan

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Tuesday, March 26, 2019 3:59 PM
To: winson_tingwei@hotmail.com
Subject: RE: FINALIZE SKA 2147L / 23/11/2018

Dear Winson,

I have double check part by part 5751.30 after 20% is lump sum \$4600/-, 6days.

Please check and get me back

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 26 March 2019 3:40 PM
To: 'winson_tingwei@hotmail.com' <winson_tingwei@hotmail.com>
Subject: FINALIZE SKA 2147L / 23/11/2018

Dear Winson,

Part by part \$5620.80, 6days

Please check and get back to me.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

- Pre repair inspection request - SKA2147L VS SMC4005R (OI) DOA 23/11/2018

From: Azlan, Syazairdina
To: admin-e@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul
Sent: 27/11/2018 8:37:35 AM
Attachments:  tmp92f8.tif

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Claim no : 17750057525G003
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.
Kindly assist to assign Mohammad Taufik as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Monday, November 26, 2018 6:15 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMC4005R AND SKA2147L ON 23/11/2018

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Mohammad Taufik of LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, Win Automotive Services, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008 for the said survey of SKA 2147 L.

Contact Person : Mr Winson
Telephone : 9750 6777

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 26 Nov 2018, at 2:55 PM, Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-12-03 14:56 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2012 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: mail@cheonghoh.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, NoorMariesa.AbuKassim@aig.com, Bajit Kaur

@aig.com, Yinnul.Hor@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMC4005R AND SKA2147L ON 23/11/2018

Date: Mon, 26 Nov 2018 06:55:27 +0000

Without Prejudice

Your Reference : LCH.lg/WeWAS-81079.18

Our Reference : 1775005752SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Chin, Ann

Sent: Monday, November 26, 2018 2:20 PM

To: PRDSG.FNOL

Cc: Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Md Ishak, Mohd Imran; Tan, Lily (AIG); Zhou, Alping; Ho, Choon-Poh; Quek, Joyceline-CH

Subject: 05#SMC4005R#002,002#DEFAULT

SINGAPORE ACCIDENT STATEMENT Sub - Total

\$

~~11,000.00~~

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2018 14:09
Date Of Accident	23/11/2018 13:50
Exact Location Of Accident	WESTGATE SHOPPING MALL BASEMENT 3 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA2147L
Insured/Policyholder	
Name Of Registered Owner	BROOKLYN ENTERPRISE PTE LTD
Co Reg No	198900813M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98214448
Alternative Phone No	OFFICE-98214448

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA014081/1
Cover Note Number	

Driver

Name of Driver	WONG CHENG JIE
NRIC No	S8903692E
Date Of Birth	01/02/1989
Occupation	OUTDOOR
Date Of Driving Pass	19/09/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90622155
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 640 CHOA CHU KANG ST 64 #07-05
Postcode	680640
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM LEE HIANG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC4005R
Vehicle Make/Model/Colour	MAZDA / SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM WAN QIN, CHARMAINE
NRIC/Passport Number	S9438931C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and mitigation in present and all future claims.

(e) the information so collected under (c) above may be shared / disclosed:

- (i) to all Insurers and/or any other third parties that assist in conducting, investigating, settling or managing fraud, regulators, law enforcement and government agencies to reasonably require for the purposes stated, or
- (ii) for complying with regulatory requirements under applicable laws or court orders.

Yunwang
Enterprise Pte Ltd
Date & Time: 5250377

Name:

Sketch Plan #2

SKETCH PLAN

Vehicle A SKA 2147L
Vehicle B SMC 4005R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT The mention Date & time of accident 23/11/2018 about 13:50pm
at westgate shopping mall Basement 3 carpark, my vehicle was
at Basement 3 carpark and my way can be going straight
or turn right. while before turning right I check my left
side ensuring car clearance was clear so as I drive to turn
right. while turning right half way out complete suddenly vehicle
B "SMC 4005R" drive straight out and collided onto
my front left car portion without stopping where his
way is a stop sign before moving out. I came down and the
driver of "SMC 4005R" apologize. saying that she did not
notice of my car turning right out. vehicle B "SMC 4005R" shifted her
car after collided my car and taken
Scene photo.

DECLARATION

I/We declare the following parties are true & correct.


Declarer's name
Date & Time


Driver's name
Driver's license number
Date & Time


Declarer's name
Date & Time

Vehicle no. : SKA 2147L
Model : TOYOTA CAMRY

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

1		FR bumper	\$ de 625.00
2		FR bumper grille <i>Radiator grille</i>	\$ aug? 528.00
3		FR bumper towing cover	\$ nn x 38.00
4		FR bumper garnish LH/RH @ \$63.40 each <i>for garnish</i>	<i>RH-X</i> \$ nn x 126.80 <i>63.40</i>
5		FR bumper centre garnish	\$ nn x 110.00
7		FR bumper retainer LH/RH	<i>nn RH X</i> \$ LH nn 210.00 <i>105</i>
8		FR bumper bracket LH/RH	<i>nn RH X</i> \$ LH nn 240.00 <i>120</i>
10		FR reinforcement	\$ nn x 475.00
11		FR support panel	\$ R 1,025.00
12		Fender LH	\$ bt 830.00
13		Fender signal lamp LH	\$ nn x 75.00
14		FR fender shield LH	\$ de 175.00
15		FR fender shield fasteners	\$ nn 28.00
12		Fender RH	\$ nn x 830.00
13		Fender signal lamp RH	\$ nn x 75.00
14		FR fender shield RH	\$ nn x 175.00
15		FR fender shield fasteners	\$ nn x 28.00
16		Bonnet	\$ R 1,510.00
17		Bonnet inner lock	\$ nn x 155.00
18		Bonnet heat indicator	\$ nn x 505.00
19		Bonnet rubber	\$ nn x 85.00
25		Headlamp LH	\$ aug 1,400.00
27		Fog lamp cover LH	\$ de 80.00
28		Fog lamp LH	\$ aug 255.00
25		Headlamp RH	\$ nn x 1,400.00
27		Fog lamp cover RH	\$ nn x 80.00
28		Fog lamp RH	\$ nn x 255.00
36		Radiator assy	\$ nn x 2,205.00
37		A/C condenser	\$ nn x 1,625.00
38		Fan motor	\$ nn x 500.00
39		Fan	\$ nn x 175.00
44		Washer tank	\$ nn x 195.00
46		Washer hose	\$ nn x 48.00
49		Engine undercover X2	\$ nn x 350.00
50		Engine undercover clips	\$ nn x 28.00
51		Front bumper sponge	\$ nn x 138.50
52		Front bumper lower grille	\$ de 174.00
53		Front absorber LH	\$ nn x 455.00 <i>nn</i>
54		Front lower arm LH	\$ nn x 600.00 <i>nn</i>
55		Front wheel bearing LH	\$ nn x 225.00 <i>bt</i>
56		Front knuckle arm LH	\$ nn x 585.00 <i>bt</i>
57		FR Toyota logo emblem	\$ nn 775.00 <i>nn</i>

Less 25%

\$ 18,697.30
\$ 4,674.33

\$ 14,022.98

Special Nett

1 1 pc FR number plate w casing

\$ ~~nn~~ x 60.00

\$ 60.00

Vehicle no. : SKA 2147L

Model : Toyota Camry

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts	\$ 800 ⁻ 1,200.00
2		To realign headlamp focus	\$ 20 35.00
3		To check wiring and rewire	\$ 30 50.00
4		To remove/ refix radiator & condensor	\$ 117 x 120.00
5		To top up coolant and aircon gas	\$ 117 x 80.00
7		Remove & refix undercarriage	\$ 120 ² photo 250.00
8		To anti-rust	\$ 30 100.00
9		To putty and spray-paint of affected areas	\$ 800 900.00
			\$ 2,735.00

16757.98

Tanjin 97495749
WP
29/11/18 @ 430pm
Ready after repair
sur @ lkkauto.com
6 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

16877.97

Grand - Total

\$

-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018 Edit Reg		27 Nov 2018 00:00 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lim Ser Heng , ID: S1304901G								
Main Claimant:	UNKNOWN								
Vehicle Reg. No.:	SKA2147L	Date of Loss:	23/11/2018 00:00 - :59 [93 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1775005752SG	Policy/Cover Note No.:	1800077028 (Comprehensive) Coverage: 29/06/2018 - 28/06/2020						
Vehicle Reg. No. (Insured):	SMC4005R	Policy No. (Claimant):							
		Excess:							
Repairer:	Zhong Cheng Enterprise () Blk 6 Woodlands Road, Yew Tee Industrial Estate 399J, 678008 Woodlands - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (28/11/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA2147L (1775005752SG)**
[SMC4005R]
TP
UNKNOWN
Nov 23 2018 12:00AM
[Lim Ser Heng]
Zhong Cheng Enterprise

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio		View View in Browser	
Assessment Reports			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 per page
1	28/11/18 12:02	Accident Statement From: OD - Reg. No: SMC4005R, Claimant: LIM SER HENG	☒ Thumbnail Print ☐ Load HTM
Photos/Images			3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	☒ Thumbnail Print
1	26/03/19 17:40	General View	☒ Load JPG
2	26/03/19 17:40	General View	☒ Load JPG
3	26/03/19 17:40	General View	☒ Load JPG
4	26/03/19 17:40	General View	☒ Load JPG
5	26/03/19 17:40	General View	☒ Load JPG
6	26/03/19 17:40	General View	☒ Load JPG
7	26/03/19 17:40	General View	☒ Load JPG
8	26/03/19 17:40	General View	☒ Load JPG
9	26/03/19 17:40	General View	☒ Load JPG
10	26/03/19 17:40	General View	☒ Load JPG
11	26/03/19 17:40	General View	☒ Load JPG
12	26/03/19 17:40	General View	☒ Load JPG
13	26/03/19 17:40	General View	☒ Load JPG
14	26/03/19 17:40	General View	☒ Load JPG
15	26/03/19 17:40	General View	☒ Load JPG
16	26/03/19 17:40	General View	☒ Load JPG
17	26/03/19 17:40	General View	☒ Load JPG
18	26/03/19 17:40	General View	☒ Load JPG
19	26/03/19 17:40	General View	☒ Load JPG
20	26/03/19 17:40	General View	☒ Load JPG
21	26/03/19 17:40	General View	☒ Load JPG
22	26/03/19 17:40	General View	☒ Load JPG
23	26/03/19 17:40	General View	☒ Load JPG
24	26/03/19 17:40	General View	☒ Load JPG
25	26/03/19 17:40	General View	☒ Load JPG
26	26/03/19 17:40	General View	☒ Load JPG
27	26/03/19 17:40	General View	☒ Load JPG
28	26/03/19 17:40	General View	☒ Load JPG
29	26/03/19 17:40	General View	☒ Load JPG
30	26/03/19 17:40	General View	☒ Load JPG
31	26/03/19 17:40	General View	☒ Load JPG
32	26/03/19 17:40	General View	☒ Load JPG
33	26/03/19 17:40	General View	☒ Load JPG

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	26/03/19 17:40	General View	 Load JPG	☒
35	26/03/19 17:40	General View	 Load JPG	☒
36	26/03/19 17:40	General View	 Load JPG	☒
37	26/03/19 17:40	General View	 Load JPG	☒
38	26/03/19 17:40	General View	 Load JPG	☒
39	26/03/19 17:40	General View	 Load JPG	☒
40	26/03/19 17:40	General View	 Load JPG	☒
41	26/03/19 17:40	General View	 Load JPG	☒
42	26/03/19 17:40	General View	 Load JPG	☒
43	26/03/19 17:40	General View	 Load JPG	☒
44	26/03/19 17:40	General View	 Load JPG	☒
45	26/03/19 17:40	General View	 Load JPG	☒
46	26/03/19 17:40	General View	 Load JPG	☒
47	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
48	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
49	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
50	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
51	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
52	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
53	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
54	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
55	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
56	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
57	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
58	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
59	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
60	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
61	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
62	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
63	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
64	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
65	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
66	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
67	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
68	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
69	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
70	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
71	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
72	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
73	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
74	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
75	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
76	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
77	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
78	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
79	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
80	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
81	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
82	29/03/19 11:18	Reinspection Photo	 Load JPG	☒
83	29/03/19 11:18	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	29/03/19 11:18	Reinspection Photo	 Load JPG	✓
85	29/03/19 11:18	Reinspection Photo	 Load JPG	✓
86	29/03/19 11:18	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/11/18 16:55	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18021441/T1TD3E2

Date: 03/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800077028
 Claimant Vehicle No: SKA2147L Insured Vehicle No: SMC4005R
 Date of Loss: 23/11/2018 Nature of Claim: TP Claim No: 1775005752SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA2147L Engine No: 1AZE181549
 Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Chassis No: MR053BK4107061654
 Reg. Date: 27/01/2011 (Man. Year: 2010) Odometer: 140426 km
 Colour: Silver
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,082.97	3,951.30	10,131.67	71.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,735.00	1,800.00	935.00	34.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,817.97	5,751.30	11,066.67	65.80
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	16,817.97	4,600.00	12,217.97	72.65

INSPECTION

Date of Assignment: 27/11/2018
 Date Inspected: 29/11/2018 Inspected At: Zhong Cheng Enterprise
 Blk 6 Woodlands Road, Yew Tee Industrial Estate 399J
 Singapore 678008

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR BUMPER	Deformed	625.00 FL	*625.00 FL
2	1		*FR BUMPER GRILLE (RADIATOR GRILLE)	Cracked	528.00 FL	*528.00 FL
3	1		*FR BUMPER TOWING COVER	Not Necessary	38.00 FL	*- FL
4	1		*FR BUMPER GARNISH LH / RH (TOP GARNISH)	O/S Not Necessary/N/S Deformed	126.80 FL	*63.40 FL
5	1		*FR BUMPER CENTRE GARNISH	Not Necessary	110.00 FL	*- FL
6	1		*FR BUMPER RETAINER LH / RH	O/S Not Necessary/N/SNecessary	210.00 FL	*105.00 FL
7	1		*FR BUMPER BRACKET LH / RH	O/S Not Necessary/N/SNecessary	240.00 FL	*120.00 FL
8	1		*FR REINFORCEMENT	Not Necessary	475.00 FL	*- FL
9	1		*FR SUPPORT PANEL	Repair	1,025.00 FL	*- FL
10	1		*FENDER LH	Bent	830.00 FL	*830.00 FL
11	1		*FENDER SIGNAL LAMP LH	Not Necessary	75.00 FL	*- FL
12	1		*FR FENDER SHIELD LH	Deformed	175.00 FL	*175.00 FL
13	1		*FR FENDER SHIELD FASTENERS	Necessary	28.00 FL	*28.00 FL
14	1		*FENDER RH	Not Necessary	830.00 FL	*- FL
15	1		*FENDER SIGNAL LAMP RH	Not Necessary	75.00 FL	*- FL
16	1		*FR FENDER SHIELD RH	Not Necessary	175.00 FL	*- FL
17	1		*FR FENDER SHIELD FASTENERS	Not Necessary	28.00 FL	*- FL
18	1		*BONNET	Repair	1,510.00 FL	*- FL
19	1		*BONNET INNER LOCK	Not Necessary	155.00 FL	*- FL
20	1		*BONNET HEAT INDICATOR	Not Necessary	505.00 FL	*- FL
21	1		*BONNET RUBBER	Not Necessary	85.00 FL	*- FL
22	1		*HEADLAMP LH	Cracked	1,400.00 FL	*1,400.00 FL
23	1		*FOG LAMP COVER LH	Deformed	80.00 FL	*80.00 FL
24	1		*FOG LAMP LH	Cracked	255.00 FL	*255.00 FL
25	1		*HEADLAMP RH	Not Necessary	1,400.00 FL	*- FL
26	1		*FOG LAMP COVER RH	Not Necessary	80.00 FL	*- FL
27	1		*FOG LAMP RH	Not Necessary	255.00 FL	*- FL
28	1		*RADIATOR ASSY	Not Necessary	2,205.00 FL	*- FL
29	1		*A/C CONDENSER	Not Necessary	1,625.00 FL	*- FL
30	1		*FAN MOTOR	Not Necessary	500.00 FL	*- FL
31	1		*FAN	Not Necessary	175.00 FL	*- FL
32	1		*WASHER TANK	Not Necessary	195.00 FL	*- FL
33	1		*WASHER HOSE	Not Necessary	48.00 FL	*- FL
34	2		*ENGINE UNDERCOVER	Not Necessary	350.00 FL	*- FL
35	1		*ENGINE UNDERCOVER CLIPS	Not Necessary	28.00 FL	*- FL
36	1		*FRONT BUMPER SPONGE	Not Necessary	138.50 FL	*- FL
37	1		*FRONT BUMPER LOWER GRILLE	Deformed	174.00 FL	*174.00 FL
38	1		*FRONT ABSORBER LH	Not Necessary	455.00 FL	*- FL
39	1		*FRONT LOWER ARM LH	Not Necessary	600.00 FL	*- FL
40	1		*FRONT WHEEL BEARING LH	Bent	225.00 FL	*225.00 FL
41	1		*FRONT KNUCKLE ARM LH	Bent	585.00 FL	*585.00 FL
42	1		*FR TOYOTA LOGO EMBLEM	Necessary	75.00 FL	*75.00 FL
43	1		*FR NUMBER PLATE W CASING	Not Necessary	60.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 18,757.30 5,268.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					4,674.33	1,317.10
Total Parts (S\$)					14,082.97	3,951.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,200.00	800.00
2	TO REALIGN HEADLAMP FOCUS	New	35.00	20.00
3	TO CHECK WIRING AND REWIRE	New	50.00	30.00
4	TO TOP UP COOLANT AND AIRCON GAS	New	80.00	0.00
5	REMOVE & REFIX UNDERCARRIAGE	New	250.00	120.00
6	TO ANTI-RUST	New	100.00	30.00
7	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	900.00	800.00
8	TO REMOVE / REFIX RADIATOR & CONDENSOR	New	120.00	0.00
Gross Labour Cost (S\$)			2,735.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >