| The state of   |                                | 1 1  | 1 . 8              | M KI ) QILKK   |                        |
|--|--------------------------------|--|--------------------|--|------------------------|
| 100.00   | Clast Jon                      | CC AIG1802 14  | 601                | TO IDA   | C.                     |
| INS. CASE OWNER:   | 1/ /                           | ASSIGNMEN  | et.                | k /  | 1.4                    |
|  | DAGW                           | DOI: ASSIGNMEN   | 4                  | Date / Time / Vo /                                     | 1 08                   |
| Surveyor:  | Prince                         | DOI: TV LOCK   |                    | Registered in Merimen:                                 | 71/11/08               |
|  |                                |  |                    | Registered in Merimen.                                 | 731                    |
| Pre-assign / CCU /   |                                | 406E   |                    | 980626   | therin                 |
| Insured Vehicle No.  |                                | 1006   | Claim No.          |  |                        |
| A  | na thenu                       | THE  | Policy No.         | 71014  | nrule-01               |
| Name of Insured  | 2.000 0000000                  | estimate and a second  | THE CALL PROPERTY. | K19  |                        |
| Insured Tel No.  |                                | 0 to 1 1 1 V   | Make / Model       | To 111 - 01  | DE IN PROWT of         |
| Excess Sec II :SS  |                                | -  | Place of Accid     | 100  | CINARDINE              |
| Is driver the owner?   | ( YES / NO))                   | Nature of Accident   |                    | DIMAH  |                        |
| If NO. Driver Nam  | 10/Age: Wh TO TE               | My FFILY   | OI GIA REPO        | RT: YES / NO : TP GIA                                  |                        |
| Driver Tel 5   | No.::                          | (V/L YES/NO)   | Insured Liabili    | ty # Fine  | ul? Yes/No             |
| SM & 760   | CX.                            |  |                    |  |                        |
| 7110 -100  |                                |  |                    |  |                        |
| INSRS:   | INSR.                          | s  | INSRS:             |  | INSRS:                 |
| WSP: C.M   | WSP.                           | K-A  | WSP:               | # #  | WSP:<br>Tel            |
| Tel: 7   | Tel:                           | D H  | Liability          | 2_0  | Liability:             |
| RMKS   | RMK                            | 116 -11  | RMKS:              | (ATA)  | RMKS:                  |
| Dute/ Time   | AWWIII                         | 7-5  |                    |  |                        |
| 1 13/  | CM012654-4                     | SUNVOLET   | y                  | STAGE  | DATE/PIC               |
| WINIE  | 2122                           |  |                    | Nen-Reporting fir (1st):                               |                        |
| 1111   |                                |  |                    | Non-Reporting lit (2nd):<br>Non-Reporting lit (Final): |                        |
| Bapters  |                                |  |                    | Nonfication by (if pen-pic                             |                        |
| 1  |                                |  |                    | Call Of 8 3/20   | 4                      |
| 4/3/149  | Soule to 020 (M                | , kelly Hg) , continued &  | nin 21             | After call lir to Of:                                  |                        |
| 4.10 gm  | 1 1 1                          |  | ous of             | Documentation Check L<br>Nonfication in til rem-pic    |                        |
|  | THE PERSON AND THE PARTY       | in and 14cb issue she o  | ugice to           | After call by to OI:                                   | Nugiri V               |
| 020  | Settle and power               | HUD will be offeeted . S.  | end letter         | Authorisation To Act                                   | V                      |
|  | 4. 02.                         |  | 14                 | Release Voucher  |                        |
|  | 4. OV.                         |  |                    | Final Repair Bill:                                     | 2                      |
|  |                                | 4 2 2 2 2 2  |                    | Car Rental Invoice                                     | V                      |
| 4 110119   | - Fike pass to                 | Shu pei to cluse   |                    | Toxing Invoice   |                        |
| Krove/ma   |                                |  |                    | LTA / GIA :<br>Medical Bill:                           |                        |
|  |                                |  |                    | PBC  |                        |
|  |                                |  |                    | Mandate/Reject Instruc                                 | tion:                  |
|  |                                |  |                    | LOD  |                        |
|  |                                |  |                    | Payment Breakdown F                                    | oem:                   |
| PRELIMINARY ADVICE   | Date/Time:                     | Sent Hy:   |                    | Post-Repair Photos:                                    |                        |
|  | The STREET                     | See Cone. LUCKOWILL CO.  |                    | Others:  |                        |
| FINALIZATION   | Date/Time.                     | Confirm with: 3 days) Reduction: 49  | en.                | Confirm by:  | ad Call                |
| Repair Cost: US  | SS 9 50<br>Date/Time: 19/10(19 | Confirm with Ton CRR   | 710                | Email Call   | 1                      |
| Final Liability:   |                                | I / Assessed) BOLA S/N No.: 77   |                    | If NO or B 28. Ass. Li                                 | 81                     |
| Repair Cost  | 55 850                         |  |                    | Front to   |                        |
| Loss of Remal (LOR):   | 55 686.94                      | 6 days X \$ 114.49   |                    | [104] 10   | 1000                   |
| Loss of Use (LOU):   |                                | x - days)  |                    | 111,6  | 1/152                  |
| Loss of Income (LOI):<br>LOR only LOU only   | SS 50 15 50                    | LOR+LO [Tick only one]   |                    | THIN   | 1-5/                   |
| LCR only LOU only<br>GIA/LTA Search  | 55 7.00                        | LAIS TILVIET [TICK mily one]   |                    |  | 1 - 0                  |
| Medical:   | SS 1                           |  |                    | 1) Chaim status. Norm                                  | /Reject/Private Settle |
| Disbursement:  | 55                             | (e.g. Tow/ Independent )   |                    | 2) Report Format:                                      | TP                     |
| Louil Cost   | 55 -                           | AND ADD AND ADD ADD  |                    | 3) Survey Ice:   | \$320                  |
| Total:   | ss 1,593.94                    | Global Sum SS:<br>Confirm with:  |                    | Emuil Call   |                        |
| FINAL PAYMENT  | SS 1,593.00                    | PF 2014 4 4 5 C 1 - C 11 2 4 F C - C   | HKIS               |  | TELTD                  |
| Payee 1<br>Payee 2. (Strike if N.A.)   | 55 1, 543.00                   | Name 2:  | -13                |  | 1. S. (S. (S. S. )     |
| Payee 3: (Strike if N.A.)  | 55                             | Name 3:  |                    |  |                        |
| THE RESERVE OF THE PARTY OF THE |                                | A STATE OF THE STA |                    |  |                        |

ł

| REF:   | 14 TAX/11/18/2090   |
|--|---|
| NA2  | GNMENT  |
| ASSE   | 1 NEV 10 NEG 2015   |
| Dale: -                                      | Veh No: SHB 765 X Yr Regn: 10 DE 6 2015   |
| From: Date:                                  | Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Brime Mover /  |
| OD/TP/WS/TP RES/OD RES/EVA/INV/MV            | Truck/ Trailer or c.c. 1998   |
|  | Make: 10 York PRINS C.C. THE  |
| To Inspect Vehicle No:                       | Colores SASTAGOSTA 1  |
| at Workshop m/s                              | Sp.Reading 449 310 T/Radip: (insured / Std / NI / N/  |
| 01   | m Nie   |
| Insured:                                     | C/No: JTD KN364305753496  |
| Policy No.                                   | Gen. Cond: Good / Fair / Poor / Burnt   |
| Ctairns No.                                  | Steering: (norder / Jammed / Leaked / Burnt or  |
| Sum Insured: Excess:                         | Brake: Inorder / Jammed / Leaked / Burnt or   |
| (Client's Record)                            |   |
| Make of Veh;                                 | Modi: Nii / S/Rim / STD A/Rim or  Tyre Sizo: F: 195 (65 RU)   |
|  | R:  |
| (Policy Condition)                           | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /   |
| Remark: The veh had commenced Its N/S 0/S    | TOYO/YOKO or FALKEN   |
| repair at the time of inspection.            | Rear  |
| Bal. or Market Value:                        | Front R/Bal. 6 mm R/Bal. 6  |
| IDAC Accident Roort: Consistent? : Yes or No | I Bal 6 m   |
| GIA / PR Seent Consistent? Yes or No         | 000 0010/18   |
| Est Repairs: days Res.: Yes or No            | Lake Joseph Joseph Joseph   |
| Lum Sum: % 3 Val.: Yes or No                 | Des. of Damages : Frt / Rear / O/S / N/S / UIC / Rooftop or   |
| CA I REV I REP. I 24 HRS                     |   |
| Venicia: INTOOT                              | The U/C / Chassis frame / Body Structure affected due to collise  |
| Date:Person Contocled:                       |   |
| Date / Time Action / Instruction             | AIG U/S   |
|  |   |
|  |   |
|  | \$ 100 mm and 100 mm an |
|  |   |
|  |   |
|  |   |
|  |   |
| Dule/How, File Pass to? : Proll: Report      | Days Of Repair:   |
| ; Final Report                               | Resurvey No. of Trip: Survey ros.   |
| Duteflime, File Roturn to?  Add Fe           | e: : Site insp (\$)s+RSSI   |
| 7)   | Interview (\$ ) Photos  |
|  | Tech. trivo (\$), piners  |
| Report Format:                               | :Weekend (\$  |
|  | Tech. Invo (\$ ), omes  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R.

|  | Affiliated to Federation Inte | rnationale Des Experts En Autom | nobile                     |  |  |  |
|--|-------------------------------|---------------------------------|----------------------------|--|--|--|
| AIG ASIA PACIFIC INS   | SURANCE PTE LTD               | Ref : CC3/AIG18021              | 460/R1fb3                  |  |  |  |
| 78 SHENTON WAY #0<br>CHARTIS BUILDING<br>SINGAPORE 079120  | 8-16                          | Date: 28-11-2018 Code: AIG      |                            |  |  |  |
| 1.   | Policy Particu                | lars :- THIRD PARTY CLA         | M                          |  |  |  |
| Insured Veh.   | SLL 8406E                     | Veh. Inspected                  | SHB 765X                   |  |  |  |
| Policy No.   |                               | Coverage (\$)                   | 0.00                       |  |  |  |
| Claim No.  |                               | Excess (\$)                     | 0.00                       |  |  |  |
| Assign From  |                               | Assign Date                     | 28/11/2018                 |  |  |  |
| 2.   | Vehicle I                     | Particulars & Condition         |                            |  |  |  |
| Make & Model   |                               | c.c                             | 0                          |  |  |  |
| Engine No.   | HIDDEN                        | Year of Reg.                    |                            |  |  |  |
| Chassis No.  |                               | Colour                          |                            |  |  |  |
| Odometer -   |                               | Steering                        |                            |  |  |  |
| Brakes   |                               | Modification                    |                            |  |  |  |
| General  |                               |                                 |                            |  |  |  |
| 3.   | Co                            | enditions of Tyres              | 186                        |  |  |  |
|  | Size                          | Make                            | Balance                    |  |  |  |
| R/H Front Tyre   |                               |                                 | mm                         |  |  |  |
| L/H Front Tyre   |                               |                                 | mm                         |  |  |  |
| R/H Rear Tyre  |                               |                                 | mm                         |  |  |  |
| L/H Rear Tyre  |                               |                                 | mm                         |  |  |  |
| 4.   | Desc                          | ription of Damages              |                            |  |  |  |
| 5.   | Ge                            | neral Information               |                            |  |  |  |
| Accident Date  | 20/11/2018                    | Inspection Date                 | 26/11/2018                 |  |  |  |
| Survey held at   | SMRT AUTOMOTIVE SER           | 11.2-14                         | para consultare consultare |  |  |  |
| Secretaria de la composição de la compos | 60 WOODLANDS INDUST           | RIAL PARK E4 SINGAPORE 7        | 57705                      |  |  |  |
| 5a.  |                               | Remarks                         |                            |  |  |  |

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Registration Number

Registration Date

Сотрапу Туре

Name of Driver
Type of Accident

Survey by

Accident Date and Time

Vehicle is Towed Back? No Towed Back Date and Time Replacement Vehicle issued? No

Special Instruction to ARC,if

any Prepared Date and Time

Job Card Number

Chassis Number

Miteage Work Shop

Accident Reported Date and Time is Surveyor Required?

Make Model

Case Reference Number

#### SMRT Accident Vehicle Repair Estimates

Section A - Accident Details

SHB765X

10/12/14

TOYOTA

PRIUS

TAX/11/18/2090

SMRT Taxis Ple Ltd

YEO KHEE SENG

Head to Rear 20/11/18 8 08 PM

21/11/18 9:21 AM

24098857

TOSIAIG - LKK

22/11/18 4:04 PM

704

EMRT Automotive Services Fix Lie


SC Vaudinia mounte Fact EX, Septem FAL Sures: \$366500

Exercise Telephone Humber: \$6002628

Date Senerated 25/12/09/4 Dearld Ferdinan

| 1  | - |
|----|---|
|    |   |
| 4  |   |
| 8  |   |
| 1  |   |
| K  |   |
| 10 |   |
| V  |   |
| -  |   |
|    |   |
|    |   |
|    |   |
| f. |   |
|    |   |
| 3. |   |
| 1  |   |
|    |   |
| 2  |   |
|    |   |
|    |   |





harts

| Repair Completion Date an<br>Time | d  |                                     |
|-----------------------------------|--|-------------------------------------|
|                                   | Section B - Summary of Repair Esti                         | mates                               |
| Summary of Repair Estim           | ates   |                                     |
| <u> </u>                          | Quotation from ARC   | Adjusted by Surveyor, if applicable |
| Total Labour Cost                 | 5338.00  | \$150.00                            |
| Total Spray Cost                  | \$738.00   | \$300.00                            |
| Total Spare Part Cost             | \$1,447.61   | \$363.42                            |
| Total Other Cost                  | \$260.00   | \$60.00                             |
| TOTAL COST                        | \$2,783.61   | \$873.42                            |
| Lump Sum Total                    | \$2,800.00   | \$850.00 (L/S)                      |
| Number of Repair Days             | 4.0  | 9.0                                 |
| Prepared / Adjusted By            | Tuck Foo Kok   | RASUL (LKK) / AIG                   |
| ARC / Surveyor Sign Off Da        | ste 28/11/2018 9:20 AM                                     | 26/11/2018 4:34 PM                  |
| Signature                         | 8)-  | Rend                                |
| Remarks                           | Initial = 3 days<br>Request number of days to extend 1 day | resurvey after repair / fump sum.   |



## SMRT Accident Vehicle Repair Estimates

ENET Automotive Environ Pto Life 02 Yeardward Handwal Park E.e. Engagere FAS Names EMERROY Extreme Tolophone Furner (860302) Aprilland Reprint Hander (880207)

Date Generated 39/12/2016 West ID. 1 Pagesta

| Quotation    | Number        | QN-1812         | -050B Invo                     | olce Numbe   | er.  |                 |             |                                     |                |              | i   |
|--------------|---------------|-----------------|--------------------------------|--------------|--|-----------------|-------------|-------------------------------------|----------------|--------------|-----|
| Quotation    | Date          | 25,12.201       | 18: Inve                       | pice Date    |  |                 |             |                                     |                |              |     |
| invoice A    | mount         |                 | Pre                            | pared Date   |  |                 |             |                                     |                |              |     |
| Augeli       | Rent          | Vargata         | Section D -                    | Details of F | tepair Estimat   | es              |             | Septimination of                    | Date No.       |              |     |
| Part 1 - La  | sbour Work    | 4               | 1384184-0                      | min sage     | A PARTITION OF THE PART | THE RES         |             |                                     | ANSIMA         |              |     |
| Job Scop     | • 75000000    | Albaha.         | II CONTRACTOR OF THE           | Quotation    | from AR  |                 |             | Adjusted b                          | y Surveyor, if |              |     |
| TO REPA      | IR REAR PO    | ORTION          |                                | \$338.00     | COOLERAN   | Locality (C.    |             | applicable<br>\$150.00              |                |              |     |
| Total Lab    | our           |                 |                                | \$338.00     |  |                 |             | \$150.00                            |                |              |     |
| Dart 2 - S   | near Painti   | on A Banel      | Beating Related Works          |              | -20-20-0   | LEVEL AS        |             | - 2                                 |                |              |     |
| Job Scop     | ASSESSED BOOK | ng o raner      | deating related Works          | Quotation    | from ARC   |                 |             | Adjusted b                          | y Surveyor, if |              |     |
| 7            | RAY REAR      | BUMPED          | model hard or                  | \$378.00     | HAMILET IN   | 1000            | 1845 176    | annicable<br>\$200.00               |                |              |     |
| Alternative. | RAY BUMP      |                 |                                | 5180.00      |  |                 |             | \$0.00                              |                |              |     |
| MS-MITTERN   | RAY BUMP      | 0035111         |                                | \$180.00     |  |                 |             | \$100.00                            |                |              |     |
|              | ay Painting   |                 | estina                         | \$738.00     |  |                 |             | \$300.00                            |                |              |     |
| out opt      | ay r ainting  | a raner o       | and a second                   | #7 JH.UU     |  |                 |             | 2300.00                             |                | J            |     |
| Part 3 - O   | ther Costs    | - Accident      | and Accident Repair Relate     | d Expense    |  | 1 678           | rijes s     | DI XIE                              | 2 J. SPX       |              |     |
| Job Scop     | <b>.</b>      |                 |                                | Quotation    | from ARC   |                 | 3551515     | Adjusted by Surveyor, if applicable |                |              |     |
| TO CHEC      | K WIRING      | AND SYST        | EM FUNCTION                    | \$80.00      |  |                 |             | SO.00                               |                |              |     |
| TO TEST      | AND REFD      | REVERSE         | SENSOR SYSTEM                  | \$120.00     |  |                 |             | 560,00                              |                |              |     |
| TO WASH      | AND VAC       | UUM             |                                | \$60,00      |  |                 |             | \$0.00                              |                |              |     |
| Total Othi   | er Costs      |                 |                                | \$250.00     |  |                 |             | \$60.00                             |                | 454.         | 28  |
| Part 4 - Sp  | pare Parts /  | Material U      | sage                           | 505          | 7 3 7  | CAV-S           | la Vall     |                                     |                | 454.<br>- 20 | 27  |
| Part         | Portion       | Stock<br>Number | Part Name                      | Quantity     | List Price   | Discount<br>(%) | Final Price | Estimator                           | Surveyor       | - 20         | 6   |
| raminer.     |               | 52159-<br>47905 | BUMPER REAR                    | 1.00         | \$458.60   | 100.00          | \$0.00      | Replace                             | Repair /       | - 1          |     |
|              |               | 52161-<br>16010 | BUMPER CLIPS                   | 0.00         | \$1.61   | 0.00            | \$0.00      | Replace                             | Not Given X    | 363.         | 42  |
|              |               | 52023-<br>12240 | BUMPER<br>REINFORCEMENT REAR   | 0.00         | \$205.70   | 0.00            | \$0.00      | Replace                             | Check X        | + 150.       | 00  |
|              |               | 52016-<br>47630 | ARM SUB-ASSY, RR<br>BUMPER LH  | 0.00         | \$139.60   | 0.00            | \$0.00      | Replace                             | Check Y        |              |     |
|              |               | 52015-<br>47050 | ARM SUB-ASSY, RR.<br>BUMPER RH | 0.00         | \$139.60   | 0.00            | 50.00       | Replace                             | Check X        | + 360.       | 00  |
|              |               | 89997-          | ANTENNA, ELECTRICAL            | 0.00         | \$157.40   | 0.00            | 50.00       | Replace                             | Check X        | 7 10         |     |
|              |               | 30578           | SENSOR REVERSE                 | 0.00         | \$180.00   | 0.00            | \$0.00      | Replace                             | Check X        |              | 42  |
|              | -             |                 | PIXEL STICKER                  | 2.00         | \$60.00  | 0.00            | \$120.00    | Replace                             | Replace        | C73          |     |
|              |               | 76891-          | BUMPER LIP REAR                | 0.00         | 5228.90  | 0.00            | 50.00       | Replace                             | Chesk X        | 81.          |     |
|              |               | 47020<br>52576- | BUMPER SIDE RETAINER           | 0.00         | 594.80   | 0.00            | \$0.00      | Replace                             | Not Given y    |              |     |
|              |               | 47020<br>52575- | BUMPER SIDE RETAINER           | 0.00         | \$94.80  | 0.00            | \$0.00      | Replace                             | Not Givern     | 71 1         | 0-  |
| Total        | _             | 47020           | RR/RH                          |              | \$1,761.01   |                 | \$120.00    |                                     | nn/            | 45\$         | 820 |
| Added So     | are Darte     | Material III    | sage After Surveyor Signed     | off          |  |                 |             |                                     | V-271 24-      | -            | 3de |
| Part         | CHEST         | Stock           | Part Name                      |              | List Price \$  | Diseased        | Final Price | ARC                                 | Surveyor       |              | 210 |
| Number       | Portion       | Number          |                                | Quantity     | 1000000  | (%)             | (5)         | Check                               | Check          | Di.          | 300 |
|              |               | 52023-<br>12240 | BUMPER<br>REINFORGEMENT BEAR   | 1.00         | \$205.70   | 25.00           | \$154.28    | Replace                             | Replace        | Bt +         | 1   |
| T-1-1        |               |                 | SENSOR REVERSE                 | 1.00         | \$180.00   | 0.00            | \$180.00    | Replace                             | Replace        | Shorted      |     |
| Total        |               |                 |                                |              | 385,70   |                 | 334.28      |                                     |                |              |     |



# Case Details

Case Reference Number: TAX/11/18/2090

Type of Repair : Accident Repair

Vehicle Registration Number: SHB765X

Company Type: SMRT Taxis Pte Ltd

Estimation ID : EST-4635-ID Assigned By : B. Thaiyal Nayagi Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Accident Date and Time : 20/11/2018 12:08 PM

Vehicle Age(In Months): 47

# Documents / Photographs

View Documents / Photographs

Total Documents: 1

# Estimation Details

#### Spare Part's Cost Detail

|                           |                 |         |                    | SMRT Recom                           | menda | ition                     |                  |        |                   |                    |                      | Surveyor Appro              | rval       |       |
|---------------------------|-----------------|---------|--------------------|--------------------------------------|-------|---------------------------|------------------|--------|-------------------|--------------------|----------------------|-----------------------------|------------|-------|
| BOM<br>Type               | Costing<br>Type | Portion | Material<br>Number | Part Name                            | Oty   | List Price<br>Per Unit(5) | List<br>Price(5) | Dis(%) | Final<br>Price(3) | Repair/<br>Replace | Surveyor<br>Quantity | Surveyor Final<br>Price(\$) | Repair/Rep | alace |
| One<br>Time<br>Key<br>In  | Main            |         |                    | BUMPER REAR                          | 1     | 458.60                    | 458.60           | 25.00  | 343.95            | Replace            | 3                    | 0                           | Repair     | **    |
| One<br>Time<br>Key<br>In  | Main            |         |                    | BUMPER CLIPS                         | 10    | 1.61                      | 16.10            | 25.00  | 12.00             | Replace            | 0                    | 0                           | Not Give   | •     |
| One<br>Time<br>Key<br>In  | Main            |         |                    | BUMPER<br>REINFORCEMENT<br>REAR      | :1    | 205.70                    | 205.70           | 25.00  | 154.27            | Replace            | 0                    | 0                           | Check      | 1.0   |
| One<br>Time<br>Key<br>In  | Main            |         |                    | ARM SUB-ASSY,<br>RR BUMPER LH        | 1     | 139.50                    | 139.60           | 25.00  | 104.70            | Replace            | 0                    | 0                           | Check      |       |
| One<br>Time<br>Key<br>In  | Main            |         |                    | ARM SUB-ASSY,<br>RR BUMPER RH        | 1     | 139.60                    | 139.60           | 25.00  | 104.70            | Replace            | 0                    | 0                           | Check      | •     |
| One<br>Time<br>Key<br>In  | Main            |         |                    | ANTENNA,<br>ELECTRICAL<br>LOWER REAR | *     | 157,40                    | 157.40           | 10.00  | 141.66            | Replace            | 0                    | 0                           | Check      |       |
| One<br>Time<br>Key<br>In  | Main            |         |                    | SENSOR<br>REVERSE                    | ti    | 180.00                    | 180.00           | 0.00   | 180.00            | Replace            | 0                    | 0                           | Check      |       |
| Orie<br>Time<br>Key<br>In | Main            |         |                    | PIXEL STICKER                        | 2     | 60.00                     | 120.06           | 0.00   | 120.00            | Replace            | 2                    | 129.00                      | Replace    | ٠     |

| Total Spare Part Coat | 1,475.24 | Surveyor               | 120.00 |
|-----------------------|----------|------------------------|--------|
| Lump Sum Discount (%) | 20.00    | Lump<br>Sum Dis<br>(%) | 20     |
| Final Spare Part Cost | 1,180.19 | Final Sur              | 96.00  |

|                          |                 |         |                    | SMRT Recom                    | menda | ition                      |                   |           |                   |         |                        | Surveyor Appro             | rvaf         |     |
|--------------------------|-----------------|---------|--------------------|-------------------------------|-------|----------------------------|-------------------|-----------|-------------------|---------|------------------------|----------------------------|--------------|-----|
| - ISOM Type              | Costing<br>Type | Portion | Material<br>Number | Part Name                     | Qty   | List Price<br>Per Unit(\$) | List<br>Price(\$) | Dis(%)    | Final<br>Price(5) | Repaix! | Surveyor<br>Quantity   | Surveyor Final<br>Price(5) | Repair/Repla | ice |
| One<br>Time<br>Key<br>In | Main *          |         |                    | BUMPER LIP<br>REAR            | 1     | 228.90                     | 228.90            | 25.00     | 171,68            | Replace | 0                      | 0                          | Check        |     |
| One<br>Time<br>Key<br>In | Main            |         |                    | BUMPER SIDE<br>RETAINER RR/LH | 1     | 94.80                      | 94.80             | 25.00     | 71.10             | Replace | 0                      | 0                          | Not Give     | •   |
| One<br>Time<br>Key<br>In | Main            |         |                    | BUMPER SIDE<br>RETAINER RR/RH | 1     | 94.80                      | 94.80             | 25.00     | 71.16             | Replace | 0                      | 0                          | Not Give     |     |
|                          |                 |         |                    |                               |       | 7                          | otal Spare        | Part Cost | 1,475.24          |         | Surveyor<br>Total      | 120.00                     |              |     |
|                          |                 |         |                    |                               |       | Lum                        | p Sum Disc        | count (%) | 29.00             |         | Lump<br>Sum Dia<br>(%) | 20                         |              |     |
|                          |                 |         |                    |                               |       | *                          | inal Spare        | Part Cost | 1,180.19          |         | Final Sur<br>Total     | 96.00                      |              |     |

## Labour's Cost Detail

| S.No.  | Job Scope              | SMRT<br>Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|------------------------|----------------------------|-------------------------|---------|
| 1      | TO REPAIR REAR PORTION | 338.00                     | 150                     |         |
| Total: |                        | 338.00                     | 150.00                  |         |

## Spray Cost Detail

| S.No.  | Job Scope              | SMRT<br>Recommendation(S) | Surveyor Adjustment(5) | Remarks |
|--------|------------------------|---------------------------|------------------------|---------|
| 31     | TO REPSRAY REAR BUMPER | 378.00                    | 200                    |         |
| 2      | TO RESPRAY BUMPER BEAM | 180.00                    | 0                      |         |
| Total: |                        | 558.00                    | 200.00                 |         |

### Other Cost Detail

| S.No.  | Job Scope                               | SMRT<br>Recommendation(5) | Surveyor Adjustment(\$) | Remarks |
|--------|---|---------------------------|-------------------------|---------|
| 1.     | TO CHECK WIRING AND SYSTEM FUNCTION     | 80.00                     | 0                       |         |
| 2      | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00                    | 60                      |         |
| 3      | TO WASH AND VACUUM                      | 60.00                     | 8                       |         |
| Total: |   | 260,00                    | 60.00                   |         |

# Summary

|                          | Estimator Assesment(S) | Surveyor Assesment(5)            |
|--------------------------|------------------------|----------------------------------|
| -Total Spare Part Detail | 1,180.19               | 96.00:                           |
| Total Labour Cost        | 338.00                 | 150.00                           |
| Total Spray Painting     | 558.00                 | 200.00                           |
| Other                    | 260.00                 | 60.00                            |
| Overall Total            | 2,336.19               | 506,00                           |
| Lump Sum Repair Option   |                        |                                  |
| Lump Sum Total           | 2,360.00               | 506.00                           |
| Surveyor Approved Amount |                        | 506.00                           |
| No of Repair Days*       | 3                      | ž                                |
| Remarks                  | 8                      | resurvey after repair / Jump sum |
| Surveyor Name            |                        | Pasul                            |
| Signature                | <u>6</u> }             | Rasul                            |
|                          |                        | Save Clear                       |
| Survey Date              | 26/11/2018             |                                  |

# Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)

Sent: Tuesday, 9 April 2019 3:41 PM

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Cc: Admin A

Subject: RE: URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL

8406E (your insured) Our Ref: TAX/11/18/2090/lg

Importance: High

# 'WITHOUT PREJUDICE' SAVE AS TO COSTS

Our Ref: CC3/AIG18021460/R1fb3

Your Ref: TAX/11/18/2090/lg

Dear Lee Gek,

We refer to above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of \$1,310.00(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: <u>pohkin@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

# Poh Kin (LKKAuto)

From:

Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>

Sent:

Wednesday, 17 April 2019 3:11 PM

To:

Poh Kin (LKKAuto)

Cc:

Admin A

Subject:

URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E

(TURS)

(your insured) Our Ref: TAX/11/18/2090/lg

Attachments:

img-417135616-0001.pdf

Dear Poh Kin,

Your offer of \$1,310.00 is unacceptable.

We have checked with our workshop and they confirmed that our taxi was surveyed by Rasul on 26/11/18 (please refer to the attachment). No records of any survey done by Naz on 23/11/18. Finalisation is also done by Rasul.

We are prepared to accept a global sum of \$1,730.00 as follows:-

| Total          | \$1733.43 |   |     |        |          |   |
|----------------|-----------|---|-----|--------|----------|---|
| LTA Search Fee | \$7.00    |   |     |        |          |   |
| Loss of Income | \$75.00   | ( | 1.5 | days x | \$50.00  | ) |
| Loss of Rental | \$801.43  | ( | **7 | days x | \$114.49 | ) |
| Cost of Repair | \$850.00  |   |     |        |          | _ |

3+3612 = 29021 18004-> Pgay, CM1.

Rounded up to a global sum of \$1,730.00.

Please reconsider your offer and let us hear from you soon. Thanks.

\*\* 3 working days + 4 days of delay (we notified your office of PRS on 23/11/18 at 8.22am and our taxi was surveyed on 26/11/18 at 4.34pm).

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]

Sent: 09/04/2019 15:41

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Cc: Admin A

Subject: RE: URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured) Our

Ref: TAX/11/18/2090/lg Importance: High

### 'WITHOUT PREJUDICE'

# Khanchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Friday, 6 September 2019 4:29 PM

To:

'Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)'

Cc:

Admin A

Subject:

RE: URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E

(your insured) Our Ref: TAX/11/18/2090/lg

Tracking:

Recipient

Delivery

Tan Lee Gek (Auto Svcs/Claims & IA/Claims &

(A/Taxis)

Admin A

Meikwan@lkkauto.com olivialau@lkkauto.com Delivered: 6/9/2019 4:29 PM

Delivered: 6/9/2019 4:29 PM

shupei@lkkauto.com

Delivered: 6/9/2019 4:29 PM

## Without Prejudice

Dear Sir/Madam,

We refer to the above matter.

We propose settlement at global sum of \$1,479.00(all in) on this matter.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) < LeeGek@smrt.com.sg>

Sent: Wednesday, 17 April 2019 3:11 PM

To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your

insured) Our Ref: TAX/11/18/2090/lg

## Khanchna (LKK Auto)

From:

Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>

Sent:

Thursday, 12 September 2019 11:22 AM

To:

Khanchna (LKK Auto)

Cc:

Admin A

Subject:

Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured) Our Ref.

TAX/11/18/2090/lg

Dear Khanchna,

Your offer of \$1,479.00 is unacceptable. In a final gesture to resolve the matter, we are prepared to accept a global sum of \$1,700.00 (LOR at 7 days - 3 + 4 days delay).

Please reconsider your offer and let us hear from you soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: 06/09/2019 16:29

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Cc: Admin A

Subject: RE: URGENT / REMINDER Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured) Our

Ref: TAX/11/18/2090/lg

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.

We propose settlement at global sum of \$1,479.00(all in) on this matter.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

# Khanchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Tuesday, 24 September 2019 4:23 PM

To:

Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Cc:

Admin A

Subject:

RE: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured) Our Ref:

TAX/11/18/2090/lg

## Without Prejudice

Dear Sir/Madam,

We refer to the above matter.

We propose settlement at global sum of \$1,593.00(all in) on this matter.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** email: <u>Khanchna@lkkauto.com</u>Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) < LeeGek@smrt.com.sg>

Sent: Thursday, 12 September 2019 11:22 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured) Our Ref:

TAX/11/18/2090/lg

Dear Khanchna,

Your offer of \$1,479.00 is unacceptable. In a final gesture to resolve the matter, we are prepared to accept a global sum of \$1,700.00 (LOR at 7 days - 3 + 4 days delay).

Please reconsider your offer and let us hear from you soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

## Poh Kin (LKKAuto)

From:

Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

<LeeGek@smrt.com.sg>

Sent:

Tuesday, 8 January 2019 12:22 PM

To:

CS A Team; Admin A

Subject:

LOD Re: Accident on 20/11/2018 involving SHB 765X & SLL 8406E (your insured)

Our Ref: TAX/11/18/2090/lg

Attachments:

11 18 2090 - LOD.pdf

Dear All,

We quantify our claim as follows:-

| Total          | \$1920.16 |   |       |        |          |   |
|----------------|-----------|---|-------|--------|----------|---|
| LTA Search Fee | \$7.00    |   |       |        |          |   |
| Loss of Income | \$90.00   | ( | **1.5 | days x | \$60.00  | 1 |
| Loss of Rental | \$973.16  | ( | 8.5   | days x | \$114.49 | ) |
| Cost of Repair | \$850.00  |   |       |        |          | _ |

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search
- 6) Vehicle attachment history

Please let us have your offer soon. Thanks.

\*\* our hirer took a courtesy taxi on 23/11/18 at 3.26pm (please refer to the vehicle attachment history).

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





51 UBLAVE 1, #01-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 67414108

#### Our Ref: CC3/AIG18021460/R1kb3

08th March 2019

NG CHENG TEE Apt Blk 139 Bishan Street 12 #04-478 Singapore 570139

Dear Sir/Madam,

# ROAD TRAFFIC ACCIDENT INVOLVING NOS, SLL8406E AND SHB765X ALONG ORCHARD ROAD IN FRONT OF PLAZA SINGAPURA ON 20.11,2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the video footage, accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong Case Handler DID: 6841 2132 FAX: 6741 4108

Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

# AUTHORISATION TO ACT

We, <u>SMRT TAXIS PTE LTD</u> ("the third party claimant") of <u>No. 60 Woodlands Industrial Park E4, Singapore 757705</u> (address), owner of <u>SHB 765X</u> (vehicle no.) hereby authorize <u>SMRT Automotive Services Pte Ltd</u> ("the workshop") to act for us with respect to our claim for repair costs and/or rental and/or loss of use ("claim") for our vehicle no. <u>SLL 8406E</u> was damaged pursuant to the accident which occurred on <u>20/11/2018</u> (date) along <u>Orchard Road in front oc Plaza Singapura</u> (location) involving vehicle no/s. <u>SHB 765X</u> ("the accident").

I further authorize the workshop to settle the above mentioned claim in a manner as they deem fit and the cheque is to be made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 10 (day) of 60 (month) 2019 (year)

Signed by "the third party claimant" (with company stamp if applicable) STATE OF STA

Signed by "the workshop" (with company stamp)

# RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS1,593.00(Global Sum) for vehicle no. SHB765X that was damaged pursuant to the accident which occurred on 20/11/2018 (date) along ORCHARD ROAD IN FRONT OF PLAZA SINGAPURA (location) involving vehicle no/s SLL8406E.

This is pursuant to the inspection conducted on 26/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>SMRT TAXIS PTE LTD</u> ("the third party claimant") of vehicle no. <u>SHB765X</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to <a href="SHB765X">SHB765X</a> (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_ (day) of \_\_\_\_ (month) 20 19 (year)

MRB

Signed by appointed surveyor

A THE STANK

Signed by "the workshop" (with chop)

This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date.

Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim ansing of the subject matter in this action.



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705



SNRT Automotive Services Pte Ltd 251 North Bridge Road Singapore 179102 Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

GST Reg No. : MR-8500001-7 CRN : 199004280Z Invoice No. : IV181200519 Date : 26.12.2018 Vehicle No. : SHB765X

Your Ref No. : TAX/11/18/2090

Our Ref No. : 24098857 Terms : 30 Days

| Description  | Qty  | Unit | Add | 1    | (Discoun<br>Amount | <u>t)</u> | Amount |
|--|------|------|-----|------|--------------------|-----------|--------|
| LUMP SUM AMOUNT FOR REPAIR<br>AS PER SURVEYOR'S RECOMMENDATION | 1.00 |      |     |      |                    | s         | 850.00 |
|  |      |      | G   | RAND | TOTAL              | ş         | 850.00 |

#### Remark :

Make/Model : TOYOTA PRIUS Accident Date : 20.11.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'. No receipt will be issued unless requested.

Authorised Signature

for SMRT Automotive Services Pte Ltd

Page 1/1

E. & O.E



### SMRT Taxis Pte Ltd

### MEMORANDUM

To:

Claims Dept

Our Ref:

TAX/11/18/2090

From:

SMRT Taxis Pte Ltd

Date:

03/12/2018

ACCIDENT INVOLVING SHB 765X & SLL 8406E ON 20/11/2018 ALONG ORCHARD ROAD

This is to confirm that the daily rental rate for SHB 765X is \$114.49 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely SMRT-TAXIS PTE LTD

for Manager



Laid Up Report

Accident Start Date: 01/11/2018

Accident End Date : 12/12/2018

Date Generated: 13/12/2018 User Name : LeeGek

| Date and Time<br>(Repair Completed) | 30/11/2018 1:52 PM  |
|-------------------------------------|---------------------|
| Date and Time<br>(Accident Repair)  | 22/11/2018 10:00 AM |
| Job Card Number                     | 24098857            |
| Vehicle Model                       | BARNS               |
| Vehicle Make                        | TOYOTA              |
| Company Type                        | SMRT Taxis Pte Ltd  |
| Vehicle Registration                | SHB765X             |
| Case Reference Number               | TAX/11/18/2090      |

3 December 2018



SMRT TAXIS PTI

Woodlands Industrial Pari Singapore Tel: 65 647 Fax: 65 636 www.smd.

| Vehicle Num | Vehicle Make | Vehicle Model | Attachment<br>Type | Attachment Start<br>Date Time | Attachment End Date<br>Time | Return Reaso |
|-------------|--------------|---------------|--------------------|-------------------------------|-----------------------------|--------------|
| SHB765X     | TOYOTA       | PRIUS         | MAIN               | 23/10/2018 02:30 PM           |                             |              |
| SHC4514Y    | TOYOTA       | PRIUS         | COURTESY           | 23/11/2018 03:26 PM           | 30/11/2018 05:15 PM         |              |

Vehicle Attachment History of YEO KHEE SENG (S6944903D)

Find | Next

>

# THE Enquire Transaction History

Log Date/Time:

home a transfer transportation 22 Nov 2018 / 12:37:40

Asset Type:

Vehicle

Transaction Amount:

\$7.49

Asset ID:

SLL8406E

HALIL

Transaction Type:

18.32 Insurance Enquiry (GIRO Payment) Channel:

External Agency

User ID:

ESASBAHO - BALQISH BINTE ABDUL

**Business Transaction** Reference No.:

20181122123740690400

Search Oate / Time:

20 Nev 2018 20:08:00

Insurance Company:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

**Enquire Related Logs** 

Back to List

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

| Case                            | Notified                 | Est Submitted    | Adj Assigned                         | Adj Rpt               |                       | Adj Submitted Ins Auth'ed |   | Status                                   |            |  |         |
|---------------------------------|--------------------------|------------------|--------------------------------------|-----------------------|-----------------------|---------------------------|---|--|------------|--|---------|
| Main                            | 21 Nov 2018<br>fidit Reg |                  | 26 Nov 2018<br>00:00<br>Edit Adj Rpt | \$\$850.0<br>Edit Est | Searce   Chicago VIII |                           | Pending for Surv<br>Report<br>Cancel Case |  | vey        |  |         |
|                                 | Main                     | R                | eference                             |                       | laim Det              | alls                      |   | Documents                                |            | Sho                                    | IIA w   |
| CLAIM SI                        | BFOLDER DE               | TAILS            |                                      |                       |                       |                           | [Created i                                | by adjuster]                             |            |  |         |
| Insured:                        | NG CHEN                  | G TEE, ID: 5013  | 3705Z                                |                       |                       |                           |   |  |            |  |         |
| Main<br>Claimant:               | SMRT TAX                 | CIS PTE LTD, C   | o. Reg. No.: 19890:                  | 5369K                 |                       |                           |   |  |            |  |         |
| Vehicle Re<br>No.:              | SHB765                   | x                |                                      |                       | Date of i             | Loss:                     |   | 3 20:00 - :59<br>and <b>10</b> Days Fron | LTA Res    | Date (Mar                              | Yr)]    |
| Claim Type                      | TP / 980                 | 6265681SG        |                                      |                       | Policy/Co<br>Note No. |                           | f 2100503224 (Comprehensive)              |  |            |  |         |
| Vehicle Re<br>No.<br>(Insured): | SLL84068                 | ı                |                                      |                       | Policy No<br>(Claimar |                           | D-18090213MFSH                            |  |            |  |         |
|                                 |                          |                  |                                      |                       | Excess:               |                           |   |  |            |  |         |
| Repairer:                       | SMRT Aut                 | tomotive Service | s Pte Ltd (Woodl                     | inds) 60 W            | oodlands              | Indust                    | trial Park E4,                            | 757705 Woodland                          | s - Tel: 6 | 8662628                                |         |
| Handling<br>Insurer:            | AIG Asia                 | Pacific Insuranc | e Pte. Ltd. (Expre                   | ss) - Tel: 6          | 5-6419-30             | 000                       | . [Handled b                              | y Foo, Chit Yan] C                       | hityan.Fo  | oo@aig.com                             | 1       |
| Claimant's<br>Insurer:          | MS First (               |                  | e Ltd (HQ) - Tel: 6                  |                       |                       |                           |   |  |            | 77 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |         |
| Adjuster:                       | LKK Auto                 | Consultants Pte  | Ltd (HQ) - Tel: 67                   | 56-3561               | [Handled              | by M                      | OHD RASU                                  | L] [Final Rpt                            | due 07     | /12/2018                               |         |
| ASSOCIA                         | TED MAIL RE              | CEIVED           |                                      |                       |                       |                           |   | View                                     | All        | Compose Ca                             | ise Mai |
| There are                       | no mail for this         | Case.            |                                      |                       |                       |                           |   |  |            |  |         |
|                                 |                          |                  |                                      |                       |                       |                           |   |  |            |  |         |
| ALL ASS                         | OCIATED TAS              | KS-              |                                      |                       |                       | 1                         | View All                                  | Search Tasks Cr                          | eate New   | Task C                                 | omplet  |
| Due Da                          |                          | Type Task        | Group Subje                          | ct Hand               | ler A                 | ssign                     | ned By                                    | Completed On                             | Crea       | ited On                                | Done    |

### Claim Documents

\*SHB765X (98062656815G) [SLL8406E]
TP
SMRT TAXIS PTE LTD Nov 20 2018 8:00PM [NG CHENG TEE] **SMRT Automotive Services Pte Ltd** 

| Lett | ers/Corresponder                  | ces  | 1 per | page 🔻                | 80   |
|------|-----------------------------------|--|-------|-----------------------|------|
| No   | Finalized On                      | LKK Auto Consultants Pte Ltd (HQ)  |       | Thumbnail             | Prin |
| 1    | (Draft)                           | Third Party Express Settlement - Payment Breakdown   | 0     | Edit                  |      |
| Pho  | tos/Images                        |  | 3 per | page 🔻                | V    |
| Na   | Relabel/Reorder                   | LKK Auto Consultants Pte Ltd (HQ)  | T     | Thumbnall             | Prin |
| 1    | 13/02/19 15:08                    | Chassis Number   | 0     | Load JPG              | V    |
| 2    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 3    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 4    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 5    | 13/02/19 15:08                    | General View   | 6     | Load JPG              | 80   |
| 6    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | W    |
| 7    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 8    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | 12   |
| 9    | 13/02/19 15:08                    | General View   | 0     | Load JPG              | Ø    |
| 10   | 13/02/19 15:08                    | General View   | 6     | Load JPG              | Z    |
| 11   | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 12   | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 13   | 13/02/19 15:08                    | General View   | 0     | Load JPG              | Z    |
| 14   | 13/02/19 15:08                    | General View   | 0     | Load JPG              | V    |
| 15   | 13/02/19 15:08                    | General View   | 0     | Load JPG              | B    |
| 16   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | V    |
| 17   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | P    |
| 18   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | Ø    |
| 19   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | 12   |
| 20   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | K    |
| 21   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | V    |
| 22   | 13/02/19 15:08                    | Reinspection Photo   | 0     | Load JPG              | V    |
| 23   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | 2    |
| 24   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 25   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 26   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 27   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | 2    |
| 28   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 29   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 30   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 31   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
| 32   | 13/02/19 15:09                    | Reinspection Photo-after repair photo  | 0     | Load JPG              | V    |
|      |                                   |  |       |                       |      |
| Doc  | cumentation                       | FIRST STATE OF THE | 1 per | -                     | V    |
| No.  | Relabel/Reorder<br>28/11/18 19:18 | LKK Auto Consultants Pte Ltd (HQ) TP ESTIMATE- MARKED  | 0     | Thumbnall<br>Load PDF | Prin |
| 2    | 28/11/18 19:18                    | TP GIA REPORT  | ő     |                       |      |
| 3    | 11/10/19 14:49                    | LETTER TO OI   | 0     |                       |      |
| 4    | 24/10/19 09:43                    | WORKSHOP INVOICE   | 0     |                       |      |
| 5    | 24/10/19 09:43                    | AUTHORISATION TO ACT FORM  | 0     | Load PDF              | -    |
| 6    | 24/10/19 09:43                    | Release Voucher  | 0     | Load PDF              | -    |

| Lett | tters/Correspondences |   | 1 per page |           |       |
|------|-----------------------|---|------------|-----------|-------|
| No   | Finalized On          | LKK Auto Consultants Pte Ltd (HQ)         |            | Thumbnall | Print |
| 7    | 24/10/19 09:43        | RENTAL RECEIPT                            | 0          | Load PDF  |       |
| 8    | 24/10/19 09:43        | RENTAL MILEAGE                            | 8          | Load PDF  |       |
| 9    | 24/10/19 09:43        | LTA SEARCH                                | 0          | Load PDF  |       |
| 10   | 24/10/19 09:43        | LOD                                       | 0          | Load PDF  |       |
| No   | Finalized On          | AIG Asia Pacific Insurance Pte. Ltd. (SG) |            | Thumbnail | Print |
| 1    | 29/11/18 10:05        | OI GIA REPORT                             | 6          | Load PDF  |       |

# **Documents Checklist**

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)  |       |      |       |
|  |       |      | ^     |
|  |       |      | ~     |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties. |       |      |       |

| NOTE: TO | BE COMP  | FTFD BY    | SURVEYOR |
|----------|----------|------------|----------|
| NOTE: IC | DE CUMPI | LE I ED DI | SOLATION |

| TEAM |   |  |   |   |
|------|---|--|---|---|
|      | _ |  | _ | _ |

# THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| Vehicle No:  | SLL8406E (Insd veh)            |                   | Model: | Į,                   | TOYOTA PRIUS TAXI 1.8 (A) |                             |  |  |
|--|--------------------------------|-------------------|--------|----------------------|---------------------------|-----------------------------|--|--|
|  | SHB765X (TP veh)<br>20/11/2018 |                   |        |                      |                           |                             |  |  |
| Date of Accident:                                      |                                |                   |        |                      |                           |                             |  |  |
|  |                                |                   |        |                      | _                         |                             |  |  |
| Global Sum Settler                                     | nent :                         | [X] Yes           |        | [ ] No               | 1                         |                             |  |  |
| Repair Estimate  |                                |                   | : \$   | 3,542.7              | 1                         |                             |  |  |
| Final Repair Cost                                      |                                |                   | : \$   | 1,593.00             |                           |                             |  |  |
| Loss of Use  |                                |                   | :\$    |                      | 1                         | .00 days at \$50.00 per day |  |  |
| Rental (if any)  |                                |                   | : \$   |                      | 6                         | days                        |  |  |
| LTA / GIA Search I                                     | Fee                            |                   | : \$   |                      |                           |                             |  |  |
| Others:  |                                |                   | : \$   |                      |                           |                             |  |  |
| grafit and a   |                                |                   | : \$   |                      | 1                         |                             |  |  |
| Final Settlement S                                     | um (Glob                       | al Sum)           | : 5    | 1,593.00             |                           |                             |  |  |
| For Non GIA I     For GIA Regis                        | stered W                       | orkshop:          |        | Assessed Liab        | ility (*)                 | s/ No BOLA Scenario No:(%)  |  |  |
|  |                                |                   | or che | in collisions and fo | r case.                   | s where BOLA does not apply |  |  |
|  |                                |                   | or che | in collisions and fo | or case.                  | s where BOLA does not apply |  |  |
| * Assessed Lit   | ability to                     | be filled only fo |        | in collisions and fo | or case.                  |                             |  |  |
| * Assessed Lie<br>Remarks                              | ion: Pay                       | be filled only fo |        | . <b>\$</b>          | or case.                  | s where BOLA does not apply |  |  |
| * Assessed Lie Remarks Payment Instruct                | ion: Pay                       | be filled only fo |        | : S                  | or case.                  |                             |  |  |
| * Assessed Lie Remarks Payment Instruct  1) SMRT Taxis | ion: Pay                       | be filled only fo |        | . <b>\$</b>          | or case.                  |                             |  |  |

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

Date

LKK Auto Consultants Pte Ltd

# LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

CC3/AIG18021460/R1KB3Q2 Our File No:

Date: 24/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100503224

Claimant Vehicle No:

SHB765X

Insured Vehicle No: SLL8406E

Date of Loss:

20/11/2018

Nature of Claim:

TP

Claim No: 9806265681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHB765X

Make & Model:

TOYOTA PRIUS TAXI, 1.8 (A)

Engine No:

2ZR1461874

0 km

Reg. Date:

10/12/2014 (Man. Year: 2014)

Chassis No: Odometer:

JTDKN36U305753496

Colour:

Maroon

Engine Capacity: Market Value/New Car 1798 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

195/65 R15

Rear Tyre Size:

195/65 R15

Front Tyre Size: Front Left Side:

Falken 5 mm

Rear Left Side:

Falken 5 mm

Front Right Side:

Falken 5 mm

Rear Right Side:

Falken 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |  | Repairer's         | Adjuster's | Difference | Diff % |
|---------------------|--|--------------------|------------|------------|--------|
| Parts               |  | 2,206.71           | 454.28     | 1,752.43   | 79.41  |
| Miscellaneous Items |  | 0.00               | 0.00       | 0.00       |        |
| Labour              |  | 1,336.00           | 510.00     | 826.00     | 61.83  |
| Paintwork Labour    |  | 0.00               | 0.00       | 0.00       |        |
| Towing              |  | 0.00               | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$)             | 3,542.71           | 964.28     | 2,578.43   | 72.78  |
| A                   | approved Total (Overridden) (S\$)        |                    | 850.00     |            |        |
|                     | Nett Amount (S\$)                        | 3,542.71           | 850.00     | 2,692.71   | 76.01  |
|                     | + Loss of Use (1.0 x S\$50.00/day) (S\$) |                    | 50.00      |            |        |
|                     | + Car Rental (6.0 x S\$1                 | 14,49/day) (S\$)   | 686.94     |            |        |
|                     | + Doc/S                                  | earch Fee (S\$)    | 7.00       |            |        |
|                     | Ne                                       | tt Liability (S\$) | 1,593.94   |            |        |
|                     | Global Sum Settlement (S\$)              |                    | 1,593.00   |            |        |
|                     |  | _                  |            |            |        |

INSPECTION

Date of Assignment:

26/11/2018

Date Inspected:

26/11/2018 Inspected At:

1 KAKI BKT AVE 6 #01-58

Repairer:SMRT Automotive Services

Pte Ltd (Woodlands)

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

# Recommended Parts

| No.  | Qty       | Part No. | Particulars                           | Condition         | Repairer's | Amount    |
|------|-----------|----------|---------------------------------------|-------------------|------------|-----------|
| 1    | 1         |          | *BUMPER REINFORCEMENT REAR (DISC 25%) | Deformed          | 205.70 F   | *154.28 F |
| 2    | 1         |          | *SENSOR REVERSE (SN)                  | Shorted           | 180,00 F   | *180.00 F |
| 3    | 2         |          | *PIXEL STICKER (SN)                   | Necessary         | 120.00 F   | *120.00 F |
| 4    | 1         |          | *BUMPER REAR                          | Repair            | 458.60 F   | *-F       |
| 5    | 1         |          | *BUMPER LIP REAR                      | Serviceable       | 228.90 F   | *-F       |
| 6    | 1         |          | *BUMPER CLIPS                         | Not Necessary     | 1.61 F     | *-F       |
| 7    | 1         |          | *BUMPER REINFORCEMENT REAR            | Not Necessary     | 205.70 F   | *-F       |
| 8    | 1         |          | *ARM SUB-ASSY ,RR BUMPER LH           | Not Necessary     | 139.60 F   | *-F       |
| 9    | 1         |          | *ARM SUB-ASSY ,RR BUMPER RH           | Not Necessary     | 139.60 F   | *-F       |
| 10   | 1         |          | *ANTENNA ,ELECTRICAL LOWER REAR       | Not Necessary     | 157.40 F   | *-F       |
| 11   | 1         |          | *SENSOR REVERSE                       | Not Necessary     | 180.00 F   | *-F       |
| 12   | 1         |          | *BUMPER SIDE RETAINER RR/LH           | Not Necessary     | 94.80 F    | *- F      |
| 13   | 1         |          | *BUMPER SIDE RETAINER RR/RH           | Not Necessary     | 94.80 F    | *-F       |
| F=Fn | anchise p | part.    |                                       | Total Parts (S\$) | 2,206.71   | 454.28    |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No  | Particulars                            | Lab.Type               | Repairer's | Amount |
|-----|--|------------------------|------------|--------|
| Lab | our Items                              |                        |            |        |
| 1   | PANEL BEATING & BODY WORK              | New                    | 338.00     | 150.00 |
| 2   | SPRAY PAINT                            | New                    | 738.00     | 300.00 |
| 3   | TO CHECK WIRING AND SYSTEM FUNCTION    | New                    | 80.00      | 0.00   |
| 4   | TO TESTAND REFIX REVERSE SENSOR SYSTEM | New                    | 120.00     | 60.00  |
| 5   | TO WASH AND VACUUM                     | New                    | 60.00      | 0.00   |
|     | Gross La                               | bour Cost (S\$)        | 1,336.00   | 510.00 |
|     | Report was unsubmitted of              | during this print-out. |            |        |

< END OF ESTIMATES >