

CC³ / CTI 180 2468, Klap³LKK:
IDAC:

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : 8BE 1188K

Name of Insured :

Insured Tel No. : HP:

Excess Sec II :SS D.O.A: 26/11/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHA 3924P

INSRS: 006E 10404.
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

SHA 3924P - X.
8BE 1188K - 06/11/16 0498X / App352 : DOA 23/11/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

08/11/21

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop no: _____

at _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No:

SHA 3924P

Yr Regn:

30 Apr 2011

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. / Prime Mover /

Truck / Trailer or

Make:

Hyundai Santa

C.C.

1997

Colour:

Blue

A/C:

Ins. C. / Std / NI / NA

Sp. Reading

778110

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHET41VMB A810.72

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

26/4/11

D.O.I.

27/4/11

Survey held at

CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CTI
4/5

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305244009

TOMER

COMFORT TRANSPORTATION PTE LTD

VS 7010045

TOMER NO. 383 SIN MING DRIVE

RESS Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.: SHA3924P

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL SONATA

DATE/TIME IN 26.11.2018 12:45

YR OF MANU 30.04.2011

TARGET DATE

CHASSIS CODE KMHE41VMB810072

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 26.11.2018


NATURE: 3P 26.11.2018 -C

S/NO

LABOR CODE

DESCRIPTION

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

re:

Vehicle No.: SHA3924P CHIANG

Vehicle No.: SHA3924P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 3924P

MAKE :

MODEL : HYUNDAI SONATA

DATE 26/11/2018 14:17

got 5 mths old

China

China

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge X			\$ 136.30
	Front Bumper Reinforcement X			\$ 504.10
	Front Bumper Grille (LH) X			\$ 17.60
	Front Bumper Bracket Top (LH) X			\$ 22.40
	Front Bumper Protector (LH) X			\$ 29.20
	Headlamp (LH) ✓			\$ 797.90
	Front Fender (LH) X repair			
	SUB TOTAL			\$ 2,046.30
	LESS 20%			\$ 409.26
	DISCOUNTED TOTAL			\$ 1,637.04
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 400.00 200
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,837.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Kalvin 10/11/18
 27/11/18 11:15 hrs
 2 days
 4/5
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance

Acknowledged by Repairer
 Signature: _____
 Date: _____

Remarks: