

ASS. REC. BY:

REF CS/AGI1802/482/Gsd3er2

Special Instruction:

Surveyor:

GO

ASSIGNMENT (Office)

From (Person):

Albert Hong

of

AGI

Date/Time:

28/11/18 @ 9:49am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 3654B

Insured:

SJR 6357T

at Workshop m/s

Ban Hock Hin

Tel:

6281 6520

of

No-6 De fu lane 4

Policy No:

Claim No:

C10002283

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/1/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:37am @ 28/11/18

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBM 3654B-X
	SJR 6357T-X

Summit

Xhd.

REF: AGI

ASSIGNMENT

(-2023)

From: _____ Date: **28/11/18**

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **FBM3654B**

at Workshop m/s: **Bun Hock Hin**

of: **No. 6 Defu Lane 4**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **FBM3654B** Yr Regn: **08 Aug 2008**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Yamaha X-1R** c.c: **135**

Colour: **Black** A/C: **Insured / Std / NI / NA**

Sp. Reading: **45354** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **45320 3150**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **80/90-17**

(New) R: **70/90-17**


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **(FA)**

Front	Rear
R/Bal. 4 mm	R/Bal. 4 mm
L/Bal. 4 mm	L/Bal. 4 mm
D.O.A. _____	D.O.I. 28-11-18

Survey held at: **n/s** **5:30pm**

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or **and**

The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **lup**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
28/11	Finalised \$1397.12 with Raymond.
11/12/18	Confirmed p/p \$1,397.12 @ 3 days with Guo Qiang. (\$50.00 Rd - 4%)

RECEIVED 12 DEC 2018

[Signature]
11/12/2018

Date/Time File Pass to? **12/12/18**

1) **Typist** : Preli. Report : Final Report

Date/Time File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ **1,397.12 p/p**)

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee: **250**

Transportation: _____ \$ + RD. _____ \$

Photos: _____

Others: _____

ADD Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

TOTAL **250**

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Wednesday, 28 November 2018 9:49 AM
To: 'assignments'
Cc: 'SUR'
Subject: Appoint LKK to conduct TP survey; Our Ref: C10002283
Attachments: 11216_Claim File.pdf

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg



Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Raymond <raymond@bhh.com.sg>
Sent: Wednesday, 28 November, 2018 9:02 AM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: Accident Involving FBM3654B & SJR6357T on 21/11/2018

Dear Albert,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for the pre-repair survey tomorrow.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3874C
Vehicle Details	
Vehicle No.:	FBM3654B
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	4S3203150
Chassis No.:	4S3203150
Maximum Power Output:	-
Open Market Value:	\$1,802.00
Original Registration Date:	08 Aug 2008
First Registration Date:	08 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$271.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2023
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,410.00
COE Rebate Amount:	\$3,199.00
Total Rebate Amount:	\$3,199.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
Transfer of ownership or deregistration is not allowed for this vehicle.	

The information contained herein is correct as at 29 Nov 2018

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details			
Vehicle No.:	FBM3654B		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	YAMAHA		
Vehicle Model:	X-1R		
Chassis No.:	4S3203150		
Propellant:	Petrol		
Engine No.:	4S3203150		
Engine Capacity:	135 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	-		
Unladen Weight:	105 kg		
Year Of Manufacture:	2008		
Original Registration Date:	08 Aug 2008		
Lifespan Expiry Date:	-		
COE Category:	D - Motorcycle		
PQP Paid:	\$3,410.00		
COE Expiry Date:	07 Aug 2023		
Road Tax Expiry Date:	30 Jan 2019		
Inspection Due Date:	30 Jan 2019		
Intended Transfer Date:	28 Nov 2018		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 30 Jan 2019. You may renew the road tax from 31 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 30 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 31 Jan 2019 to 30 Jul 2019)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	36.00	-	36.00
Total Amount Payable:			61.00
Message			
Transfer of ownership is not allowed for this vehicle.			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: Raymond <raymond@bhh.com.sg>
Sent: Tuesday, 11 December 2018 6:03 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'Guo Qiang (LKKAuto)'; 'SUR'
Subject: RE: FBM3654B - After Repair Photos & Finalisation

Dear Shirley,

Noted with thanks.

Best Regards,
Raymond
Ban Hock Hin Co., Pte Ltd
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969 Visit us at <http://www.bhh.com.sg>
Facebook: <http://www.facebook.com/bhhsg>

-----Original Message-----

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 11 December, 2018 6:02 PM
To: 'Raymond' <raymond@bhh.com.sg>
Cc: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FBM3654B - After Repair Photos & Finalisation

Hi Raymond,

Confirmed final fig of \$ 1,397.12 (part by part) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to Budget Direct Insurance.

Thank you.

Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Raymond [<mailto:raymond@bhh.com.sg>]
Sent: Monday, 10 December 2018 2:40 PM
To: 'SUR' <sur@lkkauto.com>
Cc: 'Guo Qiang (LKK Auto)' <GuoQiang@lkkauto.com>
Subject: FBM3654B - After Repair Photos & Finalisation

Dear Guo Qiang,

We attached the after repair photos and finalisation for your perusal.

Parts	- \$ 925.32
IU Meter	- \$ 165.00
Stickers	- \$ 56.80
Spray Paint	- \$ 70.00
Labour	- \$ 180.00

Total - \$1,397.12

3 days Repair

Please confirm.

Thanks & Regards,
Raymond
Ban Hock Hin Co Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2018 14:28
Date Of Accident	21/11/2018 08:30
Exact Location Of Accident	TAMPINES EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM3654B
Insured/Policyholder	
Name Of Registered Owner	NOOR RIDHUAN BIN ROSLAN
NRIC No	S8933874C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96927835
Alternative Phone No	OFFICE-96927835

Vehicle Particulars

Manufacturer	YAMAHA
Model	X-1R-135CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MC/00425667
Cover Note Number	

Driver

Name of Driver	NOOR RIDHUAN BIN ROSLAN
NRIC No	S8933874C
Date Of Birth	20/09/1989
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96927835
Fax Number	
Contact Number	OFFICE-96927835
EMail Address	NOEMAIL

Address	BLK 432A YISHUN AVE 1 #03-519
Postcode	761432
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBAWANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5549999 - FAX NO: 68522499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO TRAFFIC ACCIDENT REPORT NO. T/20181121/2117 ATTACHED.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	DON DONNY SHAKIDON
Phone Number	90098680
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR6357T
Vehicle Make/Model/Colour	KIA / CERATO PORTE / WHITE
Details Of Properties	RIGHT SIDE DOOR
Vehicle Category	PRIVATE CAR
Name of Driver	TAN YONG KANG
NRIC/Passport Number	S8321621B
Contact Number	93652914

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NOOR RIDHUAN BIN ROSLAN
Approximate Age	29
Injuries Sustain	NECK. BACK, HANDS AND LEGS PAINS
Injured person in which vehicle?	FBM3654B
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 432A YISHUN AVE 1 #03-519
Postcode	761432

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 22/11/2018 @ 12:05pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature


Name: Tan Chou Lou

NRIC/FIN No.: G77115235R



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Traffic Accident Report NO. T/20181121/2117 attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 22/11/2018 @ 1:05pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Tan Chwee Loh

NRIC/FIN No.: 97115218



**SINGAPORE
POLICE FORCE**



T/20181121/2117

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20181121/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/11/2018 17:53		Vide Report No.:		Station Diary No.: 61	
Informant's Particulars					
Name of Informant: NOOR RIDHUAN BIN ROSLAN			Address: APT BLK 432A YISHUN AVENUE 1 #03-519 SINGAPORE 761432		
ID Type / ID No.: NRIC NO / S8933874C			Contact No.: Home/Office: Mobile: 96927835		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 20/09/1989	Type of Informant: Rider		
Race: Javanese			Language:		Institution / School Name:
Occupation: Crane operator (port)			Driving Licence Information: Class: 2B,3A		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/11/2018 08:30	Type of Location: Straight Road
Location: Along Road 1 TAMPINES EXPRESSWAY towards Changi before Pasir Ris Dr 12 exit				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: right rear to front			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM3654B	Motorcycle	YAMAHA	X-1R	Black	Seriously Damaged	0
SJR6357T	Car				Seriously Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM3654B	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00425667	31/10/2017	30/01/2019



**SINGAPORE
POLICE FORCE**



T/20181121/2117

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

2 of 3

Report No. T/20181121/2117

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	NOOR RIDHUAN BIN ROSLAN	ID No.	S8933874C
Related Vehicle	FBM3654B (Motorcycle)	Contact No.	96927835
Hospital/Clinic	WELL MEDICAL CLINIC & SURGERY PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,3A Date of Expiry: NIL
Date Treatment	21/11/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 21/11/2018 at about 0830hrs, I was riding FBM3654B along TPE towards Changi before Pasir Ris Dr 12 on the extreme right lane of 4 lanes road. While I was riding a car SJR6357T on my left suddenly cut onto my lane and the right rear portion of the said car hit onto my front tyre and I was unconscious as my head hit onto the car and road. Subsequently I regained consciousness and traffic Police was there. There was no ambulance as the driver of the said car had cancel it. I was advised to lodge a Traffic Police report by the officer.



**SINGAPORE
POLICE FORCE**



T/20181121/2117

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3




Report No. T/20181121/2117

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt ISZAD BIN ISHAK	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/11/2018 17:53
Officer In Charge Of Case: TP / GIT / Sgt 2 LIM HONG LEE Contact No.: 65476438	Classification Of Case: 
Authentication Stamp NP168	Signature:  



QUOTATION

Customer :

NO. : 33306

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
190 CLEMENCEAU AVENUE,
#03-01, SINGAPORE SHOPPING CENTRE,
SINGAPORE 239924

DATE : 27/11/2018
CLAIM NO. : 11216
POLICY NO. :

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBM3654B
MAKE/MODEL : /

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE LH / BT	REPLACE	1.00	\$47.52	47.52
2	BASKET / cat	REPLACE	1.00	\$49.00	49.00
3	BOX REAR (KAPPA) K26N W/O LIGHT BLACK / cat P/N: 26031	REPLACE	1.00	\$155.40	155.40
4	COVER HANDLE BAR FRONT / cat. P/N: 35220	REPLACE	1.00	\$42.00	42.00
5	FOOTREST PILLION LH / cat. P/N: 33051	REPLACE	1.00	\$26.60	26.60
6	FOOTREST REAR / cat. P/N: 41973	REPLACE	1.00	\$12.60	12.60
7	GRIP HANDLE (RCB) / cat.	REPLACE	1.00	\$35.00	35.00
8	HEADLAMP ASSY / cat. P/N: 33197	REPLACE	1.00	\$168.00	168.00
9	HOLDER LEVER / BT.	REPLACE	1.00	\$14.00	14.00
10	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$35.00	180. 210.00
11	LAMP SIGNAL FRONT LH / cat. P/N: 35223	REPLACE	1.00	\$44.80	44.80
12	LEVER CLTUCH(RCB) / BT cat.	REPLACE	1.00	\$35.00	35.00
13	LOGO (YAMAHA) / cat. P/N: 35224	REPLACE	1.00	\$11.20	11.20



S/N	Description	Action	Qty	Unit Price	Amount
14	METER ASSY <i>BR.</i> P/N: 35230	REPLACE	1.00	\$232.40	232.40
15	METER IU (12V) NEW MODEL <i>cat.</i> P/N: 34351	REPLACE	1.00	\$165.00	165.00
16	MIRROR LH (JIN WEI) <i>BT.</i>	REPLACE	1.00	\$22.40	22.40
17	PEDAL GEAR <i>BT.</i> P/N: 33057	REPLACE	1.00	\$29.40	29.40
18	SPRAY PAINT	Spray	1.00	\$45.00 <i>35</i>	45.00
19	SPRAY PAINT	Repair	1.00	\$45.00 <i>35</i>	45.00
20	STICKER LEG SHIELD LH <i>CPA.</i> P/N: 40733	REPLACE	1.00	\$44.80	44.80
21	STICKER NUMBER PLATE FRONT (BLACK) <i>cat.</i> STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00

SUB TOTAL
GST @ 7 %

1397.12

\$1,447.12
\$101.30

GRAND TOTAL

\$1,548.42

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*3 Days.
part by cat.
After repair photos.
Cmo Qial 82880282
28/01/18.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI18021482/Gsd3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 01-01-2019	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJR 6357T	Veh. Inspected	FBM 3654B
Policy No.		Coverage (\$)	0.00
Claim No.	C10002283	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	28/11/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA X-1R	c.c	135
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	4S3203150	Colour	BLACK
Odometer	45354	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90-17	MICHELIN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/90-17	DUNLOP	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/11/2018	Inspection Date	28/11/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 3654B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BAR HANDLE LH	BENT	47.52	47.52
1	BASKET	CUT	49.00	49.00
1	BOX REAR (KAPPA) K26N W/O LIGHT BLACK	CUT	155.40	155.40
1	COVER HANDLE BAR FRONT	CUT	42.00	42.00
1	FOOTREST PILLION LH	CUT	26.60	26.60
1	FOOTREST REAR	CUT	12.60	12.60
1	GRIP HANDLE	CUT	35.00	35.00
1	HEADLAMP ASSY	SCRATCHED	168.00	168.00
1	HOLDER LEVER	BENT	14.00	14.00
1	LAMP SIGNAL FRONT LH	SCRATCHED	44.80	44.80
1	LEVER CLUTCH (RCB)	CUT	35.00	35.00
1	LOGO (YAMAHA)	NECESSARY	11.20	11.20
1	METER ASSY	BROKEN	232.40	232.40
1	METER IU (12V) NEW MODEL	CUT	165.00	165.00
1	MIRROR LH (JIN WEI)	BENT	22.40	22.40
1	PEDAL GEAR	BENT	29.40	29.40
1	STICKER LEG SHIELD LH	CRACKED	44.80	44.80
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	CUT	12.00	12.00
			1,147.12	1,147.12
LABOUR				
LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS.			210.00	180.00
SPRAY PAINT.			45.00	35.00
SPRAY PAINT			45.00	35.00
			300.00	250.00
GRAND TOTAL			1,447.12	1,397.12
RECOMMENDED COST OF REPAIRS				1,397.12

Report Ref No. CS/AGI18021482/Gsd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.