

ASS. REC. BY:

REF:

023/CT11802/489/Ged3021

Special Instruction:

Surveyor:

Guo Chong

ASSIGNMENT (Office)

From (Person):

Irene Tui

of

CTI

Date/Time:

27/11/18 @ 4:19pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLW 9213E

Insured:

GBD 2807G

at Workshop m/s

Auburn Auto

Tel:

9619 1525

of

176 Sin Ming Drive # 04-18

Policy No.:

DMCVSN3058161803

Claim No.:

SNM18D05450C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/11/2018

CA / REV / REP. / REV 24 HRS <sup>1up</sup>

H.O.D. Endorsement:

Date/Time:

28/11/18 @ 10:12am

Person Contacted:

ENC

Vehicle IN / OUT

Date/Time

Action/Instruction (4) Estimate

SLW 9213E-X

GBD 2807G-X

Demantte: 30/11/2018

PPS  
VNL

REF: C11

1917A

ASSIGNMENT

From: \_\_\_\_\_ Date: 28/11/18

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SLW9213E

at Workshop m/s: Auburn Auto

of: 176 Sin Ming Drive #04-18

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 3:30

ERIC @ 9619 1525

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>lup</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLW9213E Yr Regn: 08 Nov 2018

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda vesel c.c. 1496

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 14964 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU31261907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 25/60R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /


TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. _____	D.O.I. 28-11-18

Survey held at: w/s 3:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	\$6000 - \$7000
	
	29/11/2018

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: PRE

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Photos: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL: 150

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Nov 2018		27 Nov 2018 16:19 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	SENG KIAT CONSTRUCTION CO, Co. Reg. No.: 23088700K		
Main Claimant:	GOODWIN, PAUL ADRIAN, ID: S2771917A		
Vehicle Reg. No.:	SLW9213E	Date of Loss:	19/11/2018 18:00 - :59
Claim Type:	TP / SNM18D05450C02	Policy/Cover Note No.:	DMCVSN3058161803 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD2807G	Policy No. (Claimant):	MP307048
		Excess:	S\$0.00
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2018]		
Driver/Custodian (Insured):	CHEW LAI SENG (62 / Male), NRIC: S1174739F, Tel: +6596304649		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1917A
Vehicle Details	
Vehicle No.:	SLW9213E
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB5961924
Chassis No.:	RU31261907
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,996.00
Original Registration Date:	08 Mar 2018
First Registration Date:	08 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$16,995.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Mar 2028
PARF Rebate Amount:	\$12,746.00
Intended COE Rebate Details	
COE Expiry Date:	07 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,801.00
COE Rebate Amount:	\$35,963.00
<b>Total Rebate Amount:</b>	<b>\$48,709.00</b>

The information contained herein is correct as at 29 Nov 2018

OK

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 21/11/2018 14:47  
Date Of Accident 19/11/2018 18:40  
Exact Location Of Accident LENTOR AVENUE  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLW9213E  
**Insured/Policyholder**  
Name Of Registered Owner GOODWIN,PAUL ADRIAN  
NRIC No S2771917A  
Email Address PAULGOODWIN63@GMAIL.COM  
Mobile Phone No (LOCAL) +65-91152100  
Alternative Phone No Office-NOPHONE

**Vehicle Particulars**

Manufacturer HONDA  
Model VEZEL HYBRID 1.5X AUTO  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company HL ASSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number MP307048  
Cover Note Number 08/03/2018 TO 07/03/2019

**Driver**

Name of Driver TAN WEI CHERN JANE  
NRIC No S6822928F  
Date Of Birth 31/05/1968  
Occupation INDOOR  
Date Of Driving Pass 11/06/1996  
Driving Experience 22 YEARS AND 5 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-92315343

Fax Number	
Contact Number	
E-Mail Address	PAULGOODWIN63@GMAIL.COM
Address	APT BLK 509 CHOA CHU KANG STREET 51 #04-227
Postcode	680509
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : KWEH JIA HUI Gender: : Female

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FOOTAGE IS WITH OWNER'S WORKSHOP
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBD2807G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEW LAI SENG
NRIC/Passport Number	S1174739F
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN WEI CHERN JANE

Approximate Age

Injuries Sustain

NECK

Injured person in which vehicle?

SLW9213E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

KWEH JIA HUI

Approximate Age

Injuries Sustain

HEAD

Injured person in which vehicle?

SLW9213E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

HL  
Vehicle: SLW 923E

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 21/11/18  
13:46 hrs

Reporting Centre Personnel  
Name: Ma Lu  
NRIC/FIN No.: 21/11/18



GIA/MAC SketchPlanForm V1

Date of accident: 19/11/18 Time: 1844 hrs Location: Lentor Avenue  
My Vehicle A: SLW923E Vehicle B: GBD 2807 G Vehicle C: —  
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On this date (19-NOV-18), approximately 18:44 hrs whilst driving my vehicle along Lentor Ave, I was pulling up to traffic that had stopped in front of me due to traffic congestion in front. As I was just pulling up to stop the vehicle behind me skidded and lost control of their vehicle which then skidded into the rear of my car. The person sitting in the passenger seat hit her head and suffered minor injuries. I also suffered some minor injuries to my back, lower leg and head.

Claim OD/TP at Ah Lim Motor     Claim OD/TP at other workshop     Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :  
 Email address :  
 & myself :  
 Email address : paulgoodwin63@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SLW 9213 E

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time: 21/11/18  
 13:46 hrs.

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



Mu  
 21/11/18

Police Report



**SINGAPORE  
POLICE FORCE**



T/20181119/7027

1 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20181119/7027

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 19/11/2018 22:51		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: TAN WEI CHERN JANE			Address: APT BLK 509 CHOA CHU KANG STREET 51 #04-227 SINGAPORE 680509		
ID Type / ID No.: NRIC NO / S6822928F			Contact No.: Home/Office: Mobile: 92315343		
Nationality: SINGAPORE CITIZEN			Email: jtwc5343@gmail.com		
Sex: Female	Age: 50	Date of Birth: 31/05/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: FINANCIAL MANAGER			Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/11/2018 18:45	Type of Location: Straight Road
Location:  LENTOR AVENUE				
Weather: Raining		Road Surface: Wet		Road Speed Limit: 60 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD2807G	Lorry	TOYOTA		Silver	Slightly Damaged	2
SLW9213E	Car	HONDA	Vezei	Silver	Seriously Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLW9213E	HL ASSURANCE PTE. LTD	MP307048	07/03/2018	07/03/2019



**SINGAPORE  
POLICE FORCE**





Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20181119/7027

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Chew Lal Seng	ID No.	S1174739F
Related Vehicle	GBD2807G (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN WEI CHERN JANE	ID No.	S6822928F
Related Vehicle	SLW9213E (Car)	Contact No.	92315343
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Passenger			
Name	Kweh Jia Hui	ID No.	S9542199G
Related Vehicle	SLW9213E (Car)	Contact No.	97573180
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/11/2018	Date Discharge	19/11/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On this date at approximately 6:44pm whilst driving my vehicle along Lentor rd, I was pulling up to traffic that had stopped in front of me due to traffic congestion in front. As I was just pulling up to stop the vehicle behind me skidded and lost control of their vehicle which then skidded into the rear of my car. The person sitting in the passenger seat hit her head and suffered minor injuries. I also suffered some minor injuries to my back, lower leg and head.

The other driver upon exiting his vehicle admitted skidding and proceeded to hand over his licence details. I proceeded to take pictures of both vehicles and then subsequently proceeded to Khoo Teck Puat hospital to admit the passenger. Passenger was provided 5 days MC. I as the driver will visit local GP



**SINGAPORE  
POLICE FORCE**



T/20181119/7027

3 of 4

Report No. T/20181119/7027

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

tomorrow (20/11) for assessment.

Other vehicle registration: GBD-2807G  
Driver name: Chew LAI Seng  
License: S1174739F  
DOB: 01-01-1956



**SINGAPORE  
POLICE FORCE**



T/20181119/7027

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20181119/7027

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 19/11/2018 22:51
Officer In Charge Of Case: TP / TPHQ / SITIMARSITA BINTE BOHARI Contact No.: 65476219	Classification Of Case:
Authentication Stamp NP168	

## Driver's Particulars

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Nov 2018		27 Nov 2018 16:19 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SENG KIAT CONSTRUCTION CO</b> , Co. Reg. No.: 23088700K								
Main Claimant:	<b>GOODWIN,PAUL ADRIAN</b> , ID: S2771917A								
Vehicle Reg. No.:	<b>SLW9213E</b>	Date of Loss:	19/11/2018 18:00 - :59 [8 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D05450C02</b>	Policy/Cover Note No.:	DMCVSN3058161803 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBD2807G</b>	Policy No. (Claimant):	MP307048						
		Excess:	S\$0.00						
Repairer:	<b>Auburn Auto Pte Ltd (HQ)</b> 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Claimant's Insurer:	<b>HL Assurance Pte Ltd (HQ)</b> - Tel: 69226030								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 06/12/2018]								
Driver/Custodian (Insured):	CHEW LAI SENG (62 / Male), NRIC: S1174739F, Tel: +6596304649								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLW9213E (SNM18D05450C02)  
 [GBD2807G]  
 TP  
 GOODWIN, PAUL ADRIAN  
 Nov 19 2018 6:00PM  
 [SENG KIAT CONSTRUCTION CO]  
 Auburn Auto Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 15:29	<b>Accident Statement</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	21/11/18 14:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	21/11/18 15:09	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	29/11/18 12:18	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
19	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
20	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
21	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
22	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
23	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
24	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
25	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
26	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
27	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
28	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
29	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
30	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
31	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
32	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
33	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
34	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
35	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
36	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
37	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
38	29/11/18 12:18	General View	Load JPG	<input checked="" type="checkbox"/>
39	29/11/18 12:18	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
40	29/11/18 12:18	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
41	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	06/12/18 19:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
69	06/12/18 19:12	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
70	06/12/18 19:12	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
71	06/12/18 19:12	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/11/18 16:18	PRS		Load PDF
2	27/11/18 16:19	OI GIA		Load PDF

No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 15:12	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF
2	21/11/18 15:12	Police Report <small>[Linked Accident Report Documents]</small>		Load TIF
3	21/11/18 15:12	Driver's Particulars <small>[Linked Accident Report Documents]</small>		Load TIF

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 15:29	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	21/11/18 14:56	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	21/11/18 15:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	21/11/18 15:12	Sketch Plan		Load TIF
2	21/11/18 15:12	Police Report		Load TIF
3	21/11/18 15:12	Driver's Particulars		Load TIF

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CT118021489/GCD3E2  
**Date:** 13/12/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3058161803	
Claimant Vehicle No: SLW9213E	Insured Vehicle No: GBD2807G	
Date of Loss: 19/11/2018	Nature of Claim: TP	Claim No: SNM18D05450C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9213E		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5961924
Reg. Date:	08/03/2018 (Man. Year: 2017)	Chassis No:	RU31261907
Colour:	Silver	Odometer:	14964 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	27/11/2018	
Date Inspected:	28/11/2018 Inspected At:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	7.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW9213E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >