

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18021492/719d322

Special Instruction:

Surveyor:  
MENMEN

Taufik

From (Person):

Kwok Woon Choo

ASSIGNMENT (Office)

Estimated Cost:

of

MSG

Date/Time:

28/11/18 11.41am

OD

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

Bill to:

To Inspect Vehicle No.:

SPM 4444L

at Workshop m/s

performance

Insured:

of

303 Alexandra Rd

Tel:

91165700

Policy No:

27506304SMP

Claim No:

576836

Sum Insured:

Excess:

\$750.00

Make of Veh:

(Client's Record)

D.O.A.

28/11/18

CA / (REV)

REP. / REV 24 HRS

Date/Time:

12:31pm 28/11/18

Person Contacted:

Hun

H.O.D. Endorsement:

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SPM 4444L-X

29/11/18@7:52pm report to Woon Choo via Menmen.

29/11/18@4:34pm Lui Stan Wei informed C/A via Menmen.

30/11/18@9:37am informed PML C/A B exs B750 by email.

25/01/19@6:44pm 2nd report to Woon Choo via Menmen. (supplementary)

28/01/19@2:06pm Kenny ong informed C/A at B1737.10 inclusive of 3000. and

Taufikh

RCR

MSLH

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of:

Insured

Policy No.

Claims No.

Sum Insured:

Excess: 9750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Ken.

Date / Time Action / Instruction

29/1/19 @ 4.45pm Confirmed with Caroline Brail fig 011737-10, 10 days by email.  
(Red to 11869.10, 50%)

RECEIVED 30 JAN 2019

Vehicle

SFM4444L

Yr Regn:

2013 April

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

BMW 520i

1997

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

6284

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAXG12090DX53674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/35/17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU KPIR / SUMI / TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

28/11/18

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to:

☐

Preli. Report

11/30/1. Transfer

☐

Final Report

Date/Time: File Return to:

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee

Transportation

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Wash and \$

Report Format:

NET-00

Lump Sum / L.B. \$

11737-10

TOTAL

210

29/1/2019

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2018		28 Nov 2018 11:41 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KIM WHATT, ID: S1450183E, Tel: +6596387183, Email: JIMBUILD@SINGNET.COM.SG		
Vehicle Reg. No.:	SFM4444L	Date of Loss:	20/11/2018 11:00 - :59 [66 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 576836	Policy/Cover Note No.:	27506304SMP (Comprehensive) Coverage: 22/04/2018 - 21/04/2019
		Excess:	S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/11/2018]		
Driver/Custodian:	TAN KIM WHATT (58 / Male), NRIC: S1450183E, Tel: +6596387183		
Adj Asg. Remarks:	Car in, pls revert		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 29 January 2019 4:48 PM  
**To:** 'PBSP'; Taufikh (LKKAUTO); SUR  
**Subject:** RE: FINAL REPORT / SFM4444L

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$11,737.10 before excess \$750.00 & GST and 10 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Tuesday, 22 January 2019 4:17 PM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SFM4444L

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 8,162.00  
Total Parts : 3,575.10  
Total Labour & Parts : 11,737.10

Repair days: 10

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Nov 2018 12:22	Clim Veh Model Changed	(203428) BMW 520I 2.0 (A).	[I] Margaret Loh Wai Fun
2	24 Nov 2018 12:22	Clim Created	Reg No: SFM4444L, Acct Date: 2018/11/20. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MPML 18150731	[I] Margaret Loh Wai Fun
3	28 Nov 2018 10:58	Notification Status Changed	Ins.Status => Incoming Claim	[I] Kwok Woon Choo
4	28 Nov 2018 10:58	Clim Registration Modified	Setl.Type:3->0. Rep:1137->200071. Claim Type:SC->OD. Excess: -> 750.00.	[I] Kwok Woon Choo
5	28 Nov 2018 11:04	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):to revert	[I] Kwok Woon Choo
6	28 Nov 2018 11:04	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/11/29	[I] Kwok Woon Choo
7	28 Nov 2018 11:04	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Kwok Woon Choo
8	28 Nov 2018 11:09	Assignment 1st Accessed		[A] Ong Zi Hui
9	28 Nov 2018 11:40	Adj Assignment Cancelled	Kumar will follow-up this case, pending for his further instruction	[I] Pauline Soh Li Ping
10	28 Nov 2018 11:40	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Pauline Soh Li Ping
11	28 Nov 2018 11:41	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, pls revert	[I] Pauline Soh Li Ping
12	28 Nov 2018 11:41	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/11/29	[I] Pauline Soh Li Ping
13	28 Nov 2018 11:41	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Pauline Soh Li Ping
14	28 Nov 2018 11:58	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	28 Nov 2018 17:03	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
16	29 Nov 2018 14:47	Adj Rpt Initiated		[A] SHIAU CHAN
17	29 Nov 2018 14:50	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] SHIAU CHAN
18	29 Nov 2018 14:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] SHIAU CHAN
19	29 Nov 2018 14:52	Adj Mandate Request	Cur.Req:17663.70:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	29 Nov 2018 16:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/28. Mandate Remarks: a if c; check items to be confirmed	[I] Lui Siew Wei
21	29 Nov 2018 16:34	Adj Mandate Set	Approved:14163.40:a if c; check items to be confirmed	[I] Lui Siew Wei
22	25 Jan 2019 16:43	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] SHIAU CHAN
23	25 Jan 2019 16:44	Adj Mandate Request	Cur.Req:11737.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	28 Jan 2019 14:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/28. Mandate Remarks: a if c. Inclusive of sup p parts.	[I] Keny Ong Thiam Beng
25	28 Jan 2019 14:06	Adj Mandate Set	Approved:11737.10:a if c. Inclusive of supp parts.	[I] Keny Ong Thiam Beng

Date From  Date To  Audit Type

### ACTIVITY

[28/11/2018 11:33] Ong Zi Hui:  
Woon Choo informed to outsource this case per discussion with Jason.  
[28/11/2018 11:27] Ong Zi Hui:  
Motor make mistake, case belong to Woon Choo not Jasmine, will pend for Woon Choo instruction.  
[28/11/2018 11:20] Ong Zi Hui:  
pending for Jasmine instruction whether to outsource or not  
[28/11/2018 11:15] Ong Zi Hui:  
Han confirm car in but request external surveyor as this case may enage lawyer. Informed Jasmine about this and will pend for her further instruction

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1989634	29/11/2018 14:47	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFM4444L		10.70
1991595	24/11/2018 12:26	Motor	MSIG Insurance (Singapore) Pte. Ltd.	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	SFM4444L	576836	xx.xx

Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 25 Jan 2019

## Preliminary Advice

Vehicle No	: SFM4444L	Accident Date	: 20/11/2018
Make	: BMW 520I	Policy No.	: 27506304SMP
Assignment Date	: 28/11/2018	Excess	: S\$750.00
Date of Inspection	: 28/11/2018	Est. Duration of Repair	: 10.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,916.35	(ESTIMATE \$23,810.10 + SUPPLEMENTARY \$1,106.25)
Revised Amount	:S\$	11,737.10	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,737.10	
Lump Sum Repair	:S\$		

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	55,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,176.00

### Remarks

( X ) The vehicle is economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 30 November 2018 9:37 AM  
**To:** 'PBSP'; Gary Poh Chai Hoon  
**Cc:** SUR  
**Subject:** FW: VEHICLE SFM 4444L (DOA: 20/11/2018)

Dear Sir/Madam,

Please refer to the below email.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 30 November 2018 9:35 AM  
**To:** 'han.kwan.yong@simedarby.com.sg' <han.kwan.yong@simedarby.com.sg>  
**Subject:** VEHICLE SFM 4444L (DOA: 20/11/2018)

Dear Han,

As instructed by our client, please proceed to repair the insured vehicle **SFM 4444L (Excess \$ 750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 30 November 2018 9:35 AM  
**To:** 'han.kwan.yong@simedarby.com.sg'  
**Subject:** VEHICLE SFM 4444L (DOA: 20/11/2018)

Dear Han,

As instructed by our client, please proceed to repair the insured vehicle **SFM 4444L (Excess \$ 750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Nov 2018 12:22	<b>Clim Veh Model Changed</b>	(203428) BMW 520I 2.0 (A).	[I] Margaret Loh Wai Fun
2	24 Nov 2018 12:22	<b>Clim Created</b>	Reg No: SFM4444L, Acct Date: 2018/11/20, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MPML 18150731	[I] Margaret Loh Wai Fun
3	28 Nov 2018 10:58	<b>Notification Status Changed</b>	Ins.Status => Incoming Claim	[I] Kwok Woon Choo
4	28 Nov 2018 10:58	<b>Clim Registration Modified</b>	Setl.Type:3->0, Rep:1137->200071, Claim Type:SC->OD, Excess: -> 750.00.	[I] Kwok Woon Choo
5	28 Nov 2018 11:04	<b>Adj Co Assigned</b>	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):to revert	[I] Kwok Woon Choo
6	28 Nov 2018 11:04	<b>Adj Next Rpt Changed</b>	Next Rpt:Im, Advice.Due Date:2018/11/29	[I] Kwok Woon Choo
7	28 Nov 2018 11:04	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Kwok Woon Choo
8	28 Nov 2018 11:09	<b>Assignment 1st Accessed</b>		[A] Ong Zi Hui
9	28 Nov 2018 11:40	<b>Adj Assignment Cancelled</b>	Kumar will follow-up this case, pending for his further instruction	[I] Pauline Soh Li Ping
10	28 Nov 2018 11:40	<b>Adj Est Details Deleted</b>	Deleting Est Details For Cancelling Adjuster Assignment	[I] Pauline Soh Li Ping
11	28 Nov 2018 11:41	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):Car in, pls revert	[I] Pauline Soh Li Ping
12	28 Nov 2018 11:41	<b>Adj Next Rpt Changed</b>	Next Rpt:Im, Advice.Due Date:2018/11/29	[I] Pauline Soh Li Ping
13	28 Nov 2018 11:41	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Pauline Soh Li Ping
14	28 Nov 2018 11:58	<b>Assignment 1st Accessed</b>		[A] Nivitha Govindasamy
15	28 Nov 2018 17:03	<b>Adj Adjuster Assigned</b>	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
16	29 Nov 2018 14:47	<b>Adj Rpt Initiated</b>		[A] SHIAU CHAN
17	29 Nov 2018 14:50	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] SHIAU CHAN
18	29 Nov 2018 14:50	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] SHIAU CHAN
19	29 Nov 2018 14:52	<b>Adj Mandate Request</b>	Cur.Req:17663.70:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	29 Nov 2018 16:34	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/12/28, Mandate Remarks: a if c; check items to be confirmed	[I] Lui Siew Wei
21	29 Nov 2018 16:34	<b>Adj Mandate Set</b>	Approved:14163.40:a if c; check items to be confirmed	[I] Lui Siew Wei

Date From



Date To



Audit Type

None

Go

### ACTIVITY

[28/11/2018 11:33] Ong Zi Hui:  
Woon Choo informed to outsource this case per discussion with Jason.

[28/11/2018 11:27] Ong Zi Hui:  
Motor make mistake, case belong to Woon Choo not Jasmine, will pend for Woon Choo instruction.

[28/11/2018 11:20] Ong Zi Hui:  
pending for Jasmine instruction whether to outsource or not

[28/11/2018 11:15] Ong Zi Hui:  
Han confirm car in but request external surveyor as this case may enage lawyer. Informed Jasmine about this and will pend for her further instruction

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1989634	29/11/2018 14:47	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFM4444L		10.70

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 29 Nov 2018

## **Preliminary Advice**

Vehicle No	: SFM4444L	Accident Date	: 20/11/2018
Make	: BMW 520I	Policy No.	: 27506304SMP
Assignment Date	: 28/11/2018	Excess	: S\$750.00
Date of Inspection	: 28/11/2018	Est. Duration of Repair	: 10.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,606.20
Revised Amount	:S\$	14,163.40
Check Items (Estimated)	:S\$	3,500.30
Total	:S\$	17,663.70

Lump Sum Repair	:S\$	
-----------------	------	--

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	55,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,176.00

## **Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 0183E

**Vehicle Details**

Vehicle No.: SFM4444L  
Vehicle to be Exported: No  
Intended Deregistration Date: 29 Nov 2018  
Vehicle Make: B.M.W.  
Vehicle Model: 520i 2.0L AT D/AB  
2WD 4DR GAS/D NAV  
Primary Colour: White  
Manufacturing Year: 2013  
Engine No.: A6470456N20B20B  
Chassis No.: WBAXG12090DX53674  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$40,186.00  
Original Registration Date: 22 Apr 2013  
First Registration Date: 22 Apr 2013  
Transfer Count: 0  
Actual ARF Paid: \$43,261.00  
**Intended PARF Rebate Details**  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 21 Apr 2023  
PARF Rebate Amount: \$30,282.00  
**Intended COE Rebate Details**  
COE Expiry Date: 21 Apr 2023  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$65,001.00  
COE Rebate Amount: \$25,542.00  
**Total Rebate Amount: \$55,824.00**

The information contained herein is correct as at 29 Nov 2018

OK

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MPML18150731 Vehicle Registration No: SFM4444L  
Name (as shown in NRIC) : Mr Tan Kim Whatt NRIC/FIN/Passport No : S1450183  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 96387183  
Email Address : \_\_\_\_\_  
Date of Accident : 20/11/18 Time of Accident : 11.20 hrs  
Place of Accident : Tanjong Katong Road.  
Insurance Company: MSIG Ins (S) Pte Ltd

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I wish to revert back to own ins  
policy claim and later Counter Claim  
against 3<sup>rd</sup> party ins for uninsured  
losses

Policyholder / Driver's Signature  
Date:

27/11/18  
(5.35 pm)

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:  
Date:

**HAN KWAN YONG**  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/11/2018 12:34
Date Of Accident	20/11/2018 11:20
Exact Location Of Accident	TANJONG KATONG ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFM4444L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIM WHATT
NRIC No	S1450183E
Email Address	JIMBUILD@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96387183
Alternative Phone No	OTHERS-96319809

### Vehicle Particulars

Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	TAN KIM WHATT
NRIC No	S1450183E
Date Of Birth	24/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	12/09/1980
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96387183
Fax Number	
Contact Number	OTHERS-96319809
Email Address	JIMBUILD@SINGNET.COM.SG

Address	59 LORONG MYDIN
Postcode	416860
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACH.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4357J
Vehicle Make/Model/Colour	MAN RUBBISH TRUCK WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	BALACHANDAR A/L VERILEK DILLAY
NRIC/Passport Number	530107566
Contact Number	
Address	800 SUPER 17A SENOKO WAY
Postcode	758056
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	LEFT
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


20/11/18  
H. 20.4m  
2.26pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

20/11/18  
H. 20.4m  
2.26pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As about 11.20 a.m., I had parked my car along Tanjong Katong Road. I got down my car and opened the right rear passenger door of my car to collect my filler from the right rear passenger seat in or about that time, a garbage truck (XE 435TJ) was situated diagonally-adjacent from the rear end of my car. As I was about to close the right rear passenger door, the said truck suddenly and unexpectedly started to move towards my car and got so close that the left side of the said truck was nearly inches away from me. As a result of the truck driver's recklessness, the truck collided into my slightly opened right rear passenger door, causing it to be bent outwards.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

21/11/18  
(11.59pm)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159541Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 49178

Page No. : 1 of 5

Date Estimated : 20/11/2018

Prepared By : Han Kwan Yong

**- ESTIMATE REPAIR FOR -**Tan Kim Whatt  
59, Lorong Mydin

Singapore 416860

**- ACCOUNT - 40000**Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM4444L	DX53674	22/04/2013	520ia	0

DESCRIPTION

To replace rear right door, right 'B' pillar with side member including to jack &amp; straighten right 'B' pillar and to knock out dented area caused by the accident

Repair - 3400 ✓  
Replace - 2650VALUE  
8,500.00

To respray front right door, rear right door, rear right fender, right roof frame, right 'B' pillar and right side member

3398 2995  
2998 4,602.00To carry out body cavity preservation.  
(Per panel).

100 118.00

To carry out body cavity preservation.  
(For cut panel).451? 11  
531.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 531.00

To remove and install front seats and carpets to facilitate repairs.

743? 11  
870.00

To remove and install rear seats and carpets to facilitate repairs.

743X 11  
870.00

To conduct water leak tests.

65 11  
75.00

To check electrical wiring systems and lightings including reset and check air bags for proper function.

250 295.00

Sundries.

? 11  
150.00Total Labour 1: **16,542.00**DESCRIPTION

CLAMP

QTY PRIC  
10 0.85VALUE  
m 7 8.50

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 49178  
Date Estimated : 20/11/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM4444L	DX53674	22/04/2013	520ia	0

## DESCRIPTION

RR RH DOOR  
# COLUMN B W/RH ROCKEL PANEL  
# LEFT UPPER REAR DOOR HINGE  
# RIGHT LOWER REAR DOOR HINGE  
# CARRIER OUTSIDE DOOR HANDLE  
RH GRAB HANDLE PAINT FINISH (CA)  
REAR DOOR BRAKE  
FRT RH DOOR CHANNEL COVER EXTERIOR  
# COVER WINDOW FRAME DOOR REAR  
RR RH DOOR OUTER WEATHERSTRIP  
RR RH DOOR WINDOW CHROME FRAME TOP  
SEAL DOOR GAP DOOR RR BOTTOM  
REAR RH DOOR SEAL SEAM ROOF  
# RR RH DOOR LINING LEATHER (S  
REAR DOOR SEAL  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY	PRIC	VALUE
1	1,774.50	bt 1,774.50
1	1,724.35	Rx 1,724.35
1	58.60	? 58.60
1	57.70	? 57.70
1	161.85	Rx 161.85
1	574.30	Rx 574.30
1	86.45	? 86.45
1	115.95	? 115.95
1	54.55	? 54.55
1	115.95	nei 115.95
1	197.60	bt 197.60
1	43.40	nei 43.40
1	168.55	de 168.55
1	1,567.55	? 1,567.55
1	168.85	nei 168.85
1	26.15	wei 26.15
1	131.55	wei 131.55
1	27.85	wei 27.85

Total Parts : 7,064.20

## Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. 28/4/18 Q250 Claim No. 750  
Date&Time 28/4/18 Excess S\$ 750  
Surveyor's Name Tanjun Sign [Signature]  
Surveyor's Tel 9245344 Authorised Yes (X)  
Authorised Date Not Approved Time  
RESURVEY PARTS PHOTO BY SURVEYOR Yes (X) No PML Yes (X) No  
Surveyor's E-mail [Email]  
No. of Working Days Recommend 8-10 days

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	16,542.00
Parts	:	7,064.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,652.43
Grand Total	:	25,258.63

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

23606.20



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 49178  
Date Estimated : 20/11/2018  
Prepared By : Han Kwan Yong

Page No. : 3 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM4444L	DX53674	22/04/2013	520ia	0

**Terms & Conditions of Service**

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 49178**  
Date Estimated : **20/11/2018**  
Prepared By : **Han Kwan Yong**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SFM4444L</b>	<b>DX53674</b>	<b>22/04/2013</b>	<b>520ia</b>	<b>0</b>

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
  - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
  - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
  - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
  - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
  - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
  - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
  - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
  - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
  - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
  - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
  - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
  - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
  - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**Estimate No. : b1 49178  
Date Estimated : 20/11/2018  
Prepared By : Han Kwan Yong

Page No. : 5 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM4444L	DX53674	22/04/2013	520iA	0

17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.

- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- put his request in writing;
  - provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
  - specify the information that is incorrect and what it should be replaced with.

The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.

- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- put his request in writing by way of an email sent to the Vendor;
  - provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
  - if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer  
Performance Motors LimitedAddress:  
Sime Darby Performance Centre  
303 Alexandra Road  
Singapore 159941Email address:  
dataprotection@pml.com.sg

# Performance Motors Limited

A member of the Sino Carby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 49178  
Date Estimated : 20/11/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Tan Kim Whatt  
59, Lorong Mydin

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 416860

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SFM4444L	DX53674	22/04/2013	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# DRIVE POWER WINDOW FRT/RR RIGHT *	319.85	1.00	bt ✓	319.85
# COVER COLUMN B REAR RH *	162.80	1.00	W ✓	162.80
# RR RH DOOR WINDOW GUIDE *	98.75	1.00	dt ✓	98.75
# RR RH WINDOW LIFTER W/O MOTOR *	310.25	1.00	bt ✓	310.25
# SIDE WINDOW GREEN FIXED RH RR DOOR *	214.60	1.00	N ✓	214.60

Total Labour :	
Total Parts :	1,106.25
Total Labour & Parts :	1,106.25

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 49178  
Date Estimated : 20/11/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Tan Kim Whatt  
59, Lorong Mydin

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 416860

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
SFM4444L	DX53674	22/04/2013	520iA	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear RH door and attachments include making good the front RH door, rear RH fender, RH roof frame, RH 'B' pillar, include pulling and straightening on accident areas and knocking out dents caused by the accident	3400.00		3,400.00			
* To respray front RH door, rear RH door, rear RH fender, RH roof frame and RH 'B' pillar	3398.00		3,398.00			
To carry out body cavity preservation (Per panel)	100.00		100.00			
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00			
* To replace rear RH door fixed side window include conducting water leak tests	413.00	net /	413.00			(ch)
To check electrical wiring systems and lightings include resetting and checking air bags for proper function	250.00		250.00			
Sundries	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR RH DOOR	1,774.50	1.00		1,774.50
# DRIVE POWER WINDOW FRT/RR RIGHT *	319.85	1.00		319.85
RR RH DOOR OUTER WEATHERSTRIP	115.95	1.00		115.95
# COVER COLUMN B REAR RH *	162.80	1.00		162.80
# RR RH DOOR WINDOW GUIDE *	98.75	1.00		98.75
RR RH DOOR WINDOW CHROME FRAME TOP	197.60	1.00		197.60
SEAL DOOR GAP DOOR RR BOTTOM	43.40	1.00		43.40
REAR RH DOOR SEAL SEAM ROOF	168.55	1.00		168.55
# RR RH WINDOW LIFTER W/O MOTOR *	310.25	1.00		310.25
# SIDE WINDOW GREEN FIXED RH RR DOOR *	214.60	1.00		214.60
REAR DOOR SEAL	168.85	1.00		168.85

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

### # SUPPLEMENTARY ITEMS

Total Labour :	8,162.00
Total Parts :	3,575.10
Total Labour & Parts :	11,737.10
Deduction for Excess :	750.00
Total Repair Costs less Excess:	10,987.10
GST @7%:	769.10
Grand Total :	11,756.20

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2018		28 Nov 2018 11:41 <a href="#">Edit Adj Rpt</a>	<b>S\$11,737.10</b> <a href="#">Edit Estimates</a>	<b>S\$11,737.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TAN KIM WHATT, ID: S1450183E, Tel: +6596387183, Email: JIMBUILD@SINGNET.COM.SG								
Vehicle Reg. No.:	SFM4444L	Date of Loss:	20/11/2018 11:00 - :59 [66 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 576836	Policy/Cover Note No.:	27506304SMP (Comprehensive) Coverage: 22/04/2018 - 21/04/2019						
		Excess:	S\$750.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/12/2018]								
Driver/Custodian:	TAN KIM WHATT (58 / Male), NRIC: S1450183E, Tel: +6596387183								
Adj Asg. Remarks:	Car in, pls revert								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (28/01/2019): Alert - Adj Mandate Approved (S\$11737.10) - SFM4444L - Claim Handler: Kwok Woon ...</li> <li>MSIG_SG (29/11/2018): Alert - Adj Mandate Approved (S\$14163.40) - SFM4444L - Claim Handler: Kwok Woon ...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFM4444L (576836)

































OD

Nov 20 2018 11:00AM



[TAN KIM WHATT]


















Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Performance Motors Limited (Alexandra)							Thumbnail			Print		
1	21/11/18 12:50	Accident Statement										Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	29/11/18 14:50	Adjuster Immediate Advice										Load HTM		
2	25/01/19 16:43	Adjuster Immediate Advice										Load HTM		
									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Performance Motors Limited (Alexandra)							Thumbnail			Print		
1	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
2	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
3	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
4	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
5	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
6	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
7	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
8	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
9	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
10	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
11	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
12	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
13	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
14	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
15	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
16	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
17	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
18	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
19	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
20	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
21	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
22	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
23	21/11/18 12:46	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	29/11/18 14:21	Odometer Reading										Load JPG <input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
2	29/11/18 14:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	29/11/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	25/01/19 16:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/11/18 12:29	E-FILE REPORT (XE4357J)	 Load PDF	
2	28/11/18 10:55	PML FAX + ESTIMATE + GIA REPORT + INSD NRIC + DL.	 Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/11/18 12:45	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 14:21	ESTIMATE	 Load PDF	
2	25/01/19 16:38	SUPPLEMENTARY LIST	 Load PDF	
3	30/01/19 12:59	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/11/18 12:50	Accident Statement	 Load HTM	
2	27/11/18 17:55	Addendum Sheet	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
3	27/11/18 17:55	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	21/11/18 12:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/11/18 12:45	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18021492/T1QD3E2

Date: 30/01/2019

## REFERENCE

Insured/Claimant:	TAN KIM WHATT	Policy No:	27506304SMP	Claim No:	576836
Date of Loss:	20/11/2018	Nature of Claim:	OD		

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SFM4444L	Engine No:	A6470456N20B20B
Make & Model:	BMW 520i, 2.0 (A)	Chassis No:	WBAXG12090DX53674
Reg. Date:	22/04/2013 (Man. Year: 2013)	Odometer:	62984 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	255/55 R17	Rear Tyre Size:	255/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,320.45	3,725.10	4,595.35	55.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,805.00	8,012.00	8,793.00	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,125.45</b>	<b>11,737.10</b>	<b>13,388.35</b>	<b>53.29</b>
<b>- Excess (S\$)</b>	<b>750.00</b>	<b>750.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>24,375.45</b>	<b>10,987.10</b>	<b>13,388.35</b>	<b>54.93</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,706.28</b>	<b>769.10</b>	<b>937.18</b>	<b>54.93</b>
<b>Nett Amount (S\$)</b>	<b>26,081.73</b>	<b>11,756.20</b>	<b>14,325.53</b>	<b>54.93</b>

## INSPECTION

Date of Assignment:	28/11/2018	
Date Inspected:	28/11/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 10.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2019)
<b>Parts:</b> 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFM4444L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	10		*CLAMP	Not Necessary	8.50 FS	*- FS
3	1		*RR RH DOOR	Bent	1,774.50 FS	*1,774.50 FS
4	1		*#COLUMN B W/RH ROCKEL PANEL	Repair	1,724.35 FS	*- FS
5	1		*#LEFT UPPER REAR DOOR HINGE	Not Necessary	58.60 FS	*- FS
6	1		*#RIGHT LOWER REAR DOOR HINGE	Not Necessary	57.70 FS	*- FS
7	1		*#CARRIER OUTSIDE DOOR HANDLE	Repair	161.85 FS	*- FS
8	1		*RH GRAB HANDLE PAINT FINISH (CA)	Repair	574.30 FS	*- FS
9	1		*REAR DOOR BRAKE	Not Necessary	86.45 FS	*- FS
10	1		*FRT RH DOOR CHANNEL COVER EXTERIOR	Not Necessary	115.95 FS	*- FS
11	1		*#COVER WINDOW FRAME DOOR REAR	Not Necessary	54.55 FS	*- FS
12	1		*RR RH DOOR OUTER WEATHERSTRIP	Necessary	115.95 FS	*115.95 FS
13	1		*RR RH DOOR WINDOW CHROME FRAME TOP	Bent	197.60 FS	*197.60 FS
14	1		*SEAL DOOR GAP DOOR RR BOTTOM	Necessary	43.40 FS	*43.40 FS
15	1		*REAR RH DOOR SEAL SEAM ROOF	Deformed	168.55 FS	*168.55 FS
16	1		*#RR RH DOOR LINING LEATHER (S	Not Necessary	1,567.55 FS	*- FS
17	1		*REAR DOOR SEAL	Necessary	168.85 FS	*168.85 FS
18	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
19	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
20	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
21	1		*DRIVE POWER WINDOW FRT / RR RIGHT	Bent	319.85 FS	*319.85 FS
22	1		*COVER COLUMN B REAR RH	Necessary	162.80 FS	*162.80 FS
23	1		*RR RH DOOR WINDOW GUIDE	Deformed	98.75 FS	*98.75 FS
24	1		*RR RH WINDOW LIFTER W/O MOTOR	Bent	310.25 FS	*310.25 FS
25	1		*SIDE WINDOW GREEN FIXED RH RR DOOR	Necessary	214.60 FS	*214.60 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>8,320.45</b>	<b>3,725.10</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RIGHT DOOR, RIGHT B PILLAR WITH SIDE MEMBER INCLUDING TO JACK & STRAIGHTEN RIGHT B PILLAR AND TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	8,500.00	3,400.00
2	TO RESPRAY FRONT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, RIGHT ROOF FRAME, RIGHT B PILLAR AND RIGHT SIDE MEMBER	New	4,602.00	3,398.00
3	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
4	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	0.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
6	TO REMOVE AND INSTALL FRONT SEATS AND CARPETS TO FACILITATE REPAIRS	New	870.00	0.00
7	TO REMOVE AND INSTALL REAR SEATS AND CARPETS TO FACILITATE REPAIRS	New	870.00	0.00
8	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS INCLUDING RESET AND CHECK AIR BAGS FOR PROPER FUNCTION	New	295.00	250.00
10	TO REPLACE REAR RH DOOR FIXED SIDE WINDOW INCLUDE CONDUCTING WATER LEAK TESTS	New	413.00	413.00
Gross Labour Cost (S\$)			16,805.00	8,012.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >