

22/03/2002

ASS. REC. BY:

REF:

CS/CTI18021495/Tisd302

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

27/11/03 2:51pm

Estimated Cost:

Bill to:

①

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBB 955 (SMF 797C) ^{New}

Insured:

at Workshop m/s

Sng Ah Tee Motor

Tel:

6268 6183

of

Blk 3, Pioneer Rd North #01-18

Policy No:

DMPCSN1640791802

Claim No:

SNM18D05510C01

Sum Insured:

Excess:

\$3,000-00

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV

/ REP.

/ REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/11/18 @ 10:16am

Person Contacted:

Joyce

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SBB955-X

Taufkh

REF:

CTI

Oct 2021 Jan

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s:

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Yeh No:

SBR955

Yr Regn:

2011 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A8L

C.C. 2995

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W144ZZZ 4HX.BN00742

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255 / 45R19

R:

2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28/11/18

Survey held at

Sng Yn Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fire Case

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

check MV & any policy breach if policy condition.

Total loss, Not Economical to Repair.

There is no breach of policy for the vehicle

10/12/18

Submit Total Loss as not economical to repair.

MV - \$73,000.00

LTA - \$61,921.00

Nett = \$11,079.00

RECEIVED 10 DEC 2018

Date/Time File Pass to:

10/12/18

To

Type

Date/Time File Return to:

By



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. S+P

2. Fuel

3. Other

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Week-end (\$

Report Format:

Lump Sum / L.B.L.

Total Loss

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	27 Nov 2018 Sendback Est	27 Nov 2018 13:19 S\$0.00	27 Nov 2018 17:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MINT POWER ENGINEERING PTE LTD, Co. Reg. No.: 201115503M		
Vehicle Reg. No.:	SBB95S	Date of Loss:	20/11/2018 22:00 - :59 [93 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D05510C01	Policy/Cover Note No.:	DMPCSN1640791802 (Comprehensive) Coverage: 28/07/2018 - 27/07/2019
		Excess:	S\$3,000.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2018]		
Driver/Custodian:	CHEAH KAH MENG (43 / Male), NRIC: S7563508G, Tel: +6593665433		
Adj Asg. Remarks:	Please check market value and any possible breach of policy condition.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5503M
Vehicle Details	
Vehicle No.:	SMF7907C (SBB 955)
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (SR+HID)
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	CGW002497
Chassis No.:	WAUZZZ4HXB007042
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	\$81,983.00
Original Registration Date:	28 Jan 2011
First Registration Date:	28 Jan 2011
Transfer Count:	1
Actual ARF Paid:	\$81,983.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2021
PARF Rebate Amount:	\$49,189.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$58,910.00
COE Rebate Amount:	\$12,732.00
Total Rebate Amount:	\$61,921.00

The information contained herein is correct as at 29 Nov 2018

OK

Vehicle Registration Detail Information Enquire Vehicle Registration Details

Page 1 of 1

Owner Particulars

NRIC/Passport/Company Cert No.: 201115503M
Owner ID Type: Company
Owner Name: MINT POWER ENGINEERING PTE LTD
Registered Address: 2024 BUKIT BATOK STREET 23 #01-48 SINGAPORE 659529
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SMF7907C
Previous Vehicle No.: SBB955
Effective Date of Ownership: 13 May 2013
Original Regn Date: 28 Jan 2011
Registration Date: 28 Jan 2011
Year of Manufacture: 2010
Vehicle Type: Passenger (Co) Company Car (Single Rate)
Vehicle Scheme: -
Vehicle Attachment 1: With Sun Roof
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: AUDI
Vehicle Model: A8L 3.0 TFSI QU (5R+HID)
Primary Colour: Blue
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: WAUZZZ4HXB007042
Engine No.: CGW002497
Engine Capacity / Power Rating: 2995 cc / -
Maximum Power Output: 213.0 kW (285 bhp)
Propellant: Petrol
Max Unladen Weight: 1880 kg
Maximum Laden Weight: 2530 kg
Open Market Value: \$81,983.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jan 2021
Minimum PARF Benefit: \$40,991.00
No. of Transfers: 1
IU Label No.: 1124470286
COE No.: 2011020103000514K
COE Expiry Date: 27 Jan 2021
COE Category: B - Car (1601cc & above)
COE Registration Category: B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium: \$58,910.00 / -
Actual QP Paid: \$58,910.00
QP (Regn Cat): \$58,910.00
OPC Cash Rebate Eligibility: No
QP during COE Bidding Exercise: \$58,910.00
Additional Registration Fee Rate: 100.00 %
Actual ARF Paid: \$81,983.00
Vehicle Lifespan Expiry Date: No Lifespan
CO2 Emission: -
CO Emission: -
HC Emission: -
NOx Emission: -
PM Emission: -

Message: To renew the COE, the Prevailing Quota Premium payable is that of Category B.

Print

OK

Save as PDF

View Received Message

This mail is associated with :

SBB95S (SNM18D05510C01)

OD

Nov 20 2018 10:00PM

[MINT POWER ENGINEERING PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 07/12/2018 13:50 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - SBB95S - Claim Handler: Elaine Cheong

Approved:0.00:PLEASE FINALIZE REPORT & FORWARD BILL FOR SERVICES RENDERED WHILE WE CREATE TENDER ON WRECK

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 29 Nov 2018

Preliminary Advice

Vehicle No	: SBB95S	Accident Date	: 20/11/2018
Make	: AUDI A8	Policy No.	: DMPCSN1640791802
Assignment Date	: 27/11/2018	Excess	: S\$3,000.00
Date of Inspection	: 28/11/2018	Est. Duration of Repair	: 0
Inspection At	: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	61,921.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,079.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TOTAL LOSS AS NOT ECONOMICAL TO REPAIR. THERE IS NO BREACH OF POLICY FOR THE VEHICLE.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 14:31
Date Of Accident	20/11/2018 22:00
Exact Location Of Accident	JALAN MELAWATI NEAR GELANG PATAH
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBB95S
-----------------------------	--------

Insured/Policyholder

Name Of Registered Owner	MINT POWER ENGINEERING PTE LTD
Co Reg No	201115503M 530 86127E
Email Address	MINTPWR@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93665433
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	AUDI
Model	A8-3.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1640791802
Cover Note Number	

Driver

Name of Driver	CHEAH KAH MENG
NRIC No	S7563508G
Date Of Birth	03/08/1975
Occupation	INDOOR
Date Of Driving Pass	01/03/2006
Driving Experience	12 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93665433
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	117 BUKIT BATOK WEST AVE 6 #09-238
Postcode	650117
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFIK ISKANDAR PUTERI
Police Station Address	ROAD: TRAFIK ISKANDAR PUTERI , POSTCODE: 00000 , COUNTRY: MALAYSIA
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER MALAYSIA POLICE REPORT NO: NUSA BESTARI/007458/18

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten signature]

[Handwritten signature]


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

the per mission police report No: KUSA BESTARI / 607458 / 18-

DECLARATION

I/We declare the foregoing particulars are true in every respect.



謝嘉明

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop _____
☐ For record purpose

Policy No. DMPCSN(64079187)
Insurer Chubb Veh.No. SB395

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : MUTIARA RINI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : NUSA BESTARI/007458/18
 Tarikh : 21/11/2018
 Waktu : 1046 AM
 Bahasa Diterima : B. Malaysia

Butir-butir Penerima Repot

Nama : MUHAMMAD ASYRAF BIN ZULKIFLE

No Personel : R175145

Pangkat : L/KPL

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : CHEAH KAH MENG

No K/P (Baru) : 750803086091

No Polis/Tentera : A3120989

No Paspot : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 03/08/1975

Umur : 43 tahun 3 bulan

Keturunan : Cina

Warganegara : Malaysia

Pekerjaan : WELDING

Alamat Tempat Tinggal : NO.15 JALAN JAGUH UTAMA TAMAN HARMONI 2 SKUDAI 81300 JOHOR BAHRU JOHOR MALAYSIA

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 018-7737348

Emel : ---

Pengadu Menyatakan:-

PADA 20/11/2018 JAM L/KURANG 2200 HRS SEMASA SAYA MEMANDU KERETA JENIS AUDI A8 (SBB95S) WARNA BIRU GELAP, SAMPAI DI JALAN MELAWATI TAMAN MELAWATI TIBA-TIBA ASAP KELUAR DARI BONET DEPAN. APABILA SAYA MEMBUAT PEMERIKSAAN DAPATI ADA API DI BAHAGIAN BONET DEPAN. SETELAH ITU SAYA HUBUNGI PIHAK BOMBA DAN PIHAK BOMBA BERJAYA MEMADAMKAN API TERSEBUT. AKIBAT KEBAKARAN ITU KERETA SAYA MENGALAMI KEROSAKAN PADA KESELURUHAN KERETA. SAYA TIDAK MENGALAMI KECEDERAAN. DATANG BALAI POLIS BUAT REPOT, TUJUANNYA INGIN RUJUK PADA PIHAK BERKENAAN. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada) :

Tandatangan Penerima Repot:

BALAI POLIS MUTIARA RINI
 NO. 26, JALAN UTAMA 45,
 TAMAN MUTIARA RINI,
 81300 SKUDAI, JOHOR.
 TEL. 07-5575122

Salinan Repot Pertama

POLICE REPORT Pg. 2

AS PER MALAYSIA POLICE REPORT NO.NUSA BESTARI/007458/18. ON 20/11/2018 @ ABT 2200HRS I WAS DRIVING MY BLUE COLOR AUDI A8 (5BB955). WHEN I ARRIVE JALAN MELAWATI TAMAN MELAWATI SUDDENLY I SAW SOME SMOKE CAME OUT FROM FRT BONNET. I THEN CAME DOWN FROM MY VEHICLE & FOUND THAT THERE WAS CAUGHT FIRE FROM FRT BONNET. I THEN CALL TO FIRE FIGHTER & FIRE FIGHTER HELP TO PUT OFF THE FIRE. THE IMPACT CAUSING MY VEHICLE DAMAGE TO WHOLE VEHICLE. I DID NOT INJURED IN THIS INCIDENT. I AM LODGING THIS REPORT FOR INSURANCE CLAIM. THAT'S ALL.

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN1640791802	Date of Loss:	20/11/2018
Vehicle Reg. No.:	SBB95S	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	MINT POWER ENGINEERING PTE LTD		
Driver:	CHEAH KAH MENG		
Make/Model:	AUDI A8, 3.0 (A)	Vehicle Reg. Date:	28/01/2011
Vehicle Colour:	BLUE	Chassis No:	WAUZZZ4HXB007042
Engine No:	CGW002497		
Odometer:	5 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	AS PER MALAYSIA POLICE REPORT NO: NUSA BESTARI/007458/18		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	0.00

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Yoon 97495749
Ex \$3000
Revert 28/11/18 @ 1730
sue@lkkauto.com

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2018)

Parts: 143 AUDI A8 3.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBB95S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There,are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2018 Sendback Est	27 Nov 2018 13:19 S\$0.00	27 Nov 2018 17:51 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: MINT POWER ENGINEERING PTE LTD , Co. Reg. No.: 201115503M									
Vehicle Reg. No.: SBB95S		Date of Loss: 20/11/2018 22:00 - :59 [93 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D05510C01		Policy/Cover Note No.: DMPCSN1640791802 (Comprehensive) Coverage: 28/07/2018 - 27/07/2019							
		Excess: S\$3,000.00							
Repairer: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/12/2018]									
Driver/Custodian: CHEAH KAH MENG (43 / Male), NRIC: S7563508G, Tel: +6593665433									
Adj Asg. Remarks: Please check market value and any possible breach of policy condition.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (07/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SBB95S - Claim Handler: Elaine Cheong 									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SBB95S (SNM18D05510C01)
 OD
 Nov 20 2018 10:00PM
 [MINT POWER ENGINEERING PTE LTD]
 Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View In Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	27/11/18 13:19	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/11/18 15:51	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/11/18 15:53	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
33	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>
34	29/11/18 15:53	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
36	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
37	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
38	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
39	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
40	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
41	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
42	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
43	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
44	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
45	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
46	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
47	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
48	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
49	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
50	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
51	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
52	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
53	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
54	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
55	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
56	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
57	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
58	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
59	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
60	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
61	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
62	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
63	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
64	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
65	29/11/18 15:53	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	27/11/18 13:19	CI,IC,DL	Load TIF	
2	27/11/18 13:19	E-filed GIA report	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 15:34	LTA.pdf	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/11/18 17:21	Accident Statement	Load HTM	
2	26/11/18 13:00	Addendum Sheet	Load TIF	
3	26/11/18 13:01	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/11/18 17:20	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
2	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	23/11/18 17:20	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/11/18 17:21	POLICE REPORT	 Load TIF	
2	26/11/18 13:00	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18021495/T1SD3E2

Date: 12/12/2018

REFERENCE

Insured/Claimant:	MINT POWER ENGINEERING PTE LTD	Policy No:	DMPCSN1640791802	Claim No:	SNM18D05510C01
Date of Loss:	20/11/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBB95S	Engine No:	CGW002497
Make & Model:	AUDI A8, 3.0 (A)	Chassis No:	WAUZZZ4HXB007042
Reg. Date:	28/01/2011 (Man. Year: 2010)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	3,000.00	-3,000.00	
(S\$)	0.00	-3,000.00	3,000.00	
+ GST 7.00/7.00% (S\$)	0.00	-210.00	210.00	
Nett Amount (S\$)	0.00	-3,210.00	3,210.00	

INSPECTION

Date of Assignment:	27/11/2018 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	28/11/2018 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$73,000.00
OMV : \$81,983.00
PARF Rebate (1) : \$49,189.00
Quota Premium Paid : \$58,910.00
COE Rebate (2) : \$12,732.00
Total Rebate (1) + (2) = : \$61,921.00

The total amount incurred will be Market Value \$73,000.00 minus Total Rebate \$61,921.00 = \$11,079.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2018)

Parts: 143 AUDI A8 3.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBB95S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >