

22/03/2002

ASS. REC. BY:

REF:

es/ICS1802/497/Ksd3et

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Crystabelle Tan

of

ICS

Date/Time:

27/11/18 @ 6:34pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 8363B

Insured:

SKX8454P

at Workshop m/s

Ah Jim Motor

Tel:

64563637

of

176 Sin Ming Drive # 05-12

Policy No:

Claim No:

DMPC1800444H/02/CT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/11/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/11/18 @ 10:28am

Person Contacted:

Nui Hong

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 8363B - X

SKX 8454P - X

13/12/19

Kenneth informed owner convert to OD claim, checked with Mei Li Gypar.

ASS. REC. BY:

REF: 1051

Kenneth


## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Ah Lim  
 of S/M  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

3pm

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 04 days Res.: Yes or No  
 Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SFL 8363B Yr Regn: 09, 16  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy wish c.c. 1.788  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading 41912 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: JTDGG 20W 10 J005163

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / MRim or

Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 4 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/11/18D.O.I. 28/11/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015Rm body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/11 File pass to Catherine

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

16/2/19

☒: Prel. Report☐: Final Report

1) Type

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + R.S. SI

Fixtures

Others

TOTAL

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

Report Format:

Prel:

Lump Sum / I.B.I.: (\$

290

11

261

## Nivitha (LKK Auto)

---

**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**Sent:** Tuesday, 27 November 2018 6:34 PM  
**To:** assignments  
**Subject:** FW: Request to register TP claim - Our Client Vehicle SFL8363B insured under AXA against your insured Vehicle SKX 8454P acc on 21/11/2018 (Our Ref : DMPC1800444H/02/CT)  
**Attachments:** 8363-Estimate.pdf; 8363-AXA.PDF; SAS.PDF

Dear LKK

Please refer to below email and arrange survey.  
Liability not clear cut.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg)

ECICS Limited  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

---

**From:** [meili@almsm.com.sg](mailto:meili@almsm.com.sg) [mailto:[meili@almsm.com.sg](mailto:meili@almsm.com.sg)]  
**Sent:** Tuesday, 27 November, 2018 2:58 PM  
**To:** ECICS Claims  
**Subject:** Request to register TP claim - Our Client Vehicle SFL8363B insured under AXA against your insured Vehicle SKX 8454P acc on 21/11/2018

Dear Moto Claims Team,

We refer to the attachment.

Kindly assist to register our client's TOP claim against your insured's policy and also arrange appointment to survey on my client's vehicle.

Regards,

Meili Tan - (Sin Ming)  
176 Sin Ming Drive  
#05-12 Sin Ming Autocare  
Singapore 575721  
Tel : 6456 3637 Fax: 6456 3686  
email : [meili@almsm.com.sg](mailto:meili@almsm.com.sg)

follow us on  follow us on  visit our website [ecics.com.sg](http://ecics.com.sg) 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHAY PUI LING  
31 CASUARINA WALK  
SINGAPORE 574089

Estimate No: MCS1102605  
Date: 23 Nov 2018  
Policy No: P1969242  
Veh Reg No: SLF8363B  
Make/Model: TOYOTA WISH

ATTN:

Your Ref No: SLF8363B  
Claim Type: Third Party  
Accident Date: 21/11/2018  
TP Veh Reg No: SKX8454P

*Not Authorized*  
*1. B.1*  
*Primary B.1*

*4 days*

## Estimate Repair Cost to Vehicle No :SLF8363B

Description	Quantity	List Price	Amount
		SS	SS
<b>SPARE PARTS</b>			
1 FRONT FENDER RH	1 PC	855.00	X
2 FRONT FENDER COWLING CLIPS	10 PC	40.00	X
3 FRONT DOOR RH	1 PC	1,395.00	✓
4 FRONT DOOR TAPE	1 PC	75.00	✓
5 FRONT DOOR LOWER DOOR CHROME MOULDING	1 PC	271.00	✓
6 SIDE SKIRT RH	1 PC	1,090.00	✓
7 SIDE SKIRT LOWER CLIPS	8 PC	40.00	✓
		3,766.00	
	Less 25%	941.50	2,824.50
<b>LABOUR</b>			
8 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	1 EA	80.00	601
9 LABOUR TO DISMANTLE & INSTALL FRONT RH POWER WINDOW MOTOR AND GEAR	1 PC	80.00	601
10 TO DISMANTLE ALL DAMAGED PARTS, TO KNOCK & REPAIR FRONT RH AFFECTED AREA, ALIGN FRONT DOOR RH AND FENDER RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	3601
11 TO SPRAY FRONT FENDER RH, FRONT DOOR RH, SIDE SKIRT RH	1 PC	600.00	✓
		1,160.00	1,160.00
		Total	S\$ 3,984.50
		Add GST @ 7%	278.92
		Total Amount Payable	S\$ 4,263.42

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED SIXTY THREE AND CENTS FORTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1063H
<b>Vehicle Details</b>	
Vehicle No.:	SLF8363B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ZR1834002
Chassis No.:	JTDGG20W10J005163
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	13 Sep 2016
First Registration Date:	13 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2026
PARF Rebate Amount:	\$14,966.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$44,021.00
<b>Total Rebate Amount:</b>	<b>\$58,987.00</b>

The information contained herein is correct as at 22 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/11/2018 16:24
Date Of Accident	21/11/2018 12:30
Exact Location Of Accident	CLAYMORE HILL B4 YELLOW BOX JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF8363B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHAY PUI LING
NRIC No	S8431063H
Email Address	WHAMPLPS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91383552
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1969242
Cover Note Number	13/09/2017 TO 12/09/2019

### Driver

Name of Driver	CHAY WAI HON
NRIC No	S0016223Z
Date Of Birth	17/02/1951
Occupation	INDOOR
Date Of Driving Pass	07/02/1975
Driving Experience	43 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91383552
Fax Number	
Contact Number	
Email Address	WHAMPLPS@HOTMAIL.COM

Address	31 CASUARINA WALK
Postcode	574089
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING TO RETRIEVE VIDEO FOOTAGE FRM MEMORY CARD
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX8454P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PATRICK LOW CHUN LEONG
NRIC/Passport Number	S7619497A
Contact Number	9011770D
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

ACA

Vehicle:- SLF 8363B

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date &amp; Time:

22/11/18  
3:10pm

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

22/11/18 3:10pm

Reporting Centre Person's Signature


Name:

NRIC/PIN No.:

Hual  
22/11/18

# Sketch Plan Pg. 2

Date of accident: 21/11/2018 Time: 1230hr Location: Claymore Hill (outside)  
 My Vehicle A: SLF 8363B Vehicle B: SKX 8454P Vehicle C: —  
 SKETCH PLAN



Car A — SLF 8363B

Car B — SKX 8454P

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A was along Claymore Hill in direction towards Scotts Road at about 1230hr on 21/11/2018. It was behind the yellow box when heavy traffic built up. As traffic eases up, Car A was about to proceed forward within its left lane, but gave way to 2 buses. While within left lane, Car B moved into left lane at high speed, colliding into the right front (driver) door of Car A. The front-left bumper of Car B made direct contact with the front driver door of Car A, creating a severe dent and scratches. Car B then reversed creating more scratches on the back right bumper of Car A. A discussion was held between both parties and the initial agreement was the Car B driver was willing to settle privately by paying for both cars' damages. Subsequently Car B driver decided to let insurance settle.

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: whampls@hotmail.com.

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect. Vehicle: —

SLF 8363B

Policyholder's Signature

Date & Time: 21/11/18

2:10pm

GAEMC Sketch Plan Form 15

Driver's Signature

(If driver is not the policyholder)

Date & Time:

21/11/18 3:00pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

21/11/18



AXA INSURANCE PTE LTD  
8 Shenton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #B1-01  
Tel: (65) 63387288 Fax: (65) 63382522  
Website: www.axa.com.sg  
GST Registration Number: 199903512M  
customer.service@axa.com.sg

Driver's Particulars Pg. 1



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P1969242 Account No. : 14886  
Coverage : Comprehensive (SmartDrive Toyota Prestige)  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : CHAY PUI LING (XIE PEILING)  
Vehicle Registration No. : SLF8363B  
Period of Insurance : From 13/09/2017 To 12/09/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

- (a) The Policyholder  
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner  
(b) Any other person who is driving on the Policyholder's order or with his permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business  
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

Basic Own Damage Excess : SGD 600.00 (Q1)  
An Additional Excess is applicable as follows:  
S\$2,500.00 for Young or Inexperienced Driver.  
Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Issued by - SGOAGPH on 14/08/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

Authorized Signature

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2019 12:48 <a href="#">Edit Reg</a>		27 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,233.25</b> <a href="#">Edit Estimates</a>	<b>S\$3,233.25</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>CHAY PUI LING</b> , ID: S8431063H									
Vehicle Reg. No.: <b>SLF8363B</b>		Date of Loss: 21/11/2018 12:00 - :59 [26 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / DMPC1800444H/CT</b>		Policy/Cover Note No.: MPC17A00623500							
Vehicle Reg. No. (Insured): <b>SKX8454P</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ah Lim Motor Company (Sin Ming)</b> 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Crystabelle Tan</b> - 6303 0190]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 07/12/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLF8363B (DMPC1800444H/CT)  
[SKX8454P]  
TP  
CHAY PUI LING  
Nov 21 2018 12:00PM  
[-]  
Ah Lim Motor Company

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
2	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
3	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
4	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
5	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
6	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
7	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
8	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
9	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
10	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
11	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
12	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
13	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	
14	18/12/19 13:15	General View		Load JPG	<input checked="" type="checkbox"/>	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18021497/KSD3E2

Date: 18/12/2019

## REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC17A00623500  
 Claimant SLF8363B Insured Vehicle No : SKX8454P  
 Vehicle No : SLF8363B  
 Date of Loss: 21/11/2018 Nature of Claim: TP Claim No: DMPC1800444H/CT

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLF8363B  
 Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1834002  
 Reg. Date: 13/09/2016 (Man. Year: 2016) Chassis No: JTDGG20W10J005163  
 Colour: Metallic Black Odometer: 41912 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 4 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,824.50	2,153.25	671.25	23.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	1,080.00	80.00	6.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,984.50</b>	<b>3,233.25</b>	<b>751.25</b>	<b>18.85</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>278.92</b>	<b>226.33</b>	<b>52.59</b>	<b>18.85</b>
<b>Nett Amount (S\$)</b>	<b>4,263.42</b>	<b>3,459.58</b>	<b>803.84</b>	<b>18.85</b>

## INSPECTION

Date of Assignment: 27/11/2018  
 Date Inspected: 28/11/2018 Inspected At: Ah Lim Motor Company (Sin Ming)  
 176 Sin Ming Drive #05-12, Sin Ming  
 AutoCare  
 Singapore 575721  
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2019)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF8363B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER RH	Repair	855.00 FL	*- FL
2	10	*FRONT FENDER COWLING CLIPS	Not Necessary	40.00 FL	*- FL
3	1	*FRONT DOOR RH	Bent	1,395.00 FL	*1,395.00 FL
4	1	*FRONT DOOR TAPE	Necessary	75.00 FL	*75.00 FL
5	1	*FRONT DOOR LOWER DOOR CHROME MOULDING	Distorted	271.00 FL	*271.00 FL
6	1	*SIDE SKIRT RH	Distorted	1,090.00 FL	*1,090.00 FL
7	8	*SIDE SKIRT LOWER CLIPS	Necessary	40.00 FL	*40.00 FL
				<b>Sub Total (S\$)</b>	<b>3,766.00 2,871.00</b>
				<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>941.50 717.75</b>
				<b>Total Parts (S\$)</b>	<b>2,824.50 2,153.25</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
2	LABOUR TO DISMANTLE & INSTALL FRONT RH POWER WINDOW MOTOR AND GEAR	New	80.00	60.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT RH AFFECTED AREA, ALIGN FRONT DOOR RH AND FENDER RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	400.00	360.00
4	TO SPRAY FRONT FENDER RH, FRONT DOOR RH, SIDE SKIRT RH	New	600.00	600.00
Gross Labour Cost (\$\$)			<b>1,160.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >