

22/03/2002

ASS. REC. BY:

REF:

CS/AIG18021503/D/d302

Special Instruction:

Survivor:

Boyer

ASSIGNMENT (Office)

From (Person):

Azlan Syazairidina

of

AIG

Date/Time:

28/11/18 @ 1:11pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 6620K

Insured:

SLJ 652Z

at Workshop m/s

Gonheet Inc

Star

Automobile

Tel:

9145 4773

of

Blk 5033, AMK Ind. Park 2 #01-255

Policy No:

0999994500

Claim No:

4190297389SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/11/2018

CA / REV / REP. / REV 24 HRS

(up)

29/11/18

H.O.D. Endorsement:

Date/Time:

1:14pm @ 28/11/18

Person Contacted:

Alfred

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBG 6620K-X

SLJ 652Z-X.

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBG 6620 K Yr Regn: 9 17Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982Colour: Orange A/C: Insured / Std / NI / NASp. Reading: 65229 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDY2318030 519.Gen. Cond: Good / Fair / Poor / BurntSteering: Insider / Jammed / Leaked / Burnt orBrake: Insider / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/75R15R: 155R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Bridgestone Rear: YokohamaR/Bal. 3 mm R/Bal. 7/7 mmL/Bal. 3 mm L/Bal. 7/7 mmD.O.A. 24/11/2018 D.O.I. 29/11/2018Survey held at Goh Lee Hwa  
Satay Automobile AMIC 9/5033Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ALG SLJ 652 Z10/12/18 Jinar 1/5 2400/- with 5 days 7 yr.  
(Red) 2437! 56%

RECEIVED 12 DEC 2018

Date/Time: File Pass to?

☐ : Preli. Report10/12/18 Typist☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Photos

Other

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TP  
2400/-25020260

- Pre repair inspection request - GBG6620K VS SLJ652Z (OI) DOA: 24/11/2018

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Abu Kassim, Noor Mariesa, Kaur, Baljit, Hor, Yinrul  
Sent: 28/11/2018 1:11:55 PM  
Attachments:  img-Y28112634.pdf

Hi,

Please refer to the enclosed request from **STAR AUTOMOBILE SERVICES**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]  
**Sent:** Wednesday, November 28, 2018 12:18 PM  
**To:** Azlan, Syazairdina  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul  
**Subject:** Oref: L18.1615.cj.agreed(star) Pls code our ref - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ652Z AND GBG6620K ON 24/11/2018

Dear Sirs

We refer to your email of 28.11.18.

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

STAR AUTOMOBILE SERVICES  
Blk 5033 Ang Mo Kio Ind Pk 2 #01-255  
Singapore 569536  
Contact: 91454773 Alfred

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards  
Irene  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

On Wednesday, 28 November 2018, 11:49:40 AM SGT, Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:

<p>This is a secure, encrypted message. To read it, open the attachment.</p> <p>这是安全加密信息。如要阅读此信息，请开启附件。</p> <p>นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา</p> <p>이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.</p> <p>Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.</p> <p><a href="#">Click here</a> by 2018-12-05 11:49 +08 to read your message. After that, open the attachment.</p> <p><a href="#">More info</a></p>

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: kurulegal@yahoo.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, NoorMariesa.AbuKassim@aig.com, Baijit.Kaur@aig.com, Yin

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ652Z AND GBG6620K ON 24/11/2018

Date: Wed, 28 Nov 2018 03:49:26 +0000

Without Prejudice

Your Reference : GBG 6620K

Our Reference : SLJ652Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

**From:** Lim, Sheng Yang

**Sent:** Wednesday, November 28, 2018 11:37 AM

**To:** Azlan, Syazairdina

**Subject:** FW: L18.1615.cj.PRI / ACCIDENT INVOLVING GBG6620K, SLJ652Z & SHC6201Z on 24/11/2018 ALONG sin ming avenue NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]

**Sent:** Wednesday, November 28, 2018 11:36 AM

**To:** AIG SGP, Claims-Survey; Lim, Sheng Yang; Motor Claim - III; Sundari Nagarajan - III

**Subject:** L18.1615.cj.PRI / ACCIDENT INVOLVING GBG6620K, SLJ652Z & SHC6201Z on 24/11/2018 ALONG sin ming avenue NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear sirs

**ACCIDENT INVOLVING GBG 6620K, SLJ 652Z & SHC 6201Z ON 24/11/2018  
ALONG SIN MING AVENUE  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for Aik Chin Hin Machinery Co, whose vehicle registration number **GBG 6620K** was damaged in the above accident.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

A copy of our client's SAS report is enclosed.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	0400C
<b>Vehicle Details</b>	
Vehicle No.:	GBG6620K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 M
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2735565
Chassis No.:	KDY2318030519
Maximum Power Output:	-
Open Market Value:	\$32,708.00
Original Registration Date:	26 Sep 2017
First Registration Date:	26 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,636.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,322.00
COE Rebate Amount:	\$28,398.00
<b>Total Rebate Amount:</b>	<b>\$28,398.00</b>

The information contained herein is correct as at 12 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/11/2018 16:15
Date Of Accident	24/11/2018 12:05
Exact Location Of Accident	SIN MING AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG6620K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AIK CHIN HIN MACHINERY CO
Co Reg No	20030400C
Email Address	FANGSHEN@AIKCHINHIN.COM
Mobile Phone No	
Alternative Phone No	OFFICE-64635888

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994831
Cover Note Number	

### Driver

Name of Driver	WONG KWONG MIN
NRIC No	S1551901J
Date Of Birth	22/05/1962
Occupation	INDOOR
Date Of Driving Pass	19/11/1984
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90614245
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 270 BANGKIT ROAD #05-08
Postcode	670270
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED .

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DRIVER DID NOT PROVIDE AT TIME OF REPORTING
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ652Z
Vehicle Make/Model/Colour	MITSUBISHI / ATTRAGE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SHYR DER
NRIC/Passport Number	S7317344B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC8201Z
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



(C) SHC 8201 Z

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 26-11-18

Reporting Centre Personnel's Signature  
Name:  
NEIC/FIN No.:



HOTLINE TEL: (65) 6419-3000  
FAX: (65) 6415-3723

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.300

COMMERCIAL AUTOPLUS COMPREHENSIVE

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCES S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED S\$1.00

INSURING WITH COE/PARF YES

CERTIFICATE NO. 999994831/100864228-00003

1) VEHICLE REGISTRATION NO.

GBG6620K

2) NAME OF INSURED

Aik Chin Hin Machinery Co

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

26 Sep 2018

4) DATE OF EXPIRY OF INSURANCE

27 Jan 2019

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE \*

Any person who is driving on the Insured's order or with their permission.

An additional Young and Inexperienced Driver (YIDR) Excess of S\$3,000 (unless otherwise stated) applies to any drivers(named and unnamed) who is below age 23 or has less than 2 years driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### 6) LIMITATION AS TO USE \*

1) Use in connection with the Insured's business.

2) Use for the carriage of passenger (other than for hire or reward) in connection with the Insured's business.

3) Use for social, domestic or pleasure purposes.

The Policy does not cover : a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.

b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

SOLE AGENT'S WORKSHOP : For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.

AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. Star Automotive Ctr - 5 Portsdown Rd [Tel: 65620000]

4. Sin Yew Hup Welding - 4 Woodlands Rd [Tel: 67600819]

2. Lai Huat Meng Kee Motor - 21, Sin Ming Ind [Tel: 64538110]

5. Delgro Engrg P L - 205 Braddell Rd [Tel: 63837118]

3. Kan Fook Sing Motor - 1069, Eunos Ave 5 [Tel: 67479560]

6. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

LOSS OF USE NOT INCLUDED

\* NAMED DRIVER N/A

HIRE PURCHASE COMPANY NA

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 26 Sep 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD

504148-000

BSC INSURANCE AGENCY PTE LTD

123 BUKIT MERAH LANE 1 #03-92 ALEXANDRA VILLAGE SINGAPORE 150123

Authorised Representative

ORIGINAL

SSCFKJ

Goh Lee Hwa

**STAR AUTOMOBILE SERVICES PTE LTD**

Block 5033 Ang Mo Kio Industrial Park 2  
#01-255 Singapore 569536  
Tel no: (65) 6482 1009  
Fax no: (65) 6482 4452

- Auto Consultants hence notify the Repairer the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Ref: 281118.

Re: TP Claim.

Acknowledged by Repairer

Signature:

Date:

28-11-2018

Aik Ehin Hin Machinery Co.

Blk 5022 Ang Mo Kio Ind PK. 2.

Singapore 569525 # 01-31

Toyota Dyna.

Estimated Repair Cost For Vehicle Reg No: GBE 6620 K.

1pc Tail Boot. 1m	740.00 X
4pc Tail Boot Hanger. 2pc Bt 2pc 40.00	80.00 160.00 LL
2pc Tail Boot lock Handle 48.00	96.00 X
1pc Dyna Sticker. 45.00	45.00 Net
1pc 70 km/h Sticker. 10.00	10.00 Net
1pc Company Sticker. 90.00	90.00 Belt
1set Nippon Paint & Logo Sticker. 190.00	190.00 net
2pc Rear Lamp. 288.00	288.00 576.00 LL
2pc Rear Top Reflector. 48.00	96.00
1pc Reverser Camera. 235.00	235.00 Net
1pc No Probe. & Box Bt	50.00 Net
To check wiring.	100.00 30/-
To Knocking, Straightening, Repair & Renew all accident affected area.	900.00 700/-
To remove & Refit Reassignment Rear Carriage.	400.00 350.00
To Respray Painting on all accident affected area	550.00 500/-
<b>Total</b>	<b>4238.00</b>
1pc Rear End Panel Dented	599.00
	<b>4837.00</b>

28/11/2018 eikon

Net Amount

2/5m 5 dgs.

2/5m 5 dgs.

parts 1063.00

25% 797.25

Net 620.00

101W 1580.00

2977.25 2/5 2400/-

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Nov 2018 <a href="#">Edit Reg</a>		28 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>ANNA ORGANIC,</b> Co. Reg. No.: 53365154M								
Main Claimant:	-								
Vehicle Reg. No.:	<b>GBG6620K</b>	Date of Loss:	24/11/2018 00:00 - :59 [13 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4190297389SG</b>	Policy/Cover Note No.:	0999994560 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLJ652Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Star Automobile Services (HQ)</b> Blk 5033 Ang Mo Kio Industrial Park 2, #01-253, 569536 Ang Mo Kio - Tel: 64821009								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 07/12/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (29/11/2018): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































## Claim Documents




















\*GBG6620K (4190297389SG)  
[SLJ652Z]

TP

-

Nov 24 2018 12:00AM  
[ANNA ORGANIC]  
Star Automobile Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	10/12/18 17:59	Rear View Right														Load JPG	<input checked="" type="checkbox"/>			
2	10/12/18 17:59	Rear View Left														Load JPG	<input checked="" type="checkbox"/>			
3	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
4	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
5	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
6	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
7	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
8	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
9	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
10	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
11	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
12	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
13	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
14	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
15	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
16	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
17	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
18	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
19	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
20	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
21	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
22	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
23	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
24	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
25	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
26	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
27	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
28	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
29	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
30	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
31	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
32	10/12/18 17:59	General View														Load JPG	<input checked="" type="checkbox"/>			
33	10/12/18 17:59	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>			
34	10/12/18 17:59	Chassis Number														Load JPG	<input checked="" type="checkbox"/>			
35	10/12/18 17:59	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
36	10/12/18 17:59	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
37	10/12/18 17:59	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/12/18 17:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/12/18 17:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/12/18 17:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/12/18 18:00	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/11/18 08:49	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18021503/DTD3E2

Date: 28/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994560

Claimant Vehicle No : GBG6620K

Insured Vehicle No : SLJ652Z

Date of Loss: 24/11/2018

Nature of Claim: TP

Claim No: 4190297389SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG6620K</b>	Engine No:	1KD2735565
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Chassis No:	KDY2318030519
Reg. Date:	26/09/2017 (Man. Year: 2017)	Odometer:	65229 km
Colour:	Orange		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,887.00	1,417.25	1,469.75	50.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,580.00	370.00	18.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,837.00</b>	<b>2,997.25</b>	<b>1,839.75</b>	<b>38.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,837.00</b>	<b>2,400.00</b>	<b>2,437.00</b>	<b>50.38</b>

## INSPECTION

Date of Assignment: 28/11/2018

Date Inspected: 29/11/2018 Inspected At:

Star Automobile Services (HQ)  
BLK 5033 ANG MO KIO INDUSTRIAL  
PARK 2 #01-255  
SINGAPORE 569536

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL BOOT	Repair	740.00 F	*- FL
2	1		*TAIL BOOT HINGER (4PCS)	Bent-2pcs / Not Necessary-2pcs	160.00 F	*80.00 FL
3	2		*TAIL BOOT LOCK HANDLE	Repair	96.00 F	*- FL
4	1		*DYNA STICKER	Necessary	45.00 FS	*45.00 FS
5	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
6	1		*COMPANY STICKER	Necessary	90.00 FS	*90.00 FS
7	1		*NIPPON PAINT & LOGO STICKER	Necessary	190.00 FS	*190.00 FS
8	1		*REAR LAMP	N/S Cracked / O/S NotNecessary	576.00 F	*288.00 FL
9	2		*REAR TOP REFLECTOR	Cracked	96.00 F	*96.00 FL
10	1		*REVERSE CAMERA	Damaged	235.00 FS	*235.00 FS
11	1		*NO PLATE & BOX	Bent	50.00 FS	*50.00 FS
12	1		*REAR END PANEL	Dented	599.00 F	*599.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,887.00</b>	<b>1,683.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	<b>0.00</b>	<b>265.75</b>

<b>Total Parts (S\$)</b>	<b>2,887.00</b>	<b>1,417.25</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	100.00	30.00
2	TO KNOCKING, STRAIGHTENING, REPAIR & RENEW ALL ACCIDENT AFFECTED AREA	New	900.00	700.00
3	TO REMOVE & REFIT REALIGNMENT REAR CARRIAGE	New	400.00	350.00
4	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	550.00	500.00
Gross Labour Cost (S\$)			<b>1,950.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >