

ASS. REC. BY:

REF:

05/SPF18021508/Kiv d302

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Frankie Thuy

of

SPF

Date/Time:

28/11/18 @ 2:24pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV? CS

To Inspect Vehicle No:

GIBH 3469X

Insured:

GX 35Y

at Workshop m/s

Est/sem performance

Tel:

64841221

of

Blk 5033 Amk Ind. Park 2 #01-259

Policy No:

Claim No:

AEMD/105/009/2018/093

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30072018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

1:17pm @ 28/11/18

Person Contacted:

jenny

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

GIBH 3469X-X

Frankie said no G1A

8/11

8602-97 to Submit

Range \$600 - \$700 (Est)

ASS. REC. BY:

REF:

SPI-1

Kenneth

ASSIGNMENT

GB

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGH 346PX Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS NV200 c.c. 1461Colour: White A/C: Insured / Std / NI / NASp. Reading: 16293 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 2070157335Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 175/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/12 File pass to Catherine

RECEIVED 30 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 8/1 - typist

Days Of Repair: 2Resurvey No. of Trlp: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS, SI

Fixpos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

TP
602.97

280

280

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Wednesday, 28 November 2018 2:24 PM
To: assignments; Catherine Chong
Cc: Rosalyn TAN (SPF); Abdul Rahman MOHAMAD SALIM (SPF); Olivia Lau (LKKAuto)
Subject: RE : AEMD/105/009/2018/093 Pre-repair Inspection for GBH3469X

Your reference : GBH3469X

Our reference : AEMD/105/009/2018/093

Catherine,

Please conduct a Pre-repair Inspection for vehicle GBH3469X at Esteem Performance Pte Ltd at Blk 5033 Ang Mo Kio Industrial Park 2 #01-259, Singapore 569536.

Please contact the workshop at 64841221 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 11:28
Date Of Accident	30/07/2018 11:30
Exact Location Of Accident	STILL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH3469X
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	PURCHASING@PESTBUSTERS.COM.SG
Mobile Phone No	(LOCAL) +65-94292421
Alternative Phone No	OFFICE-94292421

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V00032/VCZ/R03
Cover Note Number	

Driver

Name of Driver	WAN AZWIN BIN WAN ARIFFIN
Passport No/FIN	G6952532L
Date Of Birth	27/03/1987
Occupation	OUTDOOR
Date Of Driving Pass	14/05/2012
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94292421
Fax Number	
Contact Number	
EMail Address	PURCHASING@PESTBUSTERS.COM.SG

Address	NO.16 JALAN ANGGERIK 2 TAMAN JOHOR JAYA
Postcode	81100
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX35Y
Vehicle Make/Model/Colour	SUBARU / WHITE
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	CHER YUAN LI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




 30/7/2018
 Policyholder's Signature / Date & Time Driver's Signature (If Driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan 4-




Describe Circumstance of the Accident:


ON 30/07/2018 at around 1130hrs, I was at the traffic light along Still road towards marine parade road. The traffic light was red so I was stationary. I was on the extreme right lane where it was the second last lane of the 5 lanes. Next to my right was a right filter lane that enters into Joo Chial Place. As I was waiting at the traffic light in my vehicle, suddenly there was a police car behind me who was trying to enter into the right filter lane on my right and as the space was quite tight, the police car managed to squeeze through but the left side of the police vehicle ended up scratching the right rear side of my vehicle. NO one was injured and subsequently traffic police arrived and I was given a case number of G/20180730/0097. I only managed to get the name of the other driver who drove the police car. I was then advised by the traffic police to lodge a traffic accident report about this. I am also lodging this report for my company's insurance claim.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Stamp



 30/7/2018
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20180730/2068

1 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No: T/20180730/2068

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/07/2018 13:20		Vide Report No.: G/20180730/0097		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: WAN AZWIN BIN WAN ARIFFIN			Address:		
ID Type / ID No.: FIN NO / G6952532L			Contact No.: Home/Office: Mobile: 94292421		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 31	Date of Birth: 27/03/1987	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: PEST TECHNICIAN			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 30/07/2018 11:30	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 STILL ROAD MARINE PARADE ROAD STILL ROAD TOWARDS MARINE PARADE ROAD BEFORE JOO CHIAT PLACE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH3469X	Van				Slightly Damaged	0
QX35Y	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180730/2068

2 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20180730/2068

CONTINUATION OF REPORT

Driver				
Name	WAN AZWIN BIN WAN ARIFFIN		ID No.	G6952532L
Related Vehicle	GBH3469X (Van)		Contact No.	94292421
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	CHER YUAN LI		ID No.	NIL
Related Vehicle	QX35Y (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 30/07/2018 at around 1130hrs, I was at the traffic light along still road towards marine parade road. The traffic light was red so I was stationary. I was on the extreme right lane where it was the second last lane of the 5 lanes. Next to my right was a right filter lane that enters into Joo Chiat Place. As I was waiting at the traffic light in my vehicle, suddenly there was a police car behind me who was trying to enter into the right filter lane on my right and as the space was quite tight, the police car managed to squeeze through but the left side of the police vehicle ended up scratching the right rear side of my vehicle. No one was injured and subsequently traffic police arrived and I was given a case number of G/20180730/0097. I only managed to get the name of the other driver who drove the police car. I was then advised by the traffic police to lodge a traffic accident report about this. I am also lodging this report for my company's insurance claim.



SINGAPORE
POLICE FORCE



T/20180730/2068

3 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999





Report No. T/20180730/2068

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 DEMI HUW ZONG LING 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/07/2018 13:20
Officer In Charge Of Case: TP / DDGVT / SSI TAY CHUN KEEN Contact No.: 65476229 	Classification Of Case:
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE

Tel: 6477 4840 Frank
Fax: 6477 4840



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

call Ukk (Linda) 6256 3581

Your Ref : QX 35 Y
Our Ref : GBH 3469 X

Date : 23th Nov 2018

SPF Accident Claim Section
Automotive Engg & Mgmt Div
Police Logistics Department
New Phoenix Park,
28 Irrawaddy Road,
Singapore 329560

Dear Sir / Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Goldbell Car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.GBH 3469 X.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : BLK 5033 Ang Mo Kio Industrial park 2 #01-259 (s) 569536

Tel : 6484 1221
Fax : 6484 7829

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Your Faithfully

Jayne Chong



Encl :GIA Report



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

GBH 3469 X

*Not Authorized
Resurvey After Repair*

Parts	(a) Cost / List Price Items	
	Plus/Less	\$ -
	Total of Cost / List	\$ -
	(b) Nett Price Items	\$ 986.90
	Less 10%	\$ 98.69
	Total of Nett Item	\$ 888.21
	(c) Special Nett Items	\$ 300.00
Total Parts Cost		\$ 1,188.21
Labour		\$ 1,690.00
Total		\$ 2,878.21

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennedy
Company : LKLC
Survey conducted on : 30/11/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : LK Date: 30/11/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBH 3469 X**
Make & Model : **NISSAN NV200**
Chassis No. : **VSKYBAM20Z0157335**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$265.00	S.N	X
2	Rear bumper	1	\$624.80	N	X
3	Rear bumper clip	10	\$35.00	S.N	X
4	Rear bumper side retainer RH	1	\$45.20	N	X
5	Rear bumper bracket RH	1	N/A		X
6	Rear bumper reflector RH	1	\$48.60	N	X
7	Rear bumper tow cover	1	\$65.00	N	X
8	Tail lamp RH	1	\$203.30	N	✓
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Veron Chen (LKKAUTO)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Tuesday, 8 January 2019 10:08 AM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: Re: CHECK VEHICLE STATUS-GBH 3469X

Dear Veron,

Noted.

Thank you



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Tue, Jan 8, 2019 at 9:56 AM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Carmen,

WITHOUT PREJUDICE

GBH 3469X- For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Monday, 7 January 2019 6:13 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: CHECK VEHICLE STATUS

Dear Veron,

I just email to Kenneth request for finalised.

Thanks



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteempowerperformance.com



On Fri, Jan 4, 2019 at 3:47 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Carmen,

Kindly advise vehicle status.

Vehicle has been repaired?

<u>VEHICLE</u>	<u>DOA</u>
----------------	------------

1.GBH 3469X	30/7/18
2.SLF 7429C	13/11/18

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 January 2019 9:56 AM
To: Carmen Lim; SUR
Subject: RE: CHECK VEHICLE STATUS-GBH 3469X

Dear Carmen,

WITHOUT PREJUDICE

GBH 3469X- For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Monday, 7 January 2019 6:13 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: CHECK VEHICLE STATUS

Dear Veron,

I just email to Kenneth request for finalised.

Thanks

Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Fri, Jan 4, 2019 at 3:47 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Carmen,

Kindly advise vehicle status.

Vehicle has been repaired?

<u>VEHICLE</u>	<u>DOA</u>
----------------	------------

- | | |
|--------------|----------|
| 1. GBH 3469X | 30/7/18 |
| 2. SLF 7429C | 13/11/18 |

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18021508/Kvd3e2		
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : FRANKIE THAY		Date : 08-01-2019 Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 35Y	Veh. Inspected	GBH 3469X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/093	Excess (\$)	0.00	
Assign From	FRANKIE THAY	Assign Date	28/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VSKYBAM20Z0157335	Colour	WHITE	
Odometer	16293	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	GOODYEAR	9 mm	
L/H Front Tyre	175/70 R14	GOODYEAR	9 mm	
R/H Rear Tyre	175/70 R14	GOODYEAR	9 mm	
L/H Rear Tyre	175/70 R14	GOODYEAR	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/07/2018	Inspection Date	30/11/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 3469X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N)	SERVICEABLE	624.80	-
1	REAR BUMPER SIDE RETAINER RH (N)	SERVICEABLE	45.20	-
1	REAR BUMPER BRACKET RH (NPA) (N)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER REFLECTOR RH (N)	SERVICEABLE	48.60	-
1	REAR BUMPER TOW COVER (N)	SERVICEABLE	65.00	-
1	TAIL LAMP RH (N)	CRACKED	203.30	203.30
	LESS 10% DISCOUNT		-98.69	-20.33
			888.21	182.97
<u>SPECIAL NETT ITEMS</u>				
2	REVERSE SENSOR (SN)	SERVICEABLE	265.00	-
10	REAR BUMPER CLIP (SN)	NOT NECESSARY	35.00	-
			300.00	-
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, RH REAR FENDER). INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET RH.		400.00	200.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, RH REAR FENDER)		400.00	200.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
	TO DO ART WORK.	NOT NECESSARY	600.00	-
			1,690.00	420.00
GRAND TOTAL			2,878.21	602.97
RECOMMENDED COST OF REPAIRS				602.97

Report Ref No. CS/SPF18021508/Kvd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$600-\$700

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.