

22/03/2002

ASS. REC. BY:

REF: CS/GAI18021509/TISD302

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Kelvyna Ngich

of

GAI

Date/Time:

28/11/08 @ 4:14pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 98935

Insured:

FBK 2417 L

at Workshop m/s

Autowheel

Tel:

91928963

of

No. 1 Bkt Butok Crescent #02-40

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/18

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time:

5:41pm @ 28/11/18

Person Contacted:

Louis

Vehicle IN ~~OUT~~

Date/Time

Action/Instruction (✓) Estimate

SJR 98935-X

FBK 2417 L-X

29/11/18-

UNI yet

05/12/18

@ 11:13 a.m. revised PA to ~~SJR 98935~~ to Kelvyna
v:2 email.

Surrey

Tanglin

REF:

GAI

ASSIGNMENT

CofE 2019 July

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

912K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJR 9893K

Yr Regn:

2019 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

C.C. 1591

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

71489

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHD4413R 94774228

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

7.5/45M7

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

fallen.

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

3/12/18

Survey held at

into wheels

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Mark: 16621

Date / Time

Action / Instruction

* Repair limit 95K

10/12/18 Confirmed L/S \$4,100/- @ 6 days with Tanglin.
(\$5,570.64 Red - 58%)

RECEIVED 10 DEC 2018

Date/Time, File Pass to?

10/12/18

1)

Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation:

) S + RS. SI

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 4,100/- 45

TOTAL

250

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Wednesday, 28 November 2018 4:14 PM
To: Catherine Chong (LKK Auto); 'Admin A'
Subject: Accident involved with vehicle SJR9893S and insd FBK2417L on 23/11/2018 along Clementi Road & Kent Crescent
Attachments: HYN AVANTE - SJR 9893 R @ GIA.pdf

Hi team

TP survey please.

Thanks
Kelvyna

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Tuesday, November 27, 2018 2:17 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] RE: RE: Re: Fw: Accident involved with vehicle SJR9893S and FBK2417L (TP) on 23/11/2018 along Clementi Road & Kent Crescent

Hi,

We would like to choose LKK for the survey.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2734H
Vehicle Details	
Vehicle No.:	SJR9893S
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U662937
Chassis No.:	KMH DU41BR9U774228
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,278.00
Original Registration Date:	27 Jul 2009
First Registration Date:	27 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$11,278.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2019
PARF Rebate Amount:	\$5,639.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$978.00
Total Rebate Amount:	\$6,617.00

The information contained herein is correct as at 05 Dec 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 10 December 2018 4:12 PM
To: louisongautowheels@yahoo.com
Cc: Taufikh (LKKAuto); SUR
Subject: RE: Finalize for vehicle SJR9893S lumpsum \$4,100.00 with 6 repair days before GST

Hi Louis,

Confirmed final fig of \$4,100.00 (lump sum) @ 6 days of repairs before GST.

Final invoice and all supporting documents sent over to Great American Insurance Company.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong [mailto:louisongautowheels@yahoo.com]
Sent: Monday, 10 December 2018 1:00 PM
To: Taufikh (LKK Auto) <taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SJR9893S lumpsum \$4,100.00 with 6 repair days before GST

Hi,

The above attachment is the finalize and after paint photo.

Can help to Finalize for vehicle SJR9893S lumpsum \$4,100.00 with 6 repair days before GST.

No Supplementary.

Please check and revert.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Wednesday, 5 December 2018 10:56 AM
To: Shirley Hiew (LKK Auto)
Subject: FW: SJR 9893S REPAIR LIMIT

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Tuesday, 4 December 2018 11:17 AM
To: 'louisongautowheels@yahoo.com'
Subject: SJR 9893S REPAIR LIMIT

Hi Louis,

Please take note repair limit for this car is \$5000.

Regards
Taufikh
Lkk Auto

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 5 December 2018 11:13 AM
To: 'Ngian, Kelvyna'
Cc: Admin-D (LKKAuto)
Subject: RE: Accident involved with vehicle SJR9893S and insd FBK2417L on 23/11/2018 along Clementi Road & Kent Crescent
Attachments: SJR 9893R - Preli Advise.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle SJR 9893S.

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Wednesday, 28 November 2018 4:14 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Accident involved with vehicle SJR9893S and insd FBK2417L on 23/11/2018 along Clementi Road & Kent Crescent

Hi team

TP survey please.

Thanks

Kelvyna

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Tuesday, November 27, 2018 2:17 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] RE: RE: Re: Fw: Accident involved with vehicle SJR9893S and FBK2417L (TP)on 23/11/2018 along Clementi Road & Kent Crescent

Hi,

We would like to choose LKK for the survey.

Thanks

Auto Wheels Motorworks PTE LTD

Louis Ong

91928963

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 05 December 2018

Our Ref: CS/GAI18021509/T1sd3

The Motor Claims Department
Great American Insurance Company

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJR 9893R .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/12/2018 at the premises of M/s Auto Wheels Motorworks Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,670.64</u> .
Revised Estimate Amount	: S\$ <u>5,123.22</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 12:12
Date Of Accident	23/11/2018 00:10
Exact Location Of Accident	CLEMENTI RD & KENT CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR9893S
Insured/Policyholder	
Name Of Registered Owner	SEA CARS PTE. LTD.
Co Reg No	201802734H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90980084
Alternative Phone No	OFFICE-90980084

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5100721430
Cover Note Number	

Driver

Name of Driver	NOR AZHAR BIN KHALIFA
NRIC No	S7344819J
Date Of Birth	27/11/1973
Occupation	OUTDOOR
Date Of Driving Pass	11/03/2004
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90980084
Fax Number	
Contact Number	OFFICE-90980084
EMail Address	NOEMAIL

Address 339 BUKIT BATOK ST 34
#05-296
Postcode S650339
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE POST
Police Station Address ROAD: BLK 103 BUKIT BATOK CENTRAL , POSTCODE: 650103 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5639999 - FAX NO: 66655794
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBK2417L
Vehicle Make/Model/Colour M/CYCLE
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver MOHAMED YUSRI BIN SUZAINI
NRIC/Passport Number S9735365D
Contact Number 87550319
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMED YUSRI BIN SUZAINI
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	FBK2417L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6561 3772 Fax: 6561 0772
E: idac@idac.com.sg


Policyholder's Signature
Date & Time:

 23 NOV 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181123/2010

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20181123/2010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/11/2018 03:05		Vide Report No.: D/20181123/0004		Station Diary No.: 11	
Informant's Particulars					
Name of Informant: NOR AZHAR BIN KHALIFA			Address: APT BLK 339 BUKIT BATOK STREET 34 #05-296 SINGAPORE 650339		
ID Type / ID No.: NRIC NO / S7344819J			Contact No.: Home/Office: Mobile: 90980084		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 44	Date of Birth: 27/11/1973	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/11/2018 00:10	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 CLEMENTI ROAD KENT RIDGE CRESCENT Lamp Post Number: 50				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: STATIONARY VEHICLE - HEAD TO REAR				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK2417L	Motorcycle					0
SJR9893S	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181123/2010

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20181123/2010

CONTINUATION OF REPORT

Driver			
Name	NOR AZHAR BIN KHALIFA	ID No.	S7344819J
Related Vehicle	NIL	Contact No.	90980084
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	Mohamed Yusri Bin Suzaini	ID No.	S9735365D
Related Vehicle	NIL	Contact No.	87550319
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 23/11/2018 at about 0013hrs I was driving my car registration no: SJR9893S. I stop my car at the T-junction of Clementi Road (towards Jln Anak Bukit) and Kent Ridge Crescent. My car was the first vehicle waiting for traffic light to turn green when suddenly I felt strong impact from the rear. I immediately alighted and discovered that a motorcycle registration: FBK2417L had collided into the rear left of my car and had toppled onto a male Malay rider later established to be:

Mohamed Yusri Bin Suzaini
S9735365D
HP: 87550319

He is on duty working under Certis Cisco Jurong (West Hub) Enforcement. The rider was observed to have suffered injuries over his front body and legs. Ambulance arrived at scene and he was conveyed in conscious state. My car is armed with in-car camera and I have checked the recordings and the incident was captured. Traffic Police subsequently arrived and I handed over one 32GB Kingston Micro SD card and was issued with NP323. My car sustained serious damages on the rear left portion however I am not injured. Traffic Police officer advised me to lodge Traffic Accident report reference: D/20181123/0004 (TP IO Bei Feng, TEL: 65476415).



**SINGAPORE
POLICE FORCE**



T/20181123/2010

3 of 3

Police Station Of Origin:

Bukit Batok N.P.C

21 Bukit Batok East Avenue 4 SINGAPORE

659840

Tel No: 1800-6659999

Report No. T/20181123/2010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt SHANIZA BINTE SITAL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/11/2018 03:05

Officer In Charge Of Case:

TP / GIT /

SI YEO CHUN JIAN

Contact No.: 65476213

Classification Of Case:

Authentication Stamp

NP168

SN 114

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018

VEHICLE NO: SJR9893S

MODEL: HYUNDAI AVANTE

YEAR: 2009

ACCIDENT DATE: 11/23/2018

TYPE OF CLAIM: TP CLAIM

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	\$ 986.30 <i>bt</i>
BOOTLID LOCK	1	\$ 196.30 <i>XRX</i>
BOOTLID LAMP	2	\$ 592.60 <i>LH-cut, RH-X</i> <i>nn</i>
REAR EMBLEM	1	\$ 65.80 <i>nn</i>
REAR LOGO - AVANTE	1	\$ 55.60 <i>nn</i>
REAR LOGO - S	1	\$ 59.10 <i>nn</i>
REAR BUMPER	1	\$ 719.30 <i>de</i> <i>nn</i>
REAR BUMPER RETAINER	2	\$ 84.80 <i>LH-nu, RH-X</i> <i>nn</i>
REAR BUMPER BRACKET	2	\$ 188.40 <i>LH-nu, RH-X</i> <i>nn</i>
TAILLAMP	2	\$ 842.40 <i>LH-cut, RH-X</i> <i>nn</i>
REAR WEATHER STRIP	1	\$ 156.70 <i>X nn</i>
END PANEL TOP GARNISH	1	\$ 178.90 <i>X nn</i>
REAR BUMPER SPONGE	1	\$ 199.40 <i>de</i>
REAR REINFORCEMENT	1	\$ 314.30 <i>nn</i>
END PANEL	1	\$ 598.10 <i>Ry</i>
SPARE TYRE PANEL	1	RESTORE

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018

VEHICLE NO: SJR9893S

MODEL: HYUNDAI AVANTE

YEAR: 2009

ACCIDENT DATE: 11/23/2018

TYPE OF CLAIM: TP CLAIM

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

LH REAR FENDER

1 RESTORE

LH REAR FENDER INNER SHIELD

1 \$ 195.80 x 3 nh

LH REAR FENDER ANTENNA RUBBER SEAL

1 \$ 102.50 x

TOTAL: \$ 5,536.30

DISCOUNT 20%: \$ 1,107.26

\$ 4,429.04

S/NET

PRICE

REAR NUMBER PLATE

1 \$ 50.00 x nh

REVERSE SENSOR

1 \$ 250.00 200 nh

REAR BUMPER LOWER SKIRT

1 \$ 597.20 250 de

REAR BUMPER LOWER SKIRT CHROME LINING

1 \$ 65.80 de

REAR BUMPER LOWER SKIRT REFLECTOR

2 \$ 188.60 LH-mis - 1RH-x nh

REAR BUMPER CLIPS

10 \$ 30.00 nh

LH REAR FENDER INNER SHIELD CLIPS

10 \$ 30.00 x nh

END PANEL SEALANT

1 \$ 100.00 x nh

\$ 1,311.60

LABOUR

PRICE

LABOUR FOR FACILITATE REPAIR - REAR

\$ 1,600.00 800

TO RESRAY AFFECTED AREAS - BOOTLID

\$ 300.00 200

TO RESPRAY AFFECTED AREAS - REAR BUMPER

\$ 300.00 200

TO RESPRAY AFFECTED AREAS - REAR BUMPER LOWER SKIRT

\$ 300.00 100

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018

VEHICLE NO: SJR9893S

MODEL: HYUNDAI AVANTE

YEAR: 2009

ACCIDENT DATE: 11/23/2018

TYPE OF CLAIM: TP CLAIM

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - END PANEL	\$	300.00	200
TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL	\$	300.00	x nn
TO RESPRAY AFFECTED AREAS - LH REAR FENDER	\$	300.00	200
RUST PROOFING	\$	80.00	40
SUNDARIES	\$	50.00	20
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$	250.00	60
TO REMOVE AND REFIT REVERSE SENSOR	\$	100.00	30
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$	50.00	30
TOTAL:	\$	3,930.00	

TOTAL: \$ 9,670.64

7% GST: \$ 676.94

\$ 10,347.58

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749547
-wp

3/12/18 1050

Resurvey after repair
6 days

swc@lkkauto.com

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018
VEHICLE NO: SJR9893S
MODEL: HYUNDAI AVANTE
YEAR: 2009
ACCIDENT DATE: 11/23/2018
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	\$ 986.30 <i>bb</i>
BOOTLID LOCK	1	\$ 196.30 <i>XK</i>
BOOTLID LAMP	2	\$ (296.30) 592.60 <i>LH-adv, RH-X</i>
REAR EMBLEM	1	\$ 65.80 <i>new</i>
REAR LOGO - AVANTE	1	\$ 55.60 <i>new</i>
REAR LOGO - S	1	\$ 59.10 <i>new</i>
REAR BUMPER	1	\$ 719.30 <i>de</i>
REAR BUMPER RETAINER	2	\$ (42.4) 84.80 <i>LH-adv, RH-X</i>
REAR BUMPER BRACKET	2	\$ (94.20) 188.40 <i>LH-adv, RH-X</i>
TAILLAMP	2	\$ (421.20) 842.40 <i>LH-adv, RH-X</i>
REAR WEATHER STRIP	1	\$ 156.70 <i>X</i>
END PANEL TOP GARNISH	1	\$ 178.90 <i>X</i>
REAR BUMPER SPONGE	1	\$ 199.40 <i>di</i>
REAR REINFORCEMENT	1	\$ 314.30 <i>new</i>
END PANEL	1	\$ 598.10 <i>Rp</i>
SPARE TYRE PANEL	1	RESTORE

3,253.9

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018
VEHICLE NO: SJR9893S
MODEL: HYUNDAI AVANTE
YEAR: 2009
ACCIDENT DATE: 11/23/2018
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

LH REAR FENDER
LH REAR FENDER INNER SHIELD
LH REAR FENDER ANTENNA RUBBER SEAL

1		RESTORE
1	\$	X 195.80 X
1	\$	X 102.50 X

TOTAL:	\$	5,536.30
DISCOUNT 20%:	\$	1,107.26
	\$	4,429.04

3,253.9
20%
2,603.12

S/NET

REAR NUMBER PLATE
REVERSE SENSOR
REAR BUMPER LOWER SKIRT
REAR BUMPER LOWER SKIRT CHROME LINING
REAR BUMPER LOWER SKIRT REFLECTOR
REAR BUMPER CLIPS
LH REAR FENDER INNER SHIELD CLIPS
END PANEL SEALANT

	PRICE
1	\$ X 50.00 X
1	\$ 250.00 250.00
1	\$ 597.20 250 de
1	\$ 65.80 de
2	\$ (94.30) 188.60 LH-mis - iRH-X
10	\$ 30.00 ne
10	\$ X 30.00 X
1	\$ X 100.00 X 640.1
	\$ 1,311.60

LABOUR

LABOUR FOR FACILITATE REPAIR - REAR
TO RESRAY AFFECTED AREAS - BOOTLID
TO RESRAY AFFECTED AREAS - REAR BUMPER
TO RESRAY AFFECTED AREAS - REAR BUMPER LOWER SKIRT

	PRICE
	\$ 1,600.00 800
	\$ 300.00 200
	\$ 300.00 200
	\$ 300.00 100

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: GREAT AMERICAN INSURANCE

DATE: 23/11/2018
VEHICLE NO: SJR9893S
MODEL: HYUNDAI AVANTE
YEAR: 2009
ACCIDENT DATE: 11/23/2018
TYPE OF CLAIM: TP CLAIM
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - END PANEL
TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL
TO RESPRAY AFFECTED AREAS - LH REAR FENDER
RUST PROOFING
SUNDARIES
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO CHECK AND RECONNECT ALL NECESSARY WIRING

\$	300.00	200
\$	300.00	X
\$	300.00	200
\$	80.00	40
\$	50.00	20
\$	250.00	60
\$	100.00	30
\$	50.00	30
TOTAL: \$	3,930.00	

TOTAL: \$	9,670.64
7% GST: \$	676.94
\$	10,347.58

total: 5,123.22
LS \$4,100/- 6 days

Tanjin 97495747
wp
3/12/18 1050
Resumy after repair
6 days
sue@lhwauto.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18021509/T1sd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 27-12-2018		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBK 2417L	Veh. Inspected	SJR 9893S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVM000000414	Excess (\$)	0.00	
Assign From	KELVYNA NGIAN	Assign Date	28/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U774228	Colour	BLACK	
Odometer	71489	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	FALKEN	6 mm	
L/H Front Tyre	215/45 R17	FALKEN	6 mm	
R/H Rear Tyre	215/45 R17	FALKEN	6 mm	
L/H Rear Tyre	215/45 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2018	Inspection Date	03/12/2018	
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 9893S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BENT	986.30	986.30
1	BOOTLID LOCK	TO REPAIR SEE LABOUR	196.30	-
2	BOOTLID LAMP	N/S CUT / O/S NOT NECESSARY	592.60	296.30
1	REAR EMBLEM	NECESSARY	65.80	65.80
1	REAR LOGO - AVANTE	NECESSARY	55.60	55.60
1	REAR LOGO - S	NECESSARY	59.10	59.10
1	REAR BUMPER	DEFORMED	719.30	719.30
2	REAR BUMPER RETAINER	N/S NECESSARY / O/S NOT NECESSARY	84.80	42.40
2	REAR BUMPER BRACKET	N/S NECESSARY / O/S NOT NECESSARY	188.40	94.20
2	TAILLAMP	N/S CUT / O/S NOT NECESSARY	842.40	421.20
1	REAR WEATHER STRIP	NOT NECESSARY	156.70	-
1	END PANEL TOP GARNISH	NOT NECESSARY	178.90	-
1	REAR BUMPER SPONGE	DEFORMED	199.40	199.40
1	REAR REINFORCEMENT	CRACKED	314.30	314.30
1	END PANEL	TO REPAIR SEE LABOUR	598.10	-
1	SPARE TYRE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH REAR FENDER INNER SHIELD	NOT NECESSARY	195.80	-
1	LH REAR FENDER ANTENNA RUBBER SEAL	NOT NECESSARY	102.50	-
	LESS 20% DISCOUNT		-1,107.26	-650.78
			4,429.04	2,603.12
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00

Report Ref No. CS/GAI18021509/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER SKIRT (SN)	DEFORMED	597.20	250.00
1	REAR BUMPER LOWER SKIRT CHROME LINING (SN)	DEFORMED	65.80	65.80
2	REAR BUMPER LOWER SKIRT REFLECTOR (SN)	N/S MISSING / O/S NOT NECESSARY	188.60	94.30
10	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
10	LH REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	SUNDARIES (SN)	NECESSARY	50.00	20.00
			1,361.60	660.10
	LABOUR			
	LABOUR FOR FACILITATE REPAIR - REAR. INCLUSIVE OF THE REPAIR OF BOOTLID LOCK, END PANEL, SPARE TYRE PANEL AND LH REAR FENDER.		1,600.00	800.00
	TO RESRAY AFFECTED AREAS - BOOTLID.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - REAR BUMPER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - REAR BUMPER LOWER SKIRT.		300.00	100.00
	TO RESPRAY AFFECTED AREAS - END PANEL.		300.00	200.00
	TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL.	NOT NECESSARY	300.00	-
	TO RESPRAY AFFECTED AREAS - LH REAR FENDER.		300.00	200.00
	RUST PROOFING.		80.00	40.00
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.		250.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	30.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		50.00	30.00
			3,880.00	1,860.00
GRAND TOTAL			9,670.64	5,123.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/GAI18021509/T1sd3e2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.