



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 28/11/2018

User ID : GohKK2

Section A - Accident Details



Registration Number	SG5808S
Case Reference Number	BUS/11/18/7027
Registration Date	06/06/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Ong Ka Shen
Type of Accident	Head to Rear
Accident Date and Time	27/11/2018 8:30 AM
Accident Reported Date and Time	27/11/2018 10:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5808S - REAR PORTION SLX1324R (TP) - INSURED WITH AXA
Prepared Date and Time	29/11/2018 7:25 AM
Chassis Number	WMAA95ZZ3G7003455
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$2,548.80	\$0.00
Total Other Cost	\$960.00	\$0.00
TOTAL COST	\$5,449.80	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	29/11/2018 7:33 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/11/2018

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	1060.
Total Labour	\$1,325.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	528
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$960.00	✓
Total Other Costs	\$960.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	Body	G20.10.05.13	FRP REAR BUMPER	1.00	\$1,857.00	10.00	\$1,671.30		CPA ✓
	Body	G20.10.05.11	FRP REAR HEADLAMP COVER NS	1.00	\$975.00	10.00	\$877.50		CPA ✓
Total					\$2,832.00		\$2,548.80		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP
29/11/18 @ 550pm
sure lkk auto
3 days
Resurvey before paint.