

ASS. REC. BY:

REF:

033/TM18021561/Gcd30

Special Instruction:

Surveyor:

Munir

ASSIGNMENT (Office)

From (Person):

Telma Gomez

of

TMI

Date/Time:

29/11/18 @ 11:16am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SMC 875Y

Insured:

SLN 1947X

at Workshop m/s

Leong Boon too Motor

Tel:

9678 5087

of

Blk 9002 Tampines St. 93 # 01-68

Policy No:

MU004651

Claim No:

M1806073

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/2018

CA / REV / REP. / REV 24 HRS

up

30/11/18 @ after 10am

H.O.D. Endorsement:

Date/Time:

1:13pm @ 29/11/18

Person Contacted:

Ah too

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMC 875Y-X

SLN 1947X-X

MS  
Khal

REF: TMI

# ASSIGNMENT

From: Date: 30/11/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 875Y  
at Workshop m/s Leong Boon too Motor  
of 81k 9002 Tampines st. 93 # 01-68

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Ah too @ 9678 5087

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMC 875Y Yr Regn: -

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Accord C.C. -

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 134545 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR HCM 46405P 200466

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 205/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 30-11-18

Survey held at w/s 2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: -

Survey Fee:

Transportation

\$ + RS. SI

Photos

Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

100

10

110

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2018		29 Nov 2018 11:16 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	BANUMATHI D/O M PASUPATHY, ID: S7129994E		[Created by insurer]	
Main Claimant:	ONG LAY WAH, ID: S1673462D			
Vehicle Reg. No.:	SMC875Y	Date of Loss:	20/11/2018 18:00 - :59	
Claim Type:	TP / M1806073	Policy/Cover Note No.:	MU004651 (Comprehensive) Coverage: 19/04/2017 - 18/04/2019	
Vehicle Reg. No. (Insured):	SLN1947X	Policy No. (Claimant):	SI18V13546/VPE/R03	
		Excess:	S\$0.00	
Repairer:	Leong Boon Loo Motor Service (HQ) Blk 9002 Tampines St 93, #01-68 Tampines Industrial Park A, 528836 Tampines - Tel:			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]			
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/12/2018]			
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE.			
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480			

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# M NEDUMARAN & CO

Advocates & Solicitors  
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan  
LLB (hons) [Buckingham]  
Barrister at Law (Lincoln's Inn)

**Please reply to our Branch Office for this matter**  
⇒ Branch Office:

11 Sin Ming Road  
#B2-09 (Unit 2) Thomson V Two  
Singapore 575629  
Tel : 6509-8480 / 6509-8481  
Fax : 6509-8482  
Email : [igene.lim@mneduco.com.sg](mailto:igene.lim@mneduco.com.sg)  
[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)

Our Reference : MN/IG/L2/1812796/st  
Your Reference : SLN 1947X

Date : 28<sup>th</sup> November 2018

**TOKIO MARINE INSURANCE SINGAPORE LTD**  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

BY EMAIL

Dear Sirs,

1. **NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**
2. **ACCIDENT ON 20/11/2018 INVOLVING VEHICLE NOS. SMC 875Y AND SLN 1947X ALONG RIVER VALLY SLIP ROAD TO CLEMENCEAU AVENUE.**

We are instructed by ONG LAY WAH (owner of motor vehicle no. SMC 875Y) and/or LEONG BOON LOO MOTOR SERVICE (the motor workshop for SMC 875Y) to notify you of a road traffic accident on 20/11/2018 at about 1850 hours along RIVER VALLEY SLIP TO CLEMENCEAU AVENUE involving our client's vehicle registration number [ SMC 875Y ] and [ SLN 1947X ] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
**M NEDUMARAN & CO**  
(Branch Office)

Encl

c.c. 1) BANUMATHI D/O M PASUPATHY

(Vehicle : SLN 1947X )

- 2) **NAME OF WORKSHOP:**  
LEONG BOON LOO MOTOR SERVICE  
Blk 9002 Tampines St. 93  
#01-68 Tampines Ind. Park A  
Singapore 528836  
Telephone : 9678-5087

(Vehicle : SMC 875Y )

(Attention : Ah Loo )

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3462D
<b>Vehicle Details</b>	
Vehicle No.:	SMC875Y
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0A
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	K20A75P01768
Chassis No.:	MRHCM46405P200466
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$26,968.00
Original Registration Date:	19 May 2006
First Registration Date:	19 May 2006
Transfer Count:	1
Actual ARF Paid:	\$29,665.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$34,288.00
<b>Total Rebate Amount:</b>	<b>\$34,288.00</b>

The information contained herein is correct as at 07 Dec 2018

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report 27/11/2018 09:18  
 Date Of Accident 20/11/2018 18:50  
 Exact Location Of Accident RIVER VALLY SLIP TO CLEMENCEAU AVE  
 Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC875Y  
**Insured/Policyholder**  
 Name Of Registered Owner ONG LAY WAH  
 NRIC No S1673462D  
 Email Address SHEILA.ONG@HOTMAIL.COM  
 Mobile Phone No (LOCAL) +65-94599546  
 Alternative Phone No OFFICE-94599546  
**Vehicle Particulars**  
 Manufacturer HONDA  
 Model ACCORD-2.0 (A)  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR  
**Insurance Company**  
 Name of Insurance Company LIBERTY INSURANCE PTE LTD  
 Type Of Coverage THIRD PARTY  
 Fleet Policy NO  
 Policy Number SI18V13546/VPE/R03  
 Cover Note Number  
**Driver**  
 Name of Driver ONG LAY WAH  
 NRIC No S1673462D  
 Date Of Birth 19/03/1964  
 Occupation INDOOR  
 Date Of Driving Pass 15/10/1994  
 Driving Experience 24 YEARS AND 1 MONTH  
 Gender FEMALE  
 Mobile Number (LOCAL) +65-94599546  
 Fax Number  
 Contact Number OFFICE-94599546  
 Email Address SHEILA.ONG@HOTMAIL.COM

Address	BLK 26D JALAN MEMBINA #26-164
Postcode	167026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN1947X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VANU
NRIC/Passport Number	
Contact Number	93866371
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:



# Sketch Plan #2

SKETCH PLAN.



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I had stopped my car at the slip road junction checking traffic along Clemenceau road to clear. A short <sup>time</sup> later, veh (B) collided into the rear of my car.

We alighted & exchanged particulars. The driver of Veh (B) had offered to settle the damaged to my car but requested that we send our vehicle to his workshop. However she later back-out & request us to claim against her insurance.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2018		29 Nov 2018 11:16 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>BANUMATHI D/O M PASUPATHY</b> , ID: S7129994E									
Main Claimant: <b>ONG LAY WAH</b> , ID: S1673462D									
Vehicle Reg. No.: <b>SMC875Y</b>		Date of Loss: 20/11/2018 18:00 - :59 [150 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / M1806073</b>		Policy/Cover Note No.: MU004651 (Comprehensive) Coverage: 19/04/2017 - 18/04/2019							
Vehicle Reg. No. (Insured): <b>SLN1947X</b>		Policy No. (Claimant): SI18V13546/VPE/R03							
		Excess: S\$0.00							
Repairer: <b>Leong Boon Loo Motor Service (HQ)</b> Blk 9002 Tampines St 93, #01-68 Tampines Industrial Park A, 528836 Tampines - Tel:									
Handling Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Telma Gomez</b> - 65926402]									
Claimant's Insurer: <b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: (65) 6221 8611									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 10/12/2018]									
Adj Asg. Remarks: PLS. CHECK CONSISTENCY OF THE DAMAGE.									
Claimant's Solicitor: <b>M NEDUMARAN &amp; CO</b> - Tel: 65098480									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











## Claim Documents

**\*SMC875Y (M1806073)**  
**[SLN1947X]**  
**TP**  
**ONG LAY WAH**  
**Nov 20 2018 6:00PM**  
**[BANUMATHI D/O M PASUPATHY]**  
**Leong Boon Loo Motor Service**

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	28/11/18 13:43	<b>Accident Statement</b> From: SC - Reg. No: SLN1947X, Claimant: BANUMATHI D/O M PASUPATHY		Load HTM	
No	Finalized On	<b>Success United Pte Ltd (HQ)</b>		Thumbnail	Print
1	27/11/18 09:34	<b>Accident Statement</b>		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)		Thumbnail	Print
1	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	27/11/18 09:28	<b>CHASSIS NO.</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	27/11/18 09:28	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	<b>LKK Auto Consultants Pte Ltd (HQ)</b>		Thumbnail	Print
1	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	07/12/18 19:00	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
22	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
28	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
30	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
31	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
32	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
33	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
34	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
35	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/12/18 19:00	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	29/11/18 10:13	PRS LTR	 Load PDF	
2	29/11/18 10:24	TMIS SURVEYOR LIST	 Load PDF	
3	29/11/18 11:15	REJECT TP SURVEYOR-ASSIGN LKK	 Load PDF	
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 09:28	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/11/18 09:28	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 09:34	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/11/18 09:28	CHASSIS NO.	 Load JPG	<input checked="" type="checkbox"/>
7	27/11/18 09:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 09:28	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/11/18 09:28	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/TMI18021561/GCD3E2

Date: 17/12/2018

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MU004651

Claimant Vehicle No : SMC875Y

Insured Vehicle No : SLN1947X

Date of Loss: 20/11/2018

Nature of Claim: TP

Claim No: M1806073

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMC875Y

Make &amp; Model: HONDA ACCORD, 2.0 (A)

Engine No: K20A75P01768

Reg. Date: 19/05/2006 (Man. Year: 2005)

Chassis No: MRHCM46405P200466

Colour: Silver

Odometer: 134545 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 29/11/2018

Date Inspected: 30/11/2018 Inspected At:

Leong Boon Loo Motor Service (HQ)  
Blk 9002 Tampines St 93, #01-68  
Tampines Industrial Park A  
Singapore 528836

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
<b>Parts:</b>	143	HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC875Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >