

22/03/2003

ASS. REC. BY:

REF:

CS3/MSG18021563/Bcd3⁵²

Special Instruction:

Surveyor:

Muneh

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSG

Date/Time:

29/11/18 @ 9.53am

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 7898M

Insured:

GBB 9729M

at Workshop m/s

MS. Our Auto

Tel:

63851838

of

8 Kaki Bkt Ave 4 # 01-07 Premier

Policy No:

A29076922Mkf

Claim No:

577180

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/11/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11.39am @ 29/11/18

Person Contacted:

Dorlund

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBM 7898M - CS / SMD 18021443/d3

DUA: 26/11/18

GBB 9729M - NA / CTI 18013808/r3

DUA: 28/7/18

REF: MS1G

ASSIGNMENT

From:

Date:

29/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBM 7898M

at Workshop m/s

MS Car Auto

of

8 koki Bkt Ave 4 # 01-07 premier

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Desmond @ 9725 4442

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBM 7898M

Yr Regn: 27/3/2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA R155

C.C. 155

Colour:

RED

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

G3J6E009A443

C/No:

NHBRG/710JCCB1227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110 170R17

R:

110 170R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

26/11/2018

D.O.I.

29/11/18

Survey held at

MS Car Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3,600/2 - 4,000/2

[Signature]
12/12/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

-

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

PRS-

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	27 Nov 2018		29 Nov 2018 09:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ORANGE CLOVE CATERING PTE LTD, Co. Reg. No.: 53314768M		
Main Claimant:	SHERWIN CHONG JUN YANG, ID: S9449456G		
Vehicle Reg. No.:	FBM7898M	Date of Loss:	26/11/2018 14:00 - :59 [7 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 577180	Policy/Cover Note No.:	A29076922MKF(COMP) (Comprehensive) Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	GBB9729M	Policy No. (Claimant):	
		Excess:	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/11/2018]		
Driver/Custodian (Insured):	MOE THANT KYI (), NRIC: G3315682R, Tel: +6594594792		
Adj. Asg. Remarks:	on WP. Liability 50%, SJE disagree - assign LKK, Contact : Mr Desmond at HP 9725 4442		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yamaha YZF-R155

🕒 1 year ago by soonhinmotors (/soonhinmotors)

💰 S\$2,500

♥️ 77 Likes

📦 New

🏠 In Class 2B (/categories/class-2b-1595)

① The All New Yamaha YZF-R155 is here.

- . Spilt-dual LED Head Lamps
- . Racy New Look & Upbeat Styling
- . New Digital Instrument Cluster
- . Upside-down Front Forks
- . Clip-on Handlebar
- . Muscular Aerodynamic Fairing
- . Aircraft-type Fuel Filler Cap
- . Rear Mono-suspension
- . Alloy Foot-pegs
- . LED Tail Lamp

Colours available: Racing Blue, Matt Black, Matt Red Metallic

Pm us for more details.

Machine Price Start From \$6XXX!!

Hurry and get yours now!

Make

Yamaha

Type

Sports Bike

Getting This

📍 Meet-up

Yishun Industrial Park A (<https://www.google.com/maps/place/1.28967,103.85007>)

Meet The Seller



soonhinmotors (/soonhinmotors)

Joined 1 year ago.

Verified

Feedback (/soonhinmotors)

😊 1 😐 0 😞 0 >

YOU MAY ALSO LIKE

Chat

Make Offer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2018 18:31
Date Of Accident	26/11/2018 14:45
Exact Location Of Accident	ALONG LOYANG AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM7898M
Insured/Policyholder	
Name Of Registered Owner	SHERWIN CHONG JUN YANG
NRIC No	S9449456G
Email Address	SHERWINCJY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94519430
Alternative Phone No	OFFICE-94519430

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF
Exact Purpose for which vehicle was being used at time of accident	MOTORCYCLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MTMCD1801001686
Cover Note Number	

Driver

Name of Driver	SHERWIN CHONG JUN YANG
NRIC No	S9449456G
Date Of Birth	27/12/1994
Occupation	INDOOR
Date Of Driving Pass	20/03/2018
Driving Experience	0 YEAR AND 8 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94519430
Fax Number	
Contact Number	OFFICE-94519430
EMail Address	SHERWINCJY@HOTMAIL.COM

Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOE THANT KYI
NRIC/Passport Number	G3315682R
Contact Number	94594792
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBD161Z
Vehicle Make/Model/Colour	MITSUBISHI / L200
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	96339639
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	SHERWIN CHONG JUN YANG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM7898M
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20181126/2172

1 of 4

Police Station Of Origin:
Pasir Ris N.P.C.
1 Pasir Ris Drive 4 #01-01 SINGAPORE
S10457
Tel No: 1800-5852555

Report No: T/20181126/2172

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2018 20:53 Vide Report No: Station Diary No: 145

Informant's Particulars

Name of Informant: SHERWIN CHONG JUN YANG	Address: APT BLK 552 PASIR RIS STREET 51 #02-81 SINGAPORE S10552		
ID Type / ID No. NRIC NO / S9449456Q	Contact No. Home/Office	Mobile: 94519430	
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 23	Date of Birth: 27/12/1994	Type of Informant: Rider
Race: Chinese	Language:		Institution / School Name:
Occupation: REGULAR IN SAF	Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident: Injury Others	Drink Drive: No	Date/Time of Accident: 26/11/2018 14:45	Type of Location: Straight Road
Location: Along Road 1 LOYANG AVENUE			
Near to bus stop (Ref Crowell Rd):			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction		Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PBM7606M	Motorcycle	YAMAHA	YZF-R155	Red	Slightly Damaged	0
GB89729M	Lorry				No Damage	0
GBD161Z	Lorry				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Is Insured	Expiry Date

POLICE REPORT



**SINGAPORE
POLICE FORCE**



1/201811202172

1 of 4

Report No. 1/201811202172

Police Station Of Origin:
Pasir Ris P.P.C.
1 Pasir Ris Drive 4 #01-01 SINGAPORE
510457
Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
26/11/2018 20:53

Video Report No.

Station Diary No.
145

Informant's Particulars

Name of Informant: SHERWIN CHONG JUN YANG		Address: APT BLK 552 PASIR RIS STREET 51 #02-81 SINGAPORE 510552	
ID Type / ID No. NRIC NO: 99449456Q	Nationality: SINGAPORE CITIZEN	Contact No. Home/Office: Mobile: 94519430	Email:
Sex: Male	Age: 23	Date of Birth: 27/12/1994	Type of Informant: Rider
Race: Chinese	Language:	Institution / School Name:	
Occupation: REGULAR IN SAP	Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident: Injury Others	Drink Drive: No	Date/Time of Accident: 26/11/2018 14:45	Type of Location: Straight Road
Location: Along Road 1 LOYANG AVENUE			
Near to bus stop (Ref. Crowell Rd)			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBM7590M	Motorcycle	YAMAHA	YZF-R155	Red	Slightly Damaged	0
GBB9729M	Lorry				No Damage	0
GBD161Z	Lorry				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station of Origin:
Pasir Ris N.P.C.
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5552999



1/20181126/2172

2 of 4

Report No: T/20181126/2172

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FDM7898M	TENET SOMPO INSURANCE PTE LTD	D18MTMC0100188	27/03/2018	26/03/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL				
Use of Pedestrian Crossing: NA				
Driver				
Name	SHERWIN CHONG JUN YANG		ID No.	S9449456G
Related Vehicle	FDM7808M (Motorcycle)		Contact No.	94519430
Hospital/Clinic	CHANGI GENERAL HOSPITAL WARD 3B @ PARKWAY EAST HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/11/2018		Date Discharge	26/11/2018
No. of Days granted Medical Leave	03		Degree of Injury	Slight
Victim				
Name	Moe Thant Kyi		ID No.	G3315882R
Related Vehicle	GBB9729M (Lorry)		Contact No.	94594792
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details:

On 26/11/2018 at about 1445hrs, I was riding my motorcycle bearing the plate number FDM7898M along Loyang Ave towards Changi. As I was riding along Loyang Ave on the left lane, there was a lorry in front of me and there was also another lorry bearing the plate number GBB9729M beside me on the right lane. I was riding close to the right side of left lane to avoid colliding onto the lorry in front of me. As I was reached somewhere before the bus stop (387 Canwell Rd), the lorry bearing the plate number GBB9729M signalled left and immediately filtered his way into the left lane. As I felt that I was travelling faster than the lorry in front of me, I decided to ride in between the both lorries as I believe that if I braked there was a chance that GBB9729M would have knocked into me. However, as I was riding in between the lorries, I believed that GBB9729M knocked onto my rear tyre which caused my vehicle to accelerate even faster, subsequently falling on to the right side of lorry in front of me. Afterwards, I fell and skidded onto the ground. My motorcycle also skidded and knocked onto the rear bumper another vehicle bearing the plate number QBD1612 which was in the right lane. After the accident the driver of GBB9729M came down and ask about my wellbeing. The driver of the lorry in front of me said that there were no damages done to his lorry and drove off. Hence, I did manage to get his contact details and the licence plate number of the

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T201811202172

3 of 4

Police Station Of Origin:
Pasir Ris N.P.C.
1 Pasir Ris Drive 4 #01-01 SINGAPORE
610457
Tel No: 1800-5852999

Report No: T201811202172

CONTINUATION OF REPORT

lorry. The contact details of the driver of G8D161Z is 96339639 I also rode back to my camp which is 2mins away from the accident location and proceeded to the CGH afterwards. I was then given 3 days of MC by the doctor.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9456G
Vehicle Details	
Vehicle No.:	FBM7898M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Nov 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R155
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G3J6E0094443
Chassis No.:	MH3RG4710JK051229
Maximum Power Output:	-
Open Market Value:	\$2,861.00
Original Registration Date:	27 Mar 2018
First Registration Date:	27 Mar 2018
Transfer Count:	1
Actual ARF Paid:	\$430.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,602.00
COE Rebate Amount:	\$7,084.00
Total Rebate Amount:	\$7,084.00

The information contained herein is correct as at 30 Nov 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2018		29 Nov 2018 09:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ORANGE CLOVE CATERING PTE LTD, Co. Reg. No.: 53314768M		
Main Claimant:	SHERWIN CHONG JUN YANG, ID: S9449456G		
Vehicle Reg. No.:	FBM7898M	Date of Loss:	26/11/2018 14:00 - :59 [7 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 577180	Policy/Cover Note No.:	A29076922MKF(COMP) (Comprehensive) Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	GBB9729M	Policy No. (Claimant):	
		Excess:	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 30/11/2018]		
Driver/Custodian (Insured):	MOE THANT KYI (), NRIC: G3315682R, Tel: +6594594792		
Adj Asg. Remarks:	on WP, Liability 50%, SJE disagree - assign LKK, Contact : Mr Desmond at HP 9725 4442		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM7898M (577180)**
[GBB9729M]
TP
SHERWIN CHONG JUN YANG
Nov 26 2018 2:00PM
[ORANGE CLOVE CATERING PTE LTD]
Ms Car Auto Pte Ltd














[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/18 10:04	Video - Accident OI video	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/18 15:59	Accident Statement From: SC - Reg. No: GBB9729M, Claimant: ORANGE CLOVE CATERING PTE LTD	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/12/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
23	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
24	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
25	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
26	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>
27	07/12/18 19:10	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
28	07/12/18 19:10	General View	 Load JPG	✓
29	07/12/18 19:10	General View	 Load JPG	✓
30	07/12/18 19:10	General View	 Load JPG	✓
31	07/12/18 19:10	General View	 Load JPG	✓
32	07/12/18 19:10	General View	 Load JPG	✓
33	07/12/18 19:10	General View	 Load JPG	✓
34	07/12/18 19:10	General View	 Load JPG	✓
35	07/12/18 19:10	General View	 Load JPG	✓
36	07/12/18 19:10	General View	 Load JPG	✓
37	07/12/18 19:10	General View	 Load JPG	✓
38	07/12/18 19:10	General View	 Load JPG	✓
39	07/12/18 19:10	General View	 Load JPG	✓
40	07/12/18 19:10	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/18 15:59	GBD161Z E-FILE REPORT From: SC - Reg. No: G8B9729M, Claimant: ORANGE CLOVE CATERING PTE LTD	 Load PDF	
2	28/11/18 16:02	FBM7898M Police Report	 Load PDF	
3	28/11/18 17:07	Survey Disagree on SJE - assign LKK	 Load PDF	
4	29/11/18 08:38	PRI from Roy & Partners	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021563/BCD3S2
 Date: 17/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29076922MKF(COMP)
 Claimant Vehicle No: FBM7898M Insured Vehicle No: GBB9729M
 Date of Loss: 26/11/2018 Nature of Claim: TP Claim No: 577180

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM7898M**
 Make & Model: YAMAHA YZF-R155, 155cc Engine No: G3J6E0094443
 Reg. Date: 27/03/2018 (Man. Year: 2018) Chassis No: MH3RG4710JK051229
 Colour: Red Odometer: 0 km
 Engine Capacity: 155 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 110/70 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/11/2018
 Date Inspected: 29/11/2018 Inspected At: Ms Car Auto Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,600.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Dec 2018)

Parts: N/A YAMAHA YZF-R155 155cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBM7898M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >