

ASS. REC. BY:

REF:

CS/GAL/8021586/17vbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Kelvyn

of

GAL

Date/Time:

30/11/2018 9:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL9 99999

Insured:

Gx 82256

at Workshop m/s

Cycle & Carriage

Tel:

of

188 Pandan Loop

Policy No:

Claim No:

CLMDMVC000003464

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-09-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wop'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Yik

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

14/12/18

Final fig \$ 1602.31 confirmed by email (Red 480, 23/1)

Signature

Tanghe

REF:

GIA1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

LS9999S

Yr Regn:

2014 my.

Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E200

1791

Colour:

Red

A/C: Insured / Std / NI / NA

Sp Reading

98633

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2073342F.240331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

235/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 1 mm

L/Bal. 6 mm

L/Bal. 1 mm

D.O.A.

D.O.I.

22/11/18

Survey held at

CE Paoh Lyp

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 17 DEC 2018

Date/Time File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time File Return to?

2) 14/12 - typist

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation

\$ + PS \$

Photos

Others

Report Format: TP

Lump Sum / I.B.I: (\$) 1602.31

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

TOTAL

250

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 14 December 2018 4:19 PM
To: Taufikh (LKKAUTO); Yik (chanhoe.yik@cyclecarriage.com.sg)
Cc: SUR
Subject: RE: SLS9999S final bill-DOA: 11/9/2018

Dear Mr Yik,

WITHOUT PREJUDICE

Confirmed amount \$1602.31 before GST @ 2 working days.

Kindly send Final invoice and all supporting documents to GREAT AMERICAN INSURANCE CO

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Taufikh (LKKAUTO)
Sent: Friday, 14 December 2018 4:03 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SLS9999S final bill

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]
Sent: Friday, 14 December 2018 12:51 PM
To: Taufikh (LKK Auto) <taufikh@lkkauto.com> (taufikh@lkkauto.com)
Subject: SLS9999S final bill

Hi Taufikh,

Fyna.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

Catherine Chong (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 30 November, 2018 9:28 AM
To: Catherine Chong (LKK Auto); 'Admin A'
Cc: 'sur@lkkauto.com'
Subject: CLMOMVC000003464 Accident involving motor vehicle nos. SLS 9999 S & insd GX 8225 G // Propose for Direct Settlement

Hi team

Our claim ref is CLMOMVC000003464. Do submit your report to us when ready.

Thanks
Kelvyna

-----Original Message-----

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>
Sent: Wednesday, November 14, 2018 9:08 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: 'sur@lkkauto.com' <sur@lkkauto.com>
Subject: [External] RE: Accident involving motor vehicle nos. SLS 9999 S & insd GX 8225 G // Propose for Direct Settlement

Dear Kelvyna,

Kindly arrange for LKK to survey our client's vehicle next Thursday 22/11/2018.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Wednesday, 19 September, 2018 11:40 AM
To: Yik Chan Hoe
Subject: RE: Accident involving motor vehicle nos. SLS 9999 S & insd GX 8225 G // Propose for Direct Settlement

WITHOUT PREJUDICE

Dear Chan Hoe

Our insured has reported. Liability clear

We append the following list of our panel surveyors for selection:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Please advise

Thanks

Kelvyna

-----Original Message-----

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>

Sent: Wednesday, September 19, 2018 8:52 AM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Subject: [External] RE: Accident involving motor vehicle nos. SLS 9999 S & GX 8225 G // Propose for Direct Settlement

Dear Kelvyna,

The vehicle is not in the workshop, kindly let us have the liability as soon as your insured reports.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]

Sent: Friday, 14 September, 2018 4:08 PM

To: Yik Chan Hoe

Subject: RE: Accident involving motor vehicle nos. SLS 9999 S & GX 8225 G // Propose for Direct Settlement

WITHOUT PREJUDICE

Dear Chan Hoe

Our insured has not lodge the accident report yet

Meantime do you want to arrange for survey?

Thanks

Kelvyna

-----Original Message-----

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>

Sent: Friday, September 14, 2018 10:05 AM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: [External] Accident involving motor vehicle nos. SLS 9999 S & GX 8225 G // Propose for Direct Settlement

To: GAIG

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. SLS 9999 S & GX 8225 G along Ang Mo Kio Ave 3 St. 31, Accident date: 11/09/2018

Dear Sir/Mdm,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SLS 9999 S), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number GX 8225 G) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence number: **S72236311**
Name:

ONG CHUI HOON
(WANG CUIYUN)

Birth Date: **04 Jul 1972**
Issue Date: **30 Jul 2003**



000700873G

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE

23 Aug 1993

stride rite

Star Card



42110098334

FOR C&C USE ONLY



Licence No: S72236311

NP 428A



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLS9999S

Ms Ong Chui Hoon (Wang Cuiyun)

25 Mimosa Place
Singapore 805550

Mobile: 97554747

Vehicle & Document Information

WIP No **26838**
Reg No/Reg Date **SLS9999S / 13/08/2014**
Date In/Mileage **/ 0**
Chassis No **WDD2073342F240331**
Engine No **27492030099903**
Make/Model **MB/E 200 2.0 CGI COUPE (C207**
Colour/Trim **025 590 Fire Opal / 042 264 Leather Jav**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	14/09/2018/ 09:56	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100382131 // 11/09/2018 DRIVE IN/EXCESS : 13/09/2018 // TP VEH NO GX8225G GAIA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				480 960.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
M RADIATOR GRILLE	1.00	742.31	00.00	742.31

ESTIMATE

Yik Chan Hoe
3/12/18

Tayfun 97495749
wp

22/11/18 @ 1045

sure@lckauto.com

0 2 days

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Authorized signatory and company stamp

7% GST on **Nett 2,082.31**
145.76
Total Payable 2,228.07

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLS9999S

Finalization

Great American Insurance Company

3 Temasek Avenue #16-01
Centennial Tower
Singapore 039190
Attn: Motor Claims Dept

Vehicle & Document Information

WIP No	26838
Reg No/Reg Date	SLS9999S / 13/08/2014
Date In/Mileage	22/11/2018/ 98633
Chassis No	WDD2073342E240331
Engine No	27492030099903
Make/Model	MB/E 200 2.0 CGI COUPE (C207
Colour/Trim	025 590 Fire Opal / 042 264 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	14/12/2018/ 12:42	YK	395 / Yik Chan Hoe

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M	BPNSUN POLICE NO/ACC DATE : 210088213 // 11/09/2018 DRIVE IN/EXCESS : 13/09/2018 // TP VEH NO GX8225G GAIA DATE IN/DATE SURVEY: 22/11/2018 // TAUFIKH LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // KELVYNA GAIA				
A	BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				480.00
A	BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
X	RADIATOR GRILLE	1.00	742.31	00.00	742.31

Yik Chan Hoe

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	1,602.31
7% GST on	1602.31	112.16
Total Payable		1,714.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18021586/T1vbn2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 24-12-2018	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GX 8225G	Veh. Inspected	SLS 9999S
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003464	Excess (\$)	0.00
Assign From	KELVYNA	Assign Date	30/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E200 COUPE	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2073342F240331	Colour	RED
Odometer	98633	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R17	MICHELIN	6 mm
L/H Front Tyre	235/45 R17	MICHELIN	6 mm
R/H Rear Tyre	235/45 R17	MICHELIN	6 mm
L/H Rear Tyre	235/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/09/2018	Inspection Date	22/11/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 9999S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	CRACKED		
	RADIATOR GRILLE (SN)		742.31	742.31
			742.31	742.31
	LABOUR			
	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		960.00	480.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
			1,340.00	860.00
GRAND TOTAL			2,082.31	1,602.31
RECOMMENDED COST OF REPAIRS				1,602.31

Report Ref No. CS/GAI18021586/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.