

AIG TP



Service Order Confirmation

SERVICE ORDER NO: 18IP3109
 CUSTOMER NO.: CV018073
 CUSTOMER NAME: FRANCIS MICHAEL MARK
 TELEPHONE NO.:
 ADDRESS: 596D ANG MO KIO STREET 52 #15-305
 Singapore

VEH No.: SKE9905Z

Order Date: 11/29/18
 Reg Date: 04/23/12 KM: 169,791
 VIN NO.: WWWZZZ16ZCM101458 ENGINE NO:
 MODEL: JETTA A6SPORT 1.4 TSI DSG118 MODEL NO.: 1623Q5

Tanpin 92495749
 up
 30/11/18 C 1715
 Resing before paint
 sure likant-w m
 To check repair limit
 23 days.
 SA: Goh Edmund

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P TOWING	156	TU	1.25		195
2	B&P MECH	1	TU	280		280
3	B&P DIAG	1	TU	480		480
4	B&P MECH	2	TU	840		840 1,680
5	B&P MECH	3	TU	840		1680 2,520
6	B&P MECH	3	TU	840		1260 2,520
7	B&P MECH	1	TU	50		50
8	B&P WHEEL ALIGNMENT	1	TU	360		360
9	B&P ALEX LABOUR	12	LAB	840		5880 10,080
10	B&P ALEX PAINT	8	LAB	800		4800 6,400
11	B&P ALEX LABOUR	2	LAB	840		840 1,680
12	B&P ALEX LABOUR	1	LAB	840		420 840
13	B&P CELETTE	1	LAB	1,500		1,500
14	CINTURATO 205/55R16	1	ST	680		680
Item						
15	1K0199262CG	1	PCS	386.19		386.19
16	1K0199555AC	1	PCS	255.61		255.61
17	1K0129607AC	1	PCS	592.80		592.80
18	1K0915333H	1	PCS	95.58		95.58
19	5C6807217D GRU	1	PCS	1,164.05		1,164.05
20	5C6805706D	1	PCS	117.81		117.81
21	5C6807183	1	PCS	36.73		36.73
22	5C6807184	1	PCS	36.73		36.73
23	5C6853651A ZLL	1	PCS	555.29		555.29
24	5C6853666A 9B9	1	PCS	81.51		81.51
25	5C8941006	1	PCS	797.65		797.65
26	5C6805588Q	1	PCS	923.75		923.75
27	5C6805932	1	PCS	42.97		42.97
28	1K0805971C 9B9	1	PCS	39.19		39.19



Service Order Confirmation

SERVICE ORDER NO: 18IP3109
 CUSTOMER NO.: CV018073
 CUSTOMER NAME: FRANCIS MICHAEL MARK
 TELEPHONE NO.:
 ADDRESS: 596D ANG MO KIO STREET 52 #15-305
 Singapore

VEH No.: SKE9905Z

Order Date: 11/29/18

Reg Date: 04/23/12 KM: 169,791

VIN NO.: WWWZZZ16ZCM101458 ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6SPORT 1.4 TSI DSG118 MODEL NO.: 1623Q5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	1K0805962D 9B9 AIR DUCT	1	PCS	21.32		21.32
30	5C6955453Q WIPER TANK	1	PCS	157.04		157.04
31	443955465 GASKET	1	PCS	1.39		1.39
32	G 052184A2 WINDSHIELD CLEANER 1 Litre Btl	1	PCS	19.50		19.50
33	5C6821106A FENDER RH	1	PCS	617.76		617.76
34	5C6821136 RHS FENDER BRACKET	1	PCS	50.93		50.93
35	5C6805912 RHS FENDER LINER	1	PCS	136.30		136.30
36	5C6821112A CLOSING ELEMENT RH	1	PCS	31.16		31.16
37	5C6864238 FENDER TOP SPONGE	1	PCS	48.59		48.59
38	5C6864236B FENDER SIDE SPONGE	1	PCS	48.59		48.59
39	5C8857508J RHS MIRROR HOUSING	1	PCS	256.23		256.23
40	3C8857538 GRU RHS MIRROR COVER	1	PCS	157.69		157.69
41	5C6857522C RHS MIRROR GLASS	1	PCS	199.81		199.81
42	5C6831056G RH FRONT DOOR	1	PCS	2,231.30		2,231.30
43	5C6837652 RF FRONT DOOR SEAL	1	PCS	68.13		68.13
44	D 378500A2 DOOR INSULATOR	1	PCS	46.22		46.22
45	8K0831402H HINGE UPPER	1	PCS	107.28		107.28
46	8K0831402H HINGE LOWER	1	PCS	107.28		107.28
47	5C6837249B CHECK ROD	1	PCS	107.90		107.90
48	5N0837267 CHECK ROD COVER	1	PCS	19.46		19.46
49	5N0839885H SUPPORT DOOR HANDLE	1	PCS	90.24		90.24
50	5C6837432 5AP CHANNEL SEAL	1	PCS	403.72		403.72
51	5C6837478B 5AP RHS DOOR TOP MLDG	1	PCS	101.43		101.43
52	5K2837016D FRONT DOOR LOCK	1	PCS	399.34		399.34
53	5K0837350A FRONT DOOR LOCK COVER	1	PCS	16.73		16.73
54	5N0837111 9B9 CAP	1	PCS	3.25		3.25
55	5C6837462K REGULATOR <i>-photo</i>	1	PCS	442.28		442.28
56	N 10516801 NUT	4	PCS	1.07		4.28
57	5C6035454A SPEAKER	1	PCS	99.61		99.61
58	N 90765701 POP-RIVET	4	PCS	1.37		5.48



Service Order Confirmation

SERVICE ORDER NO: 18IP3109
CUSTOMER NO.: CV018073
CUSTOMER NAME: FRANCIS MICHAEL MARK
TELEPHONE NO.:
ADDRESS: 596D ANG MO KIO STREET 52 #15-305
Singapore

VEH No.: SKE9905Z

Order Date: 11/29/18

Reg Date: 04/23/12 KM: 169,791

VIN NO.: WWWZZZ16ZCM101458 ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6SPORT 1.4 TSI DSG118 MODEL NO.: 1623Q5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	5C8971120 DOOR WIRE HARNESS	1	PCS	253.39		253.39
60	5C6809836 RHS A-PILLAR	1	PCS	1,121.95	bt	1,121.95
61	D 506KD1A3 2K FOAM	1	PCS	157.96	we	157.96
62	D 476KD1M2 SEALANT	1	PCS	77.38	we	77.38
63	D 007600A1 INOXSPRAY	1	PCS	67.97	we	67.97
64	D 180003M2 2KADHESIV	1	PCS	286.20	we	286.20
65	1K0601025DF16Z 16" 'ATLANTA' RIM ONLY	1	PCS	1,319.81	cut	1,319.81
66	839601361 TIRE VALVE	1	PCS	2.06	we	2.06
67	5C0407152D LOWER CONTR ARM	1	PCS	310.63	bt	310.63
68	1K0407366C JOINT	1	PCS	173.70	bt	173.70
69	5K0498621 WHEEL BEARING	1	PCS	706.68	bt	706.68
70	5C0407256 WHEEL BEARING HOUSING	1	PCS	827.11	bt	827.11
71	5C0413031BB GAS SHOCK ABSORBER	1	PCS	382.57	bt	382.57
72	1K0412249B TOP BEARING	1	PCS	48.82	we	48.82
73	1K0412331B TOP MOUNT	1	PCS	130.96	we	130.96
74	1K0423810A FRT RHS TRACK ROD	1	PCS	151.48	bt	151.48
75	1K0423812K TIEROD END	1	PCS	199.90	bt	199.90
76	N 90834901 CLIP	2	PCS	5.56	we	11.12
77	1K0407762AX DRIVESHAFT RH	1	PCS	1,457.44	dis	1,457.44
78	LIQUIMOLY3318 DEGREASER CLEANER 500ml	1	PCS	47.32	we	47.32

Remarks : ACCIDENT TO THE FRONT RIGHT SIDE



Service Order Confirmation

SERVICE ORDER NO: 18IP3109
CUSTOMER NO.: CV018073
CUSTOMER NAME: FRANCIS MICHAEL MARK
TELEPHONE NO.:
ADDRESS: 596D ANG MO KIO STREET 52 #15-305
Singapore

VEH No.: SKE9905Z

Order Date: 11/29/18

Reg Date: 04/23/12 KM: 169,791

VIN NO.: WVVZZZ16ZCM101458

ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6SPORT 1.4 TSI DSG118 MODEL NO.: 1623Q5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	48,125.55
GST AMOUNT	3,368.79
TOTAL AMOUNT	51,494.34

On Behalf Of "COMPANY"



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT