

Your Ref: TWK.RN.deb.0431.17.AIG

Date: 18th January 2019

Our Ref: CS1/LAW18021611/Atbs2

M/s Tan Kok Quan Partnership

1 Wallich Street #07-02

Guoco Tower

Singapore 078881

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJR 6761J INSURED VEHICLE: SJK 9291R ACCIDENT DATE: 19/02/2016**

We thank you for your instruction on 28/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJR 6761J from M/s MIC Survey & Assessment Service.
- b) Final Repair Bill of SJR 6761J from M/s Ampap Autocare Centre Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJR 6761J and SJK 9291R.
- d) Colour damaged vehicle photographs of SJR 6761J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJR 6761J
Make & Model	: Toyota Camry 2.0
Year of Registration	: 2009
Chassis Number	: MR053BK4107046219

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.