

ASS. REC. BY:

REF: CS/CTI/18021615/ Kv d3 ⁿ² Special Instruction:Surveyor: ASSIGNMENT (Office)From (Person): Elaine Cheong of CTI Date/Time: 30/11/2018 @ 2.26pm

Estimated Cost: _____ Bill to: _____

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: YP1138A Insured: SJB 5265Rat Workshop m/s Kang Auto Tel: 6556 0103of 160 Sin Ming Drive # 02-16Policy No: _____ Claim No: SNM18D05584C02/5

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/11/2018
(Client's Record)CA / REV / REP. / REV 24 HRS lup 04/12/2018 @ 10am-12pm H.O.D. Endorsement: _____Date/Time: 3.43pm @ 30/11/18 Person Contacted: May Vehicle-IN/OUT (OUT)

Date/Time	Action/Instruction (✓) Estimate
	<u>YP1138A-X</u>
	<u>SJB 5265R-X.</u>
<u>12/12</u>	<u>1/15m @ 16000 enal & estimate (Red 6864.50, 30%)</u>

REF: CTE

ASSIGNMENT

From:

Date: 4/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP 1138A

at Workshop m/s

Kang Auto

of 160 Sin Ming Drive # 02-16

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10am-12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 1138A

Yr Regn:

01, 16

Type: ☒ M.Cycle / Bus / Van / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU

NHR 85

c.c.

2999

Colour:

Orange

A/C:

Insured / Std / NI / NA

Sp. Reading

82384

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JAA NHR 85 EF 7100486

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B.S

195/75R15

R: Wanli

165R14X8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

4.4

mm

L/Bal.

9

mm

L/Bal.

4.4

mm

D.O.A.

28/11/18

D.O.I.

4/12/18

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/12

File pass to Catherine

RECEIVED 12 DEC 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

12/12 - typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I. (\$

1600/2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		30 Nov 2018 16:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	J & S PROFESSIONAL PAINTING SERVICES		
Vehicle Reg. No.:	YP1138A	Date of Loss:	28/11/2018 12:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SJB5265R	Policy No. (Claimant):	
		Excess:	S\$3,750.00
Repairer:	Kang Auto Engineering Pte Ltd () 160 Sin Ming Drive, #02-16, Sin Ming AutoCity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 30 November 2018 2:26 PM
To: assignments
Subject: FW: Pre-Inspection YP1138A - SNM18D05584C02/5
Attachments: DOC281118-28112018130946.pdf; DOC281118-28112018133250.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Friday, 30 November 2018 1:46 PM
To: kangauto@singnet.com.sg; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: Pre-Inspection YP1138A - SNM18D05584C02/5

WITHOUT PREJUDICE

Dear May,

We refer to your email of 28.11.18.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle.

Aside to LKK,

Please refer to the attachment and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



From: kangauto@singnet.com.sg [mailto:kangauto@singnet.com.sg]
Sent: Wednesday, 28 November, 2018 1:36 PM
To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>
Subject: Pre-Inspection YP1138A - SNM18D05572C02/8

Motor Claims Dept

Re: Accident involving YP1138A & SJB5265R on 28/11/2018 along Junction of Upper Paya Lebar Road towards Bartley Road East.

Attached with relevant document from my client YP1138A for your retention.

Please revert Survey appointment & Handler In Charge.

Yours Sincerely,
May Ang
6556 0103
Kang Auto Engineering Pte Ltd

On Wed Nov 28 2018 13:10:01 GMT+0800 (Singapore Standard Time) Kang Auto Engineering Pte Ltd <kangauto@singnet.com.sg> wrote:

----- Original Message -----

Scanned from BD034080
Date: 28/11/2018 13:10
Pages: 11
Resolution: 200x200 DPI

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

Reminder

M/S CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909.
Attn : Motor Claims Dept

Date : 28/11/2018

Your Insured: SJB5265R
Our Insured : YP1138A
OUR REF: TP18/11/1124

Notice to conduct Pre-Repair Inspection within 2 working days pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Case.

We act for J & S Professional Painting Service , the owner of motor vehicle **YP1138A** who has appointed us **Kang Auto Engineering Pte Ltd** to act on his behalf to claim against your insured's vehicle. **SJB5265R** in regards to the road traffic accident on 28/11/2018 along Upper Paya Lebar Road towards Bartley Road East Junction.

Please be informed that the said motor vehicle can be inspected at :

Kang Auto Engineering Pte Ltd
Sin Ming AutoCity
160 Sin Ming Drive, #02-16
Singapore 575722
Tel: 6556 0103 fax: 6556 1015
Contact : Kenny/May

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding and intervening Saturday, Sunday or Public holiday, the said workshop will commence repairs thereafter without further reference to you.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2018 14:00
Date Of Accident	28/11/2018 12:00
Exact Location Of Accident	UPPER PAYA LEBAR ROAD TOWARDS BARTLEY EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP1138A
Insured/Policyholder	
Name Of Registered Owner	M/S J & S PROFESSIONAL PAINTING SERVICES
Co Reg No	52992413K
Email Address	JOHNLOW5477Z@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-65560103

Vehicle Particulars

Manufacturer	ISUZU
Model	NHR85AUE4A
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3003411800
Cover Note Number	

Driver

Name of Driver	LOW THEN SHIN
NRIC No	S1710309A
Date Of Birth	04/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	11/12/2007
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98639071
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 740 YISHUN AVENUE 5 #06-498
Postcode	760740
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJB5265R
Vehicle Make/Model/Colour	MERCEDES-BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature: 
 Date & Time: 29 NOV 2018
 4:00 hrs

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 23 NOV 2018
 4:20 hrs

Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.: S6840583A

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Upper Paya Lebar Road towards Bartley Road East by the 2nd lane intend to go straight.

Suddenly, vehicle NO# SJB5265R bangs onto my Lorry's Rear Right portion causing serious damage.

Nobody was injured.

DECLARATION


I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature


Date & Time:

Company Chop (if applicable)




Driver's Signature
(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.: S6840583A

CERTIFICATE OF INSURANCE Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD

MZ300/C
N SN
AN0575A
COMPREHENSIVE
AUTOSAFE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMCVSN3003411800	Engine No : 4JJ12G2723 Chassis No: JAANHR85EF7100486
1. Index Mark and Registration Number of Vehicle	YP1138A	
2. Name of Policy Holder	M/S J & S PROFESSIONAL PAINTING SERVICES	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	20 JANUARY 2018	EX SECT. 1 S\$550. EX ON WINDSCREEN S\$100.
4. Date of Expiry of Insurance	19 JANUARY 2019	
5. Persons or Classes of Persons entitled to drive *		

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE

6. Limitations as to use: *

- (1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.

THE POLICY DOES NOT COVER.

- (1) USE FOR HIRE OR REWARD OR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
- (2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE

HIRE PURCHASE CO. : MERCEDES-BENZ FINANCIAL SERVICES SINGAPORE AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LT

Countersigned By:

Authorised Officer

Authorised Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 6111 Fax: 8225 3592 Website: www.sg.cntaiping.com

DRIVER'S NRIC + DRIVING LICENCE Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man

License Number: **S1710309A**

Name: **LOW THEN SHIN**

Birth Date: **04 Apr 1965**

Valid Until: **30 Jul 2014**

Barcode: 002329826H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1710309A**

Portrait of a man

Name: **LOW THEN SHIN**

劉 登 兴

Race: **CHINESE**

Date of birth: **04-04-1965**

Country/Place of birth: **SINGAPORE**

Sex: **M**

51710309A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

11 Dec 2007

NP 426A

Barcode: License No. S1710309A

5194018

Barcode

NRIC No. **S1710309A**

Portrait of a man

Date of issue: **16-07-2013**

Address: **APT BLK 740 YISHUN AVENUE 5
#05-496
SINGAPORE 760740**

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg


M/S J & S PROFESSIONAL PAINTING SERVICE POLICY NO : THIRD PARTY CLAIMS
BLK 740 YISHUN AVENUE 5 OUR REF : TP18/11/1124
#06-498 VEHICLE NO : YP1138A
SINGAPORE 760740 MAKE/MODEL : ISUZU LORRY
DATE OF ACCIDENT : 28.11.18

1 PC	TAILGATE METAL STEP	S\$	R1 955.00	✓
1 PC	TAILGATE HINGES		R 72.00	X
1 PC	TAILLAMP ASSY RH		B2 325.00	✓
1 PC	REAR RH MUGFLAP <i>Green</i>		R1 185.00	✓
		S\$	1,537.00	
		LESS 15%	230.55	
		S\$	1,306.45	

TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	80.00	301
TO PUTTY AND SPRAY PAINT CHARGES	500.00	350
LABOUR CHARGES	400.00	350
	S\$ 2,286.45	

SGD TWO THOUSAND TWO HUNDRED EIGHTY-SIX AND CENTS FORTY-FIVE ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Not Authorised
Recovery 84 per cent
3 days
61 days @ 1600h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18021615/KVD3N2

Date: 17/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1802311800	
Claimant Vehicle No :	YP1138A	Insured Vehicle No :	SJB5265R	
Date of Loss:	28/11/2018	Nature of Claim:	TP	Claim No: SNM18D05584C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP1138A	Engine No:	4JJ12G2723
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85EF7100486
Reg. Date:	20/01/2016 (Man. Year: 2015)	Odometer:	82364 km
Colour:	Orange		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	165R14X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Wanli 4/4 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Wanli 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,306.45	1,245.25	61.20	4.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	730.00	250.00	25.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,286.45	1,975.25	311.20	13.61
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	2,286.45	1,600.00	686.45	30.02

INSPECTION

Date of Assignment:	30/11/2018	
Date Inspected:	04/12/2018 Inspected At:	Kang Auto Engineering Pte Ltd 160 Sin Ming Drive, #02-16, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2018)	
Parts:	N/A	ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1138A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE METAL STEP	Bent	955.00 FL	*955.00 FL
2	1		*TAILGATE HINGES	Repair	72.00 FL	*- FL
3	1		*TAILLAMP ASSY RH	Broken	325.00 FL	*325.00 FL
4	1		*REAR RH MUDGUARD	Bent	185.00 FL	*185.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,537.00	1,465.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	230.55	219.75
Total Parts (\$\$)	1,306.45	1,245.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	New	80.00	30.00
2	TO PUTTY AND SPRAY PAINT CHARGES	New	500.00	350.00
3	LABOUR CHARGES	New	400.00	350.00
Gross Labour Cost (S\$)			980.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >