

NATIONAL Assessment Centre Services

[wef 1 Jan 2005]

Date In: 01/12/2018 09:53	Job description: SAS e-filing	Date & Time Completed:	Done by:
Ref No: NA/INC18024636/ky	E-mail (within 8hrs, AIC 2hrs):		
Veh No: SKP1334R	i-Motor Claim Form: NT/1022108-001	01/12/18 1039	
D.O.A: 30/11/2018 16:10	i-Motor W/O (Within: OD 2hrs, TP 4hrs):		
OD: TP: Reporting Only	i-Photo Uploaded:		
TP Insurer:	Assessment/Survey Report:		
	Ass't Report by Fax / Hand to Owner/Wksp:		

Preferred Wksp / INC Assign Wksp / QW: () Tel: () Fax: ()

TP Particulars: Veh No: YM9658D INC () / Non-INC ()

Owner / Driver: () Tel: ()

Policy No: () Period: () Cover Type: ()

Confirmed by: () Date: () Time: ()

Insured/Driver Liability: () % [Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]

Year of Registration: () Warranty: YES () / NO ()

Excess: (\$) Loading: \$1,000 () / \$2,000 ()

General Remarks: ()

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC hotline: 6788 6616)

1) Apply for Transport Allowance () / Courtesy Car ()

2) QC Check / Post Repair Inspection ()

3) Upload Resurvey Photo [Repair Cost > \$3000] ()

Injury: ()

Date/Time: Actions:

NA1807934

Invoice Preparation Checklist

Am't (\$) In Bill Am't (\$) Add Bill

- 1) AR: Accident Reporting (\$30);
- 2) DA: Damage Assessment (\$100); INC (\$80)
- 3) TP: Towing Fee \$40/\$45
- 4) FT: Follow-Through Survey \$120
- 5) RT: Follow-Through Survey (Resurvey) \$30
- For claiming against INC Only (wef 10 Jan 2005)
- 6) TR: Re-inspection \$75
- 7) N1: Idac DA + SMRT Survey \$160
- 8) NTUC Additional Services:-
- ON*
- *N5: Courtesy Car / Tpt Allowance \$5
- *N6: Repair Co-ordination \$10
- *N7: Post Repair Inspection \$25
- *N8: DV / Collect Excess Coordination \$5
- TP (N11): TP (Non INC) against INC \$20
- 9) N12: Idac Mobile 30

Invoice dated

Fee Charged

NA1807934

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/12/2018 09:53
Date Of Accident	30/11/2018 16:10
Exact Location Of Accident	KPE TWDS ECP (CHANGI AIRPORT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP1334R
Insured/Policyholder	
Name Of Registered Owner	KAMARUDIN BIN TAMBI
NRIC No	S1500268I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97833654
Alternative Phone No	OTHERS-97833654

Vehicle Particulars

Manufacturer	BMW
Model	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086391545-01
Cover Note Number	

Driver

Name of Driver	ABDUL RAHMAN BIN KAMARUDIN
NRIC No	S8827244G
Date Of Birth	21/07/1988
Occupation	INDOOR
Date Of Driving Pass	14/10/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97833654
Fax Number	
Contact Number	OTHERS-97833654
EMail Address	NOEMAIL

Address	BLK 888 TAMPINES STREET 81 #08-1098
Postcode	520888
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9658D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAM WAH SENG
NRIC/Passport Number	
Contact Number	97818405 / 96170469 AH HWEE
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 01/12/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A: BMW 520i SKP1334R
 Vehicle B: ISUZU Lorry YM9658D
 30 November 2018 @ 4:10pm
 KPE exit towards ECP (Changi Airport) (EOB k door)

I was driving along KPE exiting towards ECP (Changi Airport) behind a lorry (ISUZU YM9658D). The lorry was slowing down as I saw the red lights came on I tried to press the brakes but felt the car to slide towards the lorry. I felt an impact and saw that I had a head on collision with the back of the lorry. My car suffered heavy damage at the front of the car, with the left headlights totally disappeared, and my front license plate gone too.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

01/12/2018

**TOW JOB WORK ORDER**GST Reg No. : 19-9806389-N
Co. Reg No. : 199806389N

Contract :

NTUC

AUTOSWIFT RECOVERY PTE LTD

PART A: JOB DETAILS

W/Order No. : T 156139

Service Date 01/12/2018 Time Received 0802


Member / Customer's Name MR - Rahman Time Arrived 0833

Membership / NRIC No. _____ Time Completed 1000

Contact No. 97833654 Total Mileage 32

Vehicle Registration No. SKP 1334 R Car Make / Model BMW 5S

Breakdown Location Port Rd Towed Destination Paya ubi NAC (Idae)

NORMAL TOWING		ADDITIONAL SERVICES	
☐ Straight Towing	☐ Multi-Storey / Basement Car Park	☐ Straight Towing with King Dolley	☐ Woodlands Checkpoint / Tuas 2nd Link
☐ Flat Bed / Car Carrier	☒ Accident Towing	☐ Flat Bed / Car Carrier with King Dolley	☐ Car Ditched / Winched Up / Crane Up
☐ Heavy Goods Vehicle (Class 5 Towing)	☐ Dismantle Shaft / Release Brakes	☐ _____	☐ _____
SURCHARGES / OTHERS		ROADSIDE SERVICES	
☐ Sunday / Public Holiday Towing (full day)	☐ Jump Start	☐ Midnight Towing (2400hrs to 0700hrs)	☐ Tyre Replacement
☐ Call Cancelled / Car Missing	☐ Patch Tyre Service	☐ Standby / Waiting Time	☐ Repair Tyre & Returned
Duration : _____	☐ Battery Replacement	☐ AA Membership Enrolment / AA Renewal	Battery Receipt No: _____
REMARKS / COMMENTS BY TOW CREW			
 Tow Crew ID / Signature <u>YN886J</u> Truck No. _____ Operation Officer's Signature			
PART B: MEMBER / CUSTOMER ACKNOWLEDGEMENT			
1 I authorise AutoSwift Recovery Pte Ltd to tow my vehicle to the above-mentioned workshop of my choice. 2 I have been advised to remove all valuables (handphone, laptop, parking coupons, cash cards etc) from the vehicle. 3 I understand that items left behind are at my own risk and that AutoSwift Recovery Pte Ltd will not be held responsible for any losses. 4 I accept that there may be damages to my vehicle arising from the towing operation and I will not hold AutoSwift Recovery liable for the damages.			
5 Remarks : _____			
Member / Customer Signature		Date	
PART C: WORKSHOP / AGENT DECLARATION			
1 I hereby represent the company receiving the above mentioned vehicle. 2 AutoSwift Recovery Pte Ltd will not be held responsible for any damages or loss of valuables discovered while the vehicle is in our possession.			
3 Remarks : _____			
Workshop's Representative Signature	Workshop's Stamp	Date	

CUSTOMER COPY

Swift and Safe

AutoSwift Recovery Pte Ltd

(A wholly-owned subsidiary of AA Singapore)


Head Office: 535 Kallang Bahru #02-08 GB Point Singapore 339351 Office: 6333 8811 Fax: 6733 5094

Branch Office: 10 Kallang Way Singapore 349215 24 Hours Hotline: 6844 3611 Office: 6389 4261 Fax: 6473 4996

CERTIFICATE OF EXTRACT FROM REGISTER OF BIRTHS

851789

COE No 050222

CHILD'S PARTICULARS	Birth registered at QIJY REGISTRATION CENTRE		
	Full name (Surname first) KAMARUDIN BIN TAMBI		
	Sex Male	Date of Birth 16th November, 1961	Hour of Birth 5.00 a.m.
	Place and Address of Birth 119E, Bukit Purmei, Singapore		
MOTHER'S PARTICULARS	Maiden Name JUMA BINTE SURIP		Singapore Identity Card No. -
	Race/Dialect Group Malay	Nationality/Citizenship British Subject	Country of Birth Singapore
	Date of Birth/Age 23 years	Address 119E, Bukit Purmei	
	Name TAMBI BIN HAJI DERIS		
FATHER'S PARTICULARS	Race/Dialect Group Malay		Singapore Identity Card No. S5F 04501
	Nationality/Citizenship Singapore Citizen		Country of Birth Malacca
	Occupation Store Labourer	Address 119E, Bukit Purmei	
	Name TAMBI BIN HAJI DERIS		
INFORMANT'S PARTICULARS	Address 119E, Bukit Purmei		Singapore Identity Card No. S5F 04501
	State relationship (e.g. Father, Mother etc.) Father		
	Certified to be a true extract from the Register of Births REGISTRAR'S OFFICE 26 JAN 1962  YEAP KUN HEE Registrar of Births and Deaths		

Form BD 35A



Father is (Owner)

Son - Driver

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKP1334R
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Chassis No.:	WBANT12050CX30109
Propellant:	Petrol
Engine No.:	A861I454N46B20BE
Engine Capacity:	1995 cc
Maximum Power Output:	115.0 kW (154 bhp)
Maximum Laden Weight:	2030 kg
Unladen Weight:	1490 kg
Year Of Manufacture:	2009
Original Registration Date:	09 Feb 2010
Lifespan Expiry Date:	-
COE Category:	B - Car (1601cc & above)
Quota Premium:	\$22,400.00
COE Expiry Date:	08 Feb 2020
Road Tax Expiry Date:	08 Feb 2019
PARF Eligibility Expiry Date:	08 Feb 2020
Inspection Due Date:	08 Feb 2019
Intended Transfer Date:	01 Dec 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 08 Feb 2019. You may renew the road tax from 09 Nov 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 08 Feb 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 09 Feb 2019 to 08 Aug 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	604.00	-	604.00
Total Amount Payable:			629.00

Amount Payable (From 09 Feb 2019 to 08 Feb 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	1,208.00	-	1,208.00
Total Amount Payable:			1,233.00

You may print this page for reference.

OK

Print

Reported on 01/12/2018
@ 0945AM

ACCIDENT STATEMENT

ACCIDENT DATE: (30/11/2018) (DD/MM/YYYY), TIME: (16:10) (HH:MM)

LOCATION: KPE towards ECP (CHANGE AIRPORT)

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SKP1334R
b) INSURANCE COMPANY: _____
c) POLICY NUMBER: _____
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: _____
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: _____
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
c) ADDRESS: _____

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 97833654
c) ADDRESS: _____

*d) DATE OF BIRTH: (____/____/____) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: _____

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS) _____
b) ROAD SURFACE: (DRY / WET / OTHERS) _____

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: YM 9658D MODEL: _____
b) DRIVER'S NAME: YAM WAH SENG
c) NRIC/FIN/PASSPORT: _____ CONTACT: 97818405 / 96170469

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
e) DRIVER'S NAME: _____
f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

Driver - son
Father &
owner

on 01/12/2018 @ 0950AM
* Tow in to
idac
Vehicle key
given to idac.

own
Belonging already
Taken from Driver
from vehicle

Email =

fax =

VIDEO =

Waiting for

Driver

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8827244G



Name
ABDUL RAHMAN BIN
KAMARUDIN

Race
MALAY

Date of birth
21-07-1988

Sex
M

Country of birth
SINGAPORE



3986534



NRIC No. S8827244G



Date of issue
20-12-2006

Address
APT BLK 888 TAMPINES STREET 81
#08-1098
SINGAPORE 520888

Driver

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of Abdul Rahman Bin Kamarudin

Licence Number: **S8827244G**

Name: **ABDUL RAHMAN BIN KAMARUDIN**

Birth Date: **21 Jul 1968**

Issue Date: **25 Feb 2015**

Barcode: 002395802A

SG 50

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 14 Oct 2008

NP 428A

Barcode: Licence No: S8827244G

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	30/11/2018 16:10							
Vehicle No.(For Motor)	SKP1334R	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5086391545-01		KAMARUDIN BIN TAMB	S1500268I	GPC	drivo CLASSIC	SKP1334R	SKP1334R	09/02/2018	08/02/2019
Continue										

Policy Information

Policy No.	5086391545-01	Policyholder Name	KAMARUDIN BIN TAMBI	Policyholder NRIC	S1500268I
Certificate No.					
Address	BLK 888 #08-1098 TAMPINES STREET 81 SINGAPORE 520888				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy Issue Date	09/02/2018	Effective Date	09/02/2018 00:00	Expiry Date	08/02/2019 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0		
Agent	NSK INSURANCE AGENCY	Agent Tel.	68720457	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	BLK 888 #08-1098	Address 2	TAMPINES STREET 81	Address 3	SINGAPORE 520888
Address 4		Address Type	Singapore address	Post Code	520888
Unit No.		Related Policy Number	5086391545-01		

Insured Object: SKP1334R

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

Accident MT/1022108

Policy No.	5086391545-01	Vehicle No.	SKP1334R	GST Registration No.
Certificate No.				
Policyholder Name	KAMARUDIN BIN TAMBI			Policyholder NRIC
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)
Email Address		Special Remark		eCode
KFK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason
NCD Protection	No	NCD Entitlement(%)	0	Private Hire

▼ Accident Details

Report Date	01/12/2018 10:32	Accident Report Within 24 hrs	Yes	Accident Type
Date of Accident	30/11/2018	Time of Accident hh:mm	16:10	Country of Accident
Reporting Centre		Orange Force		ICM No.
Accident Location	KPE TWDS ECP (CHANGI AIRPORT)			

▼ Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00	
Third Party Excess	0.00	Outside Singapore TP Excess	0.00	

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 888 #08-1098	Address 2	TAMPINES STREET 81	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.		Related Policy Number	5086391545-01	

▼ OI Driver Info

Driver Name	KAMARUDIN BIN TAMBI	Driver Type	Main Driver	
Unnamed driver Name		Driver NRIC	S15002681	Driver DOB
Register Date of Driver License	01/01/2000	Driver Age	57	Driving Experience
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)
Address 1	BLK 888	Address 2	TAMPINES STREET 81	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.	#08-1098			
Does he own a Singapore Registered car?	Yes ☐ No ☐	Driver Vehicle No.		Driver Insurer Com

Declaration			
Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No

Modification History

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	KAMARUDIN BIN TAMBI
Contact No.(Mobile)		Contact No.(Home)	678396
Email Address		Vehicle Number	SKP1334R
Claim Description	SKP1334R / YM9658D ON 30 Nov 2018		
Preferred Workshop		Insured Liability	Fully at Fault
Contact No. Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown
Date Registered	01/12/2018 10:40	GIA report	Received
Report Taken By		Claim Close Date	
		Workshop Repairer	

☐ Print AK letter

Save Submit

Attachment

Accident No.	MT/1022108	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	01/12/2018 10:40
Path *		Category *	
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read			

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Des
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:39	NRIC/ Driving License	Normal	NRIC/ Driving I
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:39	NRIC/ Driving License	Normal	NRIC/ Driving I
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:37	SAS	Normal	SAS 2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:37	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:37	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:37	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 01 Dec 2018 10:36	Photos	Normal	Photos

- NTUC NET work down from 11:50am on 3/12/18

ASSIGNMENT (PART 1)

By Assessor- 1) Incident:

- 1) Vehicle hit Vehicle: ☐ a) Pedestrian ☐ b) Motorcycle ☐ c) Bicycle ☐ d) Vehicle hit 22: ☐ a) Pedestrian ☐ b) Animal ☐ c) Bicycle ☐ d) Vehicle hit Road Side Object: ☐ a) Green Property ☐ b) Road Work Object ☐ c) Private Property ☐ d) Vehicle drop into drain ☐ e) Damage due to Act of God: ☐ a) Fallen Object ☐ b) Flood ☐ c) Other: ☐ 6) Parked & Found Damaged: ☐ a) Vandalism ☐ b) Hit by Moving Object ☐ 7) Theft Case: ☐ a) Stolen ☐ b) Damage found when recovered ☐ 8) Fire: ☐ a) Whilst driving ☐ b) Parked ☐ 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss: ☐ 2) CRS Light on: ☐ 3) ABS Light on: ☐

By Assessor- 1) Vehicle Information:

Vehicle: **SKP 1334 R** Date: **9 Feb 2010**
Type: **Motorcycle / Bus / Van / Carry / Load / Tractor / Mower /**
Truck / Trailer /
Make & Model: **BMW 520i A** Year: **1995**
Colour: **Black** Transmission Type: **Manual**
Eng/Bo: **No Display**
C/No: **WBANT12050CX30109**
Gen. Cond: Good / **Poor** / Burnt / or
Steering: **Knock** / Jammed / Leaked / Burnt / or
Brake: **Knock** / Jammed / Leaked / Burnt / or
Mod: **NH /** STD A/Rim / or
Tyre Size: F: **225/55 R16 - MIC**
R: **- BS**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO / or
Front: **5** mm Rear: **4** mm
R/Bol: **5** mm L/Bol: **4** mm
Parallel Import: Yes / **No** Towed In: Yes / **No**
Repair Type: **LS** LBJ Towing Required: **Yes** No
No of Repair Days: **9** Vehicle in Idler: **Yes** No
D.O.I: **3/12/2018** Time: **9.30am**

By Assessor- 2) Comments:

- 1) Damages not due to recent accident.
2) Damages do not seem hit onto:
a) Vehicle ☐ b) Motorcycle ☐ c) Bicycle ☐ d) Pedestrian ☐
e) Animal ☐ f) Green Object ☐ g) Road Work Object ☐
h) Private Property ☐ i) Drain ☐ j) Road Edge/Cross Verge ☐
3) Vehicle does not seem damaged as a result of:
a) Fallen Object ☐ b) Flood ☐ c) Vandalism ☐ d) Fire ☐
e) Moving Object ☐ f) Stolen ☐ g) Stolen & Recovered ☐

Time Started	Time completed
09:00	09:05
By Officer/Inspector/Supervisor/Time	

MOTOR CAR (Fr)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	DIS	✓	✓
1002	991887	Frt Number Plate Base	CRA	✓	✓
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DIS	✓	✓
1005	992341	Frt Bumper Clips	NEC	6	✓
1006	991325	Frt Bumper Bracket			✓
1007	991462	Frt Bumper Side Retainer	DIS	2	✓
1008	991433	Frt Bumper Reinforcement			✓
1009	991318	Frt Bumper Beam			✓
1010	991468	Frt Bumper Sponge			✓
1011	991427	Frt Bumper Protector			✓
1012	991420	Frt Bumper Pad			✓
1013	991363	Frt Bumper Grille			✓
1014	991301	Frt Bumper Moulding			✓
1015	991407	Frt Bumper Lower Spoiler			✓
1016	991438	Frt Bumper Sensor			✓
1017	995100	Frt LH Bumper Fog Lamp Cover			✓
1018	991355	Frt RH Bumper Fog Lamp Cover			✓
1019	995079	Frt LH Bumper Fog Lamp			✓
1020	995080	Frt RH Bumper Fog Lamp			✓
1021	991793	Frt Grille	CRA	✓	✓
1022	991328	Frt Grille Emblem			✓
1023	991799	Frt Grille Chrome Moulding			✓
1024	991222	Frt Apron Panel			✓
1025	992013	Frt Support Panel	BT	✓	✓
1026	992025	Frt Support Panel Top Garnish Cover	CRA	✓	✓
1027	992416	Horn			✓
1028	991277	Frt Brace Panel	BT	✓	✓
1029	995153	Frt LH Headlamp Assy	BR	✓	✓
1030	991821	Frt RH Headlamp Assy	CRA	✓	✓
1031	995088	Frt LH Side Lamp			✓
1032	995089	Frt RH Side Lamp			✓
1033	990248	Bonnet	B/C	✓	✓
1034	991328	Bonnet Emblem	CRA	✓	✓
1035	990287	Bonnet Lock	BT	2	✓
1036	990285	Bonnet Insulator	BT	✓	✓
1037	990273	Bonnet Hinge	BT	2	✓
1038	990261	Bonnet Damper			✓
1039	990305	Bonnet Rubber	IN	✓	✓
1040	990252	Bonnet Cable			✓
1041	990311	Bonnet Stand			✓
1042	990119	Air Con Condenser	BT	✓	✓
1043	990122	Air Con Fan Assy	CRA	✓	✓
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	✓	✓
1045	990118	Air Con Suction Hose			✓
1046	990133	Air Con Discharge Pipe (High Pressure)	DD	✓	✓
1047	990114	Air Con Discharge Hose			✓
1048	990149	Air Con Liquid Pipe	BT	✓	✓
1049	995066	Air Con Receiver Drier			✓
1050	990111	Air Con Compressor Assy			✓
1051	995294	Air Con Condenser Side Deflector	DIS	2	✓
1052	995074	Radiator	DD	✓	✓
1053	992738	Radiator Cowling	CRA	✓	✓
1054	992742	Radiator Fan Assy	JM	✓	✓
1055	992745	Radiator Fan Clutch			✓
1056	992758	Radiator Hose Top	BT	✓	✓
1057	992757	Radiator Hose Bottom	BT	✓	✓
1058	992741	Radiator Expansion Tank			✓
1059	990151	Air Duct			✓
1060	990070	Air Cleaner Assy	CRA	✓	✓
1061	990056	Air Cleaner Hose	BT	✓	✓
1062	990089	Air Cleaner Resonator			✓
1063	991712	Frt Inter Manifold			✓
1064	991713	Frt Inter Manifold Cover	CRA	✓	✓
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			✓
1066	991714	Front Exhaust Pipe			✓
1067	990219	Battery			✓
1068	990224	Battery Cover			✓
1069	990223	Battery Bracket			✓
1070	990229	Battery Tray			✓

Vehicle No: SKP 1334R

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			✓
1072	994011	Relay Box			✓
1073	995053	Wiper Washer Tank			✓
1074	995052	Wiper Washer Tank Motor			✓
1075	990159	Alternator Assy			✓
1076	990160	Alternator Belt			✓
1077	992688	Power Steering Pump			✓
1078	992669	Power Steering Belt			✓
1079	994431	Power Steering Cooler Pipe	BT	✓	✓
1080	992692	Power Steering Hose			✓
1081	990010	ABS Pump Control Unit			✓
1082	990427	Brake Master Pump Assy			✓
1083	990403	Brake Booster Pump Assy			✓
1084	991005	Engine Top Cover			✓
1085	991011	Engine Under Cover			✓
1086	990946	Engine Gcn Filter			✓
1087	990949	Engine Mounting Frt			✓
1088	990950	Engine Mounting LH			✓
1089	990952	Engine Mounting RH			✓
1090	990951	Engine Mounting Rear			✓
1091	992234	Gear Box Mounting			✓
1092	991520	Frt LH Chassis Member			✓
1093	991520	Frt RH Chassis Member			✓
1094	990728	Frt Vertical Cross Member			✓
1095	991863	Frt Lower Cross Member			✓
1096	995070	Frt LH Fender			✓
1097	995072	Frt LH Fender Inner Panel			✓
1098	995147	Frt LH Fender Lamp			✓
1099	995148	Frt LH Fender Protector			✓
1100	991740	Frt LH Fender Inner Shield			✓
1101	995179	Frt LH Mudflap			✓
1102	995170	Frt LH Wheel Rim			✓
1103	994025	Frt LH Rim Cover			✓
1104	995065	Frt LH Tyre			✓
1105	995071	Frt RH Fender			✓
1106	991739	Frt RH Fender Inner Panel			✓
1107	991744	Frt RH Fender Lamp			✓
1108	991752	Frt RH Fender Protector			✓
1109	991740	Frt RH Fender Inner Shield			✓
1110	991884	Frt RH Mudflap			✓
1111	992087	Frt RH Wheel Rim			✓
1112	994025	Frt RH Rim Cover			✓
1113	995065	Frt RH Tyre			✓
1114	992093	Frt Windscreen Glass	CRA	✓	✓
1115	992117	Frt Windscreen Rubber			✓
1116	992108	Frt Windscreen Moulding	NEC	✓	✓
1117	992093	Frt Windscreen Sealant	NEC	✓	✓
1118	991019	ERP Bracket	NEC	✓	✓
1119	991020	ERP Unit			✓
1120	992140	Frt Wiper Arm			✓
1121	992142	Frt Wiper Blade			✓
1122	995045	Wiper Panel Garnish			✓
1123	991126	Firewall Panel			✓
1124	990753	Dashboard Assy			✓
1125	992282	Glove Box Cover			✓
1126	992281	Glove Box Compartment			✓
1127	994483	Steering Wheel Airbag			✓
1128	994485	Steering Wheel Airbag Sensor			✓
1129	990749	Dashboard Airbag			✓
1130	990750	Dashboard Airbag Sensor			✓
1131	990029	Airbag Control Unit			✓
1132	990864	Frt Driver Seat			✓
1133	991922	Frt RH Seat Belt Assy			✓
1134	991899	Frt Passenger Seat			✓
1135	995182	Frt LH Seat Belt Assy			✓
1136	990247	Sticker			✓
		Engine Throttle Body			✓

Claim Handling

Task Transfer Exit

Accident MT/1022108

LOS SAL SUB

Policy No.	5086391545-01	Vehicle No.	SKP1334R	GST Registration No.	
Certificate No.					
Policyholder Name	KAMARUDIN BIN TAMBI			Policyholder NRIC	S1500268I
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	01/12/2018 10:32	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	30/11/2018	Time of Accident hh:mm	16:10	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	KPE TWDS ECP (CHANGI AIRPORT)				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 888 #08-1098	Address 2	TAMPINES STREET 81	Address 3	SINGAPORE 520888
Address 4		Address Type	Singapore address	Post Code	520888
Unit No.		Related Policy Number	5086391545-01		

OI Driver Info

Driver Name	KAMARUDIN BIN TAMBI	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S1500268I	Driver DOB	16/11/1961
Register Date of Driver License	01/01/2000	Driver Age	57	Driving Experience	18
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 888	Address 2	TAMPINES STREET 81	Address 3	
Address 4		Address Type	Singapore address	Post Code	520888
Unit No.	#08-1098				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	KAMARUDIN BIN TAMBI	Insured NRIC	S1500268I
Contact No.(Mobile)		Contact No. (Home)	67839677	Contact No. (Office)	
Email Address		OI Vehicle Number	SKP1334R	TP Vehicle Number	YM9658D
Claim Description	SKP1334R / YM9658D ON 30 Nov 2018			Name of Preferred Workshop	
Preferred Workshop Contact Person	Yes	Preferred Repair Option		Preferred Workshop Name	unknown
Insured Liability report	Fully at Fault				
Date Registered	01/12/2018 10:40	Claim Close Date		Date Received	01/12/2018 10:40
Report Taken By		Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	BMW	Vehicle Model	S20	Engine Capacity	
Date of Registration	09/02/2010	Classis No.	WBANT12050CX30109		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

Remark

NO OF REPAIR DAYS : 9 /2X FRT BUMPER SIDE RETAINER REPLACE/1X FRT BUMPER REINFORCEMENT UNCONFIRM /1X HORN UNCONFIRM/1X FRT LH HEADLAMP ASSY REPLACE/ HEADLAMP ASSY REPLACE/2X BONNET LOCKREPLACE/2X BONNET HINGE REPLACE/1X AIRCON SUCTION PIPE LOW PRESSURE REPLACE/1X AIR CON SUCTION HOSE UNCONFIRM DISCHARGE PIPE HIGH PRESSURE REPLACE/1X AIR CON DISCHARGE HOSE UNCONFIRM/1X AIR CON LIQUID PIPE REPLACE/2X AIR CON CONDENSER SIDE DEFLECTOR REPLACE/1 REPLACE/1X RADIATOR COWLING REPLACE/1X RADIATOR FAN ASSY REPLACE/1X RADIATOR FAN CLUTCH UNCONFIRM/1X RADIATOR HOSE TOP REPLACE / 1X RADIATOR HOSE B REPLACE/1X AIR CLEANER ASSY REPLACE/1X AIR CLEANER HOSE REPLACE/1X AIR CLEANER RESONATOR UNCONFIRM/1X FRT INLET MANIFOLD UNCONFIRM/1X FRT INLET MANI REPLACE/1X ALTERNATOR ASSY UNCONFIRM/1X ALTERNATOR BELT UNCONFIRM/1X POWER STEERING PUMP UNCONFIRM/1X POWER STEERING COOLER PIPE REPLACE/1X POWE

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root					
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace
ABS	2	16002401	BUMPER CLIPS (FRONT)	6	Replace
ABSORBER					
ACCELERATOR	3	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
ACTUATOR	4	16000101	BUMPER (FRONT)	1	Replace
ADVERTISEMENT STICKER					
AIR BAG	5	27100101	GRILLE (FRONT)	1	Replace
AIR BLOWER	6	41300101	SUPPORT PANEL (FRONT)	1	Replace
AIR BOX					
AIR CHAMBER BOX	7	149001	BONNET	1	Replace
AIR CLEANER	8	149029	BONNET INSULATOR	1	Replace
AIR COMPRESSOR	9	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm
AIR CON	10	16003201	BUMPER GRILLE (FRONT)	1	Unconfirm
AIR CON (VAN)					
AIR COOLER	11	15600101	BRACE PANEL (FRONT)	1	Replace
AIR DISTRIBUTOR	12	149016	BONNET EMBLEM	1	Replace
AIR FILTER	13	112050	AIR CON FAN	1	Replace
AIR FLOW					
AIR GRILLE	14	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm
AIR HORN	15	245001	ERP BRACKET	1	Replace
AIR INTAKE	16	243023	ENGINE OIL FILTER	1	Unconfirm
AIR RESONATOR BOX					
AIR THROTTLE BODY AND SENSOR	17	45100401	WINDSCREEN GLASS (FRONT)	1	Replace
ALARM	18	45101401	WINDSCREEN MOULDING (LEFT)	1	Replace
ALTERNATOR					
ALUMINIUM PANEL - SIDE	19	451020	WINDSCREEN SEALANT	1	Replace

Save Submit

Claim Handling

Task Transfer Exit

Accident MT/1022108

LOS SAL SUB

Policy No.	5086391545-01	Vehicle No.	SKP1334R	GST Registration No.	
Certificate No.					
Policyholder Name	KAMARUDIN BIN TAMBI			Policyholder NRIC	S15002681
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
K/F/K	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	01/12/2018 10:32	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	30/11/2018	Time of Accident hh:mm	16:10	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	KPE TWOS ECP (CHANGI AIRPORT)				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 888 #08-1098	Address 2	TAMPINES STREET 81	Address 3	SINGAPORE 520888
Address 4		Address Type	Singapore address	Post Code	520888
Unit No.		Related Policy Number	5086391545-01		

01 Driver Info

Driver Name	KAMARUDIN BIN TAMBI	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S15002681	Driver DOB	16/11/1961
Register Date of Driver License	01/01/2000	Driver Age	57	Driving Experience	18
Contact No.(Mobile)	97833654	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 888	Address 2	TAMPINES STREET 81	Address 3	
Address 4		Address Type	Singapore address	Post Code	520888
Unit No.	#08-1098				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	KAMARUDIN BIN TAMBI	Insured NRIC	S15002681
Contact No.(Mobile)		Contact No.(Home)	67839677	Contact No.(Office)	
Email Address		OI Vehicle Number	SKP1334R	TP Vehicle Number	YM9651
Claim Description	SKP1334R / YM9658D ON 30 Nov 2018			Name of Preferred Workshop	
Preferred Workshop		Insured at	Fully at		
Preferred Repair Option	Preferred Workshop Name unknown	Insured report	Fully at		
Date Registered	01/12/2018 10:40	Claim Close Date		Date Received	03/12/2018
Report Taken By		Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print A/C letter

Modification History

Special Claim Creation Approval

Approval

Reason

Remarks

damage assessment

Attachment

Accident No.

MT/1022108

Claim No.

001

Last Doc. Received:

☒ Yes

☐ No

Upload Date

03/12/2018 17:22

Path *

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Message Read

Category *

Confidential

Urgency *

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:22	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:22	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:22	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:22	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:22	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:21	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:20	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:20	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:20	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:20	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:20	Photos	Normal	Photos 2018-12-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER	Photos	Normal	Photos 2018-12-3

VICES) on 03 Dec 2018 17:20



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:17	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Dec 2018 17:15	Photos	Normal	Photos 2018-12-3
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:39	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:39	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:37	SAS	Normal	SAS 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:37	Photos	Normal	Photos 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:37	Photos	Normal	Photos 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:37	Photos	Normal	Photos 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:36	Photos	Normal	Photos 2018-12-1
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 01 Dec 2018 10:36	Photos	Normal	Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 01 Dec 2018 10:36

Photos

Normal

Photos 2018-12-1

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)
51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SKP 1334R Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Auto Point 04 - 06

Collection Date: 5-12-18 Time: 16.35 with Keys: ☒ Yes / No

Tow Truck No: YN 4668C Tow Man: Yu Li Jun NRIC: G 6942616L

Signature: Jun 9392 5845

For office use

Attended by: Shan Hui

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In
Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Wednesday, 5 December 2018 1:37 PM
To: AMKAUTOPOINT
Cc: LKK Paya Ubi; Teng Ken Leong
Subject: MT/1022108-001, VEHICLE NUMBER: SKP1334R

Importance: High

Dear AP

Please tow this vehicle from Idac and contact owner son Mr Abdul Rahman at 97833654 when the repair is done, excess \$1177/-

Our Ref: MT/CA/OD/051/1022108-001/NHJ

05 Dec 2018

AMK AUTOPOINT PTE LTD

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A

#01-22 AMK AUTOPOINT

SINGAPORE 568047

Dear Sir

CLAIM NUMBER: MT/1022108-001

REPAIR OF VEHICLE NUMBER: SKP1334R

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 05 Dec 2018

Make: BMW

Model: 520

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 1100.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank You

Ng Hak Joo

Iata-Uftaa-Itc, Anziif (Aff)

Executive

Motor Insurance

T +65 64307890

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.