

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49161
Date Estimated : 19/11/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Oh Yi Ming (Hu Yiming)
9 Rhu Cross
#06-09

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 437436

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKS6866Z	EG21246	26/04/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To check electrical wiring system and lightings at the rear section for proper function	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	4.00		10.20 <i>rel</i>
# EXPANDING NUT *	1.00	2.00		2.00 <i>rel</i>
# BUMP STOP *	3.35	10.00		33.50 <i>rel</i>
# EXPANDING RIVET *	1.35	10.00		13.50 <i>rel</i>
# (DG) CLEANER R1 (100ML) *	26.15	1.00		26.15 <i>rel</i>
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10 <i>rel</i>
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85 <i>rel</i>

Total Labour: 150.00
Total Parts: 376.30
Total Labour & Parts: 526.30

RESERVE PARTS PHOTO BY SURVEYOR YES NO

Surveyor's Name _____

Surveyor's ID _____

Authorized Date _____

Surveyor's E-mail _____

no. of Working Days Recommended _____

Claims ID and Party's Name _____

Claim No. _____

Excess \$ _____

Date _____

Signature _____

Stamp _____