

ASS. REC. BY:

REF:

CS/CT118021678 / R1Sbn2

Special Instruction:

Survivor:

m/ma

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

03/12/2018 1:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 7033P

Insured:

GBD 1864Y

at Workshop m/s

Goldbell

Tel:

of

Blk K Panikan Loop #01-12

Policy No:

DMCVSN 30644 81802

Claim No:

GNM18D 03591C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19-11-2018

CA / REV / REP. / REV 24 HRS WP

04.12.2018 @ 11-11:30am

H.O.D. Endorsement:

Date/Time:

03/12/2018 2pm

Person Contacted:

Alan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PA 7033P - N3/INC16070731 / H1ch3m2

DIA: 28/02/2016

GBD 1864Y - CS3/CT118016812 / Gebel

DIA: 18/06/2018

Signature: *[Signature]*

REF: C79

98430

LOT NO: 2022/344

ASSIGNMENT

From:

Date: 4/12/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 7033P

at Workshop m/s

Gold Bell

of BLK K pendan Loop Ind. Est #01-12

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11-11-30 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PA 7033P

Yr Regn:

2007 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HILUX 2.5A

C.C. 2494

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp Reading

677317

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KOM 2220035051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R05C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/11/18

D.O.I.

04/12/18

Survey held at

Gold Bell

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12/18 Under? Confirmed H/S \$ 1,300/- @ 3 days with Resul (\$ 878.46 Red - 40%)

RECEIVED 13 DEC 2018

Date/Time, File Pass to?

13/12/18

1) Typst

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 1,300/- H/S

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2018		03 Dec 2018 13:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	STAR INN LIMOUSINE SERVICE		
Vehicle Reg. No.:	PA7033P	Date of Loss:	19/11/2018 00:00 - :59
Claim Type:	TP / SNM18D05591C02	Policy/Cover Note No.:	DMCVSN3064481802
Vehicle Reg. No. (Insured):	GBD1864Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tuas - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 December 2018 9:58 AM
To: 'Andy Ooi Lee Keong'; Rasul (LKKAuto)
Cc: SUR
Subject: RE: PLEASE CONFIRMED FINALISED AMOUNT - PA7033P

Hi Andy,

Confirmed final fig of \$1,300.00 (lump sum) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Wednesday, 12 December 2018 10:17 AM
To: rasul@lkkauto.com
Cc: SUR <sur@lkkauto.com>
Subject: PLEASE CONFIRMED FINALISED AMOUNT - PA7033P

Hi Rasul ,

Kindly find the above attached after paint photo ,
Please closed @ Lump sum Repairs @ \$ 1300.00

Thanks & regards

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2018 11:34
Date Of Accident	19/11/2018 14:15
Exact Location Of Accident	CAR PARK OF BLK 119 BUKIT MERAH VIEW
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA7033P
Insured/Policyholder	
Name Of Registered Owner	STAR INN LIMOUSINE SERVICE
Co Reg No	53059843D
Email Address	STAR.INN.LIMOUSINE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96429747
Alternative Phone No	OFFICE-96429747
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D18MTSCBU000454
Cover Note Number	
Driver	
Name of Driver	TAY POH HENG
NRIC No	S1618255I
Date Of Birth	07/10/1963
Occupation	OUTDOOR
Date Of Driving Pass	08/09/1998
Driving Experience	20 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93710671
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 119, BUKIT MERAH VIEW #04-77
Postcode	152119
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT MERAH WEST N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACH POLICE REPORT *THE NISSAN LORRY REGISTRATION NUMBER PLATE IS GBD 1864 Y.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 21/11/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 21/11/2018



Reporting Centre Personnel's Signature

Name: Wang Chay Han

NRIC/FIN No: 51505557

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO ATTACH POLICE REPORT

* THE NISSAN LORRY REGISTRATION NUMBER
PLATE IS GRD 1864Y.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time 21.11.2018

Driver's Signature

(If driver is not the policyholder)

Date & Time 21.11.2018

Reporting Centre Personnel's Signature

Name Wang Chai Lan

Date & Time 21.11.2018



SINGAPORE
POLICE FORCE



T/20181120/2050

1 of 3

Report No. T/20181120/2050

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/11/2018 12:40	Vide Report No.:	Station Diary No.: 44
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAY POH HENG			Address: APT BLK 119 BUKIT MERAH VIEW #04-77 SINGAPORE 152119	
ID Type / ID No.: NRIC NO / S16182551			Contact No.: Home/Office:	Mobile: 93710671
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 55	Date of Birth: 07/10/1963	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Bus driver			Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 19/11/2018 14:15	Type of Location:
Location: Along Road 1 BUKIT MERAH VIEW				
Carpark of B/119 Bukit Merah View				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: No			

Details of Vehicle Involved


Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA7033P	Bus/Coach/Mi nibus				Slightly Damaged	0



T/20181120/2050

2 of 3

Report No: T/20181120/2050

 SINGAPORE
POLICE FORCE
Police Station Of Origin:
Bukit Merah West N.P.C.
500 Bukit Merah View #01-01 SINGAPORE
159682

CONTINUATION OF REPORT

Tel No: 1800-3779999

Brief Details.

On 19/11/2018 at about 1245hrs, I went to B/119 Bukit Merah View carpark and had parked at the red lots. Subsequently on the same day, I returned to my vehicle and noticed that there was a scratch on the right front side of my vehicle(PA7033P). I then inform my company right away. I am currently working as a bus driver for Star Inn Limousine Service. My company then made a check on the camera and noticed that there is a Nissan Lorry had hit onto my vehicle and subsequently drove off.

I wish to state that when I parked my vehicle at the said location, everything was intact and there was no scratches on my vehicle.



SINGAPORE
POLICE FORCE



T/20181120/2050

3 of 3

Report No. T/20181120/2050

Police Station Of Origin:
Bukit Merah West N.P.C.
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 2 WEE WEI XIONG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
SI ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Signature Of Informant:

Date/Time:
20/11/2018 12:40

Classification Of Case:

Authentication Stamp
AF155

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of TAY POH HENG

License Number: **S1618255I**

Name: **TAY POH HENG**

Birth Date: **07 Oct 1963**

Issue Date: **19 Sep 2008**

Barcode: 001654563A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1618255I**

Portrait of TAY POH HENG

Name: **TAY POH HENG**

Race: **戴寶興**

Race: **CHINESE**

Date of birth: **07-10-1963**

Country/Place of birth: **SINGAPORE**

Sex: **M**

51618255I

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	08 Sep 1998
Class 4	*Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg *Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	03 Jul 2003

NP 428A

Barcode: Licence No: S1618255I

5193008

Barcode

NRIC No. **S1618255I**

Portrait of TAY POH HENG

Date of issue: **15-07-2013**

APT BLK 119 BUKIT MERAH VIEW #04-77

SINGAPORE 152119

S1618255I

11/10/2013

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTSCBU000454
1. Registration No. : PA7033P
2. Insured Name : STAR INN LIMOUSINE SERVICE
3. Commencement Date : 26 JULY 2018 00:00
4. Expiry Date : 25 JULY 2019 23:59
5. Coverage : Market value at time of loss - Third Party, Fire & Theft
6. Excess : \$1000 - Section II

7. Persons or Classes of Persons entitled to drive*

b) Any person provided he is in the Insured's employ and is driving on their order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

8. Limitations as to use*

- a) Use only for the carriage of passengers or goods in connection with the Insured's business.
- b) Use only in the Republic of Singapore.

The Policy does not cover

- 1) Use for racing, pacemaking, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

9. ExcelDrive Workshops & Accident Reporting


It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6226 3323

Visit www.sompo.com.sg for list of Accident Reporting Centers.

I/We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Sompo Insurance Singapore Pte. Ltd.



Date/Time of Issue : 16 JULY 2018 14:02

*Limitation rendered inoperative by section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

IMPORTANT NOTICE

- 1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use, or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- 2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the Insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).
- 3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
- 4. Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
- 5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy.

Intermediary Code & Name : 11S13002 & SSTA INSURANCE AGENCY PTE LTD CI Code: 23H DXPD5HO4KP3MTQZA



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 630894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date : 27/11/2018
To : CHINA TAIPIING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :
From : GOLDBELL ENGINEERING PTE LTD
Attn. : ANDYOOILK
Office / Mobile : +65 67730073
Email / Fax No. : AndyOoiLK@goldbell.com.sg

Reg No : PA7033P
Model : HIAGE 2.5 A
Chassis No : KDH2220035051
Engine No : 2KD1655188
Quotation No. : 76673
Ref. No. : GBE/SVC/SALES
D.O.A. : 19/11/2018
Policy No. : D18MTSCBU000454
Claim Type : THIRD PARTY
Workshop : PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER <i>scr</i>	1	523.20	-25	392.40	392.40
2		FRONT BUMPER SENSOR RH <i>as Xone</i>	1	395.50	-25	296.63	296.63
3		HEADLAMP ASSY RH <i>scr</i>	1	708.90	-25	531.68	531.68
4		DOOR SIDE MIRROR RH <i>scr</i>	1	277.00	-25	207.75	207.75
PARTS TOTAL :							1,428.46

LABOUR CHARGES

- | | | |
|---|---|-----------------------|
| 1 | TO REMOVE & REPLACE DAMAGED PARTS ,CUT,WELD ,STRAIGHTEN & PANEL BEAT ACCIDENT AREAS | 250 400.00 |
| 2 | TO PUTTY ,CLEAN ,SPRAY PAINT & POLISH ON AFFECTED AREAS | 250 300.00 |
| 3 | TO CHECK & REPAIR WIRING SYSTEM | 30 50.00 |

LABOUR TOTAL : 750.00
SUB-TOTAL : 2,178.46
GST @ 7% for \$ 2,178.46 152.49
GRAND TOTAL (S\$) : 2,330.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010088
3 days
p/r
04/12/18 @ 1110
Rasul by part

biSAFE
STARS



Certificate No: AJA/18/12/1242

Certificate No: AJA/18/12/1242



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 198003983G

Page 2 / 2

ESTIMATE

Date	: 27/11/2018	Reg No	: PA7033P
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: HIAGE 2.5 A
Attn.	:	Chassis No	: KDH2220035051
Office / Mobile	:	Engine No	: 2KD1655188
Email Address	:	Quotation No.	: 76673
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 19/11/2018
Attn.	: ANDYOOILK	Policy No.	: D18MTSCBU000454
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME :

04/12/18 @ 1116

SURVEYOR :

Ragun

MOBILE NO :

96010068

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE :

PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY :

BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

3 days

REMARKS :



Certificate No: AIA/S/101243

Certificate No: AIA/1198



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date : 27/11/2018
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : ANDYOOILK
Office / Mobile : +65 67730073
Email / Fax No. : AndyOoiLK@goldbell.com.sg

Reg No : PA7033P
Model : HIAGE 2.5 A

Chassis No : KDH2220035051
Engine No : 2KD1655188
Quotation No. : 76673
Ref. No. : GBE/SVC/SALES
D.O.A. : 19/11/2018
Policy No. : D18MTSCBU000454
Claim Type : THIRD PARTY
Workshop : PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER <i>scr</i>	1	523.20	-25	392.40	392.40
2		FRONT BUMPER SENSOR RH <i>scr</i>	1	395.50	-25	296.63	296.63
3		HEADLAMP ASSY RH <i>scr</i>	1	708.90	-25	531.68	531.68
4		DOOR SIDE MIRROR RH <i>scr</i>	1	277.00	-25	207.75	207.75
PARTS TOTAL :							1,428.46

LABOUR CHARGES

- | | | | |
|---|---|-----|--------|
| 1 | TO REMOVE & REPLACE DAMAGED PARTS ,CUT,WELD ,STRAIGHTEN & PANEL BEAT ACCIDENT AREAS | 250 | 400.00 |
| 2 | TO PUTTY ,CLEAN ,SPRAY PAINT & POLISH ON AFFECTED AREAS | 250 | 300.00 |
| 3 | TO CHECK & REPAIR WIRING SYSTEM | 30 | 50.00 |

LABOUR TOTAL : 750.00
SUB-TOTAL : 2,178.46
GST @ 7% for \$ 2,178.46 152.49
GRAND TOTAL (S\$) : 2,330.95

LLK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Inform RASHL W/C REPAIR ON 01/12/18

bizSAFE
STAR



FINALISED
P-1131-83
L-520-00
1661-83-20%
HS 1300-00

RASHL
HP 90010068
3 days
P/R
04/12/18 @ 1110

Resur by paint

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021678/R1SBN2

Date: 17/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3064481802
Claimant Vehicle No :	PA7033P	Insured Vehicle No :	GBD1864Y
Date of Loss:	19/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05591C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA7033P	Engine No:	2KD1655188
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2220035051
Reg. Date:	20/07/2007 (Man. Year: 2007)	Odometer:	677317 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,428.45	1,131.82	296.63	20.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	530.00	220.00	29.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,178.45	1,661.82	516.63	23.72
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	2,178.45	1,300.00	878.45	40.32
+ GST 7.00/7.00% (\$\$)	152.49	91.00	61.49	40.32
Nett Amount (\$\$)	2,330.94	1,391.00	939.94	40.32

INSPECTION

Date of Assignment:	03/12/2018	
Date Inspected:	04/12/2018 Inspected At:	Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12 Singapore 128219
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2018)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA7033P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	523.20 FL	*523.20 FL
2	1		*FRONT BUMPER SENSOR RH	Serviceable	395.50 FL	*- FL
3	1		*HEADLAMP ASSY RH	Scratched	708.90 FL	*708.90 FL
4	1		*DOOR SIDE MIRROR RH	Scratched	277.00 FL	*277.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,904.60	1,509.10
- List Item Discount on L Items 25.00/25.00% (S\$)	476.15	377.28
Total Parts (S\$)	1,428.45	1,131.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE DAMAGED PARTS,CUT,WELD,STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	400.00	250.00
2	TO PUTTY,CLEAN,SPRAY PAINT & POLISH ON AFFECTED AREAS	New	300.00	250.00
3	TO CHECK & REPAIR WIRING SYSTEM	New	50.00	30.00
Gross Labour Cost (S\$)			750.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >