

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM18021684/Gea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	28/03/2021	
	ATTN:WINNIE			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLF 5647C	Veh. Inspected	l	SGU 1739C	
	Policy No.	VPA/P1829962	Coverage (\$)		0.00	
	Claim No.	S8M01544	Excess (\$)		0.00	
	Assign From		Assign Date		03/12/2018	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTDGG20WX0J003850	Colour		SILVER	
	Odometer	44586 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	26/11/2018	Inspection Dat	е	05/12/2018	
	Survey held at	BLK 8 KAKI BUKIT AVENUE 4 #01-49				
	Repairer	TORQUE 5 PTE LTD				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				