

ASS. REC. BY:

REF: *ADA*

2712/16ja3

(1)


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Alan's
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 860k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE 6662R Yr Regn: 01.16
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes ^{A1} 3 c.c. 1.496
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sp. Reading 34572 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMGBM 44A8G 0328805
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: NII / S/Rim / STD / Rim or _____
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 19/11/18 D.O.I. 4/12/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
& B
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/12</u>	<u>File pass to Catherine</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

1) _____
 Date/Time, File Return to?
 2) _____

Report Format : _____
 Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others _____
 TOTAL _____

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: S1216868C
 Owner ID Type: Singapore NRIC
 Owner Name: TAN BEE KIM
 Registered Address: 43 JALAN LEMBAH THOMSON SINGAPORE 577513
 Mailing Address: -
 Birth Date: 10 Apr 1956

Vehicle Particulars

Vehicle No.: SGE6662R
 Previous Vehicle No.: -
 Effective Date of Ownership: 28 Jan 2016
 Original Regn Date: 28 Jan 2016
 Registration Date: 28 Jan 2016
 Year of Manufacture: 2015
 Vehicle Type: Passenger Motor Car
 Vehicle Scheme: -
 Vehicle Attachment 1: With Sun Roof
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: MAZDA
 Vehicle Model: MAZDA3 5-DOOR HATCHBACK 1.5L SP.6EAT
 Primary Colour: White
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: JM6BM44A8G0328805
 Engine No.: P520337821
 Engine Capacity/Power Rating: 1496 cc / -
 Maximum Power Output: 88.0 kW (118 bhp)
 Propellant: Petrol
 Max Unladen Weight: 1324 kg
 Maximum Laden Weight: 1835 kg
 Open Market Value: \$15,326.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 27 Jan 2026
 Minimum PARF Benefit: \$5,163.00
 No. of Transfers: 0
 IU Label No.: 1126330602
 COE No.: 2016020101001759H
 COE Expiry Date: 27 Jan 2026
 COE Category: A - Car (up to 1600cc & 97kW (130bhp))
 COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
 \$51,301.00 / -