

NATIONAL Assessment Centre Services [wef 1 Jan'05] **MNA118156247**

Date In: 3/14/18-19:24	Job description	Date & Time Completed	Done by
Ref No: NA/INC 18022394/C24	SAS e-filing		
Veh No: SL6397H	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 30/11/18 - 19:00	i-Motor Claim Form	NA/1022394-001	3/14/18 20:03
☒ TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: SL6397H	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (%)	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

NA1808253	Invoice Preparation Checklist	Amt (\$) In Bill	Amt (\$) Add Bill
Claimant's Particulars:-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	OD*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idac Mobile \$0		
QC Checked by (Engr-In-Charge):	Invoice dated	Fee Charged	
Auditors' Comments:-	Invoice dated	Fee Charged	
Ref 1:			
Ref 2/3:			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 15:29
Date Of Accident	30/11/2018 19:00
Exact Location Of Accident	LORNIE RD TWDS BRADDELL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6397H
Insured/Policyholder	
Name Of Registered Owner	SAW NYAN MYAT SAN
NRIC No	S8371613D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90083475
Alternative Phone No	OFFICE-90083475

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.3 CVT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096149188
Cover Note Number	

Driver

Name of Driver	TAN SHI MIN
NRIC No	S8520331B
Date Of Birth	27/06/1985
Occupation	INDOOR
Date Of Driving Pass	12/02/2011
Driving Experience	7 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97953534
Fax Number	
Contact Number	OFFICE-97953534
Email Address	NOEMAIL

Address	BLK 350 BUKIT BATOK STREET 34 #08-126
Postcode	650350
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ4941M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YM9355Y
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

except in order of envelopes/mail packages; and/or

- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time & date,
 I was driving my car (veh A: SLG6397H) on lane 3 along Lornie Rd towards Braddell Rd. There was a slow moving tow car (veh C: VM9355Y) in front of me. With the intentions to overtake veh C, I decided to switch to lane 2. However, halfway through the lane changing, the right side of my car collided onto the left side of a car (veh B: SLJ4941M), the impact caused my car to lose control and swerved left, thus causing the left side of my car to collide onto veh C's right rear bumper. I stopped my car immediately. I wish to state that there was another lorry in front of veh C but I managed to stop in time and did not come into contact with the said lorry.

DECLARATION

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

* phone no - 97953534 (Driver) / 90083475 (owner)
* weather - clear
* relationship - BIL

Date of Accident : 30/11/2018 Accident Time: 1900 (24-HR-Format)
Accident Place : Lonnie Rd Towards Braddell Rd
Vehicle Reg. No. (Car Plate No.) : SLG 6397 H
Vehicle Make/Model : Honda J922
Insurance Company : NTUC Policy No. 5096149188
Owner or Company Name / IC No. : SAW NYAN MYAT SAN S8371613D
Owner or Company Contact No. : 90083475 Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : TAN SHI MIN S8520331B
DRIVER'S Date Of Birth : 27/06/1985 DRIVER'S License Pass Date relativ
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: relative
DRIVER'S Address : BLK 350 BUKIT BATOK ST 34
DRIVER'S Contact No. / Alt No. : (1) 9795 3534 (2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1

Was there any video Captured by car camera: YES NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Other Party Driver's Particular (if any)

Vehicle Reg. No: SLG4041M

Vehicle Reg. No: YM9355Y

Vehicle Make/Model: _____

Vehicle Make/Model: _____

Name Driver: _____

Name Driver: _____

IC No. Driver: _____

IC No. Driver: _____

Driver's Contact & Add: _____

Driver's Contact & Add: _____

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8520331B



5562106



Name

TAN SHI MIN

陈诗敏

Race

CHINESE

Date of birth

27-06-1985

Sex

F

S8520331B



Country/Place of birth

SINGAPORE

NRIC No. S8520331B

Date of issue

16-02-2016

Address

APT BLK 350 BUKIT BATOK STREET 34
#08-126
SINGAPORE 650350

REPUBLIC OF SINGAPORE

Licence Number S8520331B

Name: TAN SHI MIN

Birth Date: 27 Jun 1985

Issue Date: 12 Feb 2011

001937194J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 12 Feb 2011

NP 428A



Licence No: S8520331B



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5096149188

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : SLC6397H
Chassis Number : JHMGK3850GX236678
 2. Name of Policyholder : SAW NYAN MYAT SAN
 3. Effective Date of Insurance : 27 Nov 2017
 4. Expiry Date of Insurance : 19 May 2019
 5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
 6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.
- This Policy does not cover
- (a) Use for hire or reward.
 - (b) Use for racing, pace-making, reliability trial or speed-testing.
 - (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (d) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: SAW NYAN MYAT SAN
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: MAYBANK
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : LQ INSURANCE AGENCY PTE LTD (00000613125)
Date of Issue : 27 Nov 2017 15:29 hrs

LQ INSURANCE AGENCY PTE LTD
180B BENCOOLEN STREET
#04-01 THE BENCOOLEN
SINGAPORE 189648
TEL: 6334-0783 FAX: 6-334-0624
CR. REG. NO: 199005500W

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	30/11/2018 19:00
Vehicle No. (For Motor)	SLC6397H	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5096149188		SAW NYAN MYAT SAN	S8371613D	GPC	drive CLASSIC	SLC6397H	SLC6397H	27/11/2017	19/05/2019
Continue										

Policy Information

Policy No.	5096149188	Policyholder Name	SAW NYAN MYAT SAN	Policyholder NRIC	S8371613D
Certificate No.					
Address	BLK 690B #07-96 CHOA CHU KANG CRESCENT SINGAPORE 682690				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	27/11/2017	Effective Date	27/11/2017 00:00	Expiry Date	19/05/2019 23:59
Excess Type		All Claims Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver Excess	
Agent	LQ INSURANCE AGENCY PTE LTD	Agent Tel.	63340783	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	BLK 690B #07-96	Address 2	CHOA CHU KANG CRESCENT	Address 3	SINGAPORE 682690
Address 4		Address Type	Singapore address	Post Code	682690
Unit No.	07-96	Related Policy Number	5096149188		

Insured Object: SLC6397H

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

Exit

Accident MT/1022394

Policy No.	5096149188	Vehicle No.	SLC6397H	GST Registration No.	
Certificate No.					
Policyholder Name	SAW NYAN MYAT SAN			Policyholder NRIC	58371613D
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No. (Mobile)	90083475	Contact No. (Office)	0	Contact No. (Home)	0
Email Address		Special Remark		eCode	
KPK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No

Accident Details

Report Date	03/12/2018 19:58	Accident Report Within 24 hrs	Yes	Accident Type	Side Swipe
Date of Accident	20/11/2018	Time of Accident hh:mm	19:00	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	LORNE RD TWOS BRADDELL RD				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	500.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 690B #07-96	Address 2	OHUA CHU KANG CRESCENT	Address 3	SINGAPORE 682690
Address 4		Address Type	Singapore address	Post Code	682690
Unit No.	07-96	Related Policy Number	5096149188		

OT Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	TAN SHE MIN	Driver NAIC	585203218	Driver DOB	27/06/1985
Register Date of Driver License	12/02/2011	Driver Age	33	Driving Experience	7
Contact No. (Mobile)	97953534	Contact No. (Office)	0	Contact No. (Home)	0
Address 1	BLK 350	Address 2	BUKIT BATOK STREET 34	Address 3	SINGAPORE 650350
Address 4		Address Type	Singapore address	Post Code	650350
Unit No.	08-126				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 New

Claim Type *	OD-ND	Insured Name	SAW NYAN MYAT SAN	Insured NRIC	58371613D
Contact No. (Mobile)		Contact No. (Home)		Contact No. (Office)	63340783
Email Address		OT Vehicle Number	SLC6397H	TP Vehicle Number	SL34941M
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	SLC6397H / SL34941M ON 30 Nov 2018				
Preferred Workshop Contact No.	64521208	Insured Liability *	Fully at Fault	Name of Preferred Workshop	DING AUTO PTE LTD.
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	03/12/2018 20:03	Claim Close Date		Date Received	03/12/2018 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	

☒ Print Aik letter

Save Submit

Attachment

Accident No.	MT/1022394	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	03/12/2018 20:05

Path *	Category *	Confidential	Urgency *	Description *

Attachment List							
Attachment	Uploaded By/Date	Category	Urgency	Description	Map Sent? (CO)	Action	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	SAS	Normal	SAS 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:05	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:04	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 03 Dec 2018 20:03	Photos	Normal	Photos 2018-12-3		Edit	



NAC_PAYA_UBI_8005011 NATIONAL ASSESSMENT CENTRE SERVICE on 03 Dec 2018 20:03

Photos

Normal

Photos 2018-12-3

Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
------------------	-------------	-----------	--------	--------

Display in New Window

Scan and uploading

ASSIGNMENT (ID 01)

By Cause: Natural Accident:

- 1) Vehicle hit Vehicle:
 - a) Pedestrian ☐
 - b) Motorcycle ☐
 - c) Bicycle ☐
- 2) Vehicle hit 22:
 - a) Pedestrian ☐
 - b) Animal ☐
- 3) Vehicle hit Road Side Objects:
 - a) Govt Property ☐
 - b) Road Work Object ☐
 - c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God:
 - a) Fallen Object ☐
 - b) Flood ☐
 - c) Other ☐
- 6) Parked & Found Damaged:
 - a) Vandalism ☐
 - b) Hit by Moving Object ☐
- 7) Theft Case:
 - a) Stolen ☐
 - b) Damage found when recovered ☐
- 8) Fire:
 - a) While driving ☐
 - b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

By Assessor: 1) Vehicle Information

Vehicle: **SLC6397 H** Date: **20 May 2016**

Type: **Motorcycle** / Bus / Van / Car / Taxi / Truck / Trailer or

Make/Model: **Honda Jazz 1.3 CVT** 1318

Color: **Blue** Paint/Seal Type: **Auto** Manual

Eng/No: **39499**

Chassis: **JHMGK3F50GX236678**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Good** / Jammed / Leaked / Burnt or

Brake: **Good** / Jammed / Leaked / Burnt or

Mod: **Std** / S/Rim / STD A/Rim or

Tyre Size: **F: 175/65 R15**

R: **175/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO **YOKO** or

Front: **5** mm Rear: **6** mm

R/Bal: **5** mm L/Bal: **5** mm

Parallel Import: Yes ☒ No

Towed-In: Yes ☐ No

Repair Type: LS / LBJ

Towing Required: Yes ☒ No

No of Repair Days: **8**

Vehicle in Shop: Yes ☒ No

D.O.I: **4/12/2018**

Time: **11.10am**

By Assessor: 2) Comments

- 1) Damages not due to recent accident
- 2) Damages do not seem hit onto:
 - a) Vehicle ☐
 - b) Motorcycle ☐
 - c) Bicycle ☐
 - d) Pedestrian ☐
 - e) Animal ☐
 - f) Govt Object ☐
 - g) Road Work Object ☐
 - h) Private Property ☐
 - i) Drain ☐
 - j) Road Felt/Glass Venge ☐
- 3) Vehicle does not seem damaged as a result of:
 - a) Fallen Object ☐
 - b) Flood ☐
 - c) Vandalism ☐
 - d) Fire ☐
 - e) Moving Object ☐
 - f) Stolen ☐
 - g) Stolen & Recovered ☐

Time Started

Time completed

4/12/2018

4/12/2018

Signature / Name / Date / Time

Condition (CON)

(01)Item (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing
(13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (RH)

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (7)
(4)Not Consistent (INC)

Aug 2005

Right Portion

Vehicle No:

SLC 6397 H

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	DD	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror	BR		
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle	CUT		
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	BUC		
1107	991744	Frt RH Fender <u>Inner Shield</u>	DIS		
1108	991752	Frt RH Fender <u>Protector Quarter Glass</u>	CUT		
		<u>Frt RH Wheel Rim</u>	CUT		
		<u>" " " Tyre</u>			60%
		<u>" " Fender Quarter Glass</u>	CUT		
		<u>Vertical Garnish</u>			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	R	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	DD	R	
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items:

Assessor:

(01) Bent (2) Denied (3) Disoriented (4) Cracked (5) Cut (6) Scrimched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Tons (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

ACTION 14C

(1) Replace (✓) (2) Repair (✓)
(3) Use Cracks (✓) (4) C

EaCheck

Avg 304.2

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	BUC		
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	BR		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding	CUT		
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass	CUT		
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle	CUT		
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper	DD		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	BUC		
1098	995147	Frt LH Fender Inner Shield	D/S		
1099	995148	Frt LH Fender Protector			

Vehicle No: SLC 6397 H

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	BUC		
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Fender Glass Sealant	NEC		
1307	993288	Rear LH Fender Glass			
1308	993287	Rear LH Door 1/4 Glass			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender	BUC		
1219	993449	Rear LH Fender Inner Shield	DIS		
1136	990247	Sticker			

No of Items: _____ Assessor: _____

Claim Handling

Task Transfer Exit

100% 50% 0%

Accident MT/1022394

Policy No.	5095149188	Vehicle No.	SLC6397H	GST Registration No.	
Certificate No.					
Policyholder Name	SAW NYAN MYAT SAN	Cover Type	Brivo CLASSIC	Policyholder NRIC	58371613D
Product Code	PRIVATE CAR INSURANCE	Contact No. (Office)	0	Loading	0
Contact No. (Mobile)	90083475	Special Remark		Contact No. (Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KFC	☒ No ☐ Yes	NCD Entitlement(%)	20	eCode Reason	
NCD Protection	No			Private Hire	No

Accident Details

Report Date	03/12/2018 19:58	Accident Report Within 24 hrs	Yes	Accident Type	Side Swipe
Date of Accident	20/11/2018	Time of Accident hh:mm	19:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	LORNJIE RD TWDS BRADDELL RD				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	500.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date		GST Status Verified	Yes
GST Registration No.					
Modification History					

Policyholder Mailing Address

Address 1	BLK 690B #07-96	Address 2	CHOA CHU KANG CRESCENT	Address 3	SINGAPORE 682690
Address 4		Address Type	Singapore address	Post Code	682690
Unit No.	07-96	Related Policy Number	5095149188		

OT Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	27/06/1965
Unnamed driver Name	TAN SHI MIN	Driver NRIC	S8520331B	Driving Experience	7
Register Date of Driver License	22/02/2011	Driver Age	33	Contact No. (Home)	0
Contact No. (Mobile)	97953534	Contact No. (Office)	0	Address 3	SINGAPORE 650350
Address 3	BLK 350	Address 2	BUKIT BATOK STREET 34	Address 3	SINGAPORE 650350
Address 4		Address Type	Singapore address	Post Code	650350
Unit No.	08-126				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Chee

100% 50% 0%

Claim Type	OD-MD	Insured Name	SAW NYAN MYAT SAN	Insured NRIC	58371613D
Contact No. (Mobile)		Contact No. (Home)		Contact No. (Office)	63340763
Email Address		01 Vehicle Number	SLC6397H	TP Vehicle Number	SL4941M
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	SLC6397H / SL4941M ON 30 Nov 2018	Name of Preferred Workshop	DING AUTO PTE LTD		
Preferred Workshop Contact No.	64521208	Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	03/12/2018 20:06	Claim Close Date		Date Received	05/12/2018 09:54
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

Damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	3AZZ	Engine Capacity	
Date of Registration	20/05/2016	Classis No.	3HMGK3850GX236678		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No

Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No	
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)

REMARK-NO OF REPAIR DAY-8 DAYS, 1 X FRT RH DOOR WING MIRROR - REPLACE, 1 X FRT RH FENDER QUARTER GLASS - REPLACE, 1 X FRT RH WHEEL RIM - REPLACE, 1 X FRT RH FENDER QUARTER GLASS VERTICAL GARNISH - REPLACE, 1 X FRT LH DOOR WING MIRROR - REPLACE, 1 X REAR LH DOOR INNER TRIM BOARD - UNCONFIRM, 1 X REAR LH FENDER GLASS SEALANT - REPLACE, 1 X REAR LH FENDER GLASS - UNCONFIRM.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
front						
Not Applicable	1	23300202	DOOR (FRONT RIGHT)	1	Repair	X
ABS						
ABSORBER	2	23302802	DOOR HANDLE (OUTER) (FRONT RIGHT)	1	Replace	X
ACCELERATOR	3	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	X
ACTUATOR	4	25400103	FENDER (FRONT RIGHT)	1	Replace	X
ADVERTISMENT STICKER	5	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
AIR BAG						
AIR BLOWER	6	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	X
AIR BOX						
AIR CHAMBER BOX	7	23300204	DOOR (REAR RIGHT)	1	Repair	X
AIR CLEANER	8	25400106	FENDER (REAR RIGHT)	1	Repair	X
AIR COMPRESSOR						
AIR CON	9	23300201	DOOR (FRONT LEFT)	1	Replace	X
AIR CON (VAN)						
AIR COOLER	10	23302201	DOOR GLASS OUTER Moulding (FRONT LEFT)	1	Replace	X
AIR DISTRIBUTOR	11	23302001	DOOR GLASS (FRONT LEFT)	1	Replace	X
AIR FILTER	12	23306101	DOOR RUBBER (FRONT LEFT)	1	Unconfirm	X
AIR FLOW						
AIR GRILLE	13	23302801	DOOR HANDLE (OUTER) (FRONT LEFT)	1	Replace	X
AIR HORN						
AIR INTAKE	14	16000101	BUMPER (FRONT)	1	Replace	X
AIR RESONATOR BOX						
AIR THROTTLE BODY AND SENSOR	15	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
ALARM	16	25400102	FENDER (FRONT LEFT)	1	Replace	X
ALTERNATOR	17	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
ALUMINUM PANEL - SIDE	18	23300203	DOOR (REAR LEFT)	1	Replace	X
AMPLIFIER						
ANTENNA	19	23306103	DOOR RUBBER (REAR LEFT)	1	Unconfirm	X
ANTI ROLL						
APRON	20	16000102	BUMPER (REAR)	1	Unconfirm	X
ARCH	21	25400105	FENDER (REAR LEFT)	1	Replace	X
ARM REST						
	22	25400903	FENDER INNER SHIELD (REAR LEFT)	1	Replace	X

Save Submit

LKK Paya Ubi

From: Teng Ken Leong <kenleong.teng@income.com.sg>
Sent: Monday, 17 December 2018 3:52 PM
To: NAC Paya Ubi
Cc: Ding Auto Pte Ltd (Admin); Kenneth Ding (Ding Auto); Teng Ken Leong
Subject: Vehicle No SLC6397H - Release Vehicle : OD Claim No MT/1022394-001 (DOA : 30/11/18)

Dear Mr Jackson

The repair of the above-mentioned vehicle will be undertaken by Ding Auto Pte Ltd.

Please release the vehicle to the towing agent of Ding Auto.

Dear Mr Alex, our teleconversation this afternoon refers.

Thanks & regards

Teng Ken Leong
Assistant Manager
Motor Insurance
T +65 6430 7881
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES

(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SLC63974 Date In: 17/12/18 Time In: 1650 with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: DING AUTO

Collection Date: 17/12/18 Time: 1650 with Keys: Yes / No

Tow Truck No: GBH3735C Tow Man: Leon NRIC: S7709724/D

Signature: _____

For office use

Attended by: Jackson

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____