

INS. CASE OWNER:

CC 4, A16 180 2757, A jazp

LKK:  
IDAC:

Surveyor:

LWP

DOI:

## ASSIGNMENT

30/11/2018

Date / Time:

30/11/2018

Registered in Merimen:

21/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SPK 28R

Claim No.:

Name of Insured:

Grah Hng

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

21-11-2018

Place of Accident:

Kallay Centre Park c/p

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

2X 31526



INSRS:

WSP:

Tel:

Liability:

RMKS:

Precise Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/12/18  
jry2X 31526 x; SPK 28R x  
Repairer: Prince Motor (S) Pte Ltd

HEAD-TO-REAR

\* TP demand's signature ATA &amp; GIA.

\* LTA cancel date is diff in ODA.

## STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

27-549 juy

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdowns Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email ☐ Call ☐

## FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Assessed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2,033

Loss of Rental (LOR):

SS

500

(5 days) 100

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

37

(29 + 8)

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

2,570. x +

Global Sum SS: 2,550

## FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

2,550. x +

Name 1:

PRECISE AUTO SERVICE

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT  
6/16/19

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/o:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No SLX31526 - Yr Regn: 2018 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Uios. C.C. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 26090 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR2B23F380114286.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 30/11/18

Survey held at: Preuse.

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP A/G.

16.5.19 L/S \$1.9K

R (\$3,087.12/62%)

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. S + RS. 9)

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883  
TEL : 67457367 FAX : 68413390  
CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

31-03-19

Accident Date : 21-11-18

Adrian.

OUR REF : SLX 3152G/T/18

TAN HOCK KENG  
Blk 503 Sembawang Road  
#02-28  
Singapore 757707

Date in/out: 30/11/18 to 05/12/18  
TPA's Joy.

**ESTIMATE BILL ON VEH. NO.: SLX 3152G**

**MODEL: TOYOTA VIOS**

**CHASSIS NO: MR2B23F3801114286**

## LIST ITEM

Rear Bumper Fascia	Defamed.		431.35	-
Rear Bumper Reinforcement	Bent		381.90	✓
Rear Bumper Reflector LH	new		172.10	+
Rear Bumper Clips	new	10pcs @ 12.90	129.00	30. ✓
Rear Bumper Side Attachment	new	2pcs @ 172.10	344.20	+
Rear Bumper Side Retainer	new	2pcs @ 174.45	348.90	78. ✓
Boot Lid Badge	3		63.10	-
Boot Lid Emblum "Vios"	new		63.75	-
Boot Lid Emblum "E"			51.10	-
Boot Lid Weatherstripe	new		231.35	X.
Tail Lamp LH	cracked		374.40	✓
Tail Lamp Sealant	new		50.00	X
			2,641.15	
25% Less Discount :			660.29	
			1,980.86	

## SPECIAL NETT ITEM

Rear Bumper Parking Sensor	2000	380.00	20. ✓
Boot Lid Outer Keyless Sensor	new	380.00	X.

## LABOUR CHARGE

To check wiring system

50.00 30

To tuff coat affected areas	180.00	*
To remove & refix center upholstery	120.00	*
To remove & refix reverse sensor	<del>120.00</del>	50
To respray affected areas	<del>800.00</del>	600
To renew damaged parts, straighten & repair boot lid & rear end panel and aligned all parts	<del>650.00</del>	400

1080

TOTAL :	4,660.86
GST 7% :	326.26
AMOUNT DUE :	<u>4,987.12</u>

total : 2385.20

c/s : 1.9K.

02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**- Pre repair inspection request - SLX3152G VS SDK28R (OI) DOA 21/11/2018**

From: Chan, Yoke Shi  
To: Admin A, ASSIGNMENTS@LKKAUTO.COM  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinrul; Kaur, Baljit  
Sent: 30/11/2018 2:27:53 PM  
Attachments: 30112018105437.pdf

Hi,

Please refer to the enclosed request from **precise auto service**.

Claim no : ES48373437SG003  
Case Owner : BENNIE TAN WEI ZHONG

If you have any queries/concerns, please let us know.  
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley  
AIG  
Claim Adjuster II, Singapore FNOL Claims Operations - Auto  
yokeshi.chan@aig.com | www.aig.com

From: support@preciseauto.sg [mailto:support@preciseauto.sg]  
Sent: Friday, November 30, 2018 1:01 PM  
To: Chan, Yoke Shi  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinrul; Kaur, Baljit; support@preciseauto.sg  
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDK28R AND SLX3152G ON 21/11/2018

Dear Sir,

We refer to your email on dated 30-11-2018. Please be informed that we are select Mr. Marcus Chua from LKK Auto Consultants Pte Ltd as our SJE.

Our client vehicle is in workshop for PRI.

Thank You!

Best Regards

Arine

From: Chan, Yoke Shi  
Sent: Fri, 30 Nov 2018 03:07:43 +0000  
To: Precise Auto Service  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Hor, Yinrul; Kaur, Baljit  
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDK28R AND SLX3152G ON 21/11/2018

Without Prejudice

Your Reference : SLX3152G  
Our Reference : ES48373437SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Lang Kiat	Priority Services

3.04pm @ 30/11/18  
vehicle in  
person @ mine

Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNCIL Claims Operations – Auto

[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** Precise Auto Service [mailto:Support@preciseauto.sg]  
**Sent:** Friday, November 30, 2018 11:01 AM  
**To:** AIG SGP, Claims-Survey  
**Cc:** Tan, Lily (AIG)  
**Subject:** Pre-repair Inspection for SLX 3152G. Your Insured Veh no : SDK 28R

Dear Sir,

We refer to the above mentioned subject. Herewith enclosed 2 days notice for your attention.

Please arrange a date and time to do PRI for our client's vehicle (*SLX 3152G*) in our workshop ASAP.

Thank You.

Best Regards  
 Arine

T : 6745 7367 | F : 6841 3390

E : [support@preciseauto.sg](mailto:support@preciseauto.sg)

W : [www.preciseauto.sg](http://www.preciseauto.sg)

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883

Follow us on social media:

<https://www.instagram.com/preciseautosys/>

<https://twitter.com/preciseautosys>

<https://www.facebook.com/PreciseAutoService/>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is

received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref CC4/AIG18021757/Aja3

27 MAY 2019

**GOH HNG**  
123 MEYER RD  
#19-05, SINGAPORE 437934

Dear Sir/Madam,

**ACCIDENT INVOLVING SDK 28R AND SLX 3152G ON 21/11/18**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

  
Joy Irene  
Case Handler  
DID: 6841 2409  
FAX: 6741 4108  
Email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

Date: 30/11/18 @ 11am

M/s AIG Asia Pacific Insurance Pte Ltd

By Fax 6835 7416 Only

~~M/S Chartis Singapore Insurance Pte Ltd~~

78 Shenton Way

#08-16 CHARTIS Building

Singapore 079120

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SLX 3152G AND VEHICLE NO. SDK 28R ON 21-11-18 @ 2200hrs AT Stadium Walk.

We refer to the above matter.

We are the appointed repair workshop of vehicle no. SLX 3152G.

We understand that you are the insurer of vehicle no. SDK 28R.

The owner of vehicle no. SLX 3152G has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

Kindly take note that we hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SLX 3152G at my premises.

  
Yours faithfully

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, PRECISE AUTO SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$52,550.00 (Global Sum)(All-in) for vehicle no. SLX 3152G that was damaged pursuant to the accident which occurred on 21/11/2018 (date) along KALLANG LEISURE PARK CAR PARK (location) involving vehicle no/s SDK 28R. This is pursuant to the inspection conducted on 30/11/2018 (date) at "the Oworkshop".

We/I confirm that we/I are/am authorized by the owner TAN HOCK KENG ("the third party claimant") of vehicle no. SLX 3152G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLX 3152G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of June (month) 2019 (year)



*Wf*

Signed by appointed surveyor  
chop)

*[Signature]*



Signed by "the workshop" (with

**VEHICLE DAMAGE DISCHARGE ONLY**

This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 21-11-18

OUR REF : SLX 3152G/T/18 (SJE)

**TAN HOCK KENG**

Blk 503 Sembawang Road

#02-28

Singapore 757707

## TAX INVOICE

Invoice No. : TP1904-013

DATE : 28-04-19

**FINAL BILL ON VEH. NO. : SLX 3152G**

**VEHICLE MODEL : TOYOTA VIOS**

**LUMP SUM REPAIR**

**INCLUDING SUPPLY OF PARTS & LABOUR**

**PANEL BEATING & SPRAY PAINTING**

**1,900.00**

<b>SUB-TOTAL</b>	<b>:</b>	<b>1,900.00</b>
<b>ADD GST 7%</b>	<b>:</b>	<b>133.00</b>
<b>TOTAL AMOUNT SGD</b>	<b>:</b>	<b>2,033.00</b>


This is a computer generated document and requires no signature.

---


# INVOICE

DATE: December 4, 2018  
INVOICE # PCR/RI/2018/12/037  
RA # R-0472  
FOR: Accident Car  
Replacement  
Vehicle # SJR 4748 L  
ent Method:

**Bill To:**  
PRECISE AUTO SERVICE  
CO : TAN HOCK KENG  
503 SEMBAWANG ROAD #02-28  
SINGAPORE 757707

DESCRIPTION	NUMBER OF DAYS	RATE	AMOUNT
RENTAL (30/11/2018 - 04/12/2018) YOUR REF : SLX 3152 G  	5	\$120	\$600
		TOTAL	\$ 600.00

Make all cheques payable to **Precise Car Rental Pte Ltd**



Signature \_\_\_\_\_



# PRECISE CAR RENTAL

1 Kaki Bukit Avenue 6 #02-34 Autobay @ Kakibukit S(417883)

Tel: 6745 7367 Fax: 6841 3390

RA No.: R-0472

PRECISE CAR RENTAL

VEHICLE HIRING AGREEMENT

TP CLAIM

Workshop: PRECISE


## HIRER'S PARTICULARS

Name (as in IC): TAN HOCK KENG  
 NRIC/Passport No.: 877183461 Date of Birth: 05/7/1977  
 Address: 503 SEMBAWANG ROAD #02-28 Age: \_\_\_\_\_  
 S( 757707 )  
 Name & Address of Employer: \_\_\_\_\_  
 Occupation: \_\_\_\_\_ Driving Exp.: \_\_\_\_\_  
 Driving Licence No.: \_\_\_\_\_ Passed Date: \_\_\_\_\_  
 D/L Type: Local/Int'l/Other: \_\_\_\_\_  
 Tel(O) \_\_\_\_\_ (R) \_\_\_\_\_ HP 96449577

## DRIVER'S PARTICULARS

Name (as in IC): Tan Hock Keng  
 NRIC/Passport No.: 877183461 Date of Birth: 05/7/1977  
 Address: 503 Sembawang Road Age: \_\_\_\_\_  
 #02-28 S( 757707 )  
 Occupation: \_\_\_\_\_ Driving Exp.: \_\_\_\_\_ Yrs  
 Driving Licence No.: \_\_\_\_\_ Passed / Expiry Date: 11-11-2025  
 D/L Type: Local/Int'l/Other: \_\_\_\_\_ Contact No: 96449577

\* LH Side Mirror  
(small glass drop  
off).



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given **Precise Car Rental** in connection with this agreement is true.

### IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of **Precise Car Rental**. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace a replacement vehicle if an accident occurred. Any damage to the car will be repair at our authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
  - The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
  - In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
  - The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
  - All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
  - I understand and agree to the personal data collection statement.

Date Out	Time Out	Mileage	Check By	Remarks
30/11/18	10:40 AM			

Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To **Precise Car Rental** And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"

Date In	Time In	Mileage	Check By	Remarks
04/12/18	15:24:73	4:54 pm		

Hirer's Own Vehicle No: SLX 3152G Replace Veh No: \_\_\_\_\_  
 Loan Vehicle No: SSR A748 L VR No: \_\_\_\_\_  
 Make & Model: TOYOTA AIGO Auto/Manual Group: \_\_\_\_\_  
 CHARGES : \$ cts  
 Daily 5 day @\$ 120 Per day 600 00  
 Weekly/Monthly week @\$ Per week/Monthly  
 Others  
 CDW/PAI @\$ Per day/Monthly  
 Delivery/Collection Svc  
 GST  
 OR No: (A) SUB-TOTAL  
 Petrol Level & Surcharge  
 OUT IN E 1/4 1/2 3/4 F  
 First \_\_\_\_\_ km FREE per day GST  
 Excess mileage is chargeable at \_\_\_\_\_ cents per km  
 TOTAL CHARGES 600 00

Security Deposit : \$ \_\_\_\_\_ Bank: \_\_\_\_\_  
 CASH/NETS/VISA/MC/AMEX/CHQ No: \_\_\_\_\_  
 Expiry Date: \_\_\_\_\_ Card ID No: \_\_\_\_\_  
 Name as in Card: \_\_\_\_\_

NON WAIVER EXCESS (Subject to GST): \$ 2000 + \$2000/-

### ACCESSORIES CHECK

- ☐ IU ☐ STD Tools ☐ Hub Cap ☐ Radio / CD Cartridge  
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature : dh n

Additional Driver's Signature : \_\_\_\_\_

SINGAPORE Use Only

Hirer's/Driver Signature dh n

Hirer's/Driver Signature dh n

**Enquire Vehicle & Owner Information ( Vehicle No. SDK28R As At 30 Nov 2018 / 10:30:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: PRECISE SLX3152 G

**Current Owner Details**

Owner ID Type: Singapore NRIC

Owner ID: S1742808Z

Owner Name: GOH HNG

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 123

Registered Street Name: MEYER ROAD

Registered Unit No.: # 19 - 05

Registered Building Name: -

Registered Postal Code: 437934

**Current Vehicle Details**

Vehicle No.: SDK28R

Make Description/Model: MERCEDES BENZ / C180 AVANTGARDE (R17 LED)

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-190721

Date of Request: 10/12/2018

Your Ref No: WALK IN JURAIMI

PRECISE AUTO SERVICE  
NO 1 KAKI BUKIT AVE 6, #02-34/36  
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SLX3152G

Date of Accident: 21/11/2018

Place of Accident: STADIUM WALK

Involving Vehicle No: SDK28R

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

## TAX INVOICE

Our Ref No: GR-18-190722

Date of Request: 10/12/2018

Your Ref No: WALK IN JURAIMI

PRECISE AUTO SERVICE  
NO 1 KAKI BUKIT AVE 6, #02-34/36  
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 21/11/2018

Vehicle No: SLX3152G

Place of Accident: STADIUM WALK

Involving Vehicle No: SDK28R

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SDK28R	STADIUM WALK	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2018 11:12 <a href="#">Edit Reg</a>		30 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	GOH HNG, ID: S1742808Z								
Main Claimant:	TAN HOCK KENG, ID: S7718346I								
Vehicle Reg. No.:	SLX3152G	Date of Loss:	21/11/2018 10:00 - :59 [7 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8548373437SG	Policy/Cover Note No.:	1800050588 (Comprehensive) Coverage: 21/05/2018 - 20/05/2019						
Vehicle Reg. No. (Insured):	SDK28R	Policy No. (Claimant):	CN883002						
		Excess:							
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/12/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (04/12/2018): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLX3152G (8548373437SG)  
[SDK28R]  
TP  
TAN HOCK KENG  
Nov 21 2018 10:00AM  
[GOH HNG]  
Precise Auto Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
2	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
3	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
4	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
5	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
6	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
7	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
8	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
9	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
10	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
11	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
12	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
13	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
14	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
15	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
16	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
17	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
18	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
19	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
20	16/05/19 09:51		General View															Load JPG <input checked="" type="checkbox"/>		
21	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
22	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
23	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
24	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
25	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
26	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
27	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
28	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
29	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
30	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
31	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
32	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
33	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
34	16/05/19 09:52		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 20:49	ACKNOWLEDGEMENT EMAIL TO AIG DD 30.11.2018	Load PDF	
2	03/12/18 20:49	EMAIL FROM AIG DD 30.11.2018	Load PDF	
3	03/12/18 20:49	NOTIFICATION FROM WORKSHOP +LTA SEARCH	Load PDF	
4	05/12/18 20:28	TP GIA REPORT	Load PDF	
5	17/06/19 08:56	WORKSHOP INVOICE	Load PDF	
6	17/06/19 08:56	AUTHORISATION TO ACT FORM	Load PDF	
7	17/06/19 08:56	Release Voucher	Load PDF	
8	17/06/19 08:56	RENTAL RECEIPT	Load PDF	
9	17/06/19 08:56	LTA SEARCH	Load PDF	
10	17/06/19 08:56	GIA SEARCH	Load PDF	
11	17/06/19 08:56	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/12/18 08:57	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDK28R (Insd veh)	Model:	TOYOTA VIOS 1.5 (A)
	SLX3152G (TP veh)		
Date of Accident:	21/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No	
Repair Estimate	:	\$		4,987.12
Final Repair Cost	:	\$		2,550.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		5 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		2,550.00

**Is Third Party Workshop GIA Registered?**    ☐ [ ] YES    ☒ [ X ] NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Precise Auto Service	: \$	2,550.00
2)		: \$	
3)		: \$	

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Jun  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021757/AJA3Q2

Date: 17/06/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800050588

**Claimant Vehicle No :** SLX3152G

**Insured Vehicle No :** SDK28R

Date of Loss: 21/11/2018

Nature of Claim:

TP

Claim No: 8548373437SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX3152G**

Make &amp; Model: TOYOTA VIOS, 1.5 (A)

Reg. Date: 23/03/2018 (Man. Year: 2018)

Colour: Black

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 2NR5203473

Chassis No: MR2B23F3801114286

Odometer: 26090 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,740.86	1,305.20	1,435.66	52.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,080.00	840.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,660.86</b>	<b>2,385.20</b>	<b>2,275.66</b>	<b>48.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
(S\$)	4,660.86	1,900.00	2,760.86	59.23
<b>+ GST 7.00/7.00% (S\$)</b>	326.26	133.00	193.26	59.23
<b>Nett Amount (S\$)</b>	<b>4,987.12</b>	<b>2,033.00</b>	<b>2,954.12</b>	<b>59.23</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		37.00		
<b>Nett Liability (S\$)</b>		<b>2,570.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,550.00</b>		

### INSPECTION

Date of Assignment: 30/11/2018

Date Inspected: 30/11/2018 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deformed	431.35 FL	*431.35 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	381.90 FL	*381.90 FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	172.10 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*30.00 FL
5	2		*REAR BUMPER SIDE ATTACHMENTS	Not Necessary	344.20 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	348.90 FL	*78.00 FL
7	1		*BOOT LID BADGE	Necessary	63.10 FL	*63.10 FL
8	1		*BOOT LID EMBLEM VIOS	Necessary	63.75 FL	*63.75 FL
9	1		*BOOT LID EMBLEM E	Necessary	51.10 FL	*51.10 FL
10	1		*BOOT LID WEATHERSTRIP	Not Necessary	231.35 FL	*- FL
11	1		*TAIL LAMP LH	Cracked	374.40 FL	*374.40 FL
12	1		*TAIL LAMP SEALANT	Not Necessary	50.00 FL	*- FL
13	1		*REAR BUMPER PARKING SENSOR	Damaged	380.00 FS	*200.00 FS
14	1		*BOOT LID OUTER KELESS SENSOR	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,401.15</b>	<b>1,673.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>660.29</b>	<b>368.40</b>
<b>Total Parts (\$\$)</b>	<b>2,740.86</b>	<b>1,305.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
3	TO REMOVE & REFIX CENTER UPHOLSTERY	New	120.00	0.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
5	TO RESPRAY AFFECTED AREAS	New	800.00	600.00
6	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR BOOT LID & REAR END PANEL AND ALIGNED ALL PARTS	New	650.00	400.00
Gross Labour Cost (\$\$)			<b>1,920.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >