

INS. CASE OWNER:

CC 4, 111 180 2759, K pa3

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

3/11/18

Date / Time :

30/11/2018

Registered in Merimen:

3/1/18

Pre-assign / CCU / FTE

GBB 8911 J



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

29/11/2018

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SLP 32944



INSRS:

WSP:

Tel :

Liability :

RMKS:

Comme
Auto.


INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SLP 32944 - X; GBB 8911 J - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

From: Date: 3/12/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 3294Y
at Workshop m/s Convince Auto
of 176 Sin Ming Drive # 04-04

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date:

Person Contacted:

Vehicle: IN / OUT

65561131

Veh No:

SLP 3294Y

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Handp 1721

C.C.

1496

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

54204

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

R41

1210702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

29/11/18

D.O.I.

3/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12 R41 pass to Convince

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL