

ASS. REC. BY:

REF:

CS3/MSG18021767/Gcd3⁹²

Special Instruction:

Surveyor:

Meinmen

ASSIGNMENT (Office)

From (Person):

Mund Ashik

of

MSG

Date/Time

04/12/18 @ 9:05am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 5707 Z

Insured:

SGT 979M

at Workshop m/s

Demick Motor

Tel:

96333593

of

9002 Tampines st 93 # 01-72 Tampines Ind. Park A

Policy No:

290697256DMA

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:30am @ 4/12/18

Person Contacted:

jeromy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SLW 5707Z - NA/AIG18011554/24

DOA: 25/06/2018

SGT 979M - NA/INC11004198/r

DOA: 7/3/2011

Signature

PRS

Xpd.

REF: MSIG

06911

(-2020)

ASSIGNMENT

From:

Date: 4/12/2018

Veh No:

SLW57078

Yr Regn

24 Feb 2010

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 57078

at Workshop m/s

Demick Motor

of

9002 Tampines St. 93 # 01-72,

Insured:

Tampines Ind. Park A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value:

\$16K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

G.C

1591

Colour:

white

A/C

Insured / Std / NI / NA

Sp. Reading

98728

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No:

KNAFW611MA 5204108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

04-12-18

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RA

The ☒ Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

RECEIVED 07 DE 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

PRG

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		04 Dec 2018 09:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOI KOK KHEONG, ID: S0124213Z			
Main Claimant:	TENG KAH SENG			
Vehicle Reg. No.:	SLW5707Z	Date of Loss:	29/11/2018 00:00 - :59 [17 Months and 24 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	290697256DMA (Comprehensive) Coverage: 20/01/2018 - 19/01/2019	
Vehicle Reg. No. (Insured):	SGT979M	Policy No. (Claimant):		
		Excess:		
Repairer:	Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A, 528836 Tampines - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/12/2018]			
Adj Asg. Remarks:	OI not reported, SJE disagree - assign LKK, Contact : Mr Jeromy at HP 9633 3593			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/11/2018 12:53
Date Of Accident	29/11/2018 19:10
Exact Location Of Accident	ORCHARD BLVD TO PATERSON RD BESIDE ION ORCHARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW5707Z
Insured/Policyholder	
Name Of Registered Owner	TENG KAH SENG (DING JIASHENG)
NRIC No	S9120691I
Email Address	TENGAHSENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98156827
Alternative Phone No	OTHERS-98156827

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE KOUP-1.6 SX ABS D/AB SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800024618
Cover Note Number	

Driver

Name of Driver	TENG KAH SENG (DING JIASHENG)
NRIC No	S9120691I
Date Of Birth	11/06/1991
Occupation	INDOOR
Date Of Driving Pass	31/12/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98156827
Fax Number	
Contact Number	OTHERS-98156827
Email Address	TENGAHSENG@GMAIL.COM

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TENG KAH SENG (DING JIASHENG)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLW5707Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

DUANGDAW TENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLW5707Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 12:50pm
30/11/18

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: [Signature]
NRIC/PIR No.:



**SINGAPORE
POLICE FORCE**



T/20181130/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181130/7002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLW5707Z	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800024818	12/03/2018	11/03/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Passenger				
Name	Duangdaw Teng		ID No.	G1680608R
Related Vehicle	SLW5707Z (Car)		Contact No.	97265965
Hospital/Clinic	STREET 11 CLINIC		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/11/2018		Date Discharge	30/11/2018
No. of Days granted Medical Leave	02	Degree of Injury	Serious	
Driver				
Name	TENG KAH SENG		ID No.	S9120691I
Related Vehicle	SLW5707Z (Car)		Contact No.	98156827
Hospital/Clinic	STREET 21 CLINIC (TAMPINES)		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	30/11/2018		Date Discharge	30/11/2018
No. of Days granted Medical Leave	02	Degree of Injury	Serious	

Brief Details.

My vehicle SLW5707Z was stopped behind the traffic light waiting for the traffic light to turn green. When the traffic light turn green, Vehicle SGT979M cut into my lane of travel and hit the front left portion of my vehicle. After the collision, Vehicle SGT979M sped off, turn left into Paterson Road and left the scene. My wife Duangdaw Teng G1680608R and myself suffered from neck and back pain after the incident.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0691I
Vehicle Details	
Vehicle No.:	SLW5707Z
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FCAH366727
Chassis No.:	KNAFW611MA5204108
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$15,754.00
Original Registration Date:	24 Feb 2010
First Registration Date:	24 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$15,754.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2020
PARF Rebate Amount:	\$8,664.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$2,254.00
Total Rebate Amount:	\$10,918.00

The information contained herein is correct as at 05 Dec 2018

OK

DRIVER NRIC & LICENSE Pg. 1

386633

NRIC No. S91206911

Place of birth: 01-08-2008

NT, AX, 120 UNIT DRIVE, GENTLE VALLEY, SINGAPORE 691101

NRIC No. S91206911 Date of birth: 01-11-2006 (M) No. 6627410

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 5: Motor Carpent (200kg) with 4 or fewer passengers, maximum 31 Dec 2012 at 00:00:00, and class 5B (a) vehicles on 200kg

License No. S91206911

NP 12M

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S91206911

Photo

TENG KAH SENG (DING JIAHENG)

丁嘉生

Race: CHINESE

Date of birth: 11-08-1991 Sex: M

Country of birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENSE

NRIC No. S91206911

TENG KAH SENG (DING JIAHENG)

Date of birth: 11 Jun 1991

Valid till: 31 Dec 2012

License No. S91206911

Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		04 Dec 2018 09:05 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOI KOK KHEONG, ID: S0124213Z		
Main Claimant:	TENG KAH SENG		
Vehicle Reg. No.:	SLW5707Z	Date of Loss:	29/11/2018 00:00 - :59 [105 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 577704	Policy/Cover Note No.:	290697256DMA (Comprehensive) Coverage: 20/01/2018 - 19/01/2019
Vehicle Reg. No. (Insured):	SGT979M	Policy No. (Claimant):	
		Excess:	
Repairer:	Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A, 528836 Tampines - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 05/12/2018]		
Adj Asg. Remarks:	OI not reported, SJE disagree - assign LKK, Contact : Mr Jeromy at HP 9633 3593		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLW5707Z (577704)**

[SGT979M]

TP

TENG KAH SENG

Nov 29 2018 12:00AM

[LOI KOK KHEONG]

Derrick Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 11:13	Accident Statement From: SC - Reg. No: 5GT979M, Claimant: LOI KOK KHEONG	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/18 09:58	General View	 Load JPG	☒
2	07/12/18 09:58	General View	 Load JPG	☒
3	07/12/18 09:58	General View	 Load JPG	☒
4	07/12/18 09:58	General View	 Load JPG	☒
5	07/12/18 09:58	General View	 Load JPG	☒
6	07/12/18 09:58	General View	 Load JPG	☒
7	07/12/18 09:58	General View	 Load JPG	☒
8	07/12/18 09:58	General View	 Load JPG	☒
9	07/12/18 09:58	General View	 Load JPG	☒
10	07/12/18 09:58	General View	 Load JPG	☒
11	07/12/18 09:58	General View	 Load JPG	☒
12	07/12/18 09:58	General View	 Load JPG	☒
13	07/12/18 09:58	General View	 Load JPG	☒
14	07/12/18 09:58	General View	 Load JPG	☒
15	07/12/18 09:58	General View	 Load JPG	☒
16	07/12/18 09:58	General View	 Load JPG	☒
17	07/12/18 09:58	General View	 Load JPG	☒
18	07/12/18 09:58	General View	 Load JPG	☒
19	07/12/18 09:58	General View	 Load JPG	☒
20	07/12/18 09:58	General View	 Load JPG	☒
21	07/12/18 09:58	General View	 Load JPG	☒
22	07/12/18 09:58	General View	 Load JPG	☒
23	07/12/18 09:58	General View	 Load JPG	☒
24	07/12/18 09:58	General View	 Load JPG	☒
25	07/12/18 09:58	General View	 Load JPG	☒
26	07/12/18 09:58	General View	 Load JPG	☒
27	07/12/18 09:58	General View	 Load JPG	☒
28	07/12/18 09:58	General View	 Load JPG	☒
29	07/12/18 09:58	General View	 Load JPG	☒
30	07/12/18 09:58	General View	 Load JPG	☒
31	07/12/18 09:58	General View	 Load JPG	☒

Assessment Reports			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	07/12/18 09:58	General View	 Load JPG	✓
33	07/12/18 09:58	General View	 Load JPG	✓
34	07/12/18 09:58	General View	 Load JPG	✓
35	07/12/18 09:58	General View	 Load JPG	✓
36	07/12/18 09:58	General View	 Load JPG	✓
37	07/12/18 09:58	General View	 Load JPG	✓
38	07/12/18 09:58	General View	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/12/18 13:38	Pri from Vision Law LLC	 Load PDF	
2	03/12/18 16:35	Survey Disagree on SJE - assign LKK	 Load PDF	
3	03/12/18 18:19	Workshop & Location to Survey	 Load PDF	
4	07/12/18 11:13	SLW5707Z E-FILE & POLICE REPORT From: SC - Reg. No: SGT979M, Claimant: LOI KOK KHEONG	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021767/GCD3S2

Date: 18/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 290697256DMA

Claimant Vehicle No: SLW5707Z

Insured Vehicle No: SGT979M

Date of Loss: 29/11/2018

Nature of Claim: TP

Claim No: 577704

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW5707Z

Make & Model: KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A)

Engine No: G4FCAH366727

Reg. Date: 24/02/2010 (Man. Year: 2009)

Chassis No: KNAFW611MA5204108

Colour: White

Odometer: 98728 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17

Rear Tyre Size: 225/45ZR17

Front Left Side: CST 6 mm

Rear Left Side: CST 6 mm

Front Right Side: CST 6 mm

Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/12/2018

Derrick Motor Works (HQ)

Date Inspected: 04/12/2018 Inspected At:

9002 Tampines St. 93, #01-72 Tampines Industrial Park A

Singapore 528836

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/18/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts:	143	KIA CERATO FORTE KOUP 1.6 SX ABS D/AB SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW5707Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >