

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD Ref: CS3/ASM18021784/Jcbs2

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 18-12-2018

068811


ATTN: DANIEL PAY Code: ASM

AIII	I. DANIEL FAT		Code. ASIVI				
1. Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	GBG 1212M	Veh. Inspected	SJW 7062K			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	S8M01547	Excess (\$)	0.00			
	Assign From	SMART CLAIM (DANIEL PAY)	Assign Date	04/12/2018			
2.	2. Vehicle Particulars & Condition						
	Make & Model	NISSAN	c.c	1997			
	Engine No.	HIDDEN	Year of Reg.	2010			
	Chassis No.	JN1BDUJ32Z0001513	Colour	GREY			
	Odometer	171968 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.	3. Conditions of Tyres						
		la.					

3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/40R18	CONTINENTAL	6 mm	
	L/H Front Tyre	245/40R18	CONTINENTAL	6 mm	
	R/H Rear Tyre	245/40R18	CONTINENTAL	6 mm	
	L/H Rear Tyre	245/40R18	CONTINENTAL	6 mm	

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



Page No.:1 of 1

Ş	5.	General Information					
	Ac	cident Date	27/11/2018	Inspect Date / Time	05/12/2018 ( 11:14 AM )		
Γ	Su	rvey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000 - \$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

Report Ref No. CS3/ASM18021784/Jcbs2

Inspected By

ONG HWEE JIE

K.K.LAU CPT(RET)

**Automotive Assessor** 

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.