

<<

Service Request Details

Claim

S8M01547

Reference

CS3/ASM18021784/Jcbs2 

Loss Date

November 27, 2018

Request Date

December 4, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle

SJW7062K

Registration #

Make

TPVD NISSAN

Model

TEANA LX200

Service Address

, , ,

Primary Contact/Insured

KIM SENG HENG ENGINEERING
CONSTRUCTION (PTE) LTD
36 SENOKO ROAD, 758108, Singapore

SHARUMLAM@KIMSENGHENG.COM.SG

Claim Handler

PAY Daniel

zhihao.pay@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1[3].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	December 20, 2018
 LKKPreRepairInspection[3].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	December 20, 2018
 Photo of damaged parts.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	December 11, 2018
 Photo After Spray.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	December 11, 2018
 Inspection Photographs.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	December 11, 2018
 EMAIL (No SJE).msg	Letters and Correspondence	Solicitor / Advocate	KADRI Mateen	December 4, 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SURVEY LIST SEND TO ADVOCATES & SOLICITORS.msg	Letters and Correspondence	Solicitor / Advocate	KADRI Mateen	December 3, 2018
 GIA REPORT OF SJW7062K (TP).PDF	Reports & Statement	GIA Report	KADRI Mateen	December 3, 2018
 EMAIL FROM ADVOCATES & SOLICITORS (THIRD PARTY PRI).msg	Legal	Others	KADRI Mateen	December 3, 2018
 GIA REPORT OF GBG1212M (INSD).PDF	Reports & Statement	GIA Report	KADRI Mateen	December 3, 2018